


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Arranounbai School (5656)  
**Region :** Northern Sydney  
**State Electorate :** Wakehurst  
**Local Government Area :** Warringah

**Initial Survey :** Noel Arnold & Associates : 15 - Jan - 2008  
**Reviewed By :** AECOM : 28 - Jun - 2016



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Support Unit - 1973 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground / no access points.					
Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction, access from external roof (west). 3.5m.					
Eaves Linings	Flat AC Sheeting 5656/B00A/R0057/Ceiling Structures/Linings/S2	42m2	South-west corner	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>

**Interior****B00A - R0001 - Toilet - P**

No Asbestos

**B00A - R0002 - Home Base - P**

No Asbestos

**B00A - R0003 - Home Base Store - P**

No Asbestos

**B00A - R0004 - Home Base Store - P**

No Asbestos

**B00A - R0005 - Home Base - P**

No Asbestos

**B00A - R0006 - Home Base - P**

No Asbestos

**B00A - R0007 - Home Base Store - P**

No Asbestos

**B00A - R0008 - Music Store**

No Asbestos

**B00A - R0009 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	1m2	All surfaces, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
5656/B00A/R0060/Ceiling Structures/Linings/S3						

**B00A - R0010 - Music Learning Space**

No Asbestos

**B00A - R0011 - External Movement**

No Asbestos

**B00A - R0012 - Movement**

No Asbestos

**B00A - R0013 - Speech Therapy**

No Asbestos

**B00A - R0014 - Speech Therapy**

No Asbestos

**B00A - R0015 - Speech Therapy**

No Asbestos

**B00A - R0016 - General Storeroom**

No Asbestos

**B00A - R0017 - Speech Therapy**

No Asbestos

**B00A - R0018 - Speech Therapy**

No Asbestos

**B00A - R0019 - Speech Therapy**

No Asbestos

**B00A - R0020 - Therapy Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
						No Asbestos
						<b>B00A - R0021 - Staff Kitchen</b>
						No Asbestos
						<b>B00A - R0022 - Staff Room Annexe</b>
						No Asbestos
						<b>B00A - R0023 - Therapy</b>
						No Asbestos
						<b>B00A - R0024 - Staff Toilet</b>
						No Asbestos
						<b>B00A - R0025 - Duplicating Workroom</b>
						No Asbestos
						<b>B00A - R0026 - Staff Room</b>
						No Asbestos
						<b>B00A - R0027 - Movement</b>
						No Asbestos
						<b>B00A - R0028 - Clerical Office</b>
						No Asbestos
						<b>B00A - R0029 - Clerical Office</b>
						No Asbestos
						<b>B00A - R0030 - Staff Room</b>
						No Asbestos
						<b>B00A - R0031 - Staff Kitchen</b>
						No Asbestos
						<b>B00A - R0032 - Plant</b>
						No Asbestos
						<b>B00A - R0033 - Staff Toilet</b>
						No Asbestos
						<b>B00A - R0034 - Movement</b>
						No Asbestos
						<b>B00A - R0035 - Staff Toilet</b>
						No Asbestos
						<b>B00A - R0036 - Interview</b>
						No Asbestos
						<b>B00A - R0037 - Staff Room Annexe</b>
						No Asbestos
						<b>B00A - R0038 - Deputy Principal</b>
						No Asbestos
						<b>B00A - R0039 - Principal</b>
						No Asbestos
						<b>B00A - R0040 - Movement</b>
						No Asbestos
						<b>B00A - R0041 - Clerical Office</b>
						No Asbestos
						<b>B00A - R0042 - General Storeroom</b>
						No Asbestos
						<b>B00A - R0043 - Entry Vestibule</b>
						No Asbestos
						<b>B00A - R0044 - Special Programs Room</b>
						No Asbestos
						<b>B00A - R0045 - Computer Store</b>
						No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0046 - Home Base Store - P</b>						
No Asbestos						
<b>B00A - R0047 - Distribution Board</b>						
Note: No inspection of live electrical installation.						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces, Lower portion	Some Damage / Unsealed (3)	Medium (2)	Medium Priority (4-5)
5656/B00A/R0060/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0048 - Home Base - P</b>						
No Asbestos						
<b>B00A - R0049 - Home Base - P</b>						
No Asbestos						
<b>B00A - R0050 - Home Base Store - P</b>						
No Asbestos						
<b>B00A - R0051 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0053 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0054 - Staff Room Annexe</b>						
No Asbestos						
<b>B00A - R0055 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0056 - External Movement</b>						
No Asbestos						
<b>B00A - R0057 - Covered Vehicle Area/Porte Cochere</b>						
Ceiling Structures/Linings	Flat AC Sheeting	141m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5656/B00A/R0057/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>	
Wall Linings Internal	Flat AC Sheeting	5m2	East facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
5656/B00A/R0057/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0058 - Canteen</b>						
No Asbestos						
<b>B00A - R0059 - Cleaning Supplies</b>						
No Asbestos						
<b>B00A - R0060 - P.E. Store</b>						
Ceiling Structures/Linings	Flat AC Sheeting	36m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5656/B00A/R0060/Ceiling Structures/Linings/S3					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0061 - Main Switch Board</b>						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
5656/B00A/R0057/Ceiling Structures/Linings/S2					<b>Chrysotile (white asbestos)</b>	
Electrical Mounting Board	Resinous Board	3Unit	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Electrical Hazard</b>						
<b>B00A - R0062 - Communal Space</b>						
No Asbestos						
<b>B00A - R0063 - Communal Space</b>						
No Asbestos						
<b>B00A - R0064 - Hall Chair Store</b>						
No Asbestos						
<b>B00A - R0065 - Staff Room Annexe</b>						
No Asbestos						
<b>B00A - R0066 - Cleaning Distributed Store</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0067 - Staff Room Annexe</b>						
No Asbestos						
<b>B00A - R0068 - Security Store</b>						
No Asbestos						
<b>B00A - R0069 - General Assistant/Bulk Store</b>						
No Asbestos						
<b>B00A - R0071 - Toilet - P</b>						
No Asbestos						
<b>B00A - R0072 - Reading Area</b>						
No Asbestos						
<b>B00A - R0073 - Library Office/Workroom</b>						
No Asbestos						
<b>B00A - R0074 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0075 - Craft Store</b>						
No Asbestos						
<b>B00A - R0076 - Special Programs Room</b>						
No Asbestos						
<b>B00A - R0077 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0078 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0079 - Sports Store</b>						
No Asbestos						
<b>B00A - R0080 - Toilet - P</b>						
No Asbestos						
<b>B00A - R0081 - Toilet - P</b>						
No Asbestos						
<b>B00A - R0082 - Reading Area</b>						
No Asbestos						
<b>B00A - R0083 - Home Base - P</b>						
No Asbestos						
<b>B00A - R0084 - Home Base Store - P</b>						
No Asbestos						
<b>B00A - R0085 - Home Base Store - P</b>						
No Asbestos						
<b>B00A - R0086 - Home Base - P</b>						
No Asbestos						
<b>B00A - R0087 - Therapy</b>						
No Asbestos						
<b>B00A - R0088 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0091 - Access Shower/Toilet</b>						
No Asbestos						
<b>B00A - R0092 - Access Shower/Toilet</b>						
Wall Linings Internal	Flat AC Sheeting					
	5656/B00A/R0094/Wall Linings Internal/S1					<b>No Asbestos Detected</b>
<b>B00A - R0093 - Access Shower/Toilet</b>						
No Asbestos						
<b>B00A - R0094 - Access Shower/Toilet</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
Wall Linings Internal	Flat AC Sheeting 5656/B00A/R0094/Wall Linings Internal/S1					No Asbestos Detected
<b>B00A - R0096 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting 5656/B00A/R0060/Ceiling Structures/Linings/S3	1m2	West, fire hose reel cupboard	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
Wall Linings Internal	Flat AC Sheeting 5656/B00A/R0094/Wall Linings Internal/S1					No Asbestos Detected
<b>B00A - R0097 - Practical Activities - P - 1hb</b>						
No Asbestos						
<b>B00A - R0098 - Movement</b>						
Wall Linings Internal	Flat AC Sheeting 5656/B00A/R0094/Wall Linings Internal/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting 5656/B00A/R0060/Ceiling Structures/Linings/S3	1m2	North-Western fire hose reel cupboard	Good Condition (1)	Low (1)	Low Priority (2-3) <b>Chrysotile (white asbestos)</b>
<b>B00A - R0099 - Movement</b>						
No Asbestos						
<b>B00A - R0100 - Covered Outdoor Learning Area</b>						
No Asbestos						
<b>B00A - R0101 - External Movement</b>						
No Asbestos						
<b>B00A - R0102 - External Movement</b>						
No Asbestos						
<b>B00A - R0103 - Covered Outdoor Learning Area</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

### ***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

***Listing of Electronic Attachments as of 22/03/2017***

**There are no asbestos related file attachment(s) for this school.**

2017