


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Broken Hill Public School (1369)
Region : Western NSW
State Electorate : Barwon
Local Government Area : Broken Hill

Initial Survey : Noel Arnold & Associates : 08 - May - 2008
Reviewed By : : 03 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Administration - 1965 - Sandstone (Sandstone)

Exterior

Signage	Compressed AC Sheet 1369/B00A/Signage/S1	1Unit(s)	South	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids - Slab on Ground						

Interior

B00A - R0001 - Home Base

Wall Linings Internal	Flat AC Sheeting 1369/B00A/R0001/Wall Linings Internal/S5					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00A - R0002 - Home Base Store

No Asbestos

B00A - R0003 - Movement

Wall Linings Internal	Flat AC Sheeting 1369/B00A/R0001/Wall Linings Internal/S5					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00A - R0004 - Home Base Store

No Asbestos

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - Home Base Store

No Asbestos

B00A - R0008 - Personal Effects Storage

No Asbestos

B00A - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Home Base Store

No Asbestos

B00A - R0012 - Home Base

No Asbestos

B00A - R0013 - Home Base

No Asbestos

B00A - R0014 - Home Base Store

No Asbestos

B00A - R0015 - Personal Effects Storage

Wall Linings Internal	Flat AC Sheeting 1369/B00A/R0020/Wall Linings Internal/S2					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00A - R0016 - Home Base Store

No Asbestos

B00A - R0017 - Home Base

No Asbestos

B00A - R0018 - Home Base

No Asbestos

B00A - R0019 - Home Base Store

No Asbestos

B00A - R0020 - Personal Effects Storage

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting 1369/B00A/R0020/Wall Linings Internal/S2					No Asbestos Detected
B00A - R0021 - Distribution Board					Note: No inspection of live electrical installation.	
Wall Linings Internal	Flat AC Sheeting	6m2	North, South, East	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Assumed Asbestos						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Assumed Asbestos						
B00A - R0022 - Movement						
No Asbestos						
B00A - R0023 - Home Base Store						
No Asbestos						
B00A - R0024 - Home Base						
No Asbestos						
B00A - R0028 - Clerical Office						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 1369/B00A/R0031/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00A - R0029 - General Storeroom						
No Asbestos						
B00A - R0030 - Deputy Principal						
No Asbestos						
B00A - R0031 - Entry Vestibule						
Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 1369/B00A/R0031/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00A - R0032 - Principal						
No Asbestos						
B00A - R0033 - Plant						
No Asbestos						
B00A - R0035 - Sick Bay						
No Asbestos						
B00A - R0036 - Staff Toilet						
No Asbestos						
B00A - R0037 - Staff Toilet						
No Asbestos						
B00A - R0039 - Movement						
No Asbestos						
B00A - R0041 - Movement						
No Asbestos						
B00A - R0042 - Staff Room Annexe						
No Asbestos						
B00A - R0043 - Practical Activities						
No Asbestos						
B00A - R0044 - Home Base						
No Asbestos						
B00A - R0045 - Home Base Store						
No Asbestos						
B00A - R0046 - Movement						
No Asbestos						
B00A - R0047 - Clerical Office						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0048 - Entry Vestibule						
No Asbestos						
B00A - R0049 - External Movement						
No Asbestos						
B00A - R9001 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1369/B00A/R9001/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)	
B00A - R9002 - Drinking Facilities						
No Asbestos						
B00A - R9003 - Sports Store						
No Asbestos						
B00A - R9004 - Movement						
No Asbestos						
B00A - R9005 - Communal Space						
No Asbestos						
B00A - R9006 - Movement						
No Asbestos						
B00A - R9007 - Movement						
No Asbestos						
B00A - R9008 - Movement						
No Asbestos						
B00A - R9009 - Drinking Facilities						
No Asbestos						
B00A - R9010 - Cleaning Distributed Store						
No Asbestos						
B00A - R9011 - General Assistant/Bulk Store						
No Asbestos						
B00A - R9012 - General Storeroom						
No Asbestos						
B00A - R9013 - General Storeroom						
No Asbestos						
B00A - R9014 - Main Switch Board						
No Asbestos						
B00A - R9015 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet					
1369/B00A/R0020/Wall Linings Internal/S2					No Asbestos Detected	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - General Learning/Library - 1965 - Sandstone (Sandstone)

Exterior

Underfloor Voids - Slab on Ground

Ceiling Voids - Flat Roof

Interior

B00B - R0001 - Staff Toilet

No Asbestos

B00B - R0002 - Canteen Office/Store

No Asbestos

B00B - R0003 - Canteen Office/Store

No Asbestos

B00B - R0004 - Canteen

No Asbestos

B00B - R0005 - Reading Area

No Asbestos

B00B - R0006 - K.L.A. Store

No Asbestos

B00B - R0007 - Library Office/Workroom

No Asbestos

B00B - R0008 - K.L.A. Store

No Asbestos

B00B - R0009 - Communal Space

No Asbestos

B00B - R0010 - Movement

No Asbestos

B00B - R0011 - Stairs

No Asbestos

B00B - R1001 - Home Base

No Asbestos

B00B - R1002 - Handwashing Facilities

No Asbestos

B00B - R1003 - Withdrawal Space - 1hb

No Asbestos

B00B - R1004 - Movement

No Asbestos

B00B - R1005 - Personal Effects Storage

No Asbestos

B00B - R1006 - Home Base

No Asbestos

B00B - R1007 - Home Base

No Asbestos

B00B - R1008 - Personal Effects Storage

No Asbestos

B00B - R1009 - Toilets - Boys/Girls

No Asbestos

B00B - R1013 - Staff Toilet

No Asbestos

B00B - R1014 - Distribution Board

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	4m2	North, East	Good Condition (1)	Low (1)	Low Priority (2-3)
	1369/B00B/R1014/Ceiling Structures/Linings/S4			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1369/B00B/R1014/Ceiling Structures/Linings/S4			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00B - R1015 - General Storeroom

No Asbestos

B00B - R1016 - Movement

No Asbestos

B00B - R1017 - Staff Room Annexe

No Asbestos

B00B - R1018 - Withdrawal Space - 1hb

No Asbestos

B00B - R1019 - Home Base

No Asbestos

B00B - R1020 - Personal Effects Storage

No Asbestos

B00B - R1021 - Home Base

No Asbestos

B00B - R1022 - Personal Effects Storage

No Asbestos

B00B - R1023 - Personal Effects Storage

No Asbestos

B00B - R1024 - Home Base

No Asbestos

B00B - R1025 - Movement

No Asbestos

B00B - R1026 - Stairs

No Asbestos

B00B - R1027 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1965 - Sandstone (Sandstone)

Exterior

Underfloor Voids - Slab on Ground

Ceiling Voids - Flat Roof

Interior

B00C - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1369/B00A/R9001/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)	

B00C - R0002 - Drinking Facilities

No Asbestos

B00C - R0003 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1369/B00A/R9001/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)	

B00C - R0004 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pre-School Facilities - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids No Asbestos Found

Underfloor Voids - Slab on Ground

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Entry Vestibule

No Asbestos

B00D - R0003 - Security Store

No Asbestos

B00D - R0004 - General Storeroom - Pre

No Asbestos

B00D - R0005 - Home Base - Pre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Practical Activities - Pre

No Asbestos

B00D - R0007 - Toilets - Boys/Girls - Pre

No Asbestos

B00D - R0008 - Laundry - Pre

No Asbestos

B00D - R0009 - Access Shower/Toilet

No Asbestos

B00D - R0010 - Cleaning Distributed Store

No Asbestos

B00D - R0011 - Kitchen - Pre

No Asbestos

B00D - R0012 - Clerical Office - Pre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0013 - Clerical Office - Pre

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0014 - General Storeroom - Pre

No Asbestos

B00D - R0015 - Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Mechanical Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Interior

B00E - R0001 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 2016 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B00F - R0001 - External Movement

No Asbestos

B00F - R0002 - Movement

No Asbestos

B00F - R0003 - Movement

No Asbestos

B00F - R0004 - Staff Kitchen

No Asbestos

B00F - R0005 - Toilets-Unisex

No Asbestos

B00F - R0006 - Clerical Office

No Asbestos

B00F - R0007 - External Movement

No Asbestos

B00F - R0008 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00F - R0009 - Clerical Office

No Asbestos

B00F - R0010 - Community Clinic

No Asbestos

B00F - R0011 - Community Clinic

No Asbestos

B00F - R0012 - General Storeroom

No Asbestos

B00F - R0013 - Handwashing Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017