


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Burke Ward Public School (1432)
Region : Western NSW
State Electorate : Barwon
Local Government Area : Broken Hill

Initial Survey : Noel Arnold & Associates : 08 - May - 2008
Reviewed By : Grencap-NAA : 03 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1898 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	No Asbestos Found

Interior

B00A - R0001 - General Storeroom

No Asbestos

B00A - R0002 - General Storeroom

No Asbestos

B00A - R0003 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet					
		1432/B00A/R0003/Floor Coverings Res/Textile/S7				No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Sheet					
		1432/B00A/R0003/Floor Coverings Res/Textile/S8				No Asbestos Detected

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Personal Effects Storage

No Asbestos

B00A - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0007 - Personal Effects Storage

No Asbestos

B00A - R0008 - External Movement

No Asbestos

B00A - R0009 - Home Base

No Asbestos

B00A - R0010 - Home Base

No Asbestos

B00A - R0011 - Home Base

No Asbestos

B00A - R0012 - Home Base

No Asbestos

B00A - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1898 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - Height Restricted - Approx >8m
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - Height Restricted - Approx >8m
Underfloor Voids	No Asbestos Found

Interior

B00B - R0001 - General Storeroom

No Asbestos

B00B - R0002 - Cleaning Distributed Store

No Asbestos

B00B - R0003 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Sheet 1432/B00B/R0003/Floor Coverings Res/Textile/S6	No Asbestos Detected
-----------------------------	---	----------------------

B00B - R0004 - Kiln Room

No Asbestos

B00B - R0005 - External Movement

No Asbestos

B00B - R0006 - Home Base

No Asbestos

B00B - R0007 - Home Base

No Asbestos

B00B - R0008 - Home Base

No Asbestos

B00B - R0009 - Home Base

No Asbestos

B00B - R0010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1897 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - Height Restricted - Approx >8m
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - Height Restricted - Approx >8m
Underfloor Voids	No Asbestos Found

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0002 - General Storeroom

No Asbestos

B00C - R0003 - Personal Effects Storage

No Asbestos

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Movement

No Asbestos

B00C - R0006 - Home Base

No Asbestos

B00C - R0007 - Movement

No Asbestos

B00C - R0008 - Withdrawal Space - 1hb

No Asbestos

B00C - R0009 - Movement

No Asbestos

B00C - R0010 - Practical Activities - 2hb

No Asbestos

B00C - R0011 - Personal Effects Storage

No Asbestos

B00C - R0012 - Movement

No Asbestos

B00C - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0014 - Movement

No Asbestos

B00C - R0015 - Movement

No Asbestos

B00C - R0016 - General Storeroom

No Asbestos

B00C - R0017 - Home Base

No Asbestos

B00C - R0018 - Withdrawal Space - 1hb

No Asbestos

B00C - R0019 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Building Services - 1950 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Garden Store

No Asbestos

B00D - R0003 - Cleaning Supplies

No Asbestos

B00D - R0004 - General Assistant/Bulk Store

No Asbestos

B00D - R0005 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1432/B00D/R0005/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)	

B00D - R0006 - General Assistant/Bulk Store

No Asbestos

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - General Storeroom

No Asbestos

B00D - R0009 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1432/B00D/R0005/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)	

B00D - R0010 - Cleaning Distributed Store

No Asbestos

B00D - R0011 - Drinking Facilities

No Asbestos

B00D - R1001 - External Movement


Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
1432/B00D/R1001/Wall Linings Internal/S4						

B00D - R1002 - Home Base

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
1432/B00D/R1001/Wall Linings Internal/S4						

B00D - R1003 - Home Base

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
1432/B00D/R1001/Wall Linings Internal/S4						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities/Pupil Facilities - 1964 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Extreme Access Issue - Roof - Raked Ceiling					
Eaves Linings	Flat AC Sheeting 1432/B00E/Eaves Linings/S12					No Asbestos Detected
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

Interior**B00E - R0001 - Canteen Office/Store**

Ceiling Structures/Linings	Flat AC Sheeting 1432/B00E/R0001/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00E - R0002 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting 1432/B00E/R0001/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00E - R0003 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 1432/B00E/R0001/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00E - R0004 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting 1432/B00E/R0001/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00E - R0005 - Canteen

Floor Coverings Res/Textile	Vinyl Tiles 1432/B00E/R0006/Floor Coverings Res/Textile/S1	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 1432/B00E/R0001/Ceiling Structures/Linings/S9					No Asbestos Detected

B00E - R0006 - Communal Space

Floor Coverings Res/Textile	Vinyl Tiles 1432/B00E/R0006/Floor Coverings Res/Textile/S1	239m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
-----------------------------	---	-------	------------	--------------------	---------	--

B00E - R0007 - Raised Platform

No Asbestos

B00E - R0008 - Hall Chair Store

Ceiling Structures/Linings	Flat AC Sheeting 1432/B00E/R0001/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00E - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0010 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 1432/B00E/R0001/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00E - R0011 - Disabled Toilet

Incinerator	Encapsulated Insulation material within unit Assumed Asbestos - Area inaccessible	1Unit(s)	South	Good Condition (1)	Low (1)	Low Priority (2-3)
-------------	---	----------	-------	--------------------	---------	--------------------

B00E - R0012 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 1432/B00E/R0012/Partition Walls (Cubicles)/S10	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 1432/B00E/R0001/Ceiling Structures/Linings/S9					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Incinerator	Encapsulated Insulation material within unit	1Unit(s)	North	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Area inaccessible						
B00E - R0013 - Plant						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
1432/B00E/R0001/Ceiling Structures/Linings/S9						
B00E - R0014 - Cleaning Distributed Store						
No Asbestos						
B00E - R0015 - Movement						
Electrical Backing Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
B00E - R0016 - Other-Community Use						
No Asbestos						
B00E - R0017 - General Storeroom						
No Asbestos						
B00E - R0018 - Movement						
No Asbestos						
B00E - R0019 - Movement						
No Asbestos						
B00E - R0020 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1432/B00E/R0012/Partition Walls (Cubicles)/S10						
Chrysotile (white asbestos)						
Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
1432/B00E/R0001/Ceiling Structures/Linings/S9						
B00E - R0021 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Support Unit (M P S) - 1950 - Timber (Timber)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 1432/B00F/Eaves Linings/S11	20m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)

Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Interior

B00F - R0005 - Staff Kitchen

No Asbestos

B00F - R0006 - Practical Activities - M - 1hb

No Asbestos

B00F - R0007 - Toilet - M

No Asbestos

B00F - R0008 - External Movement

No Asbestos

B00F - R0009 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Administration/Library - 1986 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 1432/B00G/Eaves Linings/S5					No Asbestos Detected

Interior

B00G - R0001 - Drinking Facilities

No Asbestos

B00G - R0002 - External Movement

No Asbestos

B00G - R0003 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 1432/B00G/R0003/Partition Walls (Cubicles)/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00G - R0004 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 1432/B00G/R0003/Partition Walls (Cubicles)/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00G - R0005 - Plant

No Asbestos

B00G - R0006 - Disabled Toilet

No Asbestos

B00G - R0007 - Principal

No Asbestos

B00G - R0008 - Entry Vestibule

No Asbestos

B00G - R0009 - Movement

No Asbestos

B00G - R0010 - Staff Room Annexe

No Asbestos

B00G - R0011 - Staff Room Annexe

No Asbestos

B00G - R0012 - Staff Toilet

No Asbestos

B00G - R0013 - External Movement

No Asbestos

B00G - R0014 - Staff Toilet

No Asbestos

B00G - R0015 - Staff Room Annexe

No Asbestos

B00G - R0016 - Staff Room

No Asbestos

B00G - R0017 - Plant

No Asbestos

B00G - R0018 - Duplicating Workroom

No Asbestos

B00G - R0019 - Security Store

No Asbestos

B00G - R0020 - Clerical Office

No Asbestos

B00G - R0021 - Sick Bay

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00G - R0022 - Security Store

No Asbestos

B00G - R0023 - Interview

No Asbestos

B00G - R0024 - Cleaning Distributed Store

No Asbestos

B00G - R0025 - Special Programs Store

No Asbestos

B00G - R0026 - Special Programs Room

No Asbestos

B00G - R0027 - Main Switch Board

No Asbestos

B00G - R0028 - Plant

No Asbestos

B00G - R0029 - Reading Area

No Asbestos

B00G - R0030 - Seminar/Study

No Asbestos

B00G - R0031 - Library Office/Workroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1950 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	20m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1432/B00H/Eaves Linings/S13			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

Interior

B00H - R0001 - Staff Toilet

Incinerator	Encapsulated Insulation material within unit	1Unit(s)	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Area inaccessible					

B00H - R0002 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	42m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1432/B00H/R0002/Ceiling Structures/Linings/S14			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00H - R0003 - Cleaning Supplies

No Asbestos

B00H - R0004 - Home Base

Wall Linings Internal	Flat AC Sheeting	2m2	Behind heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Area inaccessible					

B00H - R0005 - Home Base

Wall Linings Internal	Flat AC Sheeting	2m2	Behind heater	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Area inaccessible					

B00H - R0006 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Shed - 1996 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00I - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 1986 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	No Asbestos Found

Interior

B00J - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids	No Asbestos Found

Interior

B00K - R0001 - Practical Activities - 1hb

No Asbestos

B00K - R0002 - Home Base Store

No Asbestos

B00K - R0003 - Plant

No Asbestos

B00K - R0004 - Home Base

No Asbestos

B00K - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0006 - Home Base

No Asbestos

B00K - R0007 - Home Base Store

No Asbestos

B00K - R0008 - Plant

No Asbestos

B00K - R0009 - Practical Activities - 1hb

No Asbestos

B00K - R0010 - Withdrawal Space - 2hb

No Asbestos

B00K - R0011 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities - 2016 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B00L - R0001 - Community Clinic**

No Asbestos

B00L - R0002 - Community Clinic

No Asbestos

B00L - R0003 - General Storeroom

No Asbestos

B00L - R0004 - Handwashing Facilities

No Asbestos

B00L - R0005 - Clerical Office

No Asbestos

B00L - R0006 - Movement

No Asbestos

B00L - R0007 - Clerical Office

No Asbestos

B00L - R0008 - Toilets-Unisex

No Asbestos

B00L - R0009 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00L - R0010 - Staff Kitchen

No Asbestos

B00L - R0011 - Movement

No Asbestos

B00L - R0012 - External Movement

No Asbestos

B00L - R0013 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017