


# Asbestos Register

(Hazardous Materials and Risk Assessment)



**School :** Bridge Road School (5540)  
**Region :** Sydney  
**State Electorate :** Newtown  
**Local Government Area :** Marrickville

**Initial Survey :** Noel Arnold & Associates : 11 - Mar - 2008  
**Register Issue Date :** 23 - Mar - 2017



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/General Learning - 1882 - Brick/Block (Brick/Block)**

**Exterior**

Eaves Linings	Flat AC Sheeting	150m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	<b>Assumed Asbestos</b>					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

**Interior**

**B00A - R0001 - Home Base**

No Asbestos

**B00A - R0002 - Home Base**

No Asbestos

**B00A - R0003 - Home Base**

No Asbestos

**B00A - R0006 - Staff Toilet**

No Asbestos

**B00A - R0007 - Staff Toilet**

No Asbestos

**B00A - R0016 - Staff Room Annexe**

No Asbestos

**B00A - R0019 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5540/B00A/R0030/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00A - R0027 - Movement**

No Asbestos

**B00A - R0029 - Home Base**

No Asbestos

**B00A - R0030 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5540/B00A/R0030/Ceiling Structures/Linings/S1			<b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b>		

**B00A - R0031 - Movement**

No Asbestos

**B00A - R0032 - Security Store**

No Asbestos

**B00A - R0033 - Other-Community Use**

No Asbestos

**B00A - R0034 - Movement**

No Asbestos

**B00A - R0035 - External Movement**

No Asbestos

**B00A - R0036 - General Storeroom**

Wall Linings Internal	Flat AC Sheeting					<b>No Asbestos Detected</b>
	5540/B00A/R0037/Wall Linings Internal/S4					

**B00A - R0037 - Sports Store**

Wall Linings Internal	Flat AC Sheeting					<b>No Asbestos Detected</b>
	5540/B00A/R0037/Wall Linings Internal/S4					

**B00A - R0038 - Staff Shower/Change**

No Asbestos

**B00A - R0039 - Toilets - Boys**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting					
	5540/B00A/R0039/Wall Linings Internal/S3					No Asbestos Detected
<b>B00A - R0040 - External Movement</b>						
No Asbestos						
<b>B00A - R0041 - Staff Room</b>						
No Asbestos						
<b>B00A - R0042 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0043 - Interview</b>						
No Asbestos						
<b>B00A - R0044 - Staff Room Annexe</b>						
No Asbestos						
<b>B00A - R0045 - Movement</b>						
Wall Linings Internal	Flat AC Sheeting					
	5540/B00A/R0045/Wall Linings Internal/S2					No Asbestos Detected
<b>B00A - R0046 - Reading Area</b>						
No Asbestos						
<b>B00A - R0047 - Special Programs Room</b>						
No Asbestos						
<b>B00A - R0048 - Clerical Office</b>						
No Asbestos						
<b>B00A - R0049 - Duplicating Workroom</b>						
No Asbestos						
<b>B00A - R0050 - Home Base</b>						
No Asbestos						
<b>B00A - R0051 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0052 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0053 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0054 - Home Base</b>						
No Asbestos						
<b>B00A - R0055 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0056 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0057 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0058 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0059 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0060 - Home Base</b>						
No Asbestos						
<b>B00A - R0061 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0062 - Practical Activities - 1hb</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Staff Facilities/General Learning - 1882 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00G - R0003 - Staff Kitchen**

No Asbestos

**B00G - R0004 - External Movement**

No Asbestos

**B00G - R0005 - General Learning Space**

No Asbestos

**B00G - R0006 - Movement**

No Asbestos

**B00G - R0007 - Toilets - Boys/Girls**

No Asbestos

**B00G - R0008 - Staff Room Annexe**

No Asbestos

**B00G - R0009 - Staff Room Annexe**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017