


Asbestos Register

(Hazardous Materials and Risk Assessment)



School : Glenvale School (5627)
Region : Hunter/Central Coast
State Electorate : Gosford
Local Government Area : Gosford

Initial Survey : Noel Arnold & Associates : 28 - Mar - 2008
Reviewed By : AECOM : 29 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Support Unit - 1984 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground / no access points.
Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible, no manhole / no access points.

Interior

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - Practical Activities - S - 1hb

No Asbestos

B00A - R0003 - Practical Activities - S - 1hb

No Asbestos

B00A - R0004 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting 5627/B00A/R0005/Ceiling Structures/Linings/S4	No Asbestos Detected
----------------------------	---	-----------------------------

B00A - R0005 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 5627/B00A/R0005/Partition Walls (Cubicles)/S3	No Asbestos Detected
----------------------------	--	-----------------------------

Ceiling Structures/Linings	Flat AC Sheeting 5627/B00A/R0005/Ceiling Structures/Linings/S4	No Asbestos Detected
----------------------------	---	-----------------------------

B00A - R0006 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting 5627/B00A/R0005/Ceiling Structures/Linings/S4	No Asbestos Detected
----------------------------	---	-----------------------------

B00A - R0007 - Home Base - S

No Asbestos

B00A - R0008 - Home Base - S

No Asbestos

B00A - R0009 - Home Base Store - S

No Asbestos

B00A - R0010 - Withdrawal - S

No Asbestos

B00A - R0012 - Withdrawal - S

No Asbestos

B00A - R0013 - Home Base Store - S

No Asbestos

B00A - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Communal Facilities - 1984 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground / no access points.

Interior

B00B - R0001 - General Storeroom		
No Asbestos		
B00B - R0002 - Cleaning Supplies		
No Asbestos		
B00B - R0003 - Main Switch Board		
No Asbestos		
B00B - R0004 - Garden Store		
No Asbestos		
B00B - R0005 - Principal		
No Asbestos		
B00B - R0006 - Deputy Principal		
No Asbestos		
B00B - R0007 - Duplicating Workroom		
No Asbestos		
B00B - R0008 - Movement		
No Asbestos		
B00B - R0009 - Cleaning Distributed Store		
No Asbestos		
B00B - R0010 - Cleaning Supplies		
No Asbestos		
B00B - R0011 - Staff Toilet		
Ceiling Structures/Linings	Flat AC Sheeting 5627/B00B/R0032/Ceiling Structures/Linings/S2	No Asbestos Detected
B00B - R0012 - Staff Toilet		
Ceiling Structures/Linings	Flat AC Sheeting 5627/B00B/R0032/Ceiling Structures/Linings/S2	No Asbestos Detected
B00B - R0013 - Toilets - Boys/Girls		
No Asbestos		
B00B - R0014 - Sick Bay		
No Asbestos		
B00B - R0015 - Clerical Office		
No Asbestos		
B00B - R0016 - Entry Vestibule		
No Asbestos		
B00B - R0017 - Interview		
No Asbestos		
B00B - R0018 - Security Store		
No Asbestos		
B00B - R0019 - Toilets - Boys		
No Asbestos		
B00B - R0020 - Toilets - Girls		
Partition Walls (Cubicles)	Compressed AC Sheet 5627/B00B/R0036/Partition Walls (Cubicles)/S6	No Asbestos Detected
B00B - R0021 - Movement		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00B - R0022 - Raised Platform						
No Asbestos						
B00B - R0023 - Hall Chair Store						
No Asbestos						
B00B - R0024 - Communal Space						
No Asbestos						
B00B - R0025 - Canteen						
No Asbestos						
B00B - R0026 - Staff Toilet						
No Asbestos						
B00B - R0027 - Canteen Office/Store						
No Asbestos						
B00B - R0028 - P.E. Store						
No Asbestos						
B00B - R0029 - General Storeroom						
No Asbestos						
B00B - R0030 - Staff Kitchen						
No Asbestos						
B00B - R0031 - Special Programs Room						
No Asbestos						
B00B - R0032 - Distribution Board					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Flat AC Sheeting					
	5627/B00B/R0032/Ceiling Structures/Linings/S2					No Asbestos Detected
B00B - R0033 - General Storeroom						
No Asbestos						
B00B - R0034 - Home Base						
No Asbestos						
B00B - R0035 - Movement						
No Asbestos						
B00B - R0036 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet					
	5627/B00B/R0036/Partition Walls (Cubicles)/S6					No Asbestos Detected
B00B - R0037 - Home Base						
No Asbestos						
B00B - R0038 - Home Base Store						
No Asbestos						
B00B - R0039 - Withdrawal Space - 1hb						
No Asbestos						
B00B - R0040 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	5627/B00B/R0040/Ceiling Structures/Linings/S1					No Asbestos Detected
B00B - R0041 - Withdrawal Space - 1hb						
No Asbestos						
B00B - R0042 - Home Base Store						
No Asbestos						
B00B - R0043 - Home Base						
No Asbestos						
B00B - R0044 - Practical Activities - 1hb						
No Asbestos						
B00B - R0047 - Garage/Carport						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00B - R0048 - External Movement

Ceiling Structures/Linings Flat AC Sheeting
 5627/B00B/R0050/Ceiling Structures/Linings/S26 **No Asbestos Detected**

B00B - R0049 - External Movement

No Asbestos

B00B - R0050 - External Movement

Ceiling Structures/Linings Flat AC Sheeting
 5627/B00B/R0050/Ceiling Structures/Linings/S26 **No Asbestos Detected**

B00B - R0051 - External Movement

Ceiling Structures/Linings Flat AC Sheeting
 5627/B00B/R0050/Ceiling Structures/Linings/S26 **No Asbestos Detected**

B00B - R0052 - External Movement

Ceiling Structures/Linings Flat AC Sheeting
 5627/B00B/R0050/Ceiling Structures/Linings/S26 **No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Support Unit - 1984 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground / no access points.

Interior

B00C - R0001 - Home Base Store - S

No Asbestos

B00C - R0003 - Withdrawal - S

No Asbestos

B00C - R0004 - Home Base Store - S

No Asbestos

B00C - R0005 - Home Base - S

No Asbestos

B00C - R0006 - Withdrawal - S

No Asbestos

B00C - R0007 - Practical Activity Area

No Asbestos

B00C - R0008 - Staff Kitchen

No Asbestos

B00C - R0009 - Sports Store

No Asbestos

B00C - R0010 - Sports Store

No Asbestos

B00C - R0012 - Staff Room

No Asbestos

B00C - R0013 - General Assistant/Bulk Store

No Asbestos

B00C - R0014 - Home Base Store

No Asbestos

B00C - R0015 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 5627/B00C/R0015/Partition Walls (Cubicles)/S12	No Asbestos Detected
----------------------------	---	----------------------

Ceiling Structures/Linings	Flat AC Sheeting 5627/B00C/R0015/Ceiling Structures/Linings/S13	No Asbestos Detected
----------------------------	--	----------------------

B00C - R0016 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting 5627/B00C/R0015/Ceiling Structures/Linings/S13	No Asbestos Detected
----------------------------	--	----------------------

Partition Walls (Cubicles)	Compressed AC Sheet 5627/B00C/R0015/Partition Walls (Cubicles)/S12	No Asbestos Detected
----------------------------	---	----------------------

B00C - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0018 - Toilet - S

Ceiling Structures/Linings	Flat AC Sheeting 5627/B00C/R0015/Ceiling Structures/Linings/S13	No Asbestos Detected
----------------------------	--	----------------------

B00C - R0019 - Shower/Change

Ceiling Structures/Linings	Flat AC Sheeting 5627/B00C/R0015/Ceiling Structures/Linings/S13	No Asbestos Detected
----------------------------	--	----------------------

B00C - R0020 - Home Base - S

No Asbestos

B00C - R0021 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting		5627/B00B/R0050/Ceiling Structures/Linings/S26			No Asbestos Detected
Panels Under Windows	Flat AC Sheeting		5627/B00C/R0011/Panels Under Windows/S11			No Asbestos Detected
B00C - R0022 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting		5627/B00B/R0050/Ceiling Structures/Linings/S26			No Asbestos Detected
B00C - R0023 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Other-Community Use - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground / no access points.					
Box surround to water pump behind building	Flat AC Sheeting 5627/B00D/Box surround To Water Pump Behind Building/S22					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00D - R0001 - No Access

No Asbestos

B00D - R0002 - Covered Vehicle Area/Porte Cochere

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning/Library - 1984 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible, slab to ground / no access points.					
Ceiling Voids - Flat Roof	No Asbestos Found					
Panels Under Windows	Flat AC Sheeting					
	5627/B00E/R0018/Panels Under Windows/S8					No Asbestos Detected

Interior

B00E - R0001 - Withdrawal - S

No Asbestos

B00E - R0002 - Home Base - S

No Asbestos

B00E - R0003 - Home Base Store - S

No Asbestos

B00E - R0004 - Toilet - S

Partition Walls (Cubicles)	Compressed AC Sheet					
	5627/B00E/R0004/Partition Walls (Cubicles)/S9					No Asbestos Detected

B00E - R0005 - Laundry - Pre

No Asbestos

B00E - R0006 - Practical Activities - S - 1hb

No Asbestos

B00E - R0007 - Outdoor Learning Area

Ceiling Structures/Linings	Flat AC Sheeting					
	5627/B00E/R0018/Ceiling Structures/Linings/S10					No Asbestos Detected

B00E - R0008 - Withdrawal - S

No Asbestos

B00E - R0009 - Home Base - S

No Asbestos

B00E - R0010 - Home Base Store - S

No Asbestos

B00E - R0011 - Staff Room Annexe

No Asbestos

B00E - R0012 - Communications Room

No Asbestos

B00E - R0013 - K.L.A. Store

No Asbestos

B00E - R0014 - General Storeroom

No Asbestos

B00E - R0015 - Reading Area

No Asbestos

B00E - R0016 - Library Office/Workroom

No Asbestos

B00E - R0019 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	5627/B00B/R0050/Ceiling Structures/Linings/S26					No Asbestos Detected

B00E - R0020 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	5627/B00B/R0050/Ceiling Structures/Linings/S26					No Asbestos Detected

B00E - R0021 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	5627/B00B/R0050/Ceiling Structures/Linings/S26					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - R0022 - External Movement

No Asbestos

B00E - R0023 - Covered Outdoor Learning Area - M

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1984 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible, slab to ground / no access points.					
Ceiling Voids - Flat Roof	No Asbestos Found					
Panels Under Windows	Flat AC Sheeting					
	5627/B00F/Panels Under Windows/S16					No Asbestos Detected

Interior**B00F - R0001 - Withdrawal - S**

No Asbestos

B00F - R0002 - Home Base - S

No Asbestos

B00F - R0003 - Home Base Store - E

No Asbestos

B00F - R0004 - Toilets - Boys/Girls

Partition Walls (Cubicles)	Compressed AC Sheet					
	5627/B00F/R0004/Partition Walls (Cubicles)/S14					No Asbestos Detected

B00F - R0005 - Laundry - Pre

No Asbestos

B00F - R0006 - Practical Activities - E

No Asbestos

B00F - R0008 - Withdrawal - S

No Asbestos

B00F - R0009 - Home Base - E

No Asbestos

B00F - R0010 - Home Base Store - E

No Asbestos

B00F - R0011 - Distribution Board

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting					
	5627/B00F/R0011/Ceiling Structures/Linings/S17					No Asbestos Detected

B00F - R0013 - External Movement

No Asbestos

B00F - R0014 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	5627/B00B/R0050/Ceiling Structures/Linings/S26					No Asbestos Detected

B00F - R0015 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	5627/B00B/R0050/Ceiling Structures/Linings/S26					No Asbestos Detected

B00F - R0016 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	5627/B00B/R0050/Ceiling Structures/Linings/S26					No Asbestos Detected

B00F - R0017 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Support Unit/Administration - 1998 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground / no access points.					
Eaves Linings	Flat AC Sheeting	20m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5627/B00G/Eaves Linings/S27					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					

Interior

B00G - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5627/B00G/R0023/Ceiling Structures/Linings/S18					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0002 - Deputy Principal

No Asbestos

B00G - R0003 - General Storeroom

No Asbestos

B00G - R0004 - Home Base - S

No Asbestos

B00G - R0005 - Home Base Store - S

No Asbestos

B00G - R0006 - Withdrawal - S

Wall cladding	Flat AC Sheeting					No Asbestos Detected
	5627/B00G/R0011/Wall Linings Internal/S19					

B00G - R0007 - Home Base - S

No Asbestos

B00G - R0008 - Home Base Store - S

No Asbestos

B00G - R0009 - Home Base - S

No Asbestos

B00G - R0010 - Home Base Store - S

No Asbestos

B00G - R0011 - Withdrawal - S

Wall cladding	Flat AC Sheeting					No Asbestos Detected
	5627/B00G/R0011/Wall Linings Internal/S19					

B00G - R0012 - Home Base - S

No Asbestos

B00G - R0013 - Home Base Store - S

No Asbestos

B00G - R0014 - Laundry - S

No Asbestos

B00G - R0015 - Practical Activities - S - 1hb

No Asbestos

B00G - R0016 - Clerical Office

No Asbestos

B00G - R0017 - Special Programs Room

No Asbestos

B00G - R0018 - Main Switch Board

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
5627/B00G/R0018/Ceiling Structures/Linings/S24				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Electrical Backing Board	Resinous Board	1m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
5627/B00G/R0018/Electrical Backing Board/S25				Chrysotile (white asbestos)		

B00G - R0019 - Staff Toilet

No Asbestos

B00G - R0020 - General Assistant/Bulk Store

No Asbestos

B00G - R0021 - Cleaning Supplies

No Asbestos

B00G - R0022 - External Movement

No Asbestos

B00G - R0024 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Support Unit/Pupil Facilities - 1998 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible, slab to ground / no access points.

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5627/B00H/R0001/Ceiling Structures/Linings/S21					Chrysotile (white asbestos)	

B00H - R0002 - Toilet - S

Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5627/B00H/R0003/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	

B00H - R0003 - Toilet - S

Ceiling Structures/Linings	Flat AC Sheeting	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5627/B00H/R0003/Ceiling Structures/Linings/S20					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Shed - 1998 - Timber Shed (Timber Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible, slab to ground / no access points.

Ceiling Voids No Asbestos Found

Interior

B00I - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Support Unit (M P S) - 2007 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00J - R0001 - Residential Showers

No Asbestos

B00J - R0002 - Residential Kitchen

No Asbestos

B00J - R0003 - Residential Living Room

No Asbestos

B00J - R0004 - Residential Bedroom

No Asbestos

B00J - R0005 - Residential Pantry

No Asbestos

B00J - R0006 - Residential Bedroom

No Asbestos

B00J - R0007 - Residential Laundry

No Asbestos

B00J - R0008 - Movement

No Asbestos

B00J - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Support Unit (M P S) - 2007 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00K - R0001 - Residential Bedroom**

No Asbestos

B00K - R0002 - Residential Pantry

No Asbestos

B00K - R0003 - Residential Living Room

No Asbestos

B00K - R0004 - External Movement

No Asbestos

B00K - R0005 - Residential Dining Room

No Asbestos

B00K - R0006 - Residential Kitchen

No Asbestos

B00K - R0007 - Residential Showers

No Asbestos

B00K - R0008 - Residential Laundry

No Asbestos

B00K - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00L - R0001 - External Movement

No Asbestos

B00L - R0002 - Practical Activities - P - 1hb

No Asbestos

B00L - R0003 - Home Base Store - P

No Asbestos

B00L - R0004 - Home Base - P

No Asbestos

B00L - R0005 - Withdrawal Space - 2hb

No Asbestos

B00L - R0006 - Home Base - P

No Asbestos

B00L - R0007 - Home Base Store - P

No Asbestos

B00L - R0008 - Practical Activities - P - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible, slab to ground / no access points.

Ceiling Voids No Asbestos Found

Interior

B00M - R0001 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Other - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible, slab to ground / no access points.

Ceiling Voids No Asbestos Found

Interior

B00N - R0001 - Garage/Carport

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning - 1965 - Timber (Timber)**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Height Restriction, 3.3m					
Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Area inaccessible, no access points.					
Eaves Linings	Flat AC Sheeting	15.18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5627/B000/R0002/Ceiling Structures/Linings/S28					Chrysotile (white asbestos)

Interior**B000 - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting	37.95m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5627/B000/R0002/Ceiling Structures/Linings/S28					Chrysotile (white asbestos)
gable	Flat AC Sheeting	1.5m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	5627/B000/R0001/gable/S30					Chrysotile (white asbestos) , Amosite (brown asbestos)

B000 - R0002 - Home Base Store

Ceiling Structures/Linings	Flat AC Sheeting	6.14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5627/B000/R0002/Ceiling Structures/Linings/S28					Chrysotile (white asbestos)

B000 - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting	34.56m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5627/B000/R0003/Wall Linings Internal/S29					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Ceiling Structures/Linings	Non Accessible Area - Height Restriction, 3.3m					
----------------------------	---	--	--	--	--	--

B000 - R0004 - Home Base

Wall Linings Internal	Flat AC Sheeting	22.89m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5627/B000/R0003/Wall Linings Internal/S29					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

Ceiling Structures/Linings	Non Accessible Area - Height Restriction, 3.3m					
----------------------------	---	--	--	--	--	--

B000 - R0005 - Movement

Ceiling Structures/Linings	Non Accessible Area - Height Restriction, 3.3m					
----------------------------	---	--	--	--	--	--

B000 - R0006 - Disabled Shower/Toilet

No Asbestos

B000 - R0007 - Staff Kitchen

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Administration - 1970 - Steel (Steel)**Exterior**

Ceiling Voids - Flat Roof Non Accessible Area
 - Area inaccessible, no manhole / no access points.

Underfloor Voids -
 Packing to Floor Joists No Asbestos Found

Interior**B00P - R0001 - Clerical Office**

No Asbestos

B00P - R0002 - Movement

No Asbestos

B00P - R0003 - General Storeroom

No Asbestos

B00P - R0004 - Clerical Office

No Asbestos

B00P - R0005 - Staff Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0A1 - General Learning - 1950 - Timber (Timber)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B0A1 - R0001 - Home Base

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B0A1 - R0002 - Home Base

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B0A1 - R0003 - General Storeroom

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B0A1 - R0004 - General Storeroom

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B0A1 - R0005 - Withdrawal Space - 2hb

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B0A1 - R0006 - General Storeroom

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B0A1 - R0007 - External Movement

Recently Modified Space	Requires Inspection
-------------------------	---------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 710 - D11649 - Home Science/Pantry/Laundry : Placement Date - 8/02/2005

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	14.4 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	10 m2

R2 - Food Technology L.S.

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	73 m2

R3 - Laundry

Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2
---------	---------------	------------------	------

OS 505 - D13421 - Admin Staff/Principal/Secure Store : Placement Date - 25/10/2011

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - Principal

No Asbestos Found.

R3 - Staff Room

No Asbestos Found.

R4 - Security Store

No Asbestos Found.

R5 - Clerical Office

No Asbestos Found.

OS 601 - D13961 - Learning Unit - Standard/Withdrawal : Placement Date - 25/08/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 621 - D14501 - Single Learning Unit - H/Cap : Placement Date - 9/07/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Home Base-I.O.						
No Asbestos Found.						
R2 - Toilets-Disabled						
No Asbestos Found.						
R3 - Laundry						
No Asbestos Found.						
OS 621 - D16790 - Single Learning Unit - H/Cap : Placement Date - 9/09/2013						
Exterior						
No Asbestos Found.						
Interior						
R1 - Home Base-I.O.						
No Asbestos Found.						
R2 - Toilets-Disabled						
No Asbestos Found.						
R3 - Laundry						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017