


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Gadara School (5674)
Region : Riverina
State Electorate : Wagga Wagga
Local Government Area : Tumut

Initial Survey : Greencap-NAA : 02 - Sep - 2016
Reviewed By : Greencap-NAA : 02 - Sep - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1953 - Timber (Timber)**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	Non Accessible Area - Area inaccessible no access point					
Eaves Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5674/B00A/Eaves Linings/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Interior**B00A - R0002 - Duplicating Workroom**

No Asbestos

B00A - R0003 - General Storeroom

No Asbestos

B00A - R0004 - General Storeroom

No Asbestos

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Staff Room

No Asbestos

B00A - R0007 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5674/B00A/R0026/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00A - R0008 - Entry Vestibule

No Asbestos

B00A - R0009 - Clerical Office

No Asbestos

B00A - R0018 - Clerical Office

No Asbestos

B00A - R0019 - Sick Bay

No Asbestos

B00A - R0020 - Movement

No Asbestos

B00A - R0021 - Principal

No Asbestos

B00A - R0022 - Interview

No Asbestos

B00A - R0023 - Access Shower/Toilet

No Asbestos

B00A - R0024 - Staff Toilet

No Asbestos

B00A - R0025 - Staff Room

No Asbestos

B00A - R0026 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	88m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5674/B00A/R0026/Ceiling Structures/Linings/S10			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

Flooring	Compressed AC Sheet 5674/B00A/R0026/Flooring/S11					No Asbestos Detected
----------	---	--	--	--	--	----------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1953 - Timber (Timber)**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					
Eaves Linings	Flat AC Sheeting 5674/B00C/Eaves Linings/S7	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Wall Cladding	Flat AC Sheeting 5674/B00C/Wall Cladding/S9					No Asbestos Detected

Interior**B00C - R0007 - Home Base**

No Asbestos

B00C - R0008 - Home Base - M

No Asbestos

B00C - R0009 - Home Base - M

No Asbestos

B00C - R0010 - Home Base Store - M

No Asbestos

B00C - R0011 - Home Base - M

No Asbestos

B00C - R0012 - Home Base Store - M

No Asbestos

B00C - R0014 - Access Shower/Toilet

No Asbestos

B00C - R0015 - Movement

No Asbestos

B00C - R0016 - Laundry - S

No Asbestos

B00C - R0017 - Toilets - Girls

No Asbestos

B00C - R0018 - Toilets - Boys

No Asbestos

B00C - R0019 - Cleaning Distributed Store

No Asbestos

B00C - R0020 - Movement

No Asbestos

B00C - R0021 - Movement

No Asbestos

B00C - R0022 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Staff Facilities - 1973 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Encapsulated Insulation material within unit 5674/B00D/Ceiling Voids/S3					No Asbestos Detected
Underfloor Voids	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting 5674/B00D/Gable Verge Lining/S1	30m	East & West	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior

B00D - R0001 - Toilets-Unisex

No Asbestos

B00D - R0002 - Home Base

No Asbestos

B00D - R0003 - Staff Room

No Asbestos

B00D - R0004 - Staff Toilet

No Asbestos

B00D - R0005 - Cleaning Supplies

No Asbestos

B00D - R0006 - Movement

No Asbestos

B00D - R0007 - Personal Effects Storage

Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

B00D - R0008 - General Storeroom

Ceiling Hatch	Flat AC Sheeting 5674/B00D/R0008/Ceiling Hatch/S2	1m2	Central	Good Condition (1)	Low (1)	Low Priority (2-3) Chrysotile (white asbestos)
---------------	--	-----	---------	--------------------	---------	--

B00D - R0009 - Kitchen - Pre

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1973 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	Encapsulated Insulation material within unit 5674/B00E/Ceiling Voids/S5					No Asbestos Detected
Underfloor Voids	No Asbestos Found					
Gable Verge Lining	Flat AC Sheeting	30m	North & South	Good Condition (1)	Low (1)	Low Priority (2-3)
	5674/B00E/Gable Verge Lining/S4					Chrysotile (white asbestos)

Interior**B00E - R0001 - Toilets-Unisex**

No Asbestos

B00E - R0004 - Toilets-Unisex

No Asbestos

B00E - R0005 - General Storeroom

No Asbestos

B00E - R0006 - Personal Effects Storage

No Asbestos

B00E - R0007 - Movement

No Asbestos

B00E - R0008 - Personal Effects Storage

No Asbestos

B00E - R0009 - General Storeroom

No Asbestos

B00E - R0010 - Stairs

No Asbestos

B00E - R0011 - Home Base/Practical Activities - E

No Asbestos

B00E - R0012 - Movement

No Asbestos

B00E - R0013 - Home Base - E

No Asbestos

B00E - R0014 - Home Base - E

No Asbestos

B00E - R0015 - Home Base - E

No Asbestos

B00E - R0016 - Home Base - E

No Asbestos

B00E - R9001 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5674/B00E/R9002/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

B00E - R9002 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting	78m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5674/B00E/R9002/Ceiling Structures/Linings/S6					Chrysotile (white asbestos)

B00E - R9003 - General Storeroom

No Asbestos

B00E - R9004 - Movement

No Asbestos

B00E - R9005 - Stairs

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - R9006 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - Garage/Carport

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Building Services - 2011 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	No Asbestos Found

Interior

B001 - R0001 - General Assistant/Bulk Store

No Asbestos

B001 - R0002 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017