


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Kyeemagh Infants School (5141)
Region : Sydney
State Electorate : Rockdale
Local Government Area : Rockdale

Initial Survey : Noel Arnold & Associates : 17 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 01 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Library - 1942 - Timber (Timber)**Exterior**

Wall Cladding	Flat AC Sheeting 5141/B00A/Wall Cladding/S1					No Asbestos Detected
Pier In-fill panels	Compressed AC Sheet 5141/B00A/Pier In-fill panels/S2					No Asbestos Detected
Awnings	Flat AC Sheeting 5141/B00A/Awnings/S3					No Asbestos Detected
Underfloor Voids	AC Fragments/Debris 5141/B00A/Underfloor Voids/S10					No Asbestos Detected
Ceiling Void	No Asbestos Found					

Interior**B00A - R0001 - Staff Room**

No Asbestos

B00A - R0002 - Reading Area

No Asbestos

B00A - R0003 - Principal

No Asbestos

B00A - R0004 - Entry Vestibule

No Asbestos

B00A - R0005 - Entry Vestibule

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1942 - Timber (Timber)

Exterior

Pier In-fill panels	Compressed AC Sheet 5141/B00A/Pier In-fill panels/S2					No Asbestos Detected
Wall Cladding	Flat AC Sheeting 5141/B00A/Wall Cladding/S1					No Asbestos Detected
Underfloor Voids	No Asbestos Found					
Ceiling Void	No Asbestos Found					

Interior

B00B - R0001 - Drinking Facilities

No Asbestos

B00B - R0002 - Personal Effects Storage

No Asbestos

B00B - R0003 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1942 - Timber (Timber)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00C - R0001 - General Storeroom

No Asbestos

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - Home Base

No Asbestos

B00C - R0004 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities - 1942 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found				
Underfloor Voids - Slab on Ground	No Asbestos Found				
Wall Cladding	Flat AC Sheeting				
	5141/B00D/Wall Cladding/S7				No Asbestos Detected

Interior

B00D - R0001 - Sports Store

Ceiling Structures/Linings	Flat AC Sheeting				
	5141/B00D/R0001/Ceiling Structures/Linings/S6				No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities/Staff Facilities - 1942 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Wall Cladding	Flat AC Sheeting					
	5141/B00A/Wall Cladding/S1					No Asbestos Detected

Interior

B00E - R0001 - Toilets - Boys

Wall Linings Internal	Flat AC Sheeting					
	5141/B00E/R0001/Wall Linings Internal/S4					No Asbestos Detected
Partition Walls (Cubicles)	Compressed AC Sheet					
	5141/B00E/R0001/Partition Walls (Cubicles)/S5					No Asbestos Detected

B00E - R0002 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting					
	5141/B00E/R0001/Wall Linings Internal/S4					No Asbestos Detected

B00E - R0003 - Toilets - Girls

Wall Linings Internal	Flat AC Sheeting					
	5141/B00E/R0001/Wall Linings Internal/S4					No Asbestos Detected
Partition Walls (Cubicles)	Compressed AC Sheet					
	5141/B00E/R0001/Partition Walls (Cubicles)/S5					No Asbestos Detected

B00E - R0004 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting					
	5141/B00E/R0001/Wall Linings Internal/S4					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Administration - 1942 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00F - R0001 - General Storeroom

No Asbestos

B00F - R0002 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other-Non-Govt Pre-School - 1942 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	5141/B00G/Eaves Linings/S9			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
Ceiling Void	Non Accessible Area - No Manhole in Building					

Interior

B00G - R0001 - Other-Non Government Pre-Sch

Ceiling Structures/Linings	Flat AC Sheeting	20m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	5141/B00G/R0002/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00G - R0002 - Other-Non Government Pre-Sch

Ceiling Structures/Linings	Flat AC Sheeting	15m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	5141/B00G/R0002/Ceiling Structures/Linings/S11			Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		

B00G - R0003 - Other-Non Government Pre-Sch

Ceiling Structures/Linings	Flat AC Sheeting	20m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	5141/B00G/R0003/Ceiling Structures/Linings/S12			Chrysotile (white asbestos)		

B00G - R0004 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0005 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0006 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0007 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0008 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0009 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0010 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0011 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0012 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0013 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0014 - Other-Non Government Pre-Sch

No Asbestos

B00G - R0015 - Other-Non Government Pre-Sch

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Other-Non-Govt Pre-School - 1988 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - Other-Non Government Pre-Sch

Wall Linings Internal Flat AC Sheeting
 5141/B00H/R0001/Wall Linings Internal/S8

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Other-Non-Govt Pre-School - 1942 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00I - R0001 - Other-Non Government Pre-Sch

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Other-Non-Govt Pre-School - 1942 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Void	No Asbestos Found

Interior

B00J - R0001 - Other-Non Government Pre-Sch

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Library - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00K - R0001 - Reading Area

No Asbestos

B00K - R0002 - Communications Room

No Asbestos

B00K - R0003 - K.L.A. Store

No Asbestos

B00K - R0004 - Library Office/Workroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 503 - D17952 - Admin Lib Staff/Principal/Clerk/Store : Placement Date - 4/11/2003

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Clerical Office

No Asbestos Found.

R2 - Principal

No Asbestos Found.

R3 - Staff Toilet

No Asbestos Found.

R4 - Staff Toilet

No Asbestos Found.

R5 - Reading Area

No Asbestos Found.

R6 - Security Store

No Asbestos Found.

R7 - Staff Room

No Asbestos Found.

R8 - Entry

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017