


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Long Flat Public School (2423)
Region : North Coast
State Electorate : Oxley
Local Government Area : Port Macquarie-Hastings

Initial Survey : Noel Arnold & Associates : 05 - May - 2008
Reviewed By : Grencap-NAA : 14 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Library - 1933 - Timber (Timber)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	30m2	Surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/Eaves Linings/S6				Chrysotile (white asbestos)	
Subfloor void	No Asbestos Found					
Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

Interior

B00A - R0001 - Cleaning Distributed Store

No Asbestos

B00A - R0002 - K.L.A. Store

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0003/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0004/Wall Linings Internal/S5				Chrysotile (white asbestos)	

B00A - R0003 - K.L.A. Store

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0003/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0004/Wall Linings Internal/S5				Chrysotile (white asbestos)	

B00A - R0004 - Special Programs Room

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0003/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)	
Wall Linings Internal	Flat AC Sheeting	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0004/Wall Linings Internal/S5				Chrysotile (white asbestos)	

B00A - R0005 - Reading Area

Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0004/Wall Linings Internal/S5				Chrysotile (white asbestos)	

B00A - R0006 - Outdoor Learning Area

No Asbestos

B00A - R0007 - Raised Platform

No Asbestos

B00A - R0008 - Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1933 - Timber (Timber)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	22m2	Surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/Eaves Linings/S6				Chrysotile (white asbestos)	
Wall Cladding	Flat AC Sheeting					
	2423/B00B/Wall Cladding/S9				No Asbestos Detected	
Subfloor void	No Asbestos Found					

Interior

B00B - R0001 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00B/R0001/Ceiling Structures/Linings/S7				Chrysotile (white asbestos)	

B00B - R0002 - Practical Activities - 1hb

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00B/R0001/Ceiling Structures/Linings/S7				Chrysotile (white asbestos)	

Wall Linings Internal	Flat AC Sheeting	10m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00B/R0002/Wall Linings Internal/S8				Chrysotile (white asbestos)	

B00B - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00B/R0002/Wall Linings Internal/S8				Chrysotile (white asbestos)	

B00B - R0004 - General Assistant/Bulk Store

Wall Linings Internal	Flat AC Sheeting					
	2423/B00B/Wall Cladding/S9				No Asbestos Detected	

B00B - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities - 1982 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00C - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1933 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting	20m2	Surround	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/Eaves Linings/S6					Chrysotile (white asbestos)
Downpipes	Fibre Cement Pipe	3m	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00D/Downpipes/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)

Interior

B00D - R0001 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0003/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00D/R0001/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)

B00D - R0002 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0003/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

B00D - R0003 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0003/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
	2423/B00D/R0003/Floor Coverings Res/Textile/S3					

B00D - R0004 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0003/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00D/R0001/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)

B00D - R0005 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	13m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0003/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

B00D - R0006 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	29m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2423/B00A/R0003/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)

B00D - R0007 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Multi Purpose Facilities - 2009 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00E - R0001 - Communal Space

No Asbestos

B00E - R0002 - General Storeroom

No Asbestos

B00E - R0003 - Practical Activities

No Asbestos

B00E - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Pupil Facilities - 1999 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Subfloor void	No Asbestos Found

Interior

B001 - R0001 - Disabled Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2006 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Subfloor void	No Asbestos Found

Interior

B00J - R0001 - General Storeroom

Wall Linings Internal	Flat AC Sheeting	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
2423/B00J/R0001/Wall Linings Internal/S10				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00J - R0002 - Main Switch Board Cupboard

Electrical Backing Board	Resinous Board	2Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						

B00J - R0003 - Practical Activities - 1hb

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2423/B00A/R0003/Ceiling Structures/Linings/S4				Chrysotile (white asbestos)		

B00J - R0004 - Home Base

No Asbestos

B00J - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities - 2014 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00K - R0001 - Sports Store

No Asbestos

B00K - R0002 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 2013 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00L - R0001 - Kiln Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 505 - D10163 - Admin Staff/Principal/Secure Store : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2

R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos		16 m2
---------	---------------	------------------	--	-------

R3 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos		20 m2
---------	---------------	------------------	--	-------

R4 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos		8 m2
---------	---------------	------------------	--	------

R5 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		18 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017