

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Prestons Public School (2901)
Region : South Western Sydney
State Electorate : Holsworthy
Local Government Area : Liverpool

Initial Survey : Noel Arnold & Associates : 29 - Apr - 2008
Reviewed By : Parsons Brinckerhoff : 03 - Jan - 2017



2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00A - Administration - 1958 - Brick/Veneer (Brick/Veneer)

Exterior

| | | | | | | |
|------------------|-----------------------------|------|------------|--------------------|---------|--|
| Eaves Linings | Flat AC Sheeting | 30m2 | East, West | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2901/B00B/Eaves Linings/S16 | | | | | Chrysotile (white asbestos) , Crocidolite (blue asbestos) |
| Ceiling Void | No Asbestos Found | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |

Interior

B00A - R0001 - Clerical Office/Workroom

No Asbestos

B00A - R0002 - External Movement

| | | | | | | |
|-----------------------|--|--|--|--|--|-----------------------------|
| Wall Linings Internal | Flat AC Sheeting | | | | | No Asbestos Detected |
| | 2901/B00A/R0002/Wall Linings Internal/S1 | | | | | |

| | | | | | | |
|----------------------------|---|--|--|--|--|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | | | | | No Asbestos Detected |
| | 2901/B00A/R0002/Ceiling Structures/Linings/S2 | | | | | |

B00A - R0003 - Entry Vestibule

No Asbestos

B00A - R0004 - Duplicating Workroom

No Asbestos

B00A - R0005 - Principal

No Asbestos

B00A - R0006 - General Storeroom

No Asbestos

B00A - R0007 - Main Switch Board

No Asbestos

B00A - R0008 - Cleaning Distributed Store

No Asbestos

B00A - R0009 - Interview

No Asbestos

B00A - R0010 - Deputy Principal

No Asbestos

B00A - R0011 - Deputy Principal

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Sick Bay

No Asbestos

B00A - R0018 - External Movement

No Asbestos

B00A - R0019 - Disabled Toilet

No Asbestos

B00A - R0020 - Movement

No Asbestos

B00A - R0021 - Cleaning Distributed Store

No Asbestos

B00A - R0022 - External Movement

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00B - Staff Facilities - 1958 - Brick/Veneer (Brick/Veneer)

Exterior

| | | | | | | |
|------------------|-----------------------------|------|------------|--------------------|--|--------------------|
| Eaves Linings | Flat AC Sheeting | 30m2 | East, West | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2901/B00B/Eaves Linings/S16 | | | | Chrysotile (white asbestos) , Crocidolite (blue asbestos) | |
| Ceiling Void | No Asbestos Found | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |

Interior

B00B - R0001 - Staff Toilet

No Asbestos

B00B - R0002 - Staff Toilet

No Asbestos

B00B - R0005 - External Movement

| | | | | | | |
|----------------------------|---|--|--|--|--|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | | | | | No Asbestos Detected |
| | 2901/B00B/R0010/Ceiling Structures/Linings/S5 | | | | | |

B00B - R0010 - External Movement

| | | | | | | |
|----------------------------|---|--|--|--|--|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | | | | | No Asbestos Detected |
| | 2901/B00B/R0010/Ceiling Structures/Linings/S5 | | | | | |

B00B - R0011 - Staff Kitchen

No Asbestos

B00B - R0012 - Staff Room

| | | | | | | |
|---------------|----------------------------------|--|--|--|--|-----------------------------|
| In-fill-panel | Compressed AC Sheet | | | | | No Asbestos Detected |
| | 2901/B00B/R0012/In-fill-panel/S4 | | | | | |

B00B - R0013 - Security Store

No Asbestos

B00B - R0014 - Staff Room Annexe

No Asbestos

B00B - R0015 - Staff Toilet

| | | | | | | |
|-----------------------|--|--|--|--|--|-----------------------------|
| Wall Linings Internal | Flat AC Sheeting | | | | | No Asbestos Detected |
| | 2901/B00B/R0015/Wall Linings Internal/S3 | | | | | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00E - General Learning/Pupil Facilities - 1968 - Brick/Block (Brick/Block)

Exterior

| | | | | | | |
|------------------|--|------|------|--------------------|---------|-----------------------------|
| Eaves Linings | Flat AC Sheeting | 20m2 | West | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2901/B00E/Eaves Linings/S17 | | | | | Chrysotile (white asbestos) |
| Ceiling Void | No Asbestos Found | | | | | |
| Underfloor Voids | Non Accessible Area - No access point found in building | | | | | |

Interior

B00E - R0001 - External Movement

| | | | | | | |
|----------------------------|---|------|-----------------------------|--------------------|---------|-----------------------------|
| Wall Linings Internal | Flat AC Sheeting | 3m2 | North, South, Upper portion | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2901/B00E/R0001/Wall Linings Internal/S14 | | | | | Chrysotile (white asbestos) |
| Ceiling Structures/Linings | Flat AC Sheeting | 76m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2901/B00E/R0001/Wall Linings Internal/S14 | | | | | Chrysotile (white asbestos) |

B00E - R0002 - Practical Activities - 4hb

No Asbestos

B00E - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0004 - Kiln Room

No Asbestos

B00E - R0005 - Movement

No Asbestos

B00E - R0006 - Home Base Store

No Asbestos

B00E - R0007 - Home Base

No Asbestos

B00E - R0008 - Home Base

No Asbestos

B00E - R0009 - Withdrawal Space - 1hb

No Asbestos

B00E - R0010 - Home Base Store

No Asbestos

B00E - R0011 - Cleaning Distributed Store

No Asbestos

B00E - R0012 - Toilets - Girls

| | | | | | | |
|----------------------------|--|------|--------------|--------------------|---------|-----------------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet | 24m2 | North, South | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2901/B00E/R0012/Partition Walls (Cubicles)/S15 | | | | | Chrysotile (white asbestos) |

B00E - R0013 - Toilets - Boys

| | | | | | | |
|----------------------------|--|------|--------------|--------------------|---------|-----------------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet | 18m2 | North, South | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2901/B00E/R0012/Partition Walls (Cubicles)/S15 | | | | | Chrysotile (white asbestos) |

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00F - Support Unit - 1968 - Brick/Veneer (Brick/Veneer)

Exterior

| | | | | | | |
|------------------|-----------------------------|------|------|--------------------|---------|------------------------------------|
| Eaves Linings | Flat AC Sheeting | 10m2 | East | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2901/B00F/Eaves Linings/S18 | | | | | Chrysotile (white asbestos) |
| Ceiling Void | No Asbestos Found | | | | | |
| Underfloor Voids | No Asbestos Found | | | | | |

Interior

B00F - R0001 - Toilet - E

| | | | | | | |
|-----------------------|--|-----|------------|--------------------|---------|------------------------------------|
| Wall Linings Internal | Flat AC Sheeting | 8m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2901/B00F/R0001/Wall Linings Internal/S9 | | | | | Chrysotile (white asbestos) |

B00F - R0002 - Home Base Store - E

No Asbestos

B00F - R0003 - Personal Effects - E

No Asbestos

B00F - R0004 - Home Base - E

No Asbestos

B00F - R0005 - Practical Activities - E

No Asbestos

B00F - R0006 - Home Base - E

No Asbestos

B00F - R0007 - Practical Activities - E

No Asbestos

B00F - R0008 - Home Base Store - E

No Asbestos

B00F - R0009 - Personal Effects - E

No Asbestos

B00F - R0010 - Practical Activities - E

No Asbestos

B00F - R0011 - Home Base Store - E

No Asbestos

B00F - R0012 - Home Base - E

No Asbestos

B00F - R0013 - External Movement

| | | | | | | |
|----------------------------|--|------|------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 46m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 2901/B00F/R0013/Ceiling Structures/Linings/S12 | | | | | Chrysotile (white asbestos) |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00G - General Learning - 1968 - Brick/Veneer (Brick/Veneer)

Exterior

| | | | | | | |
|------------------|---|--|--|--|--|-----------------------------|
| Underfloor Voids | Flat AC Sheeting 2901/B00G/Underfloor Voids/S19 | | | | | No Asbestos Detected |
| Ceiling Void | No Asbestos Found | | | | | |
| Underfloor Voids | AC Fragments/Debris 2901/B00G/Underfloor Voids/S20 | | | | | No Asbestos Detected |

Interior

B00G - R0001 - Home Base

No Asbestos

B00G - R0002 - External Movement

| | | | | | | |
|--|------------------|------|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 71m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 2901/B00G/R0002/Ceiling Structures/Linings/S11 | | | | | Chrysotile (white asbestos) | |

B00G - R0003 - Practical Activities - 1hb

No Asbestos

B00G - R0004 - Home Base Store

No Asbestos

B00G - R0005 - Movement

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Home Base Store

No Asbestos

B00G - R0008 - Practical Activities - 1hb

No Asbestos

B00G - R0009 - Cleaning Distributed Store

No Asbestos

B00G - R0010 - Staff Toilet

| | | | | | | |
|---|------------------|-----|------------|--------------------|------------------------------------|--------------------|
| Wall Linings Internal | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 2901/B00G/R0010/Wall Linings Internal/S10 | | | | | Chrysotile (white asbestos) | |

B00G - R0011 - Home Base Store

No Asbestos

B00G - R0012 - Home Base

No Asbestos

B00G - R0013 - Practical Activities - 1hb

No Asbestos

B00G - R0014 - Sports Store

| | | | | | | |
|--|------------------|-----|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 3m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 2901/B00G/R0002/Ceiling Structures/Linings/S11 | | | | | Chrysotile (white asbestos) | |

B00G - R0015 - External Movement

| | | | | | | |
|--|------------------|------|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 12m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 2901/B00G/R0002/Ceiling Structures/Linings/S11 | | | | | Chrysotile (white asbestos) | |

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00H - Pupil Facilities - 1968 - Brick/Block (Brick/Block)

Exterior

| | |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Void | No Asbestos Found |

Interior

B00H - R0001 - External Movement

| | | | | | | |
|--|------------------|------|-----------------------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 32m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 2901/B00H/R0001/Ceiling Structures/Linings/S13 | | | | | Chrysotile (white asbestos) | |
| Wall Linings Internal | Flat AC Sheeting | 2m2 | North, South, Upper portion | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 2901/B00H/R0001/Ceiling Structures/Linings/S13 | | | | | Chrysotile (white asbestos) | |

B00H - R0002 - Toilets - Girls

| | | | | | | |
|--|------------------|------|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 42m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 2901/B00H/R0003/Ceiling Structures/Linings/S21 | | | | | Chrysotile (white asbestos) | |

B00H - R0003 - Cleaning Supplies

| | | | | | | |
|--|------------------|------|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 13m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 2901/B00H/R0003/Ceiling Structures/Linings/S21 | | | | | Chrysotile (white asbestos) | |

B00H - R0004 - Toilets - Boys

| | | | | | | |
|--|------------------|------|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 42m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 2901/B00H/R0003/Ceiling Structures/Linings/S21 | | | | | Chrysotile (white asbestos) | |

B00H - R0005 - Hall Chair Store

| | | | | | | |
|--|------------------|------|------------|--------------------|------------------------------------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 14m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 2901/B00H/R0003/Ceiling Structures/Linings/S21 | | | | | Chrysotile (white asbestos) | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B001 - Library - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B001 - R0001 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B001 - R0003 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0004 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00J - Special Purpose - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids | No Asbestos Found |

Interior

B00J - R0001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00J - R0002 - Special Programs Room

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00J - R0003 - Cleaning Distributed Store

No Asbestos

B00J - R0004 - General Storeroom

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00J - R0005 - Plant

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00K - Communal Facilities/Pupil Facilities - 1994 - Brick/Block (Brick/Block)

Exterior

| | |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids | No Asbestos Found |

Interior

B00K - R0001 - External Movement

No Asbestos

B00K - R0002 - Disabled Toilet

No Asbestos

B00K - R0003 - General Assistant/Bulk Store

No Asbestos

B00K - R0004 - General Storeroom

No Asbestos

B00K - R0005 - Plant

No Asbestos

B00K - R0006 - P.E. Store

No Asbestos

B00K - R0007 - Hall Chair Store

No Asbestos

B00K - R0008 - Toilets - Boys

No Asbestos

B00K - R0009 - Staff Shower/Change

No Asbestos

B00K - R0010 - Movement

No Asbestos

B00K - R0011 - External Movement

No Asbestos

B00K - R0012 - Stage

No Asbestos

B00K - R0014 - Toilets - Girls

| | | |
|----------------------------|---|-----------------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet | |
| | 2901/B00K/R0014/Partition Walls (Cubicles)/S6 | No Asbestos Detected |

B00K - R0015 - Cleaning Supplies

No Asbestos

B00K - R0016 - Plant

No Asbestos

B00K - R0017 - General Storeroom

No Asbestos

B00K - R0018 - General Assistant/Bulk Store

No Asbestos

B00K - R0019 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0020 - Communal Space

No Asbestos

B00K - R0021 - Sports Store

No Asbestos

B00K - R0022 - Canteen Office/Store

No Asbestos

B00K - R0023 - Canteen

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00K - R0024 - Movement

No Asbestos

B00K - R0025 - Lift

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00L - General Learning - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids | No Asbestos Found |

Interior

B00L - R0001 - External Movement

No Asbestos

B00L - R0002 - Practical Activities - 1hb

No Asbestos

B00L - R0003 - Home Base Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0004 - Home Base

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0005 - Home Base

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0006 - Home Base Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0007 - Home Base Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0008 - Home Base

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0009 - Home Base

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0010 - Home Base Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0011 - Access Shower/Toilet - Type 2

No Asbestos

B00L - R0012 - Laundry - Type 2

No Asbestos

B00L - R0013 - Practical Activities - 1hb

No Asbestos

B00L - R0014 - Withdrawal Space - 2hb

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00L - R0015 - Practical Activities - 1hb

No Asbestos

B00L - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0017 - Practical Activities - 1hb

No Asbestos

B00L - R0018 - Withdrawal Space - 2hb

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00M - General Learning - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids | No Asbestos Found |

Interior

B00M - R0001 - Movement

No Asbestos

B00M - R0002 - Practical Activities - 1hb

No Asbestos

B00M - R0003 - Home Base Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00M - R0004 - Home Base

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00M - R0005 - Home Base

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00M - R0006 - Home Base Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00M - R0007 - Home Base Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00M - R0008 - Home Base

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00M - R0009 - Home Base

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00M - R0010 - Home Base Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00M - R0011 - Cleaning Distributed Store

No Asbestos

B00M - R0012 - Staff Toilet

No Asbestos

B00M - R0013 - Practical Activities - 1hb

No Asbestos

B00M - R0014 - Withdrawal Space - 2hb

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00M - R0015 - Practical Activities - 1hb

No Asbestos

B00M - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0017 - Practical Activities - 1hb

No Asbestos

B00M - R0018 - Withdrawal Space - 2hb

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00N - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids | No Asbestos Found |

Interior

| | |
|--|-------------|
| B00N - R0001 - External Movement | No Asbestos |
| B00N - R0002 - Practical Activities - 1hb | No Asbestos |
| B00N - R0003 - Home Base Store | No Asbestos |
| B00N - R0004 - Home Base | No Asbestos |
| B00N - R0005 - Withdrawal Space - 2hb | No Asbestos |
| B00N - R0006 - Home Base | No Asbestos |
| B00N - R0007 - Home Base Store | No Asbestos |
| B00N - R0008 - Practical Activities - 1hb | No Asbestos |
| B00N - R0009 - Distribution Board | No Asbestos |

Note: No inspection of live electrical installation.

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B000 - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids | No Asbestos Found |

Interior

B000 - R0001 - Movement

No Asbestos

B000 - R0002 - Special Programs Room

No Asbestos

B000 - R0003 - Special Programs Store

No Asbestos

B000 - R0004 - Special Programs Store

No Asbestos

B000 - R0005 - Movement

No Asbestos

B000 - R0006 - Cleaning Distributed Store

No Asbestos

B000 - R0007 - Special Programs Store

No Asbestos

B000 - R0008 - Special Programs Room

No Asbestos

B000 - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B000 - R0010 - Practical Activities - 1hb

No Asbestos

B000 - R0011 - Home Base Store

No Asbestos

B000 - R0012 - Home Base

No Asbestos

B000 - R0013 - Home Base

No Asbestos

B000 - R0014 - Withdrawal Space - 2hb

No Asbestos

B000 - R0015 - Home Base Store

No Asbestos

B000 - R0016 - Practical Activities - 1hb

No Asbestos

B000 - R0017 - External Movement

No Asbestos



| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D13496 - Learning Unit - Standard With P.A.A. : Placement Date - 22/01/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14735 - Learning Unit - Standard With P.A.A. : Placement Date - 17/02/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14837 - Learning Unit - Standard With P.A.A. : Placement Date - 17/08/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017