

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Prairievale Public School (4554)
Region : South Western Sydney
State Electorate : Prospect
Local Government Area : Fairfield

Initial Survey : Noel Arnold & Associates : 14 - May - 2008
Reviewed By : Parsons Brinckerhoff : 03 - Jan - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00A - R0001 - Staff Toilet

No Asbestos

B00A - R0002 - Staff Toilet

No Asbestos

B00A - R0003 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0004 - Cleaning Distributed Store

No Asbestos

B00A - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0006 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0007 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0008 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0009 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0010 - Toilets - Boys/Girls

No Asbestos

B00A - R0011 - Security Store

No Asbestos

B00A - R0012 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0013 - General Storeroom

No Asbestos

B00A - R0014 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0015 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0016 - Sick Bay

No Asbestos

B00A - R0017 - Staff Toilet

No Asbestos

B00A - R0018 - Staff Shower/Change

No Asbestos

B00A - R0019 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0020 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0021 - Entry Vestibule						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0022 - Clerical Office						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0023 - Duplicating Workroom						
No Asbestos						
B00A - R0024 - Staff Room Annexe						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0025 - Staff Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0026 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	4554/B00A/R0026/Ceiling Structures/Linings/S1					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	4554/B00A/R0026/Ceiling Structures/Linings/S1					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Awnings	Flat AC Sheeting 4554/B00B/R0012/Ceiling Structures/Linings/S2					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00B - R0001 - Practical Activities - 1hb

No Asbestos

B00B - R0002 - General Storeroom

No Asbestos

B00B - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - Cleaning Distributed Store

No Asbestos

B00B - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00B/R0012/Ceiling Structures/Linings/S2					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00B - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00B/R0012/Ceiling Structures/Linings/S2					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00B - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00B/R0012/Ceiling Structures/Linings/S2					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00B - R0013 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Awnings	Flat AC Sheeting 4554/B00C/R0011/Ceiling Structures/Linings/S3					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00C - R0001 - Practical Activities - 1hb

No Asbestos

B00C - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0007 - Sports Store

No Asbestos

B00C - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00C/R0011/Ceiling Structures/Linings/S3					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00C - R0010 - Movement


Ceiling Structures/Linings	Flat AC Sheeting 4554/B00C/R0011/Ceiling Structures/Linings/S3					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00C - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00C/R0011/Ceiling Structures/Linings/S3					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00C - R0012 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Awnings	Flat AC Sheeting 4554/B00D/R0012/Ceiling Structures/Linings/S4					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00D - R0001 - Practical Activities - 1hb

No Asbestos

B00D - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - General Storeroom

No Asbestos

B00D - R0008 - Cleaning Distributed Store

No Asbestos

B00D - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00D/R0012/Ceiling Structures/Linings/S4					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00D - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00D/R0012/Ceiling Structures/Linings/S4					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00D - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00D/R0012/Ceiling Structures/Linings/S4					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00D - R0013 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Awnings	Flat AC Sheeting 4554/B00E/R0010/Ceiling Structures/Linings/S5					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00E - R0001 - Practical Activities - 1hb

No Asbestos

B00E - R0002 - Music Store

No Asbestos

B00E - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0008 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00E - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00E/R0010/Ceiling Structures/Linings/S5					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00E - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00E/R0010/Ceiling Structures/Linings/S5					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00E - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00E/R0010/Ceiling Structures/Linings/S5					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00E - R0012 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Awnings	Flat AC Sheeting 4554/B00F/R0009/Ceiling Structures/Linings/S6					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00F - R0001 - Practical Activities - 1hb

No Asbestos

B00F - R0002 - General Storeroom

No Asbestos

B00F - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00F/R0009/Ceiling Structures/Linings/S6					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00F - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00F/R0009/Ceiling Structures/Linings/S6					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00F - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00F/R0009/Ceiling Structures/Linings/S6					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00F - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0012 - Cleaning Distributed Store

No Asbestos

B00F - R0013 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 4554/B00G/R0001/Partition Walls (Cubicles)/S13	No Asbestos Detected
----------------------------	---	----------------------

B00G - R0002 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00G/R0002/Ceiling Structures/Linings/S15	No Asbestos Detected
----------------------------	--	----------------------

B00G - R0003 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 4554/B00G/R0001/Partition Walls (Cubicles)/S13	No Asbestos Detected
----------------------------	---	----------------------

B00G - R0004 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00G/R0002/Ceiling Structures/Linings/S15	No Asbestos Detected
----------------------------	--	----------------------

B00G - R0005 - Main Switch Board

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Library - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Awnings	Flat AC Sheeting 4554/B00H/R0010/Ceiling Structures/Linings/S11					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00H - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0003 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0004 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0005 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0006 - No Access

Electrical Backing Board	Resinous Board	1Unit	South	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------	-------	-------	--------------------	---------	--------------------

Assumed Asbestos - Metal Electrical Box - Electrical

B00H - R0007 - Disabled Toilet

No Asbestos

B00H - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00H/R0010/Ceiling Structures/Linings/S11					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00H - R0009 - Plant

No Asbestos

B00H - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00H/R0010/Ceiling Structures/Linings/S11					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00I - R0001 - Movement

Wall Linings Internal	Flat AC Sheeting 4554/B00I/R0001/Wall Linings Internal/S9	No Asbestos Detected
-----------------------	--	-----------------------------

B00I - R0002 - Practical Activities - 1hb

Electrical Backing Board	Resinous Board 4554/B00I/R0004/Electrical Backing Board/S8	No Asbestos Detected
--------------------------	---	-----------------------------

B00I - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0004 - Home Base

Electrical Backing Board	Resinous Board 4554/B00I/R0004/Electrical Backing Board/S8	No Asbestos Detected
--------------------------	---	-----------------------------

B00I - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0006 - Home Base

Electrical Backing Board	Resinous Board 4554/B00I/R0004/Electrical Backing Board/S8	No Asbestos Detected
--------------------------	---	-----------------------------

B00I - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0008 - Practical Activities - 1hb

Electrical Backing Board	Resinous Board 4554/B00I/R0004/Electrical Backing Board/S8	No Asbestos Detected
--------------------------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Awnings	Flat AC Sheeting 4554/B00J/R0011/Ceiling Structures/Linings/S7					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior

B00J - R0001 - Practical Activities - 1hb

No Asbestos

B00J - R0002 - General Storeroom

No Asbestos

B00J - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0008 - Cleaning Distributed Store

No Asbestos

B00J - R0009 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00J - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00J/R0011/Ceiling Structures/Linings/S7					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00J - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00J/R0011/Ceiling Structures/Linings/S7					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00J - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00J/R0011/Ceiling Structures/Linings/S7					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00J - R0013 - External Movement

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - Pupil Facilities - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00K - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 4554/B00K/R0003/Partition Walls (Cubicles)/S20	No Asbestos Detected
----------------------------	---	-----------------------------

B00K - R0002 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00K/R0002/Ceiling Structures/Linings/S19	No Asbestos Detected
----------------------------	--	-----------------------------

B00K - R0003 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 4554/B00K/R0003/Partition Walls (Cubicles)/S20	No Asbestos Detected
----------------------------	---	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Awnings	Flat AC Sheeting					No Asbestos Detected
	4554/B00L/R0009/Ceiling Structures/Linings/S10					
Ceiling Voids	No Asbestos Found					

Interior

B00L - R0001 - Special Programs Room

Kiln	Encapsulated Insulation material within unit	1Unit(s)	South	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Encapsulated kiln with Tarpaulin and						

B00L - R0002 - Craft Store

No Asbestos

B00L - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4554/B00L/R0009/Ceiling Structures/Linings/S10					

B00L - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4554/B00L/R0009/Ceiling Structures/Linings/S10					

B00L - R0010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					No Asbestos Detected
	4554/B00L/R0009/Ceiling Structures/Linings/S10					

B00L - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0012 - Cleaning Distributed Store

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Pupil Facilities/Building Services - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 4554/B00M/R0001/Partition Walls (Cubicles)/S12	No Asbestos Detected
----------------------------	---	-----------------------------

B00M - R0002 - Cleaning Supplies

No Asbestos

B00M - R0003 - Cleaning Supplies

No Asbestos

B00M - R0004 - No Access

Partition Walls (Cubicles)	Compressed AC Sheet 4554/B00M/R0001/Partition Walls (Cubicles)/S12	No Asbestos Detected
----------------------------	---	-----------------------------

B00M - R0005 - Garden Store

No Asbestos

B00M - R0006 - General Assistant/Bulk Store

No Asbestos

B00M - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0008 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting 4554/B00M/R0008/Ceiling Structures/Linings/S14	No Asbestos Detected
----------------------------	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Pupil Facilities/Communal Facilities - 1986 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Void	AC Fragments/Debris 4554/B00N/Ceiling Void/S21					No Asbestos Detected

Interior

B00N - R0001 - Communal Space

No Asbestos

B00N - R0002 - General Storeroom

No Asbestos

B00N - R0003 - Hall Chair Store

No Asbestos

B00N - R0004 - Hall Chair Store

No Asbestos

B00N - R0005 - Raised Platform

No Asbestos

B00N - R0006 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 4554/B00N/R0006/Partition Walls (Cubicles)/S18					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00N - R0007 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet 4554/B00N/R0006/Partition Walls (Cubicles)/S18					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00N - R0008 - Movement

In-fill-panel	Flat AC Sheeting 4554/B00N/R0008/In-fill-panel/S17					No Asbestos Detected
---------------	---	--	--	--	--	-----------------------------

B00N - R0009 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 4554/B00N/R0006/Partition Walls (Cubicles)/S18					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00N - R0010 - Plant

Wall Linings Internal	Flat AC Sheeting 4554/B00N/R0021/Wall Linings Internal/S16					No Asbestos Detected
-----------------------	---	--	--	--	--	-----------------------------

Incinerrette	Encapsulated Insulation material within unit	1Unit(s)	Throughout	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - No Access to Room - No key on site						

B00N - R0011 - Movement

In-fill-panel	Flat AC Sheeting 4554/B00N/R0008/In-fill-panel/S17					No Asbestos Detected
---------------	---	--	--	--	--	-----------------------------

B00N - R0012 - Shower/Change

Partition Walls (Cubicles)	Compressed AC Sheet 4554/B00N/R0006/Partition Walls (Cubicles)/S18					No Asbestos Detected
----------------------------	---	--	--	--	--	-----------------------------

B00N - R0013 - General Storeroom

No Asbestos

B00N - R0014 - Canteen

No Asbestos

B00N - R0015 - Canteen Office/Store

No Asbestos

B00N - R0016 - Canteen Office/Store

No Asbestos

B00N - R0017 - P.E. Store

No Asbestos

B00N - R0018 - Toilets - Girls

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
In-fill-panel	Flat AC Sheeting					
	4554/B00N/R0008/In-fill-panel/S17					No Asbestos Detected
B00N - R0019 - Movement						
Wall Linings Internal	Flat AC Sheeting					
	4554/B00N/R0021/Wall Linings Internal/S16					No Asbestos Detected
B00N - R0020 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00N - R0021 - Movement						
Wall Linings Internal	Flat AC Sheeting					
	4554/B00N/R0021/Wall Linings Internal/S16					No Asbestos Detected
B00N - R0022 - Movement						
Wall Linings Internal	Flat AC Sheeting					
	4554/B00N/R0021/Wall Linings Internal/S16					No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B000 - R0001 - Practical Activities - 1hb

No Asbestos

B000 - R0002 - Home Base

No Asbestos

B000 - R0003 - Home Base Store

No Asbestos

B000 - R0004 - Withdrawal Space - 2hb

No Asbestos

B000 - R0005 - Practical Activities - 1hb

No Asbestos

B000 - R0006 - Home Base

No Asbestos

B000 - R0007 - Home Base Store

No Asbestos

B000 - R0008 - Practical Activities - 1hb

No Asbestos

B000 - R0009 - Home Base

No Asbestos

B000 - R0010 - Home Base Store

No Asbestos

B000 - R0011 - Withdrawal Space - 2hb

No Asbestos

B000 - R0012 - Practical Activities - 1hb

No Asbestos

B000 - R0013 - Home Base

No Asbestos

B000 - R0014 - Home Base Store

No Asbestos

B000 - R0015 - External Movement

No Asbestos

B000 - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10480 - Learning Unit - Standard With P.A.A. : Placement Date - 1/11/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 751 - D14901 - Learning Unit - ESL : Placement Date - 31/03/2015

Exterior

No Asbestos Found.

Interior

R1 - Esl

No Asbestos Found.

R2 - Esl

No Asbestos Found.

OS 602 - D17690 - Learning Unit - Standard With P.A.A. : Placement Date - 25/03/2015

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

4554_ASB_231112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017