

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1968 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Staff Toilet

No Asbestos

B00A - R0003 - Staff Toilet

No Asbestos

B00A - R0004 - Staff Toilet

No Asbestos

B00A - R0005 - Shower/Change

No Asbestos

B00A - R0006 - Interview

No Asbestos

B00A - R0007 - Deputy Principal

No Asbestos

B00A - R0008 - Staff Room Annexe

No Asbestos

B00A - R0009 - Clerical Office/Workroom

No Asbestos

B00A - R0010 - Staff Room Annexe

No Asbestos

B00A - R0011 - Staff Room

No Asbestos

B00A - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0013 - Principal

No Asbestos

B00A - R0014 - Security Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Support Unit/Pupil Facilities - 1969 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior**B00B - R0001 - Toilets - Boys/Disabled Cubicle**

No Asbestos

B00B - R0002 - Movement

No Asbestos

B00B - R0007 - Toilets - Girls/Disabled Cubicle

No Asbestos

B00B - R0011 - General Assistant/Bulk Store

No Asbestos

B00B - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5761/B00B/R0023/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

B00B - R0013 - Main Switch Board

No Asbestos

B00B - R0014 - Cleaning Supplies

No Asbestos

B00B - R0015 - Clerical Office/Workroom

No Asbestos

B00B - R0016 - Entry Vestibule

No Asbestos

B00B - R0017 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5761/B00B/R0017/Ceiling Structures/Linings/S2					Chrysotile (white asbestos)	

B00B - R0019 - Security Store

No Asbestos

B00B - R0020 - Staff Room Annexe

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5761/B00B/R0023/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

B00B - R0021 - Clerical Office

No Asbestos

B00B - R0022 - Reading Area

No Asbestos

B00B - R0023 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	236m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
5761/B00B/R0023/Ceiling Structures/Linings/S1					Chrysotile (white asbestos)	

B00B - R0025 - Practical Activities - 1hb

No Asbestos

B00B - R0026 - Home Base

No Asbestos

B00B - R0027 - Home Base

No Asbestos

B00B - R0028 - Home Base

No Asbestos

B00B - R0029 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R0030 - Duplicating Workroom

No Asbestos

B00B - R0031 - Sick Bay

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Support Unit - 1968 - Fibre Cement Clad (Fibre Cement Clad)**Exterior**

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior**B00C - R0001 - Home Base Store - S**

No Asbestos

B00C - R0002 - Withdrawal - S

No Asbestos

B00C - R0003 - Home Base - S

No Asbestos

B00C - R0004 - Practical Activities - S - 2hb

No Asbestos

B00C - R0008 - Withdrawal - S

No Asbestos

B00C - R0009 - Home Base - S

No Asbestos

B00C - R0010 - Home Base - S

No Asbestos

B00C - R0011 - Practical Activities - S - 2hb

No Asbestos

B00C - R0012 - Practical Activities - S - 2hb

No Asbestos

B00C - R0013 - Home Base - S

No Asbestos

B00C - R0014 - Home Base Store - S

No Asbestos

B00C - R0015 - Withdrawal - S

No Asbestos

B00C - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0017 - Movement

No Asbestos

B00C - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0019 - Practical Activities - S - 2hb

No Asbestos

B00C - R0020 - Withdrawal - S

No Asbestos

B00C - R0021 - Home Base Store - S

No Asbestos

B00C - R0022 - Home Base - S

No Asbestos

B00C - R0023 - Practical Activities - S - 2hb

No Asbestos

B00C - R0024 - Staff Kitchen

No Asbestos

B00C - R0025 - Staff Room

No Asbestos

B00C - R0026 - Duplicating Workroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R0027 - Staff Room Annexe

No Asbestos

B00C - R0028 - Movement

No Asbestos

B00C - R0029 - Staff Shower/Change

No Asbestos

B00C - R0030 - Staff Toilet

No Asbestos

B00C - R0031 - Toilets - Girls

No Asbestos

B00C - R0032 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Administration/Staff Facilities - 1968 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting 5761/B00D/R0006/Wall Linings Internal/S3	No Asbestos Detected
-----------------------	--	-----------------------------

B00D - R0003 - Cleaning Distributed Store

Wall Linings Internal	Flat AC Sheeting 5761/B00D/R0006/Wall Linings Internal/S3	No Asbestos Detected
-----------------------	--	-----------------------------

B00D - R0004 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 5761/B00D/R0006/Wall Linings Internal/S3	No Asbestos Detected
-----------------------	--	-----------------------------

B00D - R0005 - General Storeroom

Wall Linings Internal	Flat AC Sheeting 5761/B00D/R0006/Wall Linings Internal/S3	No Asbestos Detected
-----------------------	--	-----------------------------

B00D - R0006 - Wheelchair Store-Special Ed

Wall Linings Internal	Flat AC Sheeting 5761/B00D/R0006/Wall Linings Internal/S3	No Asbestos Detected
-----------------------	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Support Unit/Pupil Facilities - 1968 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior**B00E - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
	5761/B00E/R0024/Ceiling Structures/Linings/S4					No Asbestos Detected

B00E - R0002 - Toilet - S

Ceiling Structures/Linings	Flat AC Sheeting					
	5761/B00E/R0024/Ceiling Structures/Linings/S4					No Asbestos Detected

B00E - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	5761/B00E/R0024/Ceiling Structures/Linings/S4					No Asbestos Detected

B00E - R0004 - Cleaning Distributed Store

No Asbestos

B00E - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	5761/B00E/R0024/Ceiling Structures/Linings/S4					No Asbestos Detected

B00E - R0012 - Toilet - S

Ceiling Structures/Linings	Flat AC Sheeting					
	5761/B00E/R0024/Ceiling Structures/Linings/S4					No Asbestos Detected

B00E - R0013 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	5761/B00E/R0024/Ceiling Structures/Linings/S4					No Asbestos Detected

B00E - R0018 - Movement

No Asbestos

B00E - R0023 - Home Base

No Asbestos

B00E - R0024 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting					
	5761/B00E/R0024/Ceiling Structures/Linings/S4					No Asbestos Detected

Wall Linings Internal	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	5761/B00E/R0024/Wall Linings Internal/S5					Chrysotile (white asbestos)

B00E - R0025 - Practical Activities - 1hb

No Asbestos

B00E - R0026 - Sports Store

No Asbestos

B00E - R0027 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Support Unit/Pupil Facilities - 2002 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00F - R0001 - Special Education Support Centre

No Asbestos

B00F - R0002 - Movement

No Asbestos

B00F - R0003 - Special Education Support Centre

No Asbestos

B00F - R0004 - Special Education Support Centre

No Asbestos

B00F - R0005 - Special Education Support Centre

No Asbestos

B00F - R0006 - Special Education Support Centre

No Asbestos

B00F - R0007 - Special Education Support Centre

No Asbestos

B00F - R0008 - Special Education Support Centre

No Asbestos

B00F - R0009 - Special Education Support Centre

No Asbestos

B00F - R0010 - Movement

No Asbestos

B00F - R0011 - Special Education Support Centre

No Asbestos

B00F - R0012 - Special Education Support Centre

No Asbestos

B00F - R0013 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017