

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ulong Public School (3304)
Region : North Coast
State Electorate : Coffs Harbour
Local Government Area : Coffs Harbour

Initial Survey : Noel Arnold & Associates : 20 - May - 2008
Reviewed By : Greencap-NAA : 05 - May - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1947 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3304/B00A/Eaves Linings/S9					Chrysotile (white asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - Movement

No Asbestos

B00A - R0002 - Home Base Store

Floor Coverings Res/Textile	Vinyl Tiles					
	3304/B00A/R0002/Floor Coverings Res/Textile/S3					No Asbestos Detected
Floor Coverings Res/Textile	Adhesive					
	3304/B00A/R0002/Floor Coverings Res/Textile/S10					No Asbestos Detected

B00A - R0003 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Administration - 1914 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	6m2	East & West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3304/B00B/Eaves Linings/S4			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Voids	Non Accessible Area - Height Restriction 4m height					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0001 - Kiln Room

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3304/B00B/R0003/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3304/B00B/R0003/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00B - R0003 - Home Base Store

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3304/B00B/R0003/Ceiling Structures/Linings/S5			Chrysotile (white asbestos) , Amosite (brown asbestos)		

Floor Coverings Res/Textile	Adhesive					
	3304/B00B/R0005/Floor Coverings Res/Textile/S7					No Asbestos Detected

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3304/B00B/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

B00B - R0004 - Home Base

Floor Coverings Res/Textile	Adhesive					
	3304/B00B/R0005/Floor Coverings Res/Textile/S7					No Asbestos Detected

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3304/B00B/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

B00B - R0005 - Withdrawal Space - 1hb

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3304/B00B/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

Floor Coverings Res/Textile	Adhesive					
	3304/B00B/R0005/Floor Coverings Res/Textile/S7					No Asbestos Detected

B00B - R0006 - General Storeroom

Floor Coverings Res/Textile	Adhesive					
	3304/B00B/R0005/Floor Coverings Res/Textile/S7					No Asbestos Detected

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet)					
	3304/B00B/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 1972 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Eaves Linings	Low Density Fibre Board 3304/B00C/Eaves Linings/S8	8m2	Throughout	Friable Asbestos (5) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Medium Priority (4-5)
Ceiling Voids	Non Accessible Area - Area inaccessible no access point					

Interior

B00C - R0001 - Drinking Facilities

Ceiling Structures/Linings	Low Density Fibre Board 3304/B00C/Eaves Linings/S8	10m2	Throughout	Friable Asbestos (5) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Medium Priority (4-5)
----------------------------	---	------	------------	---	---------	-----------------------

B00C - R0002 - Movement

No Asbestos

B00C - R0003 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 3304/B00C/R0003/Partition Walls (Cubicles)/S1	4m2	Throughout	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)
Flue	Fibre Cement Pipe 3304/B00C/R0003/Fiber cement pipe/S2	1m	Throughout	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 3304/B00C/R0003/Partition Walls (Cubicles)/S1	4m2	Throughout	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)
----------------------------	--	-----	------------	---	---------	--------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1985 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible
Underfloor Voids	No Asbestos Found

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Canteen

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Shed - 1985 - Timber Shed (Timber Shed)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Sports Store

Non Accessible

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Shed - 1958 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00F - R0001 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Shed - 1985 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00G - R0001 - Canteen Covered Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Building Services - 2007 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - Sports Store

No Asbestos

B00H - R0002 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Library - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B001 - R0001 - Reading Area

No Asbestos

B001 - R0002 - K.L.A. Store

No Asbestos

B001 - R0003 - Practical Activities

No Asbestos

B001 - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 503 - D12961 - Admin Lib Staff/Principal/Clerk/Store : Placement Date - 17/12/1998

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	23.04 m2

Interior

R1 - Clerical Office

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	24 m2

R2 - Principal

Ceiling	Flat AC Sheet	Assumed Asbestos	16 m2
---------	---------------	------------------	-------

R3 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	5 m2

R4 - Staff Toilet

Toilet partitions	Compressed AC Sheet	Assumed Asbestos	2 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	5 m2

R5 - Reading Area

Ceiling	Flat AC Sheet	Assumed Asbestos	55 m2
---------	---------------	------------------	-------

R6 - Security Store

Ceiling	Flat AC Sheet	Assumed Asbestos	8 m2
---------	---------------	------------------	------

R7 - Staff Room

Ceiling	Flat AC Sheet	Assumed Asbestos	27 m2
---------	---------------	------------------	-------

R8 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	6 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017