

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wagga Wagga Public School (3330)
Region : Riverina
State Electorate : Wagga Wagga
Local Government Area : Wagga Wagga

Initial Survey : Noel Arnold & Associates : 18 - Dec - 2009
Reviewed By : Grencap-NAA : 18 - Feb - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Library/General Learning - 1909 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Non Accessible Area - Extreme Access Issue - No Access Point into ceiling void identified					
Louvers	Flat AC Sheeting	2m2	East	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - No Access Point into ceiling void identified					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior**B00A - R0002 - Library Office/Workroom**

Ceiling Structures/Linings	Flat AC Sheeting	17m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
Thermacon Heater	Encapsulated Insulation material within unit	1Unit	North facing	Friable Asbestos (5)	Low (1)	Low Priority (2-3)

B00A - R0004 - Staff Toilet

Partition Walls (Cubicles)	Flat AC Sheeting 3330/B00A/R0004/Partition Walls (Cubicles)/S1					No Asbestos Detected
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						

B00A - R0006 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	60m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Thermacon Heater	Encapsulated Insulation material within unit	2Unit	Variable positions	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Area inaccessible						

B00A - R0007 - Security Store

Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Floor Coverings Res/Textile	Vinyl Sheet 3330/B00A/R0007/Floor Coverings Res/Textile/S2					No Asbestos Detected

B00A - R0008 - Kiln Room

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						

B00A - R0009 - Movement

Floor Coverings Res/Textile	Vinyl Tiles 3330/B00A/R0007/Floor Coverings Res/Textile/S2					No Asbestos Detected
-----------------------------	---	--	--	--	--	-----------------------------

B00A - R0010 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						

B00A - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	37m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						

B00A - R0012 - Home Base

Non Accessible

B00A - R0013 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Non Accessible

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/General Learning - 1882 - Brick/Block (Brick/Block)**Exterior**

Sunhood (Louvers)	Flat AC Sheeting	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction					
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					

Interior**B00B - R0001 - Personal Effects Storage**

No Asbestos

B00B - R0003 - Home Base

No Asbestos

B00B - R0005 - Sick Bay

No Asbestos

B00B - R0006 - Interview

No Asbestos

B00B - R0007 - Movement

No Asbestos

B00B - R0008 - Principal

No Asbestos

B00B - R0011 - Entry Vestibule

No Asbestos

B00B - R0012 - Movement

No Asbestos

B00B - R0013 - Personal Effects Storage

No Asbestos

B00B - R0014 - Uniform Shop

No Asbestos

B00B - R0015 - Staff Toilet

No Asbestos

B00B - R0016 - Staff Toilet

No Asbestos

B00B - R0017 - General Storeroom

No Asbestos

B00B - R0018 - General Assistant/Bulk Store

No Asbestos

B00B - R0019 - Movement

No Asbestos

B00B - R0020 - Clerical Office

No Asbestos

B00B - R0021 - Staff Room

No Asbestos

B00B - R0022 - Staff Kitchen

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Staff Facilities/General Learning - 1926 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	Non Accessible Area - Height Restriction

Interior**B00C - M0001 - Home Base Store**

No Asbestos

B00C - M0002 - Movement

No Asbestos

B00C - M0003 - Stairs

No Asbestos

B00C - M0004 - Stairs

No Asbestos

B00C - R0001 - Home Base

No Asbestos

B00C - R0005 - Home Base

No Asbestos

B00C - R0006 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	98m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00C - R0007 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00C - R0008 - Cleaning Supplies

No Asbestos

B00C - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
Electrical Mounting Board	Resinous Board	1Unit	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R0009/Electrical Mounting Board/S15					Chrysotile (white asbestos)	

B00C - R0010 - Home Base

No Asbestos

B00C - R0011 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00C - R0012 - Staff Room Annexe

Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00C - R0013 - General Storeroom

No Asbestos

B00C - R0014 - Movement

No Asbestos

B00C - R0015 - Home Base Store

No Asbestos

B00C - R0016 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00C - R0017 - Staff Room						
No Asbestos						
B00C - R0018 - Movement						
No Asbestos						
B00C - R0019 - Stairs						
No Asbestos						
B00C - R0020 - Stairs						
No Asbestos						
B00C - R0021 - Main Switch Board						
Non Accessible						
B00C - R1001 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00C - R1002 - Withdrawal Space - 1hb						
No Asbestos						
B00C - R1003 - Home Base						
No Asbestos						
B00C - R1004 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles					
3330/B00C/R1006/Floor Coverings Res/Textile/S4					No Asbestos Detected	
B00C - R1005 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00C - R1006 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Tiles					
3330/B00C/R1006/Floor Coverings Res/Textile/S4					No Asbestos Detected	
B00C - R1007 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00C - R1008 - Home Base						
No Asbestos						
B00C - R1011 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00C - R1012 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00C - R1014 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00C - R1015 - Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	92m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00C - R1016 - Home Base Store						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
Floor Coverings Res/Textile	Vinyl Sheet					
3330/B00C/R1016/Floor Coverings Res/Textile/S5					No Asbestos Detected	
B00C - R1017 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00C - R1018 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00C - R1019 - Personal Effects Storage						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00C - R1020 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00C/R1015/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Staff Facilities/General Learning - 1922 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible
Ceiling Voids	Non Accessible Area - Height Restriction

Interior**B00D - R0001 - Home Base**

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0002 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0003 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0004 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0005 - Movement

No Asbestos

B00D - R0007 - Personal Effects Storage

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0008 - Toilets - Boys/Girls

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0009 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0010 - Home Base - M

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles 3330/B00D/R0010/Floor Coverings Res/Textile/S6	No Asbestos Detected

B00D - R0011 - No Access

Non Accessible

B00D - R0012 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0013 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0014 - Movement

No Asbestos

B00D - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0016 - Staff Room Annexe

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00D/R0007/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0017 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting					
	3330/B00D/R0007/Ceiling Structures/Linings/S7					No Asbestos Detected
B00D - R0018 - Practical Activities - 1hb						
Ceiling Structures/Linings	Flat AC Sheeting					
	3330/B00D/R0007/Ceiling Structures/Linings/S7					No Asbestos Detected
B00D - R0019 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	3330/B00D/R0007/Ceiling Structures/Linings/S7					No Asbestos Detected
B00D - R0022 - External Movement						
No Asbestos						
B00D - R0023 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1950 - Timber (Timber)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior

B00E - R0004 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	52m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3330/B00E/R0002/Wall Linings Internal/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3330/B00E/R0002/Wall Linings Internal/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0006 - Home Base

No Asbestos

B00E - R0007 - Home Base/Practical Activities

No Asbestos

B00E - R0008 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	3330/B00E/R0002/Wall Linings Internal/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Wall Linings Internal	Flat AC Sheeting	12m2	North facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3330/B00E/R0002/Wall Linings Internal/S8			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00E - R0010 - Sports Store

Non Accessible

B00E - R0011 - Movement

Non Accessible

B00E - R0012 - Home Base

Non Accessible

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00F - Communal Facilities/Pupil Facilities - 1984 - Brick/Veneer (Brick/Veneer)**Exterior**

Gable Ends	Compressed AC Sheet 3330/B00F/Gable Ends/S10					No Asbestos Detected
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	Non Accessible Area - Area inaccessible					

Interior**B00F - R0001 - Distribution Board**

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected

B00F - R0002 - Shower/Change

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected

B00F - R0003 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected

B00F - R0004 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet 3330/B00G/R0002/Partition Walls (Cubicles)/S9	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0005 - Hall Chair Store

No Asbestos

B00F - R0007 - Toilets - Boys/Disabled Cubicle

Partition Walls (Cubicles)	Compressed AC Sheet 3330/B00G/R0002/Partition Walls (Cubicles)/S9	20m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0009 - External Movement

No Asbestos

B00F - R0014 - Hall Chair Store

No Asbestos

B00F - R0015 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 3330/B00G/R0002/Partition Walls (Cubicles)/S9	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)

B00F - R0016 - Plant

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected

B00F - R0017 - Shower/Change

Ceiling Structures/Linings	Flat AC Sheeting 3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0018 - Cleaning Supplies						
Ceiling Structures/Linings	Flat AC Sheeting					
	3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected
B00F - R0019 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting					
	3330/B00F/R0012/Ceiling Structures/Linings/S11					No Asbestos Detected
B00F - R0020 - Movement						
Wall Linings Internal	Flat AC Sheeting					
	3330/B00F/Gable Ends/S10					No Asbestos Detected
B00F - R0021 - Raised Platform						
No Asbestos						
B00F - R0026 - Communal Space						
Non Accessible						
B00F - R0027 - Sports Store						
Non Accessible						
B00F - R0029 - External Movement						
Non Accessible						
B00F - R0030 - Chair Storeroom						
Non Accessible						
B00F - R0031 - External Movement						
Non Accessible						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1970 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids Non Accessible Area
- Height Restriction

Underfloor Voids Non Accessible Area
- Area inaccessible

Interior**B00G - R0001 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	36m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00G/R0001/Ceiling Structures/Linings/S14				Chrysotile (white asbestos) , Amosite (brown asbestos)		

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00G/R0002/Partition Walls (Cubicles)/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00G - R0002 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	35m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Item is removed						

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00G/R0002/Partition Walls (Cubicles)/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1980 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00H - R0001 - Toilets - Girls

No Asbestos

B00H - R0002 - Movement

No Asbestos

B00H - R0004 - Disabled Toilet

No Asbestos

B00H - R0005 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00J - Administration - 1872 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Non Accessible Area - Height Restriction
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior**B00J - R0001 - Staff Kitchen**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00J/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Floor Coverings Res/Textile	Vinyl Sheet					
3330/B00J/R0001/Floor Coverings Res/Textile/S13				No Asbestos Detected		

B00J - R0002 - Tutorial Centre

Wall Linings Internal	Flat AC Sheeting	10m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00J/R0014/Wall Linings Internal/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						

B00J - R0003 - Staff Shower/Change

Wall Linings Internal	Flat AC Sheeting	10m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00J/R0001/Ceiling Structures/Linings/S19				Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						

B00J - R0004 - Itinerant Teachers Unit

Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						

B00J - R0005 - Therapy Store

Wall Linings Internal	Flat AC Sheeting	45m2	North facing, South facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00J/R0014/Wall Linings Internal/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00J - R0006 - Clerical Office

Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
Heater backing board	Flat AC Sheeting	2m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
3330/B00J/R0014/Wall Linings Internal/S12				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00J - R0007 - Tutorial Centre

Ceiling Structures/Linings	Flat AC Sheeting	19m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						

B00J - R0008 - Itinerant Teachers Unit

Ceiling Structures/Linings	Flat AC Sheeting	18m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						

B00J - R0009 - Therapy

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
B00J - R0010 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
B00J - R0011 - Movement						
No Asbestos						
B00J - R0012 - Staff Toilet						
Wall Linings Internal	Flat AC Sheeting	12m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3330/B00J/R0014/Wall Linings Internal/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
B00J - R0013 - Cleaning Distributed Store						
Wall Linings Internal	Flat AC Sheeting	15m2	South facing, East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3330/B00J/R0014/Wall Linings Internal/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Ceiling Structures/Linings	Flat AC Sheeting	7m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Height Restriction						
B00J - R0014 - Movement						
Electrical Mounting Board	Resinous Board	1Unit	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard						
Wall Linings Internal	Flat AC Sheeting	6m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	3330/B00J/R0014/Wall Linings Internal/S12			Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00L - Library - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Interior**B00L - R0001 - Reading Area**

No Asbestos

B00L - R0002 - Library Office/Workroom

No Asbestos

B00L - R0003 - Communications Room

No Asbestos

B00L - R0004 - K.L.A. Store

No Asbestos

B00L - R0005 - Toilet - Lobby

No Asbestos

B00L - R0006 - Staff Toilet

No Asbestos

B00L - R0007 - Cleaning Distributed Store

No Asbestos

B00L - R0008 - Main Switch Board

Non Accessible

B00L - R0009 - Plant

Non Accessible

B00L - R0010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - Pupil Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

No Asbestos

Interior

B00M - R0001 - Canteen

No Asbestos

B00M - R0002 - Canteen Office/Store

No Asbestos

B00M - R0003 - Main Switch Board

Non Accessible

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Building Services - 1980 - Timber (Timber)

Exterior

Ceiling Voids	Non Accessible Area - Extreme Access Issue - Obstructed Area - To tight to access with ladder
Ceiling Voids	Non Accessible Area - Height Restriction - Extreme Access Issue - Obstructed Area - To tight to access with ladder
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible

Interior

B00N - R0001 - P.E. Store

Non Accessible

B00N - R0002 - Sports Store

Non Accessible

B00N - R0003 - Garden Store

Non Accessible

B00N - R0004 - General Storeroom

Non Accessible

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017