

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wallsend Public School (3357)
Region : Hunter/Central Coast
State Electorate : Wallsend
Local Government Area : Newcastle

Initial Survey : Noel Arnold & Associates : 24 - Apr - 2008
Reviewed By : AECOM : 25 - Jun - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1871 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	
Underfloor Voids	AC Fragments/Debris	0.05m2	East	Poor Condition - Extensive Damage (4)	Medium (2)	High Priority (6-8)
	3357/B00A/Underfloor Voids/S7				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	Non Accessible Area - Height Restriction					

Interior**B00A - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	1.92m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0001/Ceiling Structures/Linings/S6				Chrysotile (white asbestos) , Amosite (brown asbestos)	

Electrical Backing Board	Resinous Board	1m2	North	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Electrical Hazard					

B00A - R0015 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00A - R0016 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00A - R0020 - Movement

No Asbestos

B00A - R0021 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00A - R0022 - Reading Area

Floor Coverings Res/Textile	Vinyl Tiles	30m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0022/Floor Coverings Res/Textile/S4				Chrysotile (white asbestos)	

B00A - R0023 - Practical Activities - 1hb

No Asbestos

B00A - R0024 - Staff Room

Ceiling Structures/Linings	Flat AC Sheeting	32.2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00A - R0025 - Staff Kitchen

Ceiling Structures/Linings	Flat AC Sheeting	8.7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00A - R0026 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00A - R0027 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	3.84m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

B00A - R0028 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	3.84m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	3.84m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3357/B00A/R0021/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	
B00A - R0029 - Duplicating Workroom						
Ceiling Structures/Linings	Flat AC Sheeting	21m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3357/B00A/R0021/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	
B00A - R0030 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3357/B00A/R0021/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)	
B00A - R0031 - Movement						
No Asbestos						
B00A - R0032 - Clerical Office						
No Asbestos						
B00A - R0033 - Sick Bay						
No Asbestos						
B00A - R0034 - Interview						
No Asbestos						
B00A - R0035 - Deputy Principal						
No Asbestos						
B00A - R0036 - Staff Shower/Change						
No Asbestos						
B00A - R0037 - Staff Toilet						
No Asbestos						
B00A - R0038 - Cleaning Distributed Store						
No Asbestos						
B00A - R0039 - Security Store						
No Asbestos						
B00A - R0040 - Principal						
No Asbestos						
B00A - R0041 - Movement						
No Asbestos						
B00A - R9001 - General Assistant/Bulk Store						
No Asbestos						
B00A - R9002 - Cleaning Supplies						
No Asbestos						
B00A - R9003 - General Assistant/Bulk Store						
No Asbestos						
B00A - R9005 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Communal Facilities - 1881 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting 3357/B00B/Eaves Linings/S8					No Asbestos Detected
Underfloor Voids	Non Accessible Area - Access under verandah/movement area with no underfloor access to the building.					
Ceiling Voids	Non Accessible Area - Height Restriction					

Interior**B00B - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	18.34m2	Southwest end of movement area	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00B - R0002 - Movement

No Asbestos

B00B - R0003 - Sports Store

No Asbestos

B00B - R0004 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	54.72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00B - R0005 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	54.72m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00B - R0006 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	55m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00B - R0007 - Home Base

Ceiling Structures/Linings	Flat AC Sheeting	54m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00B - R0008 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	8.25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00B - R0009 - Cleaning Distributed Store

Ceiling Structures/Linings	Flat AC Sheeting	5.4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00A/R0021/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00B - R0011 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00C - General Learning - 1892 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	40m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	3357/B00C/R0006/Wall Linings Internal/S11			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		
Ceiling Voids	Non Accessible Area - Height Restriction					
Underfloor Voids	No Asbestos Found					

Interior**B00C - R0001 - Movement**

No Asbestos

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Staff Toilet

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00C/R0006/Ceiling Structures/Linings/S10			Chrysotile (white asbestos)		
Wall Linings Internal	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00C/R0006/Wall Linings Internal/S11			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		

B00C - R0006 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00C/R0006/Ceiling Structures/Linings/S10			Chrysotile (white asbestos)		
Wall Linings Internal	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00C/R0006/Wall Linings Internal/S11			Chrysotile (white asbestos) , Crocidolite (blue asbestos)		

Floor Coverings Res/Textile	Vinyl Tiles					
	3357/B00C/R0006/Floor Coverings Res/Textile/S3			No Asbestos Detected		

B00C - R0007 - K.L.A. Store

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00C/R0006/Ceiling Structures/Linings/S10			Chrysotile (white asbestos)		

B00C - R0010 - Practical Activities - 1hb

No Asbestos

B00C - R0011 - Home Base

No Asbestos

B00C - R0012 - Home Base

No Asbestos

B00C - R0013 - Practical Activities - 1hb

No Asbestos

B00C - R0016 - Practical Activities - 3hb

Ceiling Structures/Linings	Flat AC Sheeting	25.5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos - Height Restriction. Ceiling too high to access. Does not include skylight boxes. They appear to be					

B00C - R0017 - Home Base

No Asbestos

B00C - R0018 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting 3357/B00B/Eaves Linings/S8					No Asbestos Detected
Ceiling Voids	Flat AC Sheeting 3357/B00E/Ceiling Voids/S12					No Asbestos Detected
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible.					

Interior**B00E - R0001 - Toilets - Girls**

No Asbestos

B00E - R0002 - Toilets - Girls

No Asbestos

B00E - R0003 - Drinking Facilities

No Asbestos

B00E - R0004 - Toilets - Boys

No Asbestos

B00E - R0005 - Disabled Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1912 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00G/Eaves Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	Non Accessible Area - Height Restriction. Non accessible area. Man hole access point in R0008.					
Underfloor Voids	No Asbestos Found					

Interior**B00G - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00G/Eaves Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	3357/B00H/R0004/Wall Linings Internal/S2					

B00G - R0002 - Practical Activities - 1hb

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00G/Eaves Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	3357/B00H/R0004/Wall Linings Internal/S2					

B00G - R0003 - Home Base

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	3357/B00H/R0004/Wall Linings Internal/S2					

B00G - R0004 - Home Base

Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
	3357/B00H/R0004/Wall Linings Internal/S2					

B00G - R0005 - Practical Activities - 1hb

Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00G/Eaves Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0006 - Toilets - Boys/Girls

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00G/Eaves Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0007 - General Storeroom

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00G/Eaves Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0008 - Withdrawal Space - 1hb

No Asbestos

B00G - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3357/B00G/Eaves Linings/S9					Chrysotile (white asbestos) , Amosite (brown asbestos)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00K - Communal Facilities - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - No internal ceiling access points.
Underfloor Voids - Slab on Ground	Non Accessible Area - No floor space, building on slab on ground. Non accessible area.

Interior

B00K - R0001 - Communal Space

No Asbestos

B00K - R0002 - Movement

No Asbestos

B00K - R0003 - Communications Room

No Asbestos

B00K - R0004 - Main Switch Board

No Asbestos

B00K - R0005 - Sports Store

No Asbestos

B00K - R0006 - Hall Chair Store

No Asbestos

B00K - R0007 - P.E. Store

No Asbestos

B00K - R0008 - Toilets - Boys

No Asbestos

B00K - R0009 - Toilets - Girls

No Asbestos

B00K - R0010 - Lift

No Asbestos

B00K - R0011 - Movement

No Asbestos

B00K - R0012 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Pupil Facilities - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Non Accessible Area - Height Restriction. Non accessible area.
Underfloor Voids - Slab on Ground	Non Accessible Area - Slab on ground. No floor space. Non accessible area.

Interior

B00L - R0001 - Canteen

No Asbestos

B00L - R0002 - Canteen Office/Store

No Asbestos

B00L - R0003 - Cleaning Supplies

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00M - Library - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

No Asbestos

Interior**B00M - R0001 - External Movement**

No Asbestos

B00M - R0002 - Special Programs Room

No Asbestos

B00M - R0003 - Movement

No Asbestos

B00M - R0004 - Staff Toilet

No Asbestos

B00M - R0005 - Cleaning Distributed Store

No Asbestos

B00M - R0006 - Main Switch Board

No Asbestos

B00M - R0007 - Reading Area

No Asbestos

B00M - R0008 - K.L.A. Store

No Asbestos

B00M - R0009 - Communications Room

No Asbestos

B00M - R0010 - Library Office/Workroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017