



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00A - Administration/General Learning - 1915 - Timber (Timber)**

**Exterior**

|                           |  |          |   |                    |         |                                    |
|---------------------------|--|----------|---|--------------------|---------|------------------------------------|
| Eaves Linings             | Flat AC Sheeting                       | 30m2     | North facing,<br>South facing,<br>East facing,<br>West facing | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|                           | 3364/B00A/Eaves Linings/S4             |          |   |                    |         | <b>Chrysotile (white asbestos)</b> |
| Electrical mounting board | Resinous Board                         | 1Unit(s) | North facing  | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|                           | 3364/B00A/Electrical mounting board/S9 |          |   |                    |         | <b>Chrysotile (white asbestos)</b> |
| Ceiling Void              | No Asbestos Found                      |          |   |                    |         |                                    |
| Underfloor Void           | No Asbestos Found                      |          |   |                    |         |                                    |

**Interior**

**B00A - R0001 - Duplicating Workroom**

No Asbestos

**B00A - R0002 - Home Base**

No Asbestos

**B00A - R0003 - Home Base**

No Asbestos

**B00A - R0004 - Staff Room**

No Asbestos

**B00A - R0006 - Clerical Office**

No Asbestos

**B00A - R0007 - Clerical Office/Workroom**

No Asbestos

**B00A - R0008 - Entry Vestibule**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00B - Library/General Learning - 1915 - Timber (Timber)**

**Exterior**

|                 |                   |
|-----------------|-------------------|
| Ceiling Void    | No Asbestos Found |
| Underfloor Void | No Asbestos Found |

**Interior**

**B00B - R0001 - Movement**

|                            |   |  |  |  |  |  |  |                             |
|----------------------------|---|--|--|--|--|--|--|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                              |  |  |  |  |  |  |                             |
|                            | 3364/B00B/R0001/Ceiling Structures/Linings/S5 |  |  |  |  |  |  | <b>No Asbestos Detected</b> |

**B00B - R0002 - Reading Area**

|                       |  |     |               |                    |         |   |
|-----------------------|--|-----|---------------|--------------------|---------|---|
| Wall Linings Internal | Flat AC Sheeting                         | 2m2 | Behind heater | Good Condition (1) | Low (1) | Low Priority (2-3)  |
|                       | 3364/B00B/R0002/Wall Linings Internal/S8 |     |               |                    |         | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |

**B00B - R0003 - General Storeroom**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00C - Staff Facilities - 1991 - Timber (Timber)**

**Exterior**

|                                   |  |  |  |  |  |                             |
|-----------------------------------|--|--|--|--|--|-----------------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found                              |  |  |  |  |                             |
| Wall Cladding                     | Flat AC Sheeting<br>3364/B00C/Wall Cladding/S1 |  |  |  |  | <b>No Asbestos Detected</b> |
| Eaves Linings                     | Flat AC Sheeting<br>3364/B00C/Eaves Linings/S2 |  |  |  |  | <b>No Asbestos Detected</b> |
| Ceiling Voids                     | No Asbestos Found                              |  |  |  |  |                             |

**Interior**

**B00C - R0003 - Staff Room**

No Asbestos

**B00C - R0004 - Staff Kitchen**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00D - Pupil Facilities - 1935 - Brick/Block (Brick/Block)**

**Exterior**

|                                   |                   |
|-----------------------------------|-------------------|
| Ceiling Voids - Flat Roof         | No Asbestos Found |
| Underfloor Voids - Slab on Ground | No Asbestos Found |

**Interior**

**B00D - R0002 - Toilets - Girls**

No Asbestos

**B00D - R0003 - Toilets - Boys**

No Asbestos

**B00D - R0004 - Staff Toilet**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00E - General Learning - 1995 - Timber (Timber)**

**Exterior**

|                             |   |      |       |                    |         |   |
|-----------------------------|---|------|-------|--------------------|---------|---|
| Ceiling Voids               | No Asbestos Found                                 |      |       |                    |         |   |
| Underfloor Voids            | Flat AC Sheeting<br>3364/B00E/Underfloor Voids/S3 |      |       |                    |         | <b>No Asbestos Detected</b>                                   |
| Infill panels under windows | Flat AC Sheeting                                  | 20m2 | North | Good Condition (1) | Low (1) | Low Priority (2-3)  |
|                             | 3364/B00E/Infill panels under windows/S7          |      |       |                    |         | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |

**Interior**

**B00E - R0001 - Practical Activities - 1hb**

No Asbestos

**B00E - R0002 - Practical Activities - 1hb**

No Asbestos

**B00E - R0003 - Home Base**

No Asbestos

**B00E - R0004 - Personal Effects Storage**

|                            |   |  |  |  |  |                             |
|----------------------------|---|--|--|--|--|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>3364/B00E/R0004/Ceiling Structures/Linings/S6 |  |  |  |  | <b>No Asbestos Detected</b> |
|----------------------------|---|--|--|--|--|-----------------------------|

**B00E - R0005 - External Movement**

|                            |   |  |  |  |  |                             |
|----------------------------|---|--|--|--|--|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>3364/B00E/R0004/Ceiling Structures/Linings/S6 |  |  |  |  | <b>No Asbestos Detected</b> |
|----------------------------|---|--|--|--|--|-----------------------------|

**B00E - R0006 - External Movement**

|                            |   |  |  |  |  |                             |
|----------------------------|---|--|--|--|--|-----------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting<br>3364/B00E/R0004/Ceiling Structures/Linings/S6 |  |  |  |  | <b>No Asbestos Detected</b> |
|----------------------------|---|--|--|--|--|-----------------------------|

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00F - Building Services - 2008 - Steel (Steel)**

**Exterior**

|                                   |                   |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids                     | No Asbestos Found |

**Interior**

**B00F - R0001 - General Storeroom**

No Asbestos

**B00F - R0002 - General Assistant/Bulk Store**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00G - Pupil Facilities - 2008 - Metal Shed (Metal Shed)**

**Exterior**

|                                   |                   |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids                     | No Asbestos Found |

**Interior**

**B00G - R0001 - Sports Store**

No Asbestos

2017



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B00H - Building Services - 2008 - Metal Shed (Metal Shed)**

**Exterior**

|                                   |                   |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids                     | No Asbestos Found |

**Interior**

**B00H - R0001 - Garden Store**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 837 - D12058 - Hcap Shower/Change/Toilet : Placement Date - 22/01/2010**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Disabled Shower/Toilet**

No Asbestos Found.

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017