


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Weston Public School (3431)
Region : Hunter/Central Coast
State Electorate : Cessnock
Local Government Area : Cessnock

Initial Survey : Noel Arnold & Associates : 16 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00A - Administration/General Learning - 1929 - Brick/Block (Brick/Block)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | Requires Inspection |
| Underfloor Voids | Requires Inspection |

Interior

B00A - R0001 - Staff Room Annexe

No Asbestos

B00A - R0002 - Movement

| | | | |
|----------------------------|------------------|---|----------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 3431/B00A/R0029/Ceiling Structures/Linings/S1 | No Asbestos Detected |
|----------------------------|------------------|---|----------------------|

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Withdrawal Space - 1hb

No Asbestos

B00A - R0005 - Home Base Store

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - Cleaning Supplies

No Asbestos

B00A - R0008 - Practical Activities - 1hb

No Asbestos

B00A - R0009 - Home Base Store

No Asbestos

B00A - R0010 - Home Base

No Asbestos

B00A - R0011 - Withdrawal Space - 1hb

No Asbestos

B00A - R0012 - Staff Room Annexe

No Asbestos

B00A - R0013 - Staff Room

No Asbestos

B00A - R0014 - Movement

No Asbestos

B00A - R0015 - Movement

| | | | |
|----------------------------|------------------|---|----------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 3431/B00A/R0029/Ceiling Structures/Linings/S1 | No Asbestos Detected |
|----------------------------|------------------|---|----------------------|

B00A - R0016 - Staff Toilet

| | | | |
|-----------------------|------------------|--|----------------------|
| Wall Linings Internal | Flat AC Sheeting | 3431/B00A/R0016/Wall Linings Internal/S2 | No Asbestos Detected |
|-----------------------|------------------|--|----------------------|

B00A - R0017 - Staff Toilet

| | | | |
|-----------------------|------------------|--|----------------------|
| Wall Linings Internal | Flat AC Sheeting | 3431/B00A/R0016/Wall Linings Internal/S2 | No Asbestos Detected |
|-----------------------|------------------|--|----------------------|

B00A - R0018 - Deputy Principal

No Asbestos

B00A - R0019 - Interview

No Asbestos

B00A - R0020 - Security Store

No Asbestos

B00A - R0021 - Principal

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|--|----------------------|--------|---|--------------------|-------------|-----------------------------|
| Sample No | | | | | Test Result | |
| B00A - R0022 - Sick Bay | | | | | | |
| No Asbestos | | | | | | |
| B00A - R0023 - Toilets - Boys/Girls | | | | | | |
| No Asbestos | | | | | | |
| B00A - R0024 - Shower/Change | | | | | | |
| No Asbestos | | | | | | |
| B00A - R0025 - Clerical Office | | | | | | |
| No Asbestos | | | | | | |
| B00A - R0026 - Duplicating Workroom | | | | | | |
| No Asbestos | | | | | | |
| B00A - R0027 - Entry Vestibule | | | | | | |
| No Asbestos | | | | | | |
| B00A - R0028 - Movement | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | | 3431/B00A/R0029/Ceiling Structures/Linings/S1 | | | No Asbestos Detected |
| B00A - R0029 - Movement | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | | 3431/B00A/R0029/Ceiling Structures/Linings/S1 | | | No Asbestos Detected |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00B - Pupil Facilities - 1995 - Brick/Block (Brick/Block)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00B - R0001 - Movement

| | | | | | | |
|---|------------------|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R0002 - Toilets - Boys

| | | | | | | |
|---|------------------|------|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 23m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

| | | | | | | |
|----------------------------|---------------------|---|--|--|--|-----------------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet | 3431/B00B/R0012/Partition Walls (Cubicles)/S5 | | | | No Asbestos Detected |
|----------------------------|---------------------|---|--|--|--|-----------------------------|

B00B - R0003 - Movement

| | | | | | | |
|---|------------------|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R0004 - Toilets - Girls

| | | | | | | |
|---|------------------|------|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 21m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

| | | | | | | |
|----------------------------|---------------------|---|--|--|--|-----------------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet | 3431/B00B/R0012/Partition Walls (Cubicles)/S5 | | | | No Asbestos Detected |
|----------------------------|---------------------|---|--|--|--|-----------------------------|

B00B - R0005 - No Access

| | | | | | | |
|---|------------------|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 2m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R0006 - Movement

| | | | | | | |
|---|------------------|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R0007 - Toilets - Girls

| | | | | | | |
|---|------------------|------|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 21m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

| | | | | | | |
|----------------------------|---------------------|---|--|--|--|-----------------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet | 3431/B00B/R0012/Partition Walls (Cubicles)/S5 | | | | No Asbestos Detected |
|----------------------------|---------------------|---|--|--|--|-----------------------------|

B00B - R0008 - Toilets - Girls

| | | | | | | |
|---|------------------|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 2m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R0009 - Movement

| | | | | | | |
|---|------------------|-----|------------|---|---------|--------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | 3m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |

B00B - R0010 - Cleaning Distributed Store

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---|----------------------|--------|--------------------|---|-------------|--------------------|
| Sample No | | | | Test Result | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 12m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| B00B - R0011 - Movement | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 6m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| B00B - R0012 - Toilets - Boys | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | 23m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00B/R0012/Ceiling Structures/Linings/S4 | | | | Chrysotile (white asbestos) , Amosite (brown asbestos) | | |
| Partition Walls (Cubicles) | Compressed AC Sheet | | | | | |
| 3431/B00B/R0012/Partition Walls (Cubicles)/S5 | | | | No Asbestos Detected | | |

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00D - Administration/Building Services - 1916 - Timber (Timber)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | Requires Inspection |
| Underfloor Voids | Requires Inspection |

Interior

B00D - R0001 - General Assistant/Bulk Store

Non Accessible

B00D - R0002 - Garden Store

Non Accessible

B00D - R0003 - Garden Store

Non Accessible

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00E - General Learning/Communal Facilities - 1916 - Brick/Block (Brick/Block)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | Requires Inspection |
| Underfloor Voids | Requires Inspection |

Interior

B00E - R0001 - Hall Chair Store

No Asbestos

B00E - R0002 - Movement

| | | | | | | |
|----------------------------|---|-----|--------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting | | | | | No Asbestos Detected |
| | 3431/B00A/R0029/Ceiling Structures/Linings/S1 | | | | | |
| Wall Linings Internal | Flat AC Sheeting | 8m2 | North, South | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3431/B00E/R0002/Wall Linings Internal/S3 | | | | | Chrysotile (white asbestos) |

B00E - R0003 - Movement

No Asbestos

B00E - R0004 - Withdrawal Space - 1hb

No Asbestos

B00E - R0005 - Practical Activities - 1hb

| | | | | | | |
|-----------------------|--|------|-------|--------------------|---------|------------------------------------|
| Wall Linings Internal | Flat AC Sheeting | 50m2 | North | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3431/B00E/R0002/Wall Linings Internal/S3 | | | | | Chrysotile (white asbestos) |

B00E - R0006 - Movement

No Asbestos

B00E - R0007 - Home Base

No Asbestos

B00E - R0008 - Home Base

No Asbestos

B00E - R0010 - Staff Room Annexe

No Asbestos

B00E - R0011 - Practical Activities - 1hb

| | | | | | | |
|-----------------------|--|------|-------|--------------------|---------|------------------------------------|
| Wall Linings Internal | Flat AC Sheeting | 50m2 | North | Good Condition (1) | Low (1) | Low Priority (2-3) |
| | 3431/B00E/R0002/Wall Linings Internal/S3 | | | | | Chrysotile (white asbestos) |

B00E - R0012 - Home Base

No Asbestos

B00E - R0013 - Personal Effects Storage

No Asbestos

B00E - R0014 - Cleaning Distributed Store

No Asbestos

B00E - R0015 - Movement

No Asbestos

B00E - R0016 - General Storeroom

No Asbestos

B00E - R0017 - Home Base

No Asbestos

B00E - R0018 - Practical Activities - 1hb

No Asbestos

B00E - R0019 - Home Base

No Asbestos

B00E - R0020 - Practical Activities - 1hb

No Asbestos

B00E - R0021 - Practical Activities - 1hb

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|--|----------------------|--------|----------------------|--------------------|-----------------------------|----------------------|
| Sample No | | | | | Test Result | |
| Wall Linings Internal | Flat AC Sheeting | 20m2 | North, Lower portion | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00E/R0002/Wall Linings Internal/S3 | | | | | Chrysotile (white asbestos) | |
| B00E - R0022 - Movement | | | | | | |
| Ceiling Structures/Linings | Flat AC Sheeting | | | | | No Asbestos Detected |
| 3431/B00A/R0029/Ceiling Structures/Linings/S1 | | | | | | |
| Wall Linings Internal | Flat AC Sheeting | 10m2 | Throughout | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00E/R0002/Wall Linings Internal/S3 | | | | | Chrysotile (white asbestos) | |
| B00E - R0023 - Movement | | | | | | |
| No Asbestos | | | | | | |
| B00E - R0025 - General Storeroom | | | | | | |
| No Asbestos | | | | | | |
| B00E - R0026 - Disabled Toilet | | | | | | |
| No Asbestos | | | | | | |
| B00E - R0027 - Stairs | | | | | | |
| No Asbestos | | | | | | |
| B00E - R0028 - Stairs | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1001 - Movement | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1002 - General Storeroom | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1005 - Home Base | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1006 - Movement | | | | | | |
| Wall Linings Internal | Flat AC Sheeting | 80m2 | North, Lower portion | Good Condition (1) | Low (1) | Low Priority (2-3) |
| 3431/B00E/R0002/Wall Linings Internal/S3 | | | | | Chrysotile (white asbestos) | |
| B00E - R1007 - Craft Store | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1008 - Home Base | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1009 - Withdrawal Space - 1hb | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1010 - Home Base | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1011 - Movement | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1012 - Practical Activities - 1hb | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1013 - Home Base | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1014 - Practical Activities - 1hb | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1015 - Home Base | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1016 - Stairs | | | | | | |
| No Asbestos | | | | | | |
| B00E - R1017 - Stairs | | | | | | |
| No Asbestos | | | | | | |

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|---------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| | Sample No | | | | | Test Result |

B00F - Communal Facilities - 1997 - Brick/Veneer (Brick/Veneer)**Exterior**

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior**B00F - R0001 - Communal Space**

No Asbestos

B00F - R0002 - Raised Platform

No Asbestos

B00F - R0003 - Movement

No Asbestos

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - Shower/Change

No Asbestos

B00F - R0006 - Toilets - Boys

No Asbestos

B00F - R0007 - Hall Chair Store

No Asbestos

B00F - R0008 - P.E. Store

No Asbestos

B00F - R0009 - Toilets - Girls

No Asbestos

B00F - R0010 - Disabled Toilet

No Asbestos

B00F - R0011 - Plant

No Asbestos

B00F - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0013 - Movement

No Asbestos

B00F - R0014 - Canteen

No Asbestos

B00F - R0015 - Canteen Office/Store

No Asbestos

B00F - R0016 - Cleaning Distributed Store

No Asbestos

B00F - R0017 - Hall Chair Store

No Asbestos

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00G - Library/Pupil Facilities - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00G - R0001 - Reading Area

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00G - R0002 - Library Office/Workroom

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00G - R0003 - Communications Room

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00G - R0004 - K.L.A. Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00G - R0005 - Plant

No Asbestos

B00G - R0006 - Security Store

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00G - R0007 - Cleaning Distributed Store

No Asbestos

B00G - R0008 - Staff Toilet

No Asbestos

B00G - R0009 - Special Programs Room

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

B00G - R0010 - External Movement

No Asbestos

B00G - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0012 - Special Programs Room

| | |
|---|-------------------|
| Vinyl Tiles (Under Floor Covering/Carpet) | No Asbestos Found |
|---|-------------------|

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

B00H - Shed - 2002 - Metal Shed (Metal Shed)

Exterior

| | |
|------------------|---------------------|
| Ceiling Voids | No Asbestos Found |
| Underfloor Voids | Requires Inspection |

Interior

B00H - R0001 - Garden Store

No Asbestos

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

| Product | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No | | | | | Test Result | |

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017