


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wollongbar Public School (3475)
Region : North Coast
State Electorate : Ballina
Local Government Area : Ballina

Initial Survey : Noel Arnold & Associates : 11 - Jun - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1995 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Movement**

No Asbestos

B00A - R0002 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0005 - Cleaning Distributed Store

No Asbestos

B00A - R0009 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0010 - Security Store

No Asbestos

B00A - R0011 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0012 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0013 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0015 - Sick Bay

No Asbestos

B00A - R0016 - Duplicating Workroom

No Asbestos

B00A - R0019 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00A - R0020 - Entry Vestibule

No Asbestos

B00A - R0021 - Staff Shower/Change

No Asbestos

B00A - R0022 - Staff Toilet

No Asbestos

B00A - R0023 - Toilet - Lobby

No Asbestos

B00A - R0024 - Toilet - Lobby

No Asbestos

B00A - R0025 - Staff Toilet

No Asbestos

B00A - R0026 - Toilet - Lobby

No Asbestos

B00A - R0027 - Staff Toilet

No Asbestos

B00A - R0028 - Toilet - Lobby

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00A - R0029 - Staff Toilet

No Asbestos

B00A - R0030 - Clerical Office/Workroom

No Asbestos

B00A - R0031 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Library - 1995 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Movement**

No Asbestos

B00B - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0003 - Practical Activities - 1hb

No Asbestos

B00B - R0004 - Personal Effects Storage

No Asbestos

B00B - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - Personal Effects Storage

No Asbestos

B00B - R0009 - Practical Activities - 1hb

No Asbestos

B00B - R0010 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0012 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0013 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0014 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0015 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0016 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0017 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0018 - Toilets - Girls

No Asbestos

B00B - R0019 - No Access

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R0020 - Disabled Toilet

No Asbestos

B00B - R0021 - Toilets - Boys

No Asbestos

B00B - R0022 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0023 - Cleaning Distributed Store

No Asbestos

B00B - R0024 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0003 - Practical Activities - 1hb

No Asbestos

B00C - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Personal Effects Storage

No Asbestos

B00C - R0006 - Movement

No Asbestos

B00C - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0009 - Personal Effects Storage

No Asbestos

B00C - R0010 - Practical Activities - 1hb

No Asbestos

B00C - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0012 - Movement

No Asbestos

B00C - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0004 - Personal Effects Storage

No Asbestos

B00D - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0007 - Personal Effects Storage

No Asbestos

B00D - R0008 - Practical Activities - 1hb

No Asbestos

B00D - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0010 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0011 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Canteen

No Asbestos

B00E - R0002 - Canteen Office/Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - Communal Facilities - 1995 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00F - R0001 - Sports Store**

No Asbestos

B00F - R0002 - Disabled Toilet

No Asbestos

B00F - R0003 - Cleaning Distributed Store

No Asbestos

B00F - R0004 - Toilets - Boys

No Asbestos

B00F - R0006 - Hall Chair Store

No Asbestos

B00F - R0007 - P.E. Store

No Asbestos

B00F - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0009 - Plant

No Asbestos

B00F - R0010 - Plant

No Asbestos

B00F - R0011 - Communal Space

No Asbestos

B00F - R0012 - Raised Platform

No Asbestos

B00F - R0013 - General Assistant/Bulk Store

No Asbestos

B00F - R0014 - Garden Store

No Asbestos

B00F - R0015 - Cleaning Supplies

No Asbestos

B00F - R0016 - Cleaning Supplies

No Asbestos

B00F - R0017 - Toilets - Girls

No Asbestos

B00F - R0018 - Movement

No Asbestos

B00F - R0019 - Movement

No Asbestos

B00F - R0020 - General Assistant/Bulk Store

No Asbestos

B00F - R0021 - Movement

No Asbestos

B00F - R0022 - Toilet - Lobby

No Asbestos

B00F - R0023 - Shower/Change

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Pupil Facilities - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00G - R0002 - Movement

No Asbestos

B00G - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0004 - Practical Activities - 1hb

No Asbestos

B00G - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0006 - Personal Effects Storage

No Asbestos

B00G - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0009 - Personal Effects Storage

No Asbestos

B00G - R0010 - Practical Activities - 1hb

No Asbestos

B00G - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0013 - Practical Activities - 1hb

No Asbestos

B00G - R0014 - Personal Effects Storage

No Asbestos

B00G - R0015 - Movement

No Asbestos

B00G - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0017 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0019 - Personal Effects Storage

No Asbestos

B00G - R0020 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00G - R0021 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0022 - Toilets - Girls

No Asbestos

B00G - R0023 - Kiln Room

No Asbestos

B00G - R0024 - Toilets - Boys

No Asbestos

B00G - R0025 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1900 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	50m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	Assumed Asbestos					
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00H - R0001 - Movement

No Asbestos

B00H - R0002 - Movement

No Asbestos

B00H - R0003 - Withdrawal Space - 1hb

No Asbestos

B00H - R0004 - Special Programs Room

No Asbestos

B00H - R0005 - Practical Activities - 1hb

No Asbestos

B00H - R0006 - Uniform Shop

No Asbestos

B00H - R0007 - Home Base

No Asbestos

B00H - R0008 - Practical Activities - 1hb

No Asbestos

B00H - R0009 - Home Base Store

No Asbestos

B00H - R0010 - Withdrawal Space - 1hb

Ceiling Structures/Linings	Flat AC Sheeting	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

3475/B00H/R0010/Ceiling Structures/Linings/S2

Chrysotile (white asbestos)

B00H - R0011 - General Storeroom

Floor Coverings
Res/Textile

Vinyl Tiles

3475/B00H/R0011/Floor Coverings Res/Textile/S1

No Asbestos Detected

B00H - R0012 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

3475/B00H/R0012/Ceiling Structures/Linings/S3

Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Communal Facilities - 1988 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B001 - R0001 - Garden Store

No Asbestos

B001 - R0002 - P.E. Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Building Services - 1989 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11775 - Learning Unit - Standard With P.A.A. : Placement Date - 14/01/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

- D13823 - : Placement Date - 15/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017