


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Warrimoo Public School (4195)
Region : Western Sydney
State Electorate : Blue Mountains
Local Government Area : Blue Mountains

Initial Survey : Noel Arnold & Associates : 26 - Mar - 2008
Reviewed By : Parsons Brinckerhoff : 07 - Feb - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1961 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting	15m	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4195/B00A/Gable Verge Lining/S3			Chrysotile (white asbestos) , Amosite (brown asbestos)		
Eaves Linings	Flat AC Sheeting	50m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4195/B00A/Eaves Linings/S2			Chrysotile (white asbestos)		
Ceiling Lining	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00A - R0001 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	3m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4195/B00A/R0001/Ceiling Structures/Linings/S4			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0018 - Disabled Toilet

No Asbestos

B00A - R0019 - Sick Bay

No Asbestos

B00A - R0020 - Clerical Office

No Asbestos

B00A - R0021 - Movement

No Asbestos

B00A - R0022 - Entry Vestibule

No Asbestos

B00A - R0023 - Duplicating Workroom

No Asbestos

B00A - R0024 - Staff Toilet

No Asbestos

B00A - R0025 - Staff Toilet

No Asbestos

B00A - R0026 - Staff Toilet

No Asbestos

B00A - R0027 - Deputy Principal

No Asbestos

B00A - R0028 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0029 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	2m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4195/B00A/R0001/Ceiling Structures/Linings/S4			Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0030 - Staff Kitchen

No Asbestos

B00A - R0031 - Staff Room

No Asbestos

B00A - R0032 - Staff Room Annexe

No Asbestos

B00A - R0033 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
4195/B00A/R0001/Ceiling Structures/Linings/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00A - R0034 - Security Store

No Asbestos

B00A - R0035 - Interview

No Asbestos

B00A - R0036 - Principal

No Asbestos

B00A - R0037 - Cleaning Supplies

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1961 - Brick/Block (Brick/Block)

Exterior

Gable Verge Lining	Flat AC Sheeting 4195/B00B/Gable Verge Lining/S6	15m	East facing, West facing	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)
Eaves Linings	Flat AC Sheeting 4195/B00B/Eaves Linings/S5	30m2	North facing, South facing	Good Condition (1) Chrysotile (white asbestos) , Amosite (brown asbestos)	Low (1)	Low Priority (2-3)
Ceiling Lining	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0004 - Movement

No Asbestos

B00B - R0005 - External Movement

No Asbestos

B00B - R0014 - External Movement

No Asbestos

B00B - R0021 - Practical Activities - 1hb

No Asbestos

B00B - R0022 - Home Base

No Asbestos

B00B - R0023 - Home Base Store

No Asbestos

B00B - R0024 - Personal Effects Storage

No Asbestos

B00B - R0025 - Withdrawal Space - 1hb

No Asbestos

B00B - R0026 - Home Base Store

No Asbestos

B00B - R0027 - Home Base

No Asbestos

B00B - R0028 - Practical Activities - 1hb

No Asbestos

B00B - R0029 - Practical Activities - 1hb

No Asbestos

B00B - R0030 - Home Base

No Asbestos

B00B - R0031 - Withdrawal Space - 1hb

No Asbestos

B00B - R0032 - Home Base Store

No Asbestos

B00B - R9005 - No Access

No Asbestos

B00B - R9006 - Kiln Room

No Asbestos

B00B - R9007 - Withdrawal Space - 1hb

No Asbestos

B00B - R9008 - General Storeroom

No Asbestos

B00B - R9009 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R9010 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library - 1962 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Lining	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00D - R0003 - Communications Room

No Asbestos

B00D - R0004 - Library Office/Workroom

No Asbestos

B00D - R0005 - Staff Toilet

No Asbestos

B00D - R0006 - Communications Room

No Asbestos

B00D - R0007 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	2m2	North facing, East facing, Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4195/B00D/R0007/Wall Linings Internal/S1				Chrysotile (white asbestos)	
Ceiling Structures/Linings	Flat AC Sheeting	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4195/B00D/R0007/Wall Linings Internal/S1				Chrysotile (white asbestos)	

B00D - R0008 - Special Programs Room

No Asbestos

B00D - R0009 - Practical Activities - 1hb

No Asbestos

B00D - R0010 - Home Base Store

No Asbestos

B00D - R0011 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Library - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00E - R0001 - Reading Area

No Asbestos

B00E - R0002 - Library Office/Workroom

No Asbestos

B00E - R0003 - Communications Room

No Asbestos

B00E - R0004 - K.L.A. Store

No Asbestos

B00E - R0005 - Staff Toilet

No Asbestos

B00E - R0006 - Toilet - Lobby

No Asbestos

B00E - R0007 - Cleaning Distributed Store

No Asbestos

B00E - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0009 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B0A1 - Communal Facilities/Pupil Facilities - 1998 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B0A1 - R0001 - Raised Platform

No Asbestos

B0A1 - R0002 - Lift

No Asbestos

B0A1 - R0003 - Communal Space

No Asbestos

B0A1 - R0004 - Canteen

No Asbestos

B0A1 - R0005 - Disabled Toilet

No Asbestos

B0A1 - R0006 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0A1 - R0007 - Toilets - Girls

No Asbestos

B0A1 - R0008 - Toilets - Boys

No Asbestos

B0A1 - R0009 - Cleaning Distributed Store

No Asbestos

B0A1 - R0010 - Plant

No Asbestos

B0A1 - R0011 - P.E. Store

No Asbestos

B0A1 - R0012 - Hall Chair Store

No Asbestos

B0A1 - R0013 - General Assistant/Bulk Store

No Asbestos

B0A1 - R0014 - External Movement

No Asbestos

B0A1 - R0015 - External Movement

No Asbestos

B0A1 - R0016 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0B1 - General Learning/Pupil Facilities - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	

Interior

B0B1 - R0001 - Home Base Store

No Asbestos

B0B1 - R0002 - Practical Activities - 1hb

No Asbestos

B0B1 - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0B1 - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0B1 - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0B1 - R0006 - Practical Activities - 1hb

No Asbestos

B0B1 - R0007 - Home Base Store

No Asbestos

B0B1 - R0008 - Cleaning Distributed Store

No Asbestos

B0B1 - R0009 - Distribution Board

Note: No inspection of live electrical installation.

New board No Asbestos Found

B0B1 - R0010 - Toilets - Boys

No Asbestos

B0B1 - R0011 - Toilets - Girls

No Asbestos

B0B1 - R0012 - External Movement

No Asbestos

B0B1 - R0013 - Personal Effects Storage

No Asbestos

B0B1 - R0014 - Personal Effects Storage

No Asbestos

B0B1 - R9001 - General Storeroom

Ceiling Structures/Linings Flat AC Sheeting 4195/B0B1/R9001/Ceiling Structures/Linings/S7 **No Asbestos Detected**

B0B1 - R9002 - Sports Store

Ceiling Structures/Linings Flat AC Sheeting 4195/B0B1/R9001/Ceiling Structures/Linings/S7 **No Asbestos Detected**

B0B1 - R9003 - General Storeroom

Ceiling Structures/Linings Flat AC Sheeting 4195/B0B1/R9001/Ceiling Structures/Linings/S7 **No Asbestos Detected**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0C1 - General Learning - 1998 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids No Asbestos Found

Interior

B0C1 - R0001 - Practical Activities - 1hb

No Asbestos

B0C1 - R0002 - Home Base Store

No Asbestos

B0C1 - R0003 - Home Base

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B0C1 - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B0C1 - R0005 - Home Base

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B0C1 - R0006 - Practical Activities - 1hb

Vinyl Tiles (Under Floor No Asbestos Found
Covering/Carpet)

B0C1 - R0007 - Home Base Store

No Asbestos

B0C1 - R0008 - Personal Effects Storage

No Asbestos

B0C1 - R0009 - Personal Effects Storage

No Asbestos

B0C1 - R0010 - External Movement

No Asbestos

B0C1 - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D11269 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 20/02/2008

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017