


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Werrington County Public School (4541)
Region : Western Sydney
State Electorate : Londonderry
Local Government Area : Penrith

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Communal Facilities/Building Services - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00A - R0001 - Toilets - Girls

No Asbestos

B00A - R0002 - Sports Store

No Asbestos

B00A - R0003 - Cleaning Supplies

No Asbestos

B00A - R0004 - Main Switch Board

No Asbestos

B00A - R0005 - Hall Chair Store

No Asbestos

B00A - R0006 - Communal Space

No Asbestos

B00A - R0007 - Raised Platform

No Asbestos

B00A - R0008 - Movement

No Asbestos

B00A - R0009 - Plant

No Asbestos

B00A - R0010 - P.E. Store

No Asbestos

B00A - R0011 - Cleaning Distributed Store

No Asbestos

B00A - R0012 - General Assistant/Bulk Store

No Asbestos

B00A - R0013 - Toilets - Boys

No Asbestos

B00A - R0014 - External Movement

No Asbestos

B00A - R0015 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Staff Facilities - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00B - R0001 - Cleaning Supplies

No Asbestos

B00B - R0002 - Duplicating Workroom

No Asbestos

B00B - R0003 - Entry Vestibule

No Asbestos

B00B - R0004 - Movement

No Asbestos

B00B - R0005 - Deputy Principal

No Asbestos

B00B - R0006 - Interview

No Asbestos

B00B - R0007 - Clerical Office/Workroom

No Asbestos

B00B - R0008 - Security Store

No Asbestos

B00B - R0009 - Staff Room Annexe

No Asbestos

B00B - R0010 - Staff Room

No Asbestos

B00B - R0011 - Staff Toilet

No Asbestos

B00B - R0012 - Community Clinic

No Asbestos

B00B - R0013 - Community Clinic

No Asbestos

B00B - R0014 - Staff Toilet

No Asbestos

B00B - R0015 - Staff Toilet

No Asbestos

B00B - R0016 - Cleaning Distributed Store

No Asbestos

B00B - R0017 - Security Store

No Asbestos

B00B - R0018 - Principal

No Asbestos

B00B - R0019 - Sick Bay

No Asbestos

B00B - R0020 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00B - R0021 - Clerical Office

No Asbestos

B00B - R0022 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0023 - Movement						
No Asbestos						
B00B - R0024 - External Movement						
No Asbestos						
B00B - R0025 - External Movement						
No Asbestos						
B00B - R0026 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Withdrawal Space - 1hb

No Asbestos

B00C - R0003 - Home Base Store

No Asbestos

B00C - R0004 - Home Base

No Asbestos

B00C - R0005 - External Movement

No Asbestos

B00C - R0006 - Practical Activities - 1hb

No Asbestos

B00C - R0007 - Toilets - Boys

No Asbestos

B00C - R0008 - Home Base Store

No Asbestos

B00C - R0009 - Home Base

No Asbestos

B00C - R0010 - General Storeroom

No Asbestos

B00C - R0011 - Kiln Room

No Asbestos

B00C - R0012 - Withdrawal Space - 1hb

No Asbestos

B00C - R0013 - Home Base Store

No Asbestos

B00C - R0014 - Home Base

No Asbestos

B00C - R0015 - External Movement

No Asbestos

B00C - R0016 - External Movement

No Asbestos

B00C - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0018 - Home Base

No Asbestos

B00C - R0019 - Home Base Store

No Asbestos

B00C - R0020 - Withdrawal Space - 1hb

No Asbestos

B00C - R0021 - Home Base

No Asbestos

B00C - R0022 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0023 - Home Base Store						
No Asbestos						
B00C - R0024 - Practical Activities - 1hb						
No Asbestos						
B00C - R0025 - General Storeroom						
No Asbestos						
B00C - R0026 - Security Store						
No Asbestos						
B00C - R0027 - Toilets - Girls						
No Asbestos						
B00C - R0028 - External Movement						
No Asbestos						
B00C - R0029 - External Movement						
No Asbestos						
B00C - R0030 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library/Tiered Learning - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00D - M0001 - Plant

No Asbestos

B00D - R0001 - Special Programs Room

No Asbestos

B00D - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0003 - Special Programs Store

No Asbestos

B00D - R0004 - Cleaning Distributed Store

No Asbestos

B00D - R0006 - Library Office/Workroom

No Asbestos

B00D - R0007 - Communications Room

No Asbestos

B00D - R0008 - External Movement

No Asbestos

B00D - R0009 - Special Programs Room

No Asbestos

B00D - R0010 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning/Pupil Facilities - 1988 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00E - R0001 - External Movement**

No Asbestos

B00E - R0002 - Home Base

No Asbestos

B00E - R0003 - Home Base Store

No Asbestos

B00E - R0004 - General Storeroom

No Asbestos

B00E - R0005 - Toilets - Boys

No Asbestos

B00E - R0006 - Practical Activities - 1hb

No Asbestos

B00E - R0007 - Craft Store

No Asbestos

B00E - R0008 - Withdrawal Space - 1hb

No Asbestos

B00E - R0009 - Home Base

No Asbestos

B00E - R0010 - Home Base Store

No Asbestos

B00E - R0011 - External Movement

No Asbestos

B00E - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0013 - Home Base

No Asbestos

B00E - R0014 - Home Base Store

No Asbestos

B00E - R0015 - Withdrawal Space - 1hb

No Asbestos

B00E - R0016 - External Movement

No Asbestos

B00E - R0017 - Home Base

No Asbestos

B00E - R0018 - Home Base Store

No Asbestos

B00E - R0019 - Practical Activities - 1hb

No Asbestos

B00E - R0020 - General Storeroom

No Asbestos

B00E - R0021 - Toilets - Girls

No Asbestos

B00E - R0022 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0023 - Home Base						
No Asbestos						
B00E - R0024 - Home Base Store						
No Asbestos						
B00E - R0025 - Withdrawal Space - 1hb						
No Asbestos						
B00E - R0026 - External Movement						
No Asbestos						
B00E - R0027 - External Movement						
No Asbestos						
B00E - R0028 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1988 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - External Movement

No Asbestos

B00F - R0002 - Canteen

No Asbestos

B00F - R0003 - Canteen Office/Store

No Asbestos

B00F - R0004 - Canteen Office/Store

No Asbestos

B00F - R0005 - Disabled Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Library - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0003 - Toilet - Lobby

No Asbestos

B00G - R0004 - Cleaning Distributed Store

No Asbestos

B00G - R0005 - Staff Toilet

No Asbestos

B00G - R0006 - K.L.A. Store

No Asbestos

B00G - R0007 - Communications Room

No Asbestos

B00G - R0008 - Library Office/Workroom

No Asbestos

B00G - R0009 - Reading Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00H - R0001 - External Movement

No Asbestos

B00H - R0002 - Practical Activities - 1hb

No Asbestos

B00H - R0003 - Home Base Store

No Asbestos

B00H - R0004 - Home Base

No Asbestos

B00H - R0005 - Withdrawal Space - 2hb

No Asbestos

B00H - R0006 - Home Base

No Asbestos

B00H - R0007 - Home Base Store

No Asbestos

B00H - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D10553 - Learning Unit - Standard With P.A.A. : Placement Date - 11/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11634 - Learning Unit - Standard With P.A.A. : Placement Date - 22/05/2015

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 621 - D12375 - Single Learning Unit - H/Cap : Placement Date - 9/12/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Home Base-I.O.

No Asbestos Found.

R2 - Toilets-Disabled

No Asbestos Found.

R3 - Laundry

No Asbestos Found.

OS 603 - D14118 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 8/12/2009

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store


No Asbestos Found.

OS 603 - D14916 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 5/03/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 602 - D16065 - Learning Unit - Standard With P.A.A. : Placement Date - 15/03/2013						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017