


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wirreanda Public School (4564)
Region : Hunter/Central Coast
State Electorate : Port Stephens
Local Government Area : Port Stephens

Initial Survey : Noel Arnold & Associates : 29 - Apr - 2008
Reviewed By : AECOM : 27 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Pupil Facilities - 1985 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible, no access points
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points.

Interior**B00A - R0001 - External Movement**

No Asbestos

B00A - R0002 - Toilets - Girls

No Asbestos

B00A - R0003 - Home Base

No Asbestos

B00A - R0004 - Home Base Store

No Asbestos

B00A - R0005 - General Storeroom

No Asbestos

B00A - R0006 - Craft Store

No Asbestos

B00A - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0008 - External Movement

No Asbestos

B00A - R0009 - Practical Activities - 1hb

No Asbestos

B00A - R0010 - External Movement

No Asbestos

B00A - R0011 - Craft Store

No Asbestos

B00A - R0012 - General Storeroom

No Asbestos

B00A - R0013 - Home Base Store

No Asbestos

B00A - R0014 - Home Base

No Asbestos

B00A - R0015 - External Movement

No Asbestos

B00A - R0016 - Withdrawal Space - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Communal Facilities/Pupil Facilities - 1985 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points.

Interior

B00B - R0001 - External Movement

No Asbestos

B00B - R0002 - Canteen Office/Store

No Asbestos

B00B - R0003 - Canteen

No Asbestos

B00B - R0004 - Canteen Office/Store

No Asbestos

B00B - R0005 - Cleaning Distributed Store

No Asbestos

B00B - R0006 - External Movement

No Asbestos

B00B - R0007 - Movement

No Asbestos

B00B - R0008 - Disabled Toilet

No Asbestos

B00B - R0009 - External Movement

No Asbestos

B00B - R0010 - Toilets - Boys

No Asbestos

B00B - R0011 - Movement

No Asbestos

B00B - R0012 - Shower/Change

No Asbestos

B00B - R0013 - Toilets - Girls

No Asbestos

B00B - R0014 - Movement

No Asbestos

B00B - R0015 - Shower/Change

No Asbestos

B00B - R0016 - Raised Platform

No Asbestos

B00B - R0017 - Communal Space

No Asbestos

B00B - R0018 - Music Store

No Asbestos

B00B - R0019 - General Storeroom

No Asbestos

B00B - R0020 - External Movement

No Asbestos

B00B - R0021 - External Movement

No Asbestos

B00B - R0022 - Cleaning Supplies

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R0023 - Main Switch Board

No Asbestos

B00B - R0024 - General Assistant/Bulk Store

No Asbestos

B00B - R0025 - Sports Store

No Asbestos

B00B - R0026 - External Movement

No Asbestos

B00B - R0027 - Cleaning Supplies

No Asbestos

B00B - R0028 - External Movement

No Asbestos

B00B - R0029 - Craft Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00C - Administration/Staff Facilities - 1985 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points.
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible - access point in CR0011 too small to access <0.01m2

Interior**B00C - R0002 - Staff Room Annexe**

No Asbestos

B00C - R0003 - Movement

No Asbestos

B00C - R0005 - Security Store

No Asbestos

B00C - R0006 - Staff Toilet

No Asbestos

B00C - R0007 - Staff Toilet

No Asbestos

B00C - R0008 - Cleaning Distributed Store

No Asbestos

B00C - R0009 - Clerical Office

No Asbestos

B00C - R0010 - Staff Room Annexe

No Asbestos

B00C - R0011 - Security Store

No Asbestos

B00C - R0012 - Duplicating Workroom

No Asbestos

B00C - R0013 - Sick Bay

No Asbestos

B00C - R0014 - Clerical Office

No Asbestos

B00C - R0015 - Principal

No Asbestos

B00C - R0016 - Deputy Principal

No Asbestos

B00C - R0017 - External Movement

No Asbestos

B00C - R0018 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00C - R0019 - Entry Vestibule

No Asbestos

B00C - R0020 - External Movement

No Asbestos

B00C - R0022 - External Movement

No Asbestos

B00C - R0023 - Staff Room

No Asbestos

B00C - R0024 - Staff Kitchen

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R0025 - External Movement

No Asbestos

B00C - R0026 - Movement

No Asbestos

B00C - R0027 - Disabled Toilet

No Asbestos

B00C - R0028 - Staff Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1985 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible, no access points
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points.

Interior

B00D - R0001 - External Movement	No Asbestos
B00D - R0002 - Toilets - Girls	No Asbestos
B00D - R0003 - Home Base	No Asbestos
B00D - R0004 - Home Base Store	No Asbestos
B00D - R0005 - General Storeroom	No Asbestos
B00D - R0006 - Sports Store	No Asbestos
B00D - R0007 - Distribution Board	Note: No inspection of live electrical installation. No Asbestos
B00D - R0008 - External Movement	No Asbestos
B00D - R0009 - Practical Activities - 1hb	No Asbestos
B00D - R0010 - External Movement	No Asbestos
B00D - R0011 - Craft Store	No Asbestos
B00D - R0012 - General Storeroom	No Asbestos
B00D - R0013 - Home Base Store	No Asbestos
B00D - R0014 - Home Base	No Asbestos
B00D - R0015 - External Movement	No Asbestos
B00D - R0016 - Withdrawal Space - 1hb	No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Pupil Facilities - 1985 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points.
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible, no access points

Interior

B00E - R0001 - External Movement	No Asbestos
B00E - R0002 - Home Base	No Asbestos
B00E - R0003 - Home Base Store	No Asbestos
B00E - R0004 - General Storeroom	No Asbestos
B00E - R0005 - External Movement	No Asbestos
B00E - R0006 - Practical Activities - 1hb	No Asbestos
B00E - R0007 - External Movement	No Asbestos
B00E - R0008 - Distribution Board	Note: No inspection of live electrical installation.
B00E - R0009 - Music Store	No Asbestos
B00E - R0010 - Toilets - Girls	No Asbestos
B00E - R0011 - Craft Store	No Asbestos
B00E - R0012 - General Storeroom	No Asbestos
B00E - R0013 - Home Base Store	No Asbestos
B00E - R0014 - Home Base	No Asbestos
B00E - R0015 - External Movement	No Asbestos
B00E - R0016 - Withdrawal Space - 1hb	No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Pupil Facilities - 1985 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points.
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible, no access points

Interior

B00F - R0001 - External Movement	No Asbestos
B00F - R0002 - Home Base	No Asbestos
B00F - R0003 - Home Base Store	No Asbestos
B00F - R0004 - General Storeroom	No Asbestos
B00F - R0005 - External Movement	No Asbestos
B00F - R0006 - Practical Activities - 1hb	No Asbestos
B00F - R0007 - External Movement	No Asbestos
B00F - R0008 - Distribution Board	Note: No inspection of live electrical installation.
B00F - R0009 - Cleaning Distributed Store	No Asbestos
B00F - R0010 - Toilets - Boys	No Asbestos
B00F - R0011 - Craft Store	No Asbestos
B00F - R0012 - General Storeroom	No Asbestos
B00F - R0013 - Home Base Store	No Asbestos
B00F - R0014 - Home Base	No Asbestos
B00F - R0015 - External Movement	No Asbestos
B00F - R0016 - Withdrawal Space - 1hb	No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Library/Tiered Learning - 1985 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible no access points.
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points.

Interior

B00G - R0001 - Reading Area

No Asbestos

B00G - R0002 - Communications Room

No Asbestos

B00G - R0003 - Library Office/Workroom

No Asbestos

B00G - R0004 - Special Programs Room

No Asbestos

B00G - R0005 - Uniform Shop

No Asbestos

B00G - R0006 - External Movement

No Asbestos

B00G - R0007 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0008 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning/Pupil Facilities - 1985 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points.
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible, no access points

Interior

B00H - R0001 - External Movement	No Asbestos
B00H - R0002 - Toilets - Boys	No Asbestos
B00H - R0003 - Home Base	No Asbestos
B00H - R0004 - Home Base Store	No Asbestos
B00H - R0005 - General Storeroom	No Asbestos
B00H - R0006 - Cleaning Distributed Store	No Asbestos
B00H - R0007 - Distribution Board	Note: No inspection of live electrical installation. No Asbestos
B00H - R0008 - External Movement	No Asbestos
B00H - R0009 - Practical Activities - 1hb	No Asbestos
B00H - R0010 - External Movement	No Asbestos
B00H - R0011 - Craft Store	No Asbestos
B00H - R0012 - General Storeroom	No Asbestos
B00H - R0013 - Home Base Store	No Asbestos
B00H - R0014 - Home Base	No Asbestos
B00H - R0015 - External Movement	No Asbestos
B00H - R0016 - Withdrawal Space - 1hb	No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Other-Community Use - 1984 - Steel (Steel)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible, council run, no keys available at the time of the inspection.					
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 4564/B001/Eaves Linings/S1					No Asbestos Detected

Interior

B001 - R0001 - Out Of School Hours Care Centre

No Asbestos

B001 - R0002 - Out Of School Hours Care Centre

No Asbestos

B001 - R0003 - Out Of School Hours Care Centre

No Asbestos

B001 - R0004 - Out Of School Hours Care Centre

No Asbestos

B001 - R0005 - Out Of School Hours Care Centre

Floor Coverings Res/Textile	Vinyl Sheet	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
-----------------------------	-------------	------	------------	--------------------	---------	--------------------

Assumed Asbestos - Area inaccessible, council run, no

B001 - R0006 - Out Of School Hours Care Centre

No Asbestos

B001 - R0007 - Other-Community Use

No Asbestos

B001 - R0008 - Out Of School Hours Care Centre

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2004 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00J - R0001 - External Movement

No Asbestos

B00J - R0002 - Practical Activities - 1hb

No Asbestos

B00J - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 2008 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Area inaccessible, access points bolted shut.
Ceiling Voids	No Asbestos Found

Interior

B00K - R0001 - External Movement

No Asbestos

B00K - R0002 - Practical Activities - 1hb

No Asbestos

B00K - R0003 - Home Base Store

No Asbestos

B00K - R0004 - Home Base

No Asbestos

B00K - R0005 - Withdrawal Space - 2hb

No Asbestos

B00K - R0006 - Home Base

No Asbestos

B00K - R0007 - Home Base Store

No Asbestos

B00K - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - General Learning - 2008 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Underfloor Voids - Packing to Floor Joists	Non Accessible Area - Area inaccessible, access points bolted shut.
Ceiling Voids	No Asbestos Found

Interior

B00L - R0001 - External Movement

No Asbestos

B00L - R0002 - Practical Activities - 1hb

No Asbestos

B00L - R0003 - Home Base Store

No Asbestos

B00L - R0004 - Home Base

No Asbestos

B00L - R0005 - Withdrawal Space - 2hb

No Asbestos

B00L - R0006 - Home Base

No Asbestos

B00L - R0007 - Home Base Store

No Asbestos

B00L - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible, slab on ground, no access points.

Ceiling Voids No Asbestos Found

Interior

B00M - R0001 - External Movement

No Asbestos

B00M - R0002 - Practical Activities - 1hb

No Asbestos

B00M - R0003 - Home Base Store

No Asbestos

B00M - R0004 - Home Base

No Asbestos

B00M - R0005 - Withdrawal Space - 2hb

No Asbestos

B00M - R0006 - Practical Activities - 1hb

No Asbestos

B00M - R0007 - Home Base

No Asbestos

B00M - R0008 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points.
Ceiling Voids	No Asbestos Found

Interior

B00N - R0001 - External Movement	No Asbestos
B00N - R0002 - Practical Activities - 1hb	No Asbestos
B00N - R0003 - Home Base Store	No Asbestos
B00N - R0004 - Home Base	No Asbestos
B00N - R0005 - Withdrawal Space - 2hb	No Asbestos
B00N - R0006 - Practical Activities - 1hb	No Asbestos
B00N - R0007 - Home Base	No Asbestos
B00N - R0008 - Home Base Store	No Asbestos
B00N - R0009 - Practical Activities - 1hb	No Asbestos
B00N - R0010 - Home Base Store	No Asbestos
B00N - R0011 - Home Base	No Asbestos
B00N - R0012 - Withdrawal Space - 2hb	No Asbestos
B00N - R0013 - Practical Activities - 1hb	No Asbestos
B00N - R0014 - Home Base	No Asbestos
B00N - R0015 - Home Base Store	No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Communal Facilities - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible, slab on ground, no access points.

Ceiling Voids No Asbestos Found

Interior**B000 - R0001 - Toilets - Girls**

No Asbestos

B000 - R0002 - Toilets - Boys

No Asbestos

B000 - R0003 - Raised Platform

No Asbestos

B000 - R0004 - Ramp

No Asbestos

B000 - R0005 - Chair Storeroom

No Asbestos

B000 - R0006 - Communal/Performance Store

No Asbestos

B000 - R0007 - P.E. Store

No Asbestos

B000 - R0008 - Toilets - Girls

No Asbestos

B000 - R0009 - Toilet - Lobby

No Asbestos

B000 - R0010 - Sound Cupboard

No Asbestos

B000 - R0011 - Toilets - Boys

No Asbestos

B000 - R0012 - Toilet - Lobby

No Asbestos

B000 - R0013 - Cleaning Distributed Store

No Asbestos

B000 - R0014 - Access Shower/Toilet/Change

No Asbestos

B000 - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B000 - R0016 - Communal Space

No Asbestos

B000 - R0017 - Covered Outdoor Learning Area

No Asbestos

B000 - R0018 - Movement

No Asbestos

B000 - R0019 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D10287 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 16/04/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15917 - Learning Unit - Standard With P.A.A. : Placement Date - 6/02/2017

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017