

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : William Dean Public School (4576)
Region : Western Sydney
State Electorate : Mount Druit
Local Government Area : Blacktown

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B001 - R0001 - Toilets - Boys

No Asbestos

B001 - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0004 - External Movement

No Asbestos

B001 - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0006 - External Movement

No Asbestos

B001 - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B001 - R0009 - Security Store

No Asbestos

B001 - R0010 - Practical Activities - 1hb

No Asbestos

B001 - R0011 - Personal Effects Storage

No Asbestos

B001 - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B001 - R0013 - External Movement

No Asbestos

B001 - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B002 - General Learning - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B002 - R0001 - Security Store

No Asbestos

B002 - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B002 - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B002 - R0004 - External Movement

No Asbestos

B002 - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B002 - R0006 - External Movement

No Asbestos

B002 - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B002 - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B002 - R0009 - Toilets - Girls

No Asbestos

B002 - R0010 - Cleaning Distributed Store

No Asbestos

B002 - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B002 - R0012 - Personal Effects Storage

No Asbestos

B002 - R0013 - Practical Activities - 1hb

No Asbestos

B002 - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B003 - General Learning - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B003 - R0001 - Toilets - Boys

No Asbestos

B003 - R0002 - Cleaning Distributed Store

No Asbestos

B003 - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B003 - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B003 - R0005 - External Movement

No Asbestos

B003 - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B003 - R0007 - External Movement

No Asbestos

B003 - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B003 - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B003 - R0010 - Security Store

No Asbestos

B003 - R0011 - Practical Activities - 1hb

No Asbestos

B003 - R0012 - Kiln Room

No Asbestos

B003 - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B003 - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B004 - General Learning - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B004 - R0001 - Security Store

No Asbestos

B004 - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B004 - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B004 - R0004 - External Movement

No Asbestos

B004 - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B004 - R0006 - External Movement

No Asbestos

B004 - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B004 - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B004 - R0009 - Toilets - Girls

No Asbestos

B004 - R0010 - Cleaning Distributed Store

No Asbestos

B004 - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B004 - R0012 - Personal Effects Storage

No Asbestos

B004 - R0013 - Practical Activities - 1hb

No Asbestos

B004 - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B005 - General Learning - 1988 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B005 - R0001 - Security Store

No Asbestos

B005 - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B005 - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B005 - R0004 - External Movement

No Asbestos

B005 - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B005 - R0006 - External Movement

No Asbestos

B005 - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B005 - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B005 - R0009 - Toilets - Boys

No Asbestos

B005 - R0010 - Cleaning Distributed Store

No Asbestos

B005 - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B005 - R0012 - Personal Effects Storage

No Asbestos

B005 - R0013 - Practical Activities - 1hb

No Asbestos

B005 - R0014 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B006 - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B006 - R0001 - External Movement

No Asbestos

B006 - R0002 - Practical Activities - 1hb

No Asbestos

B006 - R0003 - Home Base Store

No Asbestos

B006 - R0004 - Home Base

No Asbestos

B006 - R0005 - Withdrawal Space - 2hb

No Asbestos

B006 - R0006 - Home Base

No Asbestos

B006 - R0007 - Home Base Store

No Asbestos

B006 - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B007 - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B007 - R0001 - External Movement

No Asbestos

B007 - R0002 - Special Programs Room

No Asbestos

B007 - R0003 - Special Programs Store

No Asbestos

B007 - R0004 - Practical Activities - 1hb

No Asbestos

B007 - R0005 - Home Base Store

No Asbestos

B007 - R0006 - Home Base

No Asbestos

B007 - R0007 - Withdrawal Space - 2hb

No Asbestos

B007 - R0008 - Home Base

No Asbestos

B007 - R0009 - Home Base Store

No Asbestos

B007 - R0010 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1988 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Sick Bay

No Asbestos

B00A - R0003 - Staff Toilet

No Asbestos

B00A - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0005 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0006 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0007 - Staff Toilet

No Asbestos

B00A - R0008 - Community Clinic

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0009 - Cleaning Distributed Store

No Asbestos

B00A - R0010 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0011 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0012 - Staff Toilet

No Asbestos

B00A - R0013 - Staff Toilet

No Asbestos

B00A - R0014 - Security Store

No Asbestos

B00A - R0015 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0016 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0017 - Security Store

No Asbestos

B00A - R0018 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0019 - Duplicating Workroom

No Asbestos

B00A - R0020 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0021 - Entry Vestibule						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0022 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00A - R0023 - External Movement						
No Asbestos						
B00A - R0024 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1988 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00B - R0002 - Cleaning Distributed Store

No Asbestos

B00B - R0003 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0006 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Plant

No Asbestos

B00B - R0009 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0010 - External Movement

No Asbestos

B00B - R0011 - External Movement

No Asbestos

B00B - R0012 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0013 - Resource/Toy Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0014 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities/Pupil Facilities - 1988 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0002 - External Movement

No Asbestos

B00C - R0003 - General Assistant/Bulk Store

No Asbestos

B00C - R0004 - Shower/Change

No Asbestos

B00C - R0005 - Cleaning Supplies

No Asbestos

B00C - R0006 - Cleaning Supplies

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0007 - Main Switch Board

No Asbestos

B00C - R0008 - Disabled Toilet

No Asbestos

B00C - R0009 - Canteen Office/Store

No Asbestos

B00C - R0010 - Canteen Office/Store

No Asbestos

B00C - R0011 - Canteen

No Asbestos

B00C - R0012 - Communal Space

No Asbestos

B00C - R0013 - P.E. Store

No Asbestos

B00C - R0014 - Hall Chair Store

No Asbestos

B00C - R0015 - Raised Platform

No Asbestos

B00C - R0016 - Plant

No Asbestos

B00C - R0017 - Shower/Change

No Asbestos

B00C - R0018 - Toilets - Girls

No Asbestos

B00C - R0019 - Garden Store

No Asbestos

B00C - R0020 - General Assistant/Bulk Store

No Asbestos

B00C - R0021 - External Movement

No Asbestos

B00C - R0022 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017