


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Windsor Park Public School (4614)
Region : Western Sydney
State Electorate : Hawkesbury
Local Government Area : Hawkesbury

Initial Survey : Noel Arnold & Associates : 30 - Mar - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0004 - Main Switch Board

No Asbestos

B00A - R0005 - Cleaning Distributed Store

No Asbestos

B00A - R0006 - Staff Toilet

No Asbestos

B00A - R0007 - Staff Toilet

No Asbestos

B00A - R0008 - Staff Toilet

No Asbestos

B00A - R0009 - Security Store

No Asbestos

B00A - R0010 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0011 - Duplicating Workroom

No Asbestos

B00A - R0012 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0013 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Sick Bay

No Asbestos

B00A - R0015 - Sick Bay - Shower/Toilet

No Asbestos

B00A - R0016 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0017 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0018 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0019 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library/Pupil Facilities - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - External Movement

No Asbestos

B00B - R0002 - Toilets - Boys

No Asbestos

B00B - R0003 - Uniform Shop

No Asbestos

B00B - R0004 - Disabled Toilet

No Asbestos

B00B - R0005 - Toilets - Girls

No Asbestos

B00B - R0006 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0007 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0008 - K.L.A. Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0009 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0010 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00B - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0012 - Plant

No Asbestos

B00B - R0013 - General Assistant/Bulk Store

No Asbestos

B00B - R0014 - Canteen Office/Store

No Asbestos

B00B - R0015 - Canteen

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0003 - Practical Activities - 1hb

No Asbestos

B00C - R0004 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0007 - Personal Effects Storage

No Asbestos

B00C - R0008 - Personal Effects Storage

No Asbestos

B00C - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0010 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0012 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1995 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - External Movement

No Asbestos

B00D - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Personal Effects Storage

No Asbestos

B00D - R0005 - Practical Activities - 1hb

No Asbestos

B00D - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0009 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0010 - Personal Effects Storage

No Asbestos

B00D - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0012 - External Movement

No Asbestos

B00D - R0013 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0014 - Personal Effects Storage

No Asbestos

B00D - R0015 - Practical Activities - 1hb

No Asbestos

B00D - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0017 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0019 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0020 - Personal Effects Storage						
No Asbestos						
B00D - R0021 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00D - R0022 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R0023 - Sports Store						
No Asbestos						
B00D - R0024 - Toilets - Girls						
No Asbestos						
B00D - R0025 - Kiln Room						
No Asbestos						
B00D - R0026 - Toilets - Boys						
No Asbestos						
B00D - R0027 - External Movement						
No Asbestos						
B00D - R0028 - Garden Store						
No Asbestos						
B00D - R0029 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1996 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - External Movement

No Asbestos

B00E - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0004 - Personal Effects Storage

No Asbestos

B00E - R0005 - Practical Activities - 1hb

No Asbestos

B00E - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0008 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0010 - Personal Effects Storage

No Asbestos

B00E - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0013 - Personal Effects Storage

No Asbestos

B00E - R0014 - Practical Activities - 1hb

No Asbestos

B00E - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0016 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0017 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0018 - Practical Activities - 1hb

No Asbestos

B00E - R0019 - Personal Effects Storage

No Asbestos

B00E - R0020 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0021 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00E - R0022 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Support Unit - 1996 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - External Movement

No Asbestos

B00F - R0002 - Home Base - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0003 - Practical Activities - S - 1hb

No Asbestos

B00F - R0004 - Home Base Store - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0006 - Withdrawal - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0007 - Toilet - S

No Asbestos

B00F - R0008 - Laundry - S

No Asbestos

B00F - R0009 - Toilet - S

No Asbestos

B00F - R0010 - Practical Activities - S - 1hb

No Asbestos

B00F - R0011 - Practical Activities - S - 1hb

No Asbestos

B00F - R0012 - Home Base - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0013 - Withdrawal - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0014 - Home Base Store - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0015 - External Movement

No Asbestos

B00F - R0016 - Covered Vehicle Area/Porte Cochere

No Asbestos

B00F - R0017 - Wheelchair Store

No Asbestos

B00F - R0018 - Practical Activities - S - 1hb

No Asbestos

B00F - R0019 - Home Base - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0020 - Home Base Store - S

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0021 - Withdrawal - S						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R0022 - Movement						
No Asbestos						
B00F - R0023 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00F - R0024 - Community Clinic						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R0025 - Staff Toilet						
No Asbestos						
B00F - R0026 - Staff Room						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00F - R0027 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Communal Facilities/Pupil Facilities - 1996 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Communal Space

No Asbestos

B00G - R0003 - Movement

No Asbestos

B00G - R0004 - Toilets - Girls

No Asbestos

B00G - R0005 - Raised Platform

No Asbestos

B00G - R0006 - Lift

No Asbestos

B00G - R0007 - Movement

No Asbestos

B00G - R0008 - Toilets - Boys

No Asbestos

B00G - R0009 - P.E. Store

No Asbestos

B00G - R0010 - Hall Chair Store

No Asbestos

B00G - R0011 - Plant

No Asbestos

B00G - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0013 - Disabled Toilet

No Asbestos

B00G - R0014 - External Movement

No Asbestos

B00G - R0015 - External Movement

No Asbestos

B00G - R0016 - Cleaning Distributed Store

No Asbestos

B00G - R0017 - Special Programs Room

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2010 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - External Movement

No Asbestos

B00H - R0002 - Practical Activities - 1hb

No Asbestos

B00H - R0003 - Home Base Store

No Asbestos

B00H - R0004 - Home Base

No Asbestos

B00H - R0005 - Withdrawal Space - 2hb

No Asbestos

B00H - R0006 - Home Base

No Asbestos

B00H - R0007 - Home Base Store

No Asbestos

B00H - R0008 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

4614_ASB_010313_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017