


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wadalba Community School (8278)
Region : Hunter/Central Coast
State Electorate : Wyong
Local Government Area : Wyong

Initial Survey : Noel Arnold & Associates : 28 - Mar - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 2000 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Interview/Office - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0003 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0004 - Pupil Entry

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0005 - Sick Bay

No Asbestos

B00A - R0006 - Clinic-Waiting

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0007 - Disabled Toilet

No Asbestos

B00A - R0008 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0009 - Pupil Entry

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0010 - Clinic - Girls

No Asbestos

B00A - R0011 - Clinic-Toilets

No Asbestos

B00A - R0012 - Clinic-Toilets

No Asbestos

B00A - R0013 - Clinic - Boys

No Asbestos

B00A - R0014 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0015 - Security Store

No Asbestos

B00A - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0017 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0018 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0019 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0020 - Security Store						
No Asbestos						
B00A - R0021 - Lift						
No Asbestos						
B00A - R0022 - Movement						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R0023 - Staff - Toilet						
No Asbestos						
B00A - R0024 - Staff - Toilet						
No Asbestos						
B00A - R0025 - Staff - Toilet						
No Asbestos						
B00A - R0026 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R0027 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R0028 - Movement						
No Asbestos						
B00A - R0029 - Public Entry						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R0030 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R0031 - Principal Office						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R0032 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R0033 - Principal Office						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R0034 - Movement						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00A - R0035 - Disabled Toilet						
No Asbestos						
B00A - R0036 - Staff Kitchen						
No Asbestos						
B00A - R0037 - External Movement						
No Asbestos						
B00A - R0038 - External Movement						
No Asbestos						
B00A - R0039 - External Movement						
No Asbestos						
B00A - R0040 - Movement						
No Asbestos						
B00A - R0041 - No Access						
No Asbestos						
B00A - R0042 - External Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00A - R0043 - External Movement						
No Asbestos						
B00A - R1001 - Staff Room Annexe						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1002 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1003 - Cleaning Store - Distributed						
No Asbestos						
B00A - R1004 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1005 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1006 - Interview/Meeting						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1007 - Duplicating Workroom						
No Asbestos						
B00A - R1008 - No Access						
No Asbestos						
B00A - R1009 - External Movement						
No Asbestos						
B00A - R1010 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1011 - Interview/Office - Type 1						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1012 - Disabled Toilet						
No Asbestos						
B00A - R1013 - Staff - Toilet						
No Asbestos						
B00A - R1014 - Staff - Toilet						
No Asbestos						
B00A - R1015 - Staff - Toilet						
No Asbestos						
B00A - R1016 - Staff - Toilet						
No Asbestos						
B00A - R1017 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1018 - Staff Room Annexe						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1019 - Commonroom						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1020 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00A - R1021 - External Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1022 - No Access						
No Asbestos						
B00A - R1023 - External Movement						
No Asbestos						
B00A - R1024 - External Movement						
No Asbestos						
B00A - R1025 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - Library - 2000 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0002 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0003 - Security Store

No Asbestos

B00B - R0004 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0005 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0006 - Computer Resource

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0007 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0008 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0009 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0010 - Staff - Toilet

No Asbestos

B00B - R0011 - Staff - Toilet

No Asbestos

B00B - R0012 - Careers Advisers Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0013 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0014 - Computer Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0015 - Disabled Toilet

No Asbestos

B00B - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0017 - Communications Room

No Asbestos

B00B - R0018 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0019 - Seminar

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0020 - Reading Area						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0021 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0022 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0023 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00B - R0024 - External Movement						
No Asbestos						
B00B - R0025 - External Movement						
No Asbestos						
B00B - R0026 - External Movement						
No Asbestos						
B00B - R0027 - External Movement						
No Asbestos						
B00B - R0028 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Toilets - Boys

No Asbestos

B00C - R0002 - Toilets - Girls

No Asbestos

B00C - R0003 - Main Switch Board

No Asbestos

B00C - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Science - 2000 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - General Learning Space - Type 3**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0002 - Science Laboratory

No Asbestos

B00D - R0003 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0004 - Plant

No Asbestos

B00D - R0005 - Chemical Store

No Asbestos

B00D - R0006 - Movement

No Asbestos

B00D - R0007 - General Storeroom

No Asbestos

B00D - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0009 - Security Store

No Asbestos

B00D - R0010 - Preparation

No Asbestos

B00D - R0011 - Science Laboratory

No Asbestos

B00D - R0012 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0013 - General Learning Space - Type 3

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0014 - External Movement

No Asbestos

B00D - R0015 - External Movement

No Asbestos

B00D - R0016 - External Movement

No Asbestos

B00D - R1001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R1002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R1003 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R1004 - Staff Lounge

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R1005 - Senior Seminar						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R1007 - Distribution Board						
No Asbestos		Note: No inspection of live electrical installation.				
B00D - R1008 - Personal Effects Storage						
No Asbestos						
B00D - R1009 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R1011 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R1012 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R1013 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R1014 - External Movement						
No Asbestos						
B00D - R1015 - External Movement						
No Asbestos						
B00D - R1016 - External Movement						
No Asbestos						
B00D - R1017 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				
B00D - R1018 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)		No Asbestos Found				

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00E - R0002 - Plant

No Asbestos

B00E - R0003 - Sport Equipment Store

No Asbestos

B00E - R0004 - Lift

No Asbestos

B00E - R0005 - Stage

No Asbestos

B00E - R0006 - Sport Equipment Store

No Asbestos

B00E - R0007 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00E - R0008 - Multi-Purpose Space

No Asbestos

B00E - R0009 - Chair Store

No Asbestos

B00E - R0010 - Control Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0011 - Clinic - Boys

No Asbestos

B00E - R0012 - Stage

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0013 - Performance Workshop

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0014 - Plant

No Asbestos

B00E - R0015 - Garden Store Room

No Asbestos

B00E - R0016 - Maintenance Bulk Store

No Asbestos

B00E - R0017 - Performing Arts Store

No Asbestos

B00E - R0018 - General Assistants

No Asbestos

B00E - R0019 - Cleaning Supplies Store

No Asbestos

B00E - R0020 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00E - R0021 - Toilets - Girls

No Asbestos

B00E - R0022 - Sport Equipment Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00E - R0023 - Staff - Toilet					
	No Asbestos					
	B00E - R0024 - Disabled Toilet					
	No Asbestos					
	B00E - R0025 - Toilets - Boys					
	No Asbestos					
	B00E - R0026 - External Movement					
	No Asbestos					
	B00E - R0027 - External Movement					
	No Asbestos					
	B00E - R0028 - Student Canteen					
	No Asbestos					
	B00E - R0029 - Office/Store					
	No Asbestos					
	B00E - R0030 - Distribution Board Cupboard					Note: No inspection of live electrical installation.
	No Asbestos					
	B00E - R0031 - Plant					
	No Asbestos					
	B00E - R0032 - Performing Arts Changeroom					
	No Asbestos					
	B00E - R0033 - Performing Arts Changeroom					
	No Asbestos					
	B00E - R0034 - Performing Arts Changeroom					
	No Asbestos					
	B00E - R0035 - Performing Arts Changeroom					
	No Asbestos					
	B00E - R0036 - Performing Arts Changeroom					
	No Asbestos					
	B00E - R0037 - Performing Arts Changeroom					
	No Asbestos					
	B00E - R0038 - Student Canteen					
	No Asbestos					
	B00E - R0039 - Performance Workspace					
	No Asbestos					
	B00E - R0040 - Performance Store					
	No Asbestos					
	B00E - R0041 - Performance Store					
	No Asbestos					
	B00E - R0042 - Control Room					
	No Asbestos					
	B00E - R0043 - Performance Workshop					
	No Asbestos					
	B00E - R0044 - Performance Workshop					
	No Asbestos					
	B00E - R0045 - Movement					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - Special Purpose - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00F - R0002 - General Learning Space - Type 8

No Asbestos

B00F - R0003 - Resource/Project Store

No Asbestos

B00F - R0004 - Materials Workshop - Type 2

No Asbestos

B00F - R0005 - Wood Technology Bay

No Asbestos

B00F - R0006 - General Learning Space - Type 9

No Asbestos

B00F - R0009 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00F - R0011 - Dust Extraction Space

No Asbestos

B00F - R0012 - Metal Technology Bay

No Asbestos

B00F - R0013 - Materials Workshop - Type 2

No Asbestos

B00F - R0014 - General Learning Space - Type 8

No Asbestos

B00F - R0015 - General Learning Space - Type 9

No Asbestos

B00F - R0016 - Darkroom Space

No Asbestos

B00F - R0017 - General Learning Space - Type 5

No Asbestos

B00F - R0018 - General Learning Space - Type 4

No Asbestos

B00F - R0019 - Distribution Board Cupboard Note: No inspection of live electrical installation.

No Asbestos

B00F - R0020 - Visual Arts Store

No Asbestos

B00F - R0021 - Visual Arts Workshop

No Asbestos

B00F - R0022 - Materials Store

No Asbestos

B00F - R0023 - Materials Store

No Asbestos

B00F - R0024 - Outdoor Workshop

No Asbestos

B00F - R0025 - Kiln Space

No Asbestos

B00F - R0026 - Materials Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
					No Asbestos	
	B00F - R0027 - Welding/Hot Metals Area				No Asbestos	
	B00F - R0029 - L.P.G. Store				No Asbestos	
	B00F - R0030 - External Movement				No Asbestos	
	B00F - R0031 - External Movement				No Asbestos	
	B00F - R0032 - Outdoor Learning Area				No Asbestos	
	B00F - R0033 - Project Store - Type 1				No Asbestos	
	B00F - R0034 - Project Store - Type 1				No Asbestos	
	B00F - R0035 - Preparation - Materials				No Asbestos	
	B00F - R0036 - Design L.S.				No Asbestos	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Special Purpose - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Performing Arts Changeroom

No Asbestos

B00G - R0002 - Performing Arts Changeroom

No Asbestos

B00G - R0003 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0005 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0006 - Fitness Laboratory

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0007 - Performing Arts Store

No Asbestos

B00G - R0008 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0011 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0012 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0014 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0016 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0017 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0018 - Laundry

No Asbestos

B00G - R0023 - External Movement

No Asbestos

B00G - R0024 - Movement

No Asbestos

B00G - R0025 - External Movement

No Asbestos

B00G - R0026 - Plant

No Asbestos

B00G - R0027 - Covered Area

No Asbestos

B00G - R0028 - Covered Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - R0029 - Laundry						
No Asbestos						
B00G - R0030 - General Storeroom						
No Asbestos						
B00G - R0031 - Kitchen - Type 1						
No Asbestos						
B00G - R0032 - General Learning Space - Type 6						
No Asbestos						
B00G - R0033 - Materials Workshop - Type 2						
No Asbestos						
B00G - R0034 - Pantry						
No Asbestos						
B00G - R0035 - Preparation - Materials						
No Asbestos						
B00G - R0036 - Kitchen - Type 1						
No Asbestos						
B00G - R9001 - General Learning Space - Type 3						
No Asbestos						
B00G - R9002 - General Learning Space - Type 3						
No Asbestos						
B00G - R9003 - Science Laboratory						
No Asbestos						
B00G - R9004 - Seminar						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00G - R9005 - General Storeroom						
No Asbestos						
B00G - R9006 - Distribution Board Cupboard					Note: No inspection of live electrical installation.	
No Asbestos						
B00G - R9007 - Preparation						
No Asbestos						
B00G - R9008 - Growing/Breeding						
No Asbestos						
B00G - R9009 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0003 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0005 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0006 - Security Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0008 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0009 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R0010 - Cleaning Store - Distributed

No Asbestos

B00H - R0012 - Covered Area

No Asbestos

B00H - R0013 - External Movement

No Asbestos

B00H - R0014 - Home Base

No Asbestos

B00H - R0015 - Movement

No Asbestos

B00H - R1001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R1002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R1003 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R1004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00H - R1005 - General Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1006 - Security Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1007 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00H - R1008 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1009 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1012 - Shared Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00H - R1013 - External Movement						
No Asbestos						
B00H - R1014 - External Movement						
No Asbestos						
B00H - R1015 - Access Shower/Toilet/Change						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Agriculture - 2005 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B001 - R0001 - Botany/Zoology

No Asbestos

B001 - R0002 - Botany/Zoology

No Asbestos

B001 - R0003 - External Movement

No Asbestos

B001 - R0004 - Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0003 - Security Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0004 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0005 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0006 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0007 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0008 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0009 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R0011 - Covered Area

No Asbestos

B00J - R0012 - External Movement

No Asbestos

B00J - R0013 - Movement

No Asbestos

B00J - R0014 - Home Base

No Asbestos

B00J - R1001 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R1002 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R1003 - Security Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R1004 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R1005 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00J - R1006 - Seminar

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1007 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1008 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1009 - Cleaning Store - Distributed						
No Asbestos						
B00J - R1010 - Shared Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00J - R1011 - Movement						
No Asbestos						
B00J - R1012 - Distribution Board Cupboard				Note: No inspection of live electrical installation.		
No Asbestos						
B00J - R1013 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00K - Communal Facilities - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Movement

No Asbestos

B00K - R0002 - Stage

No Asbestos

B00K - R0003 - Movement

No Asbestos

B00K - R0004 - Cleaning Store - Distributed

No Asbestos

B00K - R0005 - Chair Store

No Asbestos

B00K - R0006 - Sport Equipment Store

No Asbestos

B00K - R0007 - Toilets - Girls

No Asbestos

B00K - R0008 - Toilets - Boys

No Asbestos

B00K - R0009 - Communications Cupboard

No Asbestos

B00K - R0010 - Disabled Toilet

No Asbestos

B00K - R0011 - Communal Space

No Asbestos

B00K - R0012 - Covered Area

No Asbestos

B00K - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0014 - Student Canteen

No Asbestos

B00K - R0015 - Canteen Office/Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Building Services - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00L - R0001 - Toilets - Boys

No Asbestos

B00L - R0002 - Toilets - Girls

No Asbestos

B00L - R0003 - Kiln Space

No Asbestos

B00L - R0004 - General Assistant/Bulk Store

No Asbestos

B00L - R0005 - Sport Equipment Store

No Asbestos

B00L - R0007 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 2001 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00M - R0001 - Toilets - Girls

No Asbestos

B00M - R0002 - Toilets - Boys

No Asbestos

B00M - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0005 - Practical Activities - 1hb

No Asbestos

B00M - R0006 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0007 - Practical Activities - 1hb

No Asbestos

B00M - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0012 - Practical Activities - 1hb

No Asbestos

B00M - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0014 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0015 - Practical Activities - 1hb

No Asbestos

B00M - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0017 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0019 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00M - R0020 - Practical Activities - 1hb						
No Asbestos						
B00M - R0021 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00M - R0022 - Withdrawal Space - 2hb						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00M - R0023 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00M - R0024 - Practical Activities - 1hb						
No Asbestos						
B00M - R0025 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B00M - R0026 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - General Learning - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00N - R0001 - Practical Activities - 1hb**

No Asbestos

B00N - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0004 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0007 - Practical Activities - 1hb

No Asbestos

B00N - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0010 - Practical Activities - 1hb

No Asbestos

B00N - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0012 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0014 - Practical Activities - 1hb

No Asbestos

B00N - R0015 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00N - R0016 - External Movement

No Asbestos

B00N - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Other-Community Use - 2001 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00P - R0001 - Special Programs Room**

No Asbestos

B00P - R0002 - General Storeroom

No Asbestos

B00P - R0003 - CommonroomVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00P - R0004 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

B00P - R0005 - General Storeroom

No Asbestos

B00P - R0006 - Administration - ClericalVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00P - R0007 - Staff Kitchen**

No Asbestos

B00P - R0008 - General Storeroom

No Asbestos

B00P - R0009 - Pantry

No Asbestos

B00P - R0010 - Staff Kitchen

No Asbestos

B00P - R0011 - Administration - ClericalVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00P - R0012 - Movement**

No Asbestos

B00P - R0013 - Plant

No Asbestos

B00P - R0014 - General Storeroom

No Asbestos

B00P - R0015 - Special Programs Room

No Asbestos

B00P - R0016 - Special Programs Room

No Asbestos

B00P - R0017 - General Storeroom

No Asbestos

B00P - R0018 - Sport Equipment Store

No Asbestos

B00P - R0019 - Cleaning Store - Distributed

No Asbestos

B00P - R0022 - Access Staff Shower/Toilet

No Asbestos

B00P - R0023 - External Movement

No Asbestos

B00P - R0024 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00P - R0025 - Toilet - Lobby

No Asbestos

B00P - R0026 - Toilets-Girls

No Asbestos

B00P - R0027 - Toilets-Boys

No Asbestos

B00P - R0028 - Toilet - Lobby

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - General Learning/Other - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00Q - R0001 - Home Base - Bd/Cd/Ed

No Asbestos

B00Q - R0002 - Practical Activities

No Asbestos

B00Q - R0003 - Special Programs Store

No Asbestos

B00Q - R0004 - Practical Activities - 1hb

No Asbestos

B00Q - R0005 - Home Base - Bd/Cd/Ed

No Asbestos

B00Q - R0006 - Home Base Store

No Asbestos

B00Q - R0007 - Withdrawal Space - 1hb

No Asbestos

B00Q - R0008 - External Movement

No Asbestos

B00Q - R0009 - Access Shower/Toilet/Change

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00R - Agricultural Science - - Greenhouse (Greenhouse)

Exterior

Ceiling Void	Requires Inspection
Underfloor Void	Requires Inspection

Interior

B00R - R0001 - Growing/Breeding

Recently Modified Space	Requires Inspection
-------------------------	---------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00S - Agricultural Science - - Metal Shed (Metal Shed)

Exterior

Ceiling Void	Requires Inspection
Underfloor Void	Requires Inspection

Interior

B00S - R0001 - Agriculture Covered Area

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00S - R0002 - Animal Space

Recently Modified Space	Requires Inspection
-------------------------	---------------------

B00S - R0003 - Animal Space

Recently Modified Space	Requires Inspection
-------------------------	---------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 700 - D10447 - Art Learning Space/Workshop/Store : Placement Date - 29/03/2011

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - Art Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 602 - D10868 - Learning Unit - Standard With P.A.A. : Placement Date - 18/05/2016

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 601 - D11164 - Learning Unit - Standard/Withdrawal : Placement Date - 24/12/2009

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

OS 601 - D11607 - Learning Unit - Standard/Withdrawal : Placement Date - 24/12/2009

Exterior

No Asbestos Found.

Interior

R1 - Entry

No Asbestos Found.

R2 - General Learning Space

No Asbestos Found.

R3 - Store

No Asbestos Found.

NS 110 - D13159 - Learning Unit - Single Secondary/Secure : Placement Date - 4/04/2006

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
Interior						
R1 - General Learning Space						
No Asbestos Found.						
R2 - Entry						
No Asbestos Found.						
R3 - Secure Storeroom						
No Asbestos Found.						
OS 523 - D13943 - Staff Study With Toilets : Placement Date - 18/05/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - Staff Room						
No Asbestos Found.						
R3 - Staff Toilet						
No Asbestos Found.						
OS 601 - D14964 - Learning Unit - Standard/Withdrawal : Placement Date - 21/01/2011						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Entry						
No Asbestos Found.						
R2 - General Learning Space						
No Asbestos Found.						
R3 - Store						
No Asbestos Found.						
OS 836 - D16080 - H Cap Shower/Change/Toilet : Placement Date - 19/08/2016						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Disabled Shower/Toilet						
No Asbestos Found.						
- D16378 - : Placement Date - 13/02/2017						
No Asbestos Found.						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017