

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : East Hills Public School (3924)


Region : South Western Sydney

State Electorate : East Hills

Local Government Area : Bankstown

Initial Survey : Noel Arnold & Associates : 04 - May - 2008

Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00A - Library - 1952 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior**B00A - R0001 - External Movement**

Ceiling Structures/Linings Flat AC Sheeting 5m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

3924/B00A/R0001/Ceiling Structures/Linings/S4

Chrysotile (white asbestos)**B00A - R0002 - Movement**

No Asbestos

B00A - R0003 - Clerical Office/Workroom

No Asbestos

B00A - R0004 - Reading Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00B - Administration/General Learning - 1952 - Brick/Veneer (Brick/Veneer)						
Exterior						
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					
Interior						
B00B - R0001 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3924/B00B/R0001/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	
B00B - R0002 - Duplicating Workroom						
No Asbestos						
B00B - R0003 - Principal						
No Asbestos						
B00B - R0004 - Movement						
No Asbestos						
B00B - R0005 - General Storeroom						
No Asbestos						
B00B - R0006 - Clerical Office/Workroom						
No Asbestos						
B00B - R0007 - Movement						
No Asbestos						
B00B - R0008 - Uniform Shop						
No Asbestos						
B00B - R0009 - Home Base						
Wall Linings Internal	Flat AC Sheeting	2m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3924/B00B/R0011/Wall Linings Internal/S3				Chrysotile (white asbestos)	
B00B - R0010 - General Storeroom						
No Asbestos						
B00B - R0011 - Home Base						
Wall Linings Internal	Flat AC Sheeting	2m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3924/B00B/R0011/Wall Linings Internal/S3				Chrysotile (white asbestos)	
B00B - R0012 - General Storeroom						
No Asbestos						
B00B - R0013 - Sports Store						
Wall Linings Internal	Flat AC Sheeting	1m2	Left hand side of door	Good Condition (1)	Low (1)	Low Priority (2-3)
	3924/B00B/R0014/Wall Linings Internal/S2				Chrysotile (white asbestos)	
B00B - R0014 - Movement						
Wall Linings Internal	Flat AC Sheeting	1m2	Right hand side of door	Good Condition (1)	Low (1)	Low Priority (2-3)
	3924/B00B/R0014/Wall Linings Internal/S2				Chrysotile (white asbestos)	
B00B - R0015 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	3924/B00B/R0001/Ceiling Structures/Linings/S1				Chrysotile (white asbestos)	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00C - General Learning/Staff Facilities - 1952 - Concrete (Concrete)**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - External Movement**

No Asbestos

B00C - R0002 - Movement

No Asbestos

B00C - R0005 - Sports Store

No Asbestos

B00C - R0006 - General Storeroom

No Asbestos

B00C - R0007 - Staff Room

No Asbestos

B00C - R0008 - Personal Effects Storage

No Asbestos

B00C - R0009 - Movement

No Asbestos

B00C - R0010 - Home Base

No Asbestos

B00C - R0011 - Home Base Store

No Asbestos

B00C - R0012 - External Movement

Ceiling Structures/Linings Flat AC Sheeting
3924/B00C/R0012/Ceiling Structures/Linings/S5

No Asbestos Detected**B00C - R0013 - Staff Toilet**

No Asbestos

B00C - R0014 - Toilet - Lobby

No Asbestos

B00C - R0015 - Movement

No Asbestos

B00C - R0016 - Sports Store

No Asbestos

B00C - R0017 - Toilet - Lobby

No Asbestos

B00C - R0018 - Staff Toilet

No Asbestos

B00C - R0019 - Staff Toilet

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00D - General Learning - 1952 - Concrete (Concrete)**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior**B00D - R0001 - External Movement**

Wall Linings Internal	Flat AC Sheeting 3924/B00D/R0016/Wall Linings Internal/S8	No Asbestos Detected
-----------------------	--	----------------------

B00D - R0002 - Communal Space

No Asbestos

B00D - R0003 - Movement

No Asbestos

B00D - R0004 - Deputy Principal

No Asbestos

B00D - R0005 - Cleaning Distributed Store

No Asbestos

B00D - R0006 - General Storeroom

No Asbestos

B00D - R0011 - Home Base

No Asbestos

B00D - R0016 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 3924/B00D/R0018/Ceiling Structures/Linings/S7	No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 3924/B00D/R0016/Wall Linings Internal/S8	No Asbestos Detected

B00D - R0018 - Practical Activities - 1hb

Ceiling Structures/Linings	Flat AC Sheeting 3924/B00D/R0018/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0022 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 3924/B00D/R0018/Ceiling Structures/Linings/S7	No Asbestos Detected
----------------------------	---	----------------------

B00D - R0023 - Home Base Store

No Asbestos

B00D - R0024 - Communications Room

No Asbestos

B00D - R0025 - Library Office/Workroom

No Asbestos

B00D - R0026 - Practical Activities

No Asbestos

B00D - R0027 - Reading Area

No Asbestos

B00D - R0028 - Reading Area

No Asbestos

B00D - R0029 - K.L.A. Store

No Asbestos

B00D - R0030 - Home Base Store

No Asbestos

B00D - R0031 - Movement

No Asbestos

B00D - R0032 - Raised Platform

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1952 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior**B00E - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3924/B00E/R0001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00E - R0002 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3924/B00E/R0001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00E - R0003 - Canteen Office/Store

Ceiling Structures/Linings	Flat AC Sheeting	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3924/B00E/R0001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00E - R0004 - Canteen

Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3924/B00E/R0001/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00F - General Learning - 1952 - Steel (Steel)**Exterior**

Eaves Linings	Flat AC Sheeting	80m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos						
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00F - R0001 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
3924/B00F/R0001/Ceiling Structures/Linings/S17				No Asbestos Detected		

B00F - R0002 - General Storeroom

No Asbestos

B00F - R0003 - General Storeroom

No Asbestos

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - Special Programs Room

No Asbestos

B00F - R0006 - Movement

No Asbestos

B00F - R0007 - Toilets - Boys/Girls

Wall Linings Internal	Flat AC Sheeting	2m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
3924/B00F/R0007/Wall Linings Internal/S18				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00F - R0008 - Personal Effects Storage

No Asbestos

B00F - R0009 - Home Base

No Asbestos

B00F - R0010 - Home Base

No Asbestos

B00F - R0011 - External Movement

Wall Linings Internal	Flat AC Sheeting					
3924/B00F/R0011/Wall Linings Internal/S19				No Asbestos Detected		

B00F - R0012 - Practical Activities - 1hb

No Asbestos

B00F - R0013 - Movement

No Asbestos

B00F - R0014 - Home Base Store

No Asbestos

B00F - R0015 - Staff Room Annexe

No Asbestos

B00F - R0016 - Personal Effects Storage

No Asbestos

B00F - R0017 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00G - General Learning - 1952 - Timber (Timber)**Exterior**

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior**B00G - R0001 - Cleaning Distributed Store**

Wall Linings Internal Flat AC Sheeting
 3924/B00G/R0001/Wall Linings Internal/S20 **No Asbestos Detected**

B00G - R0002 - External Movement

No Asbestos

B00G - R0003 - Home Base

Wall Linings Internal Flat AC Sheeting
 3924/B00G/R0001/Wall Linings Internal/S20 **No Asbestos Detected**

B00G - R0004 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00H - General Learning - 1952 - Steel (Steel)**Exterior**

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior**B00H - R0001 - External Movement**

No Asbestos

B00H - R0002 - Withdrawal Space - 1hb

No Asbestos

B00H - R0003 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00I - General Learning - 1952 - Steel (Steel)**Exterior**

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior**B00I - R0001 - Withdrawal Space - 1hb**

No Asbestos

B00I - R0002 - Home Base

No Asbestos

B00I - R0003 - Cleaning Distributed Store

No Asbestos

B00I - R0004 - External Movement

No Asbestos

B00I - R0005 - Sports Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00J - General Learning - 1958 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior**B00J - R0001 - External Movement**

Ceiling Structures/Linings Flat AC Sheeting 5m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

3924/B00J/R0001/Ceiling Structures/Linings/S21

Chrysotile (white asbestos) , Amosite (brown asbestos)**B00J - R0002 - Movement**

No Asbestos

B00J - R0003 - Personal Effects Storage

No Asbestos

B00J - R0004 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00K - Pupil Facilities - 1952 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	12m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	3924/B00K/Eaves Linings/S15	Chrysotile (white asbestos)				
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00K - R0001 - Drinking Facilities**

No Asbestos

B00K - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3924/B00K/R0004/Partition Walls (Cubicles)/S14	Chrysotile (white asbestos)				

B00K - R0003 - Staff Toilet

No Asbestos

B00K - R0004 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	3924/B00K/R0004/Partition Walls (Cubicles)/S14	Chrysotile (white asbestos)				

B00K - R0005 - Garden Store

No Asbestos

B00K - R0006 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00L - Pupil Facilities - 1952 - Concrete (Concrete)**Exterior**

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior**B00L - R0001 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	33m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

3924/B00L/R0001/Ceiling Structures/Linings/S10

Chrysotile (white asbestos)

Partition Walls (Cubicles) Compressed AC Sheet

3924/B00L/R0001/Partition Walls (Cubicles)/S11

No Asbestos Detected**B00L - R0002 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00M - Pupil Facilities - 1952 - Concrete (Concrete)**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior**B00M - R0001 - Drinking Facilities**

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3924/B00M/R0001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)		

B00M - R0002 - Drinking Facilities

Ceiling Structures/Linings	Flat AC Sheeting	19m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
3924/B00M/R0001/Ceiling Structures/Linings/S9				Chrysotile (white asbestos) , Amosite (brown asbestos)		

2017

B00N - Pupil Facilities - 1952 - Concrete (Concrete)

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

B00N - R0001 - Toilets - Boys

B00N - R0002 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables
There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017