

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Forster Public School (1936)

Region : North Coast

State Electorate : Myall Lakes

Local Government Area : Great Lakes

Initial Survey : Noel Arnold & Associates : 16 - Apr - 2008

Reviewed By : Parsons Brinckerhoff : 31 - Oct - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration/Staff Facilities - 1981 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

Interior**B00A - R0001 - Principal**

No Asbestos

B00A - R0002 - Deputy Principal

No Asbestos

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Staff Toilet

No Asbestos

B00A - R0005 - Staff Toilet

No Asbestos

B00A - R0006 - Cleaning Distributed Store

No Asbestos

B00A - R0007 - Entry Vestibule

No Asbestos

B00A - R0008 - Movement

No Asbestos

B00A - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0010 - Clerical Office

No Asbestos

B00A - R0011 - Duplicating Workroom

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Movement

No Asbestos

B00A - R0014 - Interview

No Asbestos

B00A - R0015 - Security Store

No Asbestos

B00A - R0016 - Staff Toilet

No Asbestos

B00A - R0017 - Movement

No Asbestos

B00A - R0018 - Sick Bay

No Asbestos

B00A - R0019 - Toilets - Boys/Girls

No Asbestos

B00A - R0020 - Deputy Principal

No Asbestos

B00A - R0021 - Movement

No Asbestos

B00A - R0022 - Staff Room

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
		Sample No			Test Result	
B00A - R0023 - Movement						
No Asbestos						
B00A - R0024 - Main Switch Board						
Electrical Backing Board	Resinous Board					
	1936/B00A/R0024/Electrical Backing Board/S28					No Asbestos Detected
B00A - R0025 - Plant						
No Asbestos						
B00A - R0026 - Entry Vestibule						
No Asbestos						
B00A - R0027 - Lift						
No Asbestos						
B00A - R0028 - Stairs						
No Asbestos						
B00A - R1001 - Staff Room Annexe						
No Asbestos						
B00A - R1002 - Interview						
No Asbestos						
B00A - R1003 - Cleaning Supplies						
Floor Coverings Res/Textile	Vinyl Tiles					
	1936/B00A/R1007/Floor Coverings Res/Textile/S18					No Asbestos Detected
B00A - R1004 - Movement						
No Asbestos						
B00A - R1005 - Cleaning Distributed Store						
Floor Coverings Res/Textile	Vinyl Tiles					
	1936/B00A/R1007/Floor Coverings Res/Textile/S18					No Asbestos Detected
B00A - R1007 - Distribution Board					Note: No inspection of live electrical installation.	
Floor Coverings Res/Textile	Vinyl Tiles					
	1936/B00A/R1007/Floor Coverings Res/Textile/S18					No Asbestos Detected
B00A - R1008 - Staff Room Annexe						
No Asbestos						
B00A - R1009 - Home Base						
No Asbestos						
B00A - R1010 - Home Base						
No Asbestos						
B00A - R1011 - Movement						
No Asbestos						
B00A - R1012 - General Storeroom						
No Asbestos						
B00A - R1013 - General Storeroom						
No Asbestos						
B00A - R1014 - Practical Activities - 1hb						
No Asbestos						
B00A - R1015 - Special Programs Room						
No Asbestos						
B00A - R1016 - Home Base						
No Asbestos						
B00A - R1017 - Practical Activities - 1hb						
No Asbestos						
B00A - R1018 - Entry Vestibule						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

No Asbestos

B00A - R1019 - Lift

No Asbestos

B00A - R1020 - Withdrawal Space - 1hbFloor Coverings
Res/TextileVinyl Tiles (Under Floor
Covering/Carpet)

1936/B00A/R1021/Floor Coverings Res/Textile/S27

No Asbestos Detected**B00A - R1021 - Movement**Floor Coverings
Res/TextileVinyl Tiles (Under Floor
Covering/Carpet)

1936/B00A/R1021/Floor Coverings Res/Textile/S27

No Asbestos Detected**B00A - R1022 - Stairs**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1981 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

Interior**B00B - R0001 - Cleaning Distributed Store**

No Asbestos

B00B - R0002 - Toilets - Girls

Partition Walls (Cubicles) Compressed AC Sheet
1936/B00B/R0027/Partition Walls (Cubicles)/S1 **No Asbestos Detected**

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - Staff Toilet

Partition Walls (Cubicles) Compressed AC Sheet
1936/B00B/R0027/Partition Walls (Cubicles)/S1 **No Asbestos Detected**

B00B - R0005 - Disabled Toilet

No Asbestos

B00B - R0006 - Movement

No Asbestos

B00B - R0007 - Movement

No Asbestos

B00B - R0008 - Practical Activities - 1hb

No Asbestos

B00B - R0009 - Home Base

No Asbestos

B00B - R0010 - Practical Activities - 1hb

No Asbestos

B00B - R0011 - Home Base

No Asbestos

B00B - R0012 - Practical Activities - 1hb

No Asbestos

B00B - R0015 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0016 - Movement

No Asbestos

B00B - R0017 - Cleaning Distributed Store

Floor Coverings Res/Textile Vinyl Tiles
1936/B00B/R0017/Floor Coverings Res/Textile/S2 **No Asbestos Detected**

B00B - R0019 - Kiln Room

No Asbestos

B00B - R0020 - Home Base

No Asbestos

B00B - R0021 - Withdrawal Space - 1hb

No Asbestos

B00B - R0022 - Staff Room Annexe

No Asbestos

B00B - R0023 - Practical Activities - 1hb

No Asbestos

B00B - R0024 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
No Asbestos						
B00B - R0025 - Movement						
No Asbestos						
B00B - R0026 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet					
	1936/B00B/R0027/Partition Walls (Cubicles)/S1					No Asbestos Detected
B00B - R0027 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet					
	1936/B00B/R0027/Partition Walls (Cubicles)/S1					No Asbestos Detected
B00B - R0028 - Home Base						
No Asbestos						
B00B - R0029 - Movement						
No Asbestos						
B00B - R0030 - Movement						
No Asbestos						
B00B - R0031 - Special Programs Room						
No Asbestos						
B00B - R0032 - Stairs						
No Asbestos						
B00B - R0033 - Stairs						
No Asbestos						
B00B - R0034 - Stairs						
No Asbestos						
B00B - R1001 - Cleaning Distributed Store						
No Asbestos						
B00B - R1002 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet					
	1936/B00B/R0027/Partition Walls (Cubicles)/S1					No Asbestos Detected
B00B - R1003 - Staff Toilet						
Partition Walls (Cubicles)	Compressed AC Sheet					
	1936/B00B/R0027/Partition Walls (Cubicles)/S1					No Asbestos Detected
B00B - R1004 - Staff Toilet						
Partition Walls (Cubicles)	Compressed AC Sheet					
	1936/B00B/R0027/Partition Walls (Cubicles)/S1					No Asbestos Detected
B00B - R1005 - Movement						
No Asbestos						
B00B - R1006 - Drinking Facilities						
No Asbestos						
B00B - R1007 - Home Base						
No Asbestos						
B00B - R1008 - Practical Activities - 1hb						
No Asbestos						
B00B - R1009 - Movement						
No Asbestos						
B00B - R1010 - Withdrawal Space - 1hb						
No Asbestos						
B00B - R1011 - Staff Kitchen						
No Asbestos						
B00B - R1012 - General Storeroom						
No Asbestos						
B00B - R1013 - Staff Kitchen						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
B00B - R1014 - Home Base						
No Asbestos						
B00B - R1015 - Practical Activities - 1hb						
No Asbestos						
B00B - R1016 - Home Base						
No Asbestos						
B00B - R1017 - Distribution Board				Note: No inspection of live electrical installation.		
Floor Coverings Res/Textile	Vinyl Tiles					
	1936/B00B/R0017/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00B - R1018 - Practical Activities - 1hb						
No Asbestos						
B00B - R1019 - Home Base						
No Asbestos						
B00B - R1020 - Movement						
No Asbestos						
B00B - R1021 - Withdrawal Space - 1hb						
No Asbestos						
B00B - R1022 - Security Store						
No Asbestos						
B00B - R1023 - Cleaning Distributed Store						
Floor Coverings Res/Textile	Vinyl Tiles					
	1936/B00B/R0017/Floor Coverings Res/Textile/S2					No Asbestos Detected
B00B - R1024 - Practical Activities - 1hb						
No Asbestos						
B00B - R1025 - Home Base						
No Asbestos						
B00B - R1026 - Music Store						
No Asbestos						
B00B - R1027 - Practical Activities - 1hb						
No Asbestos						
B00B - R1028 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet					
	1936/B00B/R0027/Partition Walls (Cubicles)/S1					No Asbestos Detected
B00B - R1029 - Movement						
No Asbestos						
B00B - R1030 - Stairs						
No Asbestos						
B00B - R1031 - Stairs						
No Asbestos						
B00B - R1032 - Stairs						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00C - Pupil Facilities/General Learning - 1981 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Void	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
1936/B00C/Ceiling Void/S21				Chrysotile (white asbestos)		

Interior**B00C - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting					
1936/B00C/R0002/Ceiling Structures/Linings/S3				No Asbestos Detected		

B00C - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
1936/B00C/R0002/Ceiling Structures/Linings/S3				No Asbestos Detected		

B00C - R0003 - Canteen

No Asbestos

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Disabled Toilet

No Asbestos

B00C - R0006 - Uniform Shop

No Asbestos

B00C - R0007 - Cleaning Distributed Store

No Asbestos

B00C - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0009 - Movement

Ceiling Structures/Linings	Flat AC Sheeting					
1936/B00C/R0002/Ceiling Structures/Linings/S3				No Asbestos Detected		

B00C - R0010 - Movement

No Asbestos

B00C - R0011 - Home Base Store

No Asbestos

B00C - R0012 - Home Base

No Asbestos

B00C - R0013 - Practical Activities - 1hb

No Asbestos

B00C - R0014 - Practical Activities - 1hb

No Asbestos

B00C - R0015 - Home Base

No Asbestos

B00C - R0016 - Withdrawal Space - 1hb

No Asbestos

B00C - R0017 - General Assistant/Bulk Store

Ceiling Structures/Linings	Flat AC Sheeting					
1936/B00C/R0002/Ceiling Structures/Linings/S3				No Asbestos Detected		

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities - 1981 - Brick/Block (Brick/Block)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

Interior**B00D - R0001 - Movement**

Ceiling Structures/Linings Flat AC Sheetting 97m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

1936/B00D/R0001/Ceiling Structures/Linings/S4

Chrysotile (white asbestos)

B00D - R0002 - Hall Chair Store

No Asbestos

B00D - R0003 - Communal Space

No Asbestos

B00D - R0004 - General Storeroom

No Asbestos

B00D - R0005 - Cleaning Distributed Store

No Asbestos

B00D - R0006 - Toilets - Boys

Partition Walls (Cubicles) Compressed AC Sheet 6m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

1936/B00D/R0006/Partition Walls (Cubicles)/S5

Chrysotile (white asbestos)

B00D - R0007 - Movement

No Asbestos

B00D - R0008 - Raised Platform

No Asbestos

B00D - R0009 - Movement

No Asbestos

B00D - R0010 - Movement

No Asbestos

B00D - R0011 - Cleaning Distributed Store

No Asbestos

B00D - R0012 - Toilets - Girls

Partition Walls (Cubicles) Compressed AC Sheet 15m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

1936/B00D/R0006/Partition Walls (Cubicles)/S5

Chrysotile (white asbestos)

B00D - R0013 - Shower/Change

Partition Walls (Cubicles) Compressed AC Sheet 20m2 Middle portion Good Condition (1) Low (1) Low Priority (2-3)

1936/B00D/R0014/Partition Walls (Cubicles)/S26

Chrysotile (white asbestos)

B00D - R0014 - Shower/Change

Partition Walls (Cubicles) Compressed AC Sheet 10m2 Middle portion Good Condition (1) Low (1) Low Priority (2-3)

1936/B00D/R0014/Partition Walls (Cubicles)/S26

Chrysotile (white asbestos)

B00D - R0015 - Staff Shower/Change

No Asbestos

B00D - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0017 - Sports Store

No Asbestos

B00D - R0018 - Staff Kitchen

No Asbestos

B00D - R0019 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

No Asbestos

B00D - R0020 - Seminar/Study

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00E - Library - 1974 - Brick/Block (Brick/Block)						
Exterior						
Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Void	No Asbestos Found					
Interior						
B00E - R0001 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	103m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1936/B00E/R0001/Ceiling Structures/Linings/S24				Chrysotile (white asbestos)	
B00E - R0002 - Staff Toilet						
Ceiling Structures/Linings	Vermiculite	1936/B00E/R0002/Ceiling Structures/Linings/S6				
	No Asbestos Detected					
B00E - R0003 - Distribution Board						
				Note: No inspection of live electrical installation.		
No Asbestos						
B00E - R0004 - Cleaning Distributed Store						
Ceiling Structures/Linings	Vermiculite	1936/B00E/R0002/Ceiling Structures/Linings/S6				
	No Asbestos Detected					
B00E - R0005 - Staff Toilet						
Ceiling Structures/Linings	Vermiculite	1936/B00E/R0002/Ceiling Structures/Linings/S6				
	No Asbestos Detected					
B00E - R0006 - K.L.A. Store						
Ceiling Structures/Linings	Vermiculite	1936/B00E/R0002/Ceiling Structures/Linings/S6				
	No Asbestos Detected					
B00E - R0007 - K.L.A. Store						
Ceiling Structures/Linings	Vermiculite	1936/B00E/R0002/Ceiling Structures/Linings/S6				
	No Asbestos Detected					
B00E - R0008 - Seminar/Study						
Ceiling Structures/Linings	Vermiculite	1936/B00E/R0002/Ceiling Structures/Linings/S6				
	No Asbestos Detected					
B00E - R0009 - Seminar/Study						
Ceiling Structures/Linings	Vermiculite	1936/B00E/R0002/Ceiling Structures/Linings/S6				
	No Asbestos Detected					
B00E - R0010 - Reading Area						
Ceiling Structures/Linings	Vermiculite	1936/B00E/R0002/Ceiling Structures/Linings/S6				
	No Asbestos Detected					
B00E - R0011 - Special Programs Room						
Ceiling Structures/Linings	Vermiculite	1936/B00E/R0002/Ceiling Structures/Linings/S6				
	No Asbestos Detected					
B00E - R0012 - Library Office/Workroom						
Ceiling Structures/Linings	Vermiculite	1936/B00E/R0002/Ceiling Structures/Linings/S6				
	No Asbestos Detected					
B00E - R0013 - Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00F - General Learning - 1966 - Timber (Timber)**Exterior**

Eaves Linings	Flat AC Sheeting	60m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1936/B00F/Eaves Linings/S22					Chrysotile (white asbestos)
Underfloor Voids	Flat AC Sheeting					No Asbestos Detected
	1936/B00F/Underfloor Voids/S19					
Underfloor Void	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	1936/B00F/Underfloor Void/S20					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Void	No Asbestos Found					

Interior**B00F - R0001 - Home Base Store**

Floor Coverings Res/Textile	Vinyl Tiles					
	1936/B00F/R0001/Floor Coverings Res/Textile/S12					No Asbestos Detected

B00F - R0002 - Withdrawal Space - 1hb

No Asbestos

B00F - R0003 - Home Base

No Asbestos

B00F - R0004 - Practical Activities - 1hb

No Asbestos

B00F - R0005 - Practical Activities - 1hb

No Asbestos

B00F - R0006 - Practical Activities - 1hb

No Asbestos

B00F - R0007 - Withdrawal Space - 1hb

No Asbestos

B00F - R0008 - Home Base

No Asbestos

B00F - R0009 - Home Base Store

No Asbestos

B00F - R0010 - Home Base

No Asbestos

B00F - R0011 - Movement

No Asbestos

B00F - R0012 - Home Base Store

No Asbestos

B00F - R0013 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No				Test Result		

B00G - General Learning/Administration - 1961 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting	200m2	North, South, East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1936/B00F/Eaves Linings/S22					Chrysotile (white asbestos)
Ceiling Void	AC Fragments/Debris					No Asbestos Detected
	1936/B00G/Ceiling Void/S23					
Underfloor Void	No Asbestos Found					

Interior**B00G - R0002 - Staff Toilet**

Floor Coverings Res/Textile	Vinyl Tiles					
	1936/B00G/R0002/Floor Coverings Res/Textile/S16					No Asbestos Detected

B00G - R0003 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	1936/B00G/R0002/Floor Coverings Res/Textile/S16					No Asbestos Detected

B00G - R0004 - Movement

No Asbestos

B00G - R0005 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	1936/B00G/R0005/Floor Coverings Res/Textile/S17					No Asbestos Detected

B00G - R0006 - Practical Activities - 1hb

No Asbestos

B00G - R0007 - Home Base

No Asbestos

B00G - R0008 - Movement

No Asbestos

B00G - R0009 - Home Base

No Asbestos

B00G - R0010 - Home Base

No Asbestos

B00G - R0011 - Withdrawal Space - 1hb

No Asbestos

B00G - R0012 - Home Base Store

No Asbestos

B00G - R0013 - Home Base Store

No Asbestos

B00G - R0014 - Home Base

No Asbestos

B00G - R0015 - Practical Activities - 1hb

No Asbestos

B00G - R0017 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1936/B00G/R0016/Ceiling Structures/Linings/S13					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00G - R0018 - Movement

No Asbestos

B00G - R0019 - Home Base Store

No Asbestos

B00G - R0020 - Withdrawal Space - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
No Asbestos						
B00G - R0021 - Practical Activities - 1hb						
No Asbestos						
B00G - R0022 - Home Base						
No Asbestos						
B00G - R0023 - Home Base						
No Asbestos						
B00G - R0024 - Home Base						
No Asbestos						
B00G - R0025 - Toilets - Girls						
No Asbestos						
B00G - R0026 - Practical Activities - 1hb						
Floor Coverings Res/Textile	Vinyl Tiles					
	1936/B00G/R0026/Floor Coverings Res/Textile/S14				No Asbestos Detected	
B00G - R0027 - Toilets - Girls						
No Asbestos						
B00G - R0028 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet					
	1936/B00G/R0028/Partition Walls (Cubicles)/S15				No Asbestos Detected	
B00G - R0030 - Staff Room						
No Asbestos						
B00G - R0031 - External Movement						
Ceiling Structures/Linings	Flat AC Sheeting	119m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1936/B00G/R0031/Ceiling Structures/Linings/S25				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00K - General Learning - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00K - R0001 - External Movement**

No Asbestos

B00K - R0002 - Home Base

No Asbestos

B00K - R0003 - Home Base Store

No Asbestos

B00K - R0004 - Practical Activities

No Asbestos

B00K - R0005 - Access Shower/Toilet/Change

No Asbestos

B00K - R0006 - No Access

No Asbestos

B00K - R0007 - Laundry - S

No Asbestos

B00K - R0008 - Access Shower/Toilet/Change

No Asbestos

B00K - R0009 - Home Base

No Asbestos

B00K - R0010 - Home Base Store

No Asbestos

B00K - R0011 - External Movement

No Asbestos

B00K - R0012 - No Access

No Asbestos

B00K - R0013 - Withdrawal Space - 1hb

No Asbestos

B00K - R0014 - Home Base Store

No Asbestos

B00K - R0015 - Home Base

No Asbestos

B00K - R0016 - Practical Activities/Movement - 1hb

No Asbestos

B00K - R0017 - General Storeroom

No Asbestos

B00K - R0018 - General Storeroom

No Asbestos

B00K - R0019 - External Stairs

No Asbestos

B00K - R0020 - External Stairs

No Asbestos

B00K - R1001 - External Movement

No Asbestos

B00K - R1002 - Practical Activities/Movement - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No				Test Result	
B00K - R1003 - Home Base						
No Asbestos						
B00K - R1004 - Home Base Store						
No Asbestos						
B00K - R1005 - Withdrawal Space - 1hb						
No Asbestos						
B00K - R1006 - Deputy Principal						
No Asbestos						
B00K - R1007 - Practical Activities/Movement - 1hb						
No Asbestos						
B00K - R1008 - Home Base Store						
No Asbestos						
B00K - R1009 - Home Base						
No Asbestos						
B00K - R1010 - Withdrawal Space - 2hb						
No Asbestos						
B00K - R1011 - Home Base						
No Asbestos						
B00K - R1012 - Home Base Store						
No Asbestos						
B00K - R1013 - Practical Activities/Movement - 1hb						
No Asbestos						
B00K - R1014 - External Stairs						
No Asbestos						
B00K - R1015 - External Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00L - Pupil Facilities - 2011 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior**B00L - R0001 - External Movement**

No Asbestos

B00L - R0003 - Toilets - Girls

No Asbestos

B00L - R0004 - Disabled Shower/Toilet

No Asbestos

B00L - R0005 - Toilets - Boys

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No	Test Result				

B00M - Building Services - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D10693 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 16/10/2006

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11354 - Learning Unit - Standard With P.A.A. : Placement Date - 14/08/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15406 - Learning Unit - Standard With P.A.A. : Placement Date - 4/06/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017