Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Five Dock Public School (1920)**
Region :	**Sydney**
State Electorate :	**Drummoyne**
Local Government Area :	**Canada Bay**

Initial Survey :	**Noel Arnold & Associates : 17 - Mar - 2008**
Reviewed By :	**Parsons Brinckerhoff : 28 - Aug - 2015**

1920 - Five Dock Public School
Site Plan (12519)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - General Learning/Administration - 1929 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	80m2	Upper portion, Lower portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/Eaves Linings/S4					**Chrysotile (white asbestos)**
Awnings	Flat AC Sheeting	9m2	Over East and West entrances 3x	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/Awnings/S5					**Chrysotile (white asbestos)**
Underfloor Voids	No Asbestos Found					
Ceiling Voids	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Low Priority (2-3)
	1920/B00A/Ceiling Voids/S17					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

Interior

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - Entry Vestibule

Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**

B00A - R0003 - External Movement

No Asbestos

B00A - R0004 - Movement

No Asbestos

B00A - R0005 - Clerical Office

No Asbestos

B00A - R0006 - Interview

No Asbestos

B00A - R0007 - Duplicating Workroom

No Asbestos

B00A - R0008 - Interview

No Asbestos

B00A - R0009 - Principal

No Asbestos

B00A - R0010 - Security Store

No Asbestos

B00A - R0011 - Staff Room

No Asbestos

B00A - R0012 - Home Base

No Asbestos

B00A - R0013 - Home Base

No Asbestos

B00A - R0014 - External Movement

No Asbestos

B00A - R0015 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	9m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**

B00A - R0016 - Uniform Shop

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R0017 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R0018 - Staff Toilet						
Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R0019 - Movement						
No Asbestos						
B00A - R0020 - P.E. Store						
No Asbestos						
B00A - R0023 - External Movement						
No Asbestos						
B00A - R0024 - General Storeroom						
No Asbestos						
B00A - R0025 - Interview						
No Asbestos						
B00A - R0026 - Movement						
No Asbestos						
B00A - R0027 - Cleaning Supplies						
No Asbestos						
B00A - R0028 - Movement						
No Asbestos						
B00A - R0029 - Stairs						
No Asbestos						
B00A - R0030 - Stairs						
No Asbestos						
B00A - R0031 - Home Base						
No Asbestos						
B00A - R0032 - Movement						
Floor Coverings Res/Textile	Vinyl Sheet					
	1920/B00A/R0032/Floor Coverings Res/Textile/S21					**No Asbestos Detected**
B00A - R0033 - Home Base						
No Asbestos						
B00A - R1001 - Craft Store						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Vinyl Tiles					
	1920/B00A/R1001/Floor Coverings Res/Textile/S2					**No Asbestos Detected**
B00A - R1002 - Personal Effects Storage						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1003 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1004 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	48m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R1005 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1006 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1007 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1008 - Handwashing Facilities						
Ceiling Structures/Linings	Flat AC Sheeting	9m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1009 - Personal Effects Storage						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1010 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1011 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	16m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1012 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	21m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1013 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	47m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1014 - Home Base						
Ceiling Structures/Linings	Flat AC Sheeting	80m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1015 - Practical Activities - 1hb						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1016 - Staff Room Annexe						
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R1016/Floor Coverings Res/Textile/S3					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1017 - Home Base Store						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
Floor Coverings Res/Textile	Vinyl Tiles	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R1016/Floor Coverings Res/Textile/S3					**Chrysotile (white asbestos)**
B00A - R1018 - Withdrawal Space - 1hb						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Flat AC Sheeting	20m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1019 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	24m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1020 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R1021 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	13m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00A/R0002/Ceiling Structures/Linings/S1					**Chrysotile (white asbestos)**
B00A - R9001 - Cleaning Supplies						
No Asbestos						
B00A - R9002 - Movement						
No Asbestos						
B00A - R9003 - Movement						
No Asbestos						
B00A - R9004 - Sports Store						
No Asbestos						
B00A - R9005 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - Other-D.E.C. Admin/Other-After School Care - 1920 - Brick/Block (Brick/Block)

Exterior

Wall Cladding	Flat AC Sheeting	8m2	External adjacent Rooms BR0010 & BR0011, Upper Portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00B/Wall Cladding/S15					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00B - R0001 - Out Of School Hours Care Centre

No Asbestos

B00B - R0002 - Home Base

Chalk Board	Flat AC Sheeting	20m2	All surfaces, Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Chalk Board/S7					**Chrysotile (white asbestos)**
Wall Linings Internal	Flat AC Sheeting	8m2	West facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Wall Linings Internal/S8					**Chrysotile (white asbestos)**

B00B - R0003 - Home Base

Chalk Board	Flat AC Sheeting	10m2	All surfaces, Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Chalk Board/S7					**Chrysotile (white asbestos)**
Wall Linings Internal	Flat AC Sheeting	16m2	East facing, West facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Wall Linings Internal/S8					**Chrysotile (white asbestos)**

B00B - R0004 - Home Base

Chalk Board	Flat AC Sheeting	20m2	All surfaces, Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Chalk Board/S7					**Chrysotile (white asbestos)**
Wall Linings Internal	Flat AC Sheeting	8m2	East facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Wall Linings Internal/S8					**Chrysotile (white asbestos)**

B00B - R0005 - Home Base

Chalk Board	Flat AC Sheeting	20m2	All surfaces, Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Chalk Board/S7					**Chrysotile (white asbestos)**
Wall Linings Internal	Flat AC Sheeting	8m2	West facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Wall Linings Internal/S8					**Chrysotile (white asbestos)**

B00B - R0006 - Home Base

Chalk Board	Flat AC Sheeting	10m2	All surfaces, Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Chalk Board/S7					**Chrysotile (white asbestos)**
Wall Linings Internal	Flat AC Sheeting	16m2	East facing, West facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Wall Linings Internal/S8					**Chrysotile (white asbestos)**

B00B - R0007 - Home Base

Chalk Board	Flat AC Sheeting	20m2	All surfaces, Middle portion	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Chalk Board/S7					**Chrysotile (white asbestos)**
Wall Linings Internal	Flat AC Sheeting	8m2	East facing, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00B/R0007/Wall Linings Internal/S8					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00B - R0009 - Other - Regional Use						
No Asbestos						
B00B - R0010 - Other - Regional Use						
No Asbestos						
B00B - R0011 - Other - Regional Use						
No Asbestos						
B00B - R0012 - General Storeroom						
No Asbestos						
B00B - R0013 - Other - Regional Use						
No Asbestos						
B00B - R0014 - Other - Regional Use						
No Asbestos						
B00B - R0015 - Other - Regional Use						
Wall Linings Internal	Flat AC Sheeting	5m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00B/R0020/Wall Linings Internal/S6					**Chrysotile (white asbestos)**
B00B - R0016 - Movement						
No Asbestos						
B00B - R0017 - Movement						
No Asbestos						
B00B - R0018 - General Assistant/Bulk Store						
No Asbestos						
B00B - R0019 - Out Of School Hours Care Centre						
No Asbestos						
B00B - R0020 - Practical Activities - 1hb						
Wall Linings Internal	Flat AC Sheeting	1m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00B/R0020/Wall Linings Internal/S6					**Chrysotile (white asbestos)**
B00B - R0021 - Movement						
Wall Linings Internal	Flat AC Sheeting	5m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00B/R0020/Wall Linings Internal/S6					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - Pupil Facilities - 1978 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Low Priority (2-3)
	1920/B00C/Ceiling Voids/S20				**Chrysotile (white asbestos)**	
Underfloor Voids	No Asbestos Found					

Interior

B00C - R0001 - Canteen

No Asbestos

B00C - R0002 - Canteen Office/Store

No Asbestos

B00C - R0003 - Canteen Office/Store

No Asbestos

B00C - R0004 - Toilets - Boys

Ceiling Structures/Linings	Flat AC Sheeting	23m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00C/R0005/Ceiling Structures/Linings/S9				**Chrysotile (white asbestos)**	
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00C/R0005/Partition Walls (Cubicles)/S10				**Chrysotile (white asbestos)**	

B00C - R0005 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	29m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00C/R0005/Ceiling Structures/Linings/S9				**Chrysotile (white asbestos)**	
Partition Walls (Cubicles)	Compressed AC Sheet	30m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00C/R0005/Partition Walls (Cubicles)/S10				**Chrysotile (white asbestos)**	

B00C - R0006 - External Movement

No Asbestos

B00C - R0007 - Main Switch Board

Ceiling Structures/Linings	Flat AC Sheeting	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00C/R0005/Ceiling Structures/Linings/S9				**Chrysotile (white asbestos)**	
Electrical Mounting Board	Resinous Board	1Unit	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00C/R0007/Electrical Mounting Board/S19				**Chrysotile (white asbestos)**	

B00C - R0009 - Disabled Toilet

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - Library - 1980 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00D - R0001 - External Movement

No Asbestos

B00D - R0002 - Reading Area

No Asbestos

B00D - R0003 - Library Office/Workroom

No Asbestos

B00D - R0004 - Library Office/Workroom

No Asbestos

B00D - R0005 - Distribution Board

Note: No inspection of live electrical installation.

Wall Linings Internal	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00D/R0005/Wall Linings Internal/S11				**Chrysotile (white asbestos)**	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - General Learning - 1876 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00E - R0003 - Security Store

No Asbestos

B00E - R0006 - External Movement

No Asbestos

B00E - R0007 - Home Base

No Asbestos

B00E - R0009 - Clerical Office

No Asbestos

B00E - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	8m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00E/R0010/Ceiling Structures/Linings/S12					**Chrysotile (white asbestos)**

B00E - R0013 - External Movement

No Asbestos

B00E - R0015 - Home Base

No Asbestos

B00E - R0017 - Movement

No Asbestos

B00E - R0018 - External Movement

No Asbestos

B00E - R0019 - Home Base

No Asbestos

B00E - R0020 - Home Base

No Asbestos

B00E - R0022 - Movement

No Asbestos

B00E - R0023 - Movement

No Asbestos

B00E - R0024 - Practical Activities - 2hb

No Asbestos

B00E - R0025 - Home Base

No Asbestos

B00E - R0026 - Ramp

No Asbestos

B00E - R0027 - Home Base

Recently Modified Space	Requires Inspection

B00E - R0028 - Cleaning Distributed Store

Recently Modified Space	Requires Inspection

B00E - R0029 - Staff Toilet

Recently Modified Space	Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - Pre-School Facilities - 1978 - Brick/Veneer (Brick/Veneer)

Exterior

Eaves Linings	Flat AC Sheeting	25m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00F/Eaves Linings/S14					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Compressed AC Sheet	20m2	Ceiling North-East Floor to Room R0010 above)	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
	1920/B00F/Underfloor Voids/S16					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

Interior

B00F - R0003 - Staff Toilet - Pre

No Asbestos

B00F - R0004 - Kitchen - Pre

No Asbestos

B00F - R0010 - Toilets - Boys/Girls - Pre

No Asbestos

B00F - R0011 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00F/R0019/Ceiling Structures/Linings/S18					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00F - R0012 - Movement

No Asbestos

B00F - R0013 - Practical Activities - Pre

No Asbestos

B00F - R0014 - Practical Activities - Pre

No Asbestos

B00F - R0015 - General Storeroom - Pre

No Asbestos

B00F - R0016 - General Storeroom - Pre

No Asbestos

B00F - R0017 - Withdrawal - Pre

No Asbestos

B00F - R0018 - General Storeroom - Pre

No Asbestos

B00F - R0019 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	16m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00F/R0019/Ceiling Structures/Linings/S18					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00F - R0020 - Staff Room - Pre

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - Pupil Facilities - 1911 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00G - R0001 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00C/R0005/Partition Walls (Cubicles)/S10					**Chrysotile (white asbestos)**

B00G - R0002 - Sports Store

No Asbestos

B00G - R0003 - Cleaning Distributed Store

No Asbestos

B00G - R0004 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	1920/B00C/R0005/Partition Walls (Cubicles)/S10					**Chrysotile (white asbestos)**

B00G - R0005 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - Shed - 1955 - Timber (Timber)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00H - R0001 - Garden Store

No Asbestos

B00H - R0002 - General Storeroom

No Asbestos

B00H - R0003 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00J - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior

B00J - R0001 - Communal Space

No Asbestos

B00J - R0002 - Raised Platform

No Asbestos

B00J - R0003 - Hall Chair Store

No Asbestos

B00J - R0004 - Communal/Performance Store

No Asbestos

B00J - R0005 - P.E. Store

No Asbestos

B00J - R0006 - Toilet - Lobby

No Asbestos

B00J - R0007 - Toilets - Girls

No Asbestos

B00J - R0008 - Sound Cupboard

No Asbestos

B00J - R0009 - Toilet - Lobby

No Asbestos

B00J - R0010 - Toilets - Boys

No Asbestos

B00J - R0011 - Cleaning Distributed Store

No Asbestos

B00J - R0012 - General Storeroom

No Asbestos

B00J - R0013 - Main Switch Board

No Asbestos

B00J - R0014 - Access Shower/Toilet/Change

No Asbestos

B00J - R0015 - Covered Outdoor Learning Area

No Asbestos

B00J - R0016 - Movement

No Asbestos

B00J - R0017 - Movement

No Asbestos

B00J - R0018 - General Storeroom

No Asbestos

B00J - R0019 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11686 - Learning Unit - Standard With P.A.A. : Placement Date - 12/01/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017