Asbestos Register

(Hazardous Materials and Risk Assessment)

School :	**Walters Road Public School (4310)**
Region :	**Western Sydney**
State Electorate :	**Blacktown**
Local Government Area :	**Blacktown**

Initial Survey :	**Noel Arnold & Associates : 19 - Mar - 2008**
Reviewed By :	**Parsons Brinckerhoff : 01 - Nov - 2016**

4310 - Walters Road Public School
Site Plan (14734)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00A - General Learning - 1963 - Brick/Block (Brick/Block)

Exterior

Gable Ends	Compressed AC Sheet	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00A/Gable Ends/S43					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Eaves Linings	Compressed AC Sheet	60m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Eaves Linings/S39					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Underfloor Voids	Flat AC Sheeting					
	4310/B00A/Underfloor Voids/S44					**No Asbestos Detected**
Ceiling Void	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	4310/B00A/Underfloor Voids/S46					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

Interior

B00A - R0001 - Staff Room Annexe

No Asbestos

B00A - R0002 - Staff Toilet

Wall Linings Internal	Compressed AC Sheet	10m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00A/R0002/Wall Linings Internal/S6					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Floor Coverings Res/Textile	Textile					
	4310/B00A/R0002/Floor Coverings Res/Textile/S2					**No Asbestos Detected**

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Personal Effects Storage

No Asbestos

B00A - R0005 - General Storeroom

No Asbestos

B00A - R0006 - External Movement

Ceiling Structures/Linings	Compressed AC Sheet	5m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00A/R0006/Ceiling Structures/Linings/S3					**Clerical Error - No Sample Taken**

B00A - R0007 - Home Base

No Asbestos

B00A - R0008 - Home Base Store

No Asbestos

B00A - R0009 - Home Base

No Asbestos

B00A - R0010 - Home Base Store

No Asbestos

B00A - R0011 - Personal Effects Storage

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - External Movement

Ceiling Structures/Linings	Compressed AC Sheet	5m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00A/R0023/Ceiling Structures/Linings/S37					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00A - R0014 - Staff Room						
No Asbestos						
B00A - R0015 - Personal Effects Storage						
No Asbestos						
B00A - R0016 - Home Base Store						
No Asbestos						
B00A - R0017 - Practical Activities - 1hb						
No Asbestos						
B00A - R0018 - Home Base						
No Asbestos						
B00A - R0019 - Home Base Store						
No Asbestos						
B00A - R0020 - Toilets - Boys/Girls						
Wall Linings Internal	Compressed AC Sheet	2m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00A/R0002/Wall Linings Internal/S1					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Floor Coverings Res/Textile	Textile					
	4310/B00A/R0002/Floor Coverings Res/Textile/S2					**No Asbestos Detected**
B00A - R0021 - Personal Effects Storage						
No Asbestos						
B00A - R0022 - Movement						
No Asbestos						
B00A - R0023 - Outdoor Learning Area						
Ceiling Structures/Linings	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00A/R0023/Ceiling Structures/Linings/S37					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Infill above door	Compressed AC Sheet	0.5m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00A/R0023/Infill above door/S38					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00A - R9001 - General Storeroom						
Ceiling Structures/Linings	Compressed AC Sheet	40m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00A/R9001/Ceiling Structures/Linings/S7					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
B00A - R9002 - Sports Store						
Ceiling Structures/Linings	Compressed AC Sheet	12m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00A/R9001/Ceiling Structures/Linings/S7					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Wall Linings Internal	Compressed AC Sheet					
	4310/B00A/R9002/Wall Linings Internal/S8					**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00B - General Learning/Administration - 1963 - Brick/Block (Brick/Block)

Exterior

Gable Ends	Compressed AC Sheet	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Gable Ends/S42					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Eaves Linings	Compressed AC Sheet	60m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Eaves Linings/S39					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Underfloor Voids	Flat AC Sheeting					
	4310/B00B/Underfloor Voids/S45					**No Asbestos Detected**
Ceiling Void	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	4310/B00B/Underfloor Voids/S47					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

Interior

B00B - R0001 - Cleaning Distributed Store

No Asbestos

B00B - R0002 - Duplicating Workroom

Floor Coverings Res/Textile	Vinyl Sheet					
	4310/B00B/R0002/Floor Coverings Res/Textile/S36					**No Asbestos Detected**

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - External Movement

Ceiling Structures/Linings	Compressed AC Sheet	5m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00B/R0004/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Infill above door	Compressed AC Sheet	0.5m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00B/R0004/Infill above door/S35					**Chrysotile (white asbestos)**

B00B - R0005 - Home Base

No Asbestos

B00B - R0006 - Home Base Store

No Asbestos

B00B - R0007 - Personal Effects Storage

No Asbestos

B00B - R0008 - Movement

No Asbestos

B00B - R0009 - External Movement

Ceiling Structures/Linings	Compressed AC Sheet	5m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00B/R0004/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Infill above door	Compressed AC Sheet	0.5m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00B/R0004/Infill above door/S35					**Chrysotile (white asbestos)**

B00B - R0010 - Personal Effects Storage

No Asbestos

B00B - R0011 - Home Base Store

No Asbestos

B00B - R0012 - Home Base

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
No Asbestos						
B00B - R0013 - Home Base						
No Asbestos						
B00B - R0014 - Home Base Store						
No Asbestos						
B00B - R0015 - Personal Effects Storage						
No Asbestos						
B00B - R0016 - Movement						
No Asbestos						
B00B - R0017 - External Movement						
Ceiling Structures/Linings	Compressed AC Sheet	5m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00B/R0004/Ceiling Structures/Linings/S5					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Infill above door	Compressed AC Sheet	0.5m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00B/R0004/Infill above door/S35					**Chrysotile (white asbestos)**
B00B - R0018 - Home Base						
No Asbestos						
B00B - R0019 - Home Base Store						
No Asbestos						
B00B - R9001 - Community Clinic						
No Asbestos						
B00B - R9002 - Community Clinic						
No Asbestos						
B00B - R9003 - Community Clinic						
No Asbestos						
B00B - R9004 - Community Clinic						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00C - General Learning - 1963 - Brick/Block (Brick/Block)

Exterior

Gable Ends	Compressed AC Sheet	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Gable Ends/S42					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Eaves Linings	Compressed AC Sheet	30m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Eaves Linings/S39					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Void	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris					
	4310/B00C/Underfloor Voids/S48					**No Asbestos Detected**

Interior

B00C - R0001 - Home Base

No Asbestos

B00C - R0002 - Home Base Store

No Asbestos

B00C - R0003 - Personal Effects Storage

No Asbestos

B00C - R0004 - External Movement

Ceiling Structures/Linings	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/R0004/Ceiling Structures/Linings/S32					**Chrysotile (white asbestos)**
Infill above door	Compressed AC Sheet	0.5m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/R0004/Infill above door/S33					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00C - R0005 - Home Base

No Asbestos

B00C - R0006 - Home Base Store

No Asbestos

B00C - R0007 - Home Base

No Asbestos

B00C - R0008 - Home Base Store

No Asbestos

B00C - R0009 - Personal Effects Storage

No Asbestos

B00C - R0010 - Movement

No Asbestos

B00C - R0011 - External Movement

Ceiling Structures/Linings	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/R0004/Ceiling Structures/Linings/S32					**Chrysotile (white asbestos)**
Infill above door	Compressed AC Sheet	0.5m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/R0004/Infill above door/S33					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00D - Administration/Staff Facilities - 1963 - Brick/Block (Brick/Block)

Exterior

Gable Ends	Compressed AC Sheet	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Gable Ends/S42					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Eaves Linings	Compressed AC Sheet	60m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Eaves Linings/S39					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Void	No Asbestos Found					

Interior

B00D - R0001 - Principal

Infill panel to wlndow	Compressed AC Sheet					
	4310/B00D/R0009/Infill panel to wlndow/S26					**No Asbestos Detected**

B00D - R0002 - Sick Bay

No Asbestos

B00D - R0003 - Clerical Office

No Asbestos

B00D - R0004 - General Storeroom

No Asbestos

B00D - R0005 - Staff Toilet

Wall Linings Internal	Compressed AC Sheet	6m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R0006/Wall Linings Internal/S28					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00D - R0006 - Staff Toilet

Wall Linings Internal	Compressed AC Sheet	15m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R0006/Wall Linings Internal/S28					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00D - R0007 - Cleaning Distributed Store

Non Accessible

B00D - R0008 - Cleaning Distributed Store

Infill panel to wlndow	Compressed AC Sheet					
	4310/B00D/R0009/Infill panel to wlndow/S26					**No Asbestos Detected**

B00D - R0009 - Staff Room

Infill panel to wlndow	Compressed AC Sheet					
	4310/B00D/R0009/Infill panel to wlndow/S26					**No Asbestos Detected**

B00D - R0010 - Movement

No Asbestos

B00D - R0011 - Entry Vestibule

No Asbestos

B00D - R0012 - External Movement

Ceiling Structures/Linings	Compressed AC Sheet	4m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R0017/Ceiling Structures/Linings/S27					**Chrysotile (white asbestos)**
Infill above door	Compressed AC Sheet	0.5m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R0012/Infill above door/S34					**Chrysotile (white asbestos)**

B00D - R0013 - Deputy Principal

No Asbestos

B00D - R0014 - General Storeroom

No Asbestos

B00D - R0015 - General Storeroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
No Asbestos						
B00D - R0016 - Movement						
No Asbestos						
B00D - R0017 - External Movement						
Ceiling Structures/Linings	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R0017/Ceiling Structures/Linings/S27					**Chrysotile (white asbestos)**
Infill above door	Compressed AC Sheet	0.5m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R0012/Infill above door/S34					**Chrysotile (white asbestos)**
B00D - R0018 - General Storeroom						
No Asbestos						
B00D - R0019 - Communal Space						
No Asbestos						
B00D - R0020 - General Storeroom						
No Asbestos						
B00D - R0021 - General Storeroom						
No Asbestos						
B00D - R0022 - Movement						
No Asbestos						
B00D - R0023 - External Movement						
Ceiling Structures/Linings	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R0017/Ceiling Structures/Linings/S27					**Chrysotile (white asbestos)**
Infill above door	Compressed AC Sheet	0.5m2	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R0012/Infill above door/S34					**Chrysotile (white asbestos)**
B00D - R0024 - Home Base						
No Asbestos						
B00D - R0025 - Home Base Store						
No Asbestos						
B00D - R9001 - General Assistant/Bulk Store						
Ceiling Structures/Linings	Compressed AC Sheet	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R9002/Ceiling Structures/Linings/S19					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Wall Linings Internal	Compressed AC Sheet	20m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R9002/Wall Linings Internal/S20					**Chrysotile (white asbestos)**
Electrical Mounting Board	Resinous Board	1Unit	North facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R9001/Electrical Mounting Board/S25					**Chrysotile (white asbestos)**
B00D - R9002 - Garden Store						
Ceiling Structures/Linings	Compressed AC Sheet	28m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R9002/Ceiling Structures/Linings/S19					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Wall Linings Internal	Compressed AC Sheet	20m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00D/R9002/Wall Linings Internal/S20					**Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00E - General Learning - 1963 - Brick/Block (Brick/Block)

Exterior

Gable Ends	Compressed AC Sheet	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Gable Ends/S42					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Eaves Linings	Compressed AC Sheet	30m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Eaves Linings/S39					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Void	No Asbestos Found					
Underfloor Voids	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	4310/B00E/Underfloor Voids/S49					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

Interior

B00E - R0001 - Home Base

No Asbestos

B00E - R0002 - Home Base Store

No Asbestos

B00E - R0003 - Personal Effects Storage

No Asbestos

B00E - R0004 - External Movement

Ceiling Structures/Linings	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00E/R0004/Ceiling Structures/Linings/S30					**Chrysotile (white asbestos)**
Infill above door	Compressed AC Sheet	0.5m2	South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00E/R0004/Infill above door/S31					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00E - R0005 - Home Base

No Asbestos

B00E - R0006 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00F - General Learning - 1963 - Brick/Block (Brick/Block)

Exterior

Gable Ends	Compressed AC Sheet	20m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Gable Ends/S42					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Eaves Linings	Compressed AC Sheet	30m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00F/Eaves Linings/S40					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Void	No Asbestos Found					
Underfloor Voids	Non Accessible Area - No Access - No key fits lock on site					

Interior

B00F - R0001 - Home Base

No Asbestos

B00F - R0002 - Home Base Store

No Asbestos

B00F - R0003 - Personal Effects Storage

No Asbestos

B00F - R0004 - Movement

No Asbestos

B00F - R0005 - External Movement

Ceiling Structures/Linings	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00F/R0005/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00F - R0006 - Home Base

No Asbestos

B00F - R0007 - Home Base Store

No Asbestos

B00F - R0008 - Home Base

No Asbestos

B00F - R0009 - Home Base Store

No Asbestos

B00F - R0010 - Personal Effects Storage

No Asbestos

B00F - R0011 - Movement

No Asbestos

B00F - R0012 - External Movement

Ceiling Structures/Linings	Compressed AC Sheet	5m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00F/R0005/Ceiling Structures/Linings/S29					**Chrysotile (white asbestos) , Amosite (brown asbestos)**

B00F - R0013 - Home Base

No Asbestos

B00F - R0014 - Home Base Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00G - General Learning - 1964 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Gable Ends	Compressed AC Sheet	20m2	North facing, South facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Gable Ends/S42					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Eaves Linings	Compressed AC Sheet	40m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00C/Eaves Linings/S39					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Wall Cladding	Compressed AC Sheet	40m2	West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00G/R1007/Wall Linings Internal/S14					**Chrysotile (white asbestos)**
Ceiling Void	No Asbestos Found					

Interior

B00G - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	23m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	4310/B00G/R0001/Partition Walls (Cubicles)/S10					**Clerical Error - No Sample Taken**
Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00G - R0002 - Cleaning Distributed Store

Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00G - R0003 - External Movement

Wall Linings Internal	Compressed AC Sheet	20m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00G/R1007/Wall Linings Internal/S14					**Chrysotile (white asbestos)**

B00G - R0004 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	15m2	All surfaces	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
	4310/B00G/R0001/Partition Walls (Cubicles)/S9					**Chrysotile (white asbestos)**
Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00G - R0005 - Security Store

No Asbestos

B00G - R0006 - General Storeroom

No Asbestos

B00G - R0007 - Home Base

Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00G - R0008 - Home Base Store

Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**

B00G - R0009 - Personal Effects Storage

Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**
Floor Coverings Res/Textile	Emerald floor tiles					
	4310/B00G/R0009/Floor Coverings Res/Textile/S15					**No Asbestos Detected**
Floor Coverings Res/Textile	Mottled floor tiles					
	4310/B00G/R0009/Floor Coverings Res/Textile/S16					**No Asbestos Detected**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Floor Coverings Res/Textile	Green floor tiles	13m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00G/R0009/Floor Coverings Res/Textile/S17					**Chrysotile (white asbestos)**
B00G - R0010 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00G - R0011 - Home Base Store						
Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00G - R0012 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00G - R0013 - Home Base Store						
Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00G - R0014 - Personal Effects Storage						
Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**
Floor Coverings Res/Textile	Mottled floor tiles	14m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00G/R0009/Floor Coverings Res/Textile/S17					**Chrysotile (white asbestos)**
B00G - R0015 - Distribution Board						Note: No inspection of live electrical installation.
Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0015/Ceiling Structures/Linings/S52					**No Asbestos Detected**
B00G - R0016 - Home Base						
Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00G - R0017 - Home Base Store						
Ceiling Structures/Linings	Vermiculite					
	4310/B00G/R0001/Ceiling Structures/Linings/S11					**No Asbestos Detected**
B00G - R0018 - Movement						
No Asbestos						
B00G - R0019 - Sports Store						
No Asbestos						
B00G - R0020 - Stairs						
No Asbestos						
B00G - R0021 - Stairs						
No Asbestos						
B00G - R1001 - Interview						
No Asbestos						
B00G - R1002 - Staff Toilet						
No Asbestos						
B00G - R1003 - Staff Toilet						
No Asbestos						
B00G - R1004 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles					
	4310/B00G/R1004/Floor Coverings Res/Textile/S12					**No Asbestos Detected**
B00G - R1005 - General Assistant/Bulk Store						
No Asbestos						
B00G - R1006 - General Storeroom						
No Asbestos						
B00G - R1007 - Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
Ceiling Structures/Linings	Compressed AC Sheet	122m2	All surfaces	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00G/R1007/Ceiling Structures/Linings/S13					**Chrysotile (white asbestos)**
Wall Linings Internal	Compressed AC Sheet	30m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00G/R1007/Wall Linings Internal/S14					**Chrysotile (white asbestos)**
B00G - R1008 - Movement						
No Asbestos						
B00G - R1009 - Library Office/Workroom						
No Asbestos						
B00G - R1010 - Reading Area						
No Asbestos						
B00G - R1011 - Home Base						
No Asbestos						
B00G - R1012 - Home Base Store						
No Asbestos						
B00G - R1013 - Personal Effects Storage						
No Asbestos						
B00G - R1014 - Distribution Board						Note: No inspection of live electrical installation.
Floor Coverings Res/Textile	Vinyl Tiles					
	4310/B00G/R1004/Floor Coverings Res/Textile/S12					**No Asbestos Detected**
B00G - R1015 - Home Base						
No Asbestos						
B00G - R1016 - Home Base Store						
No Asbestos						
B00G - R1017 - General Assistant/Bulk Store						
No Asbestos						
B00G - R1018 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00G/R1018/Ceiling Structures/Linings/S51					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
B00G - R1019 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00G/R1018/Ceiling Structures/Linings/S51					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00H - General Learning/Pupil Facilities - 1968 - Timber (Timber)

Exterior

Underfloor Voids	AC Fragments/Debris	1m2	Variable positions	Poor Condition - Extensive Damage (4)	Low (1)	Medium Priority (4-5)
	4310/B00H/Underfloor Voids/S50					**Chrysotile (white asbestos) , Amosite (brown asbestos)**
Ceiling Void	No Asbestos Found					

Interior

B00H - R0001 - External Movement

No Asbestos

B00H - R0002 - General Storeroom

No Asbestos

B00H - R0003 - Home Base

No Asbestos

B00H - R0004 - Uniform Shop

No Asbestos

B00H - R0005 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00J - Pupil Facilities - 1963 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Compressed AC Sheet	20m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00J/Eaves Linings/S41					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**
Ceiling Voids - Flat Roof	No Asbestos Found					

Interior

B00J - R0001 - Drinking Facilities

No Asbestos

B00J - R0002 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00J/R0002/Partition Walls (Cubicles)/S4					**Chrysotile (white asbestos)**

B00J - R0003 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	25m2	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00J/R0002/Partition Walls (Cubicles)/S4					**Chrysotile (white asbestos)**

B00J - R0004 - Drinking Facilities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00K - Pupil Facilities/Building Services - 1963 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Compressed AC Sheet	10m2	East facing, West facing	Good Condition (1)	Low (1)	Low Priority (2-3)
	4310/B00J/Eaves Linings/S41					**Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)**

Interior

B00K - R0001 - Drinking Facilities

No Asbestos

B00K - R0002 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	
	4310/B00K/R0002/Partition Walls (Cubicles)/S18	**No Asbestos Detected**

B00K - R0003 - Cleaning Supplies

No Asbestos

B00K - R0004 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	
	4310/B00K/R0002/Partition Walls (Cubicles)/S18	**No Asbestos Detected**

B00K - R0005 - Drinking Facilities

No Asbestos

B00K - R0006 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00L - Administration - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00L - R0001 - Entry Vestibule
No Asbestos

B00L - R0002 - Interview
No Asbestos

B00L - R0003 - Principal
No Asbestos

B00L - R0004 - Deputy Principal
No Asbestos

B00L - R0005 - Staff Room
No Asbestos

B00L - R0006 - Staff Room
No Asbestos

B00L - R0007 - Security Store
No Asbestos

B00L - R0008 - Interview
No Asbestos

B00L - R0009 - Staff Toilet
No Asbestos

B00L - R0010 - Staff Toilet
No Asbestos

B00L - R0011 - Staff Toilet
No Asbestos

B00L - R0012 - Cleaning Distributed Store
No Asbestos

B00L - R0013 - Disabled Shower/Toilet
No Asbestos

B00L - R0014 - Sick Bay
No Asbestos

B00L - R0015 - Clerical Office
No Asbestos

B00L - R0016 - External Movement
No Asbestos

B00L - R0017 - External Movement
No Asbestos

B00L - R0018 - Clerical Office
No Asbestos

B00L - R0019 - Deputy Principal
No Asbestos

B00L - R0020 - Movement
No Asbestos

B00L - R0021 - Plant
No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority

Sample No	Test Result

B00M - Communal Facilities/Other - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00M - R0001 - Communal Space

No Asbestos

B00M - R0002 - Raised Platform

No Asbestos

B00M - R0003 - Sound Cupboard

No Asbestos

B00M - R0004 - Access Shower/Toilet

No Asbestos

B00M - R0005 - Toilets - Girls

No Asbestos

B00M - R0006 - Garden Store

No Asbestos

B00M - R0007 - Other

No Asbestos

B00M - R0008 - Hall Chair Store

No Asbestos

B00M - R0009 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00M - R0010 - Communal/Performance Store

No Asbestos

B00M - R0011 - Cleaning Distributed Store

No Asbestos

B00M - R0012 - P.E. Store

No Asbestos

B00M - R0013 - Toilets - Boys

No Asbestos

B00M - R0014 - Canteen

No Asbestos

B00M - R0015 - Canteen Office/Store

No Asbestos

B00M - R0016 - Canteen Covered Area

No Asbestos

B00M - R0017 - Covered Outdoor Learning Area

No Asbestos

B00M - R0018 - External Movement

No Asbestos

B00M - R0019 - Toilet - Lobby

No Asbestos

B00M - R0020 - Movement

No Asbestos

B00M - R0021 - External Movement

No Asbestos

B00M - R0022 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**
B00M - R0023 - Movement						
No Asbestos						
B00M - R0024 - Movement						
No Asbestos						
B00M - R0025 - Movement						
No Asbestos						
B00M - R0026 - Movement						
No Asbestos						
B00M - R0027 - External Movement						
No Asbestos						
B00M - R0028 - Toilet - Lobby						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

B00N - Electrical Services - 2010 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00N - R0001 - Main Switch Board

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					**Test Result**

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017