


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Alstonville High School (8578)  
**Region :** North Coast  
**State Electorate :** Ballina  
**Local Government Area :** Ballina

**Initial Survey :** Noel Arnold & Associates : 11 - Jun - 2008  
**Reviewed By :** Parsons Brinckerhoff : 08 - Oct - 2015



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Multi Purpose Facilities - 1992 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00A - R0001 - Multi-Purpose Space**

No Asbestos

**B00A - R0002 - Sport Equipment Store**

No Asbestos

**B00A - R0003 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0004 - Interview/Meeting**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00A - R0005 - Staff Shower**

No Asbestos

**B00A - R0006 - Movement**

No Asbestos

**B00A - R0007 - Shower/Change**

No Asbestos

**B00A - R0008 - Stage**

No Asbestos

**B00A - R0009 - Shower/Change**

No Asbestos

**B00A - R0010 - Movement**

No Asbestos

**B00A - R0011 - Toilets-Boys**

No Asbestos

**B00A - R0012 - Toilets-Girls**

No Asbestos

**B00A - R0013 - Toilets-Disabled**

No Asbestos

**B00A - R0014 - Cleaning Store - Distributed**

No Asbestos

**B00A - R0015 - General Storeroom**

No Asbestos

**B00A - R0016 - Student Canteen**

No Asbestos

**B00A - R0017 - General Assistants**

No Asbestos

**B00A - R0018 - General Storeroom**

No Asbestos

**B00A - R0019 - Uniform Shop**

No Asbestos

**B00A - R0020 - Garden Store Room**

No Asbestos

**B00A - R0021 - Sport Equipment Store**

No Asbestos

**B00A - R0023 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Administration - 1992 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00B - R0001 - Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0002 - Secure Storeroom**

No Asbestos

**B00B - R0003 - Administration - Clerical**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0004 - Duplicating Workroom**

No Asbestos

**B00B - R0005 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0006 - Cleaning Store - Distributed**

No Asbestos

**B00B - R0007 - Clinic - Boys**

No Asbestos

**B00B - R0008 - Staff - Toilet**

No Asbestos

**B00B - R0009 - Staff - Toilet**

No Asbestos

**B00B - R0010 - Clinic - Girls**

No Asbestos

**B00B - R0011 - Staff - Toilet**

No Asbestos

**B00B - R0012 - Ancillary Staff**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0013 - Deputy Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0014 - Pupil Entry**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0015 - Deputy Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0016 - Administration - Clerical**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0017 - Administration - Clerical**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0018 - Public Entry**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0020 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00B - R0021 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	<b>Sample No</b>					<b>Test Result</b>

No Asbestos

**B00B - R0022 - External Movement**

No Asbestos

**B00B - R0023 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Science Learning - 1987 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00C - R0001 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0002 - Cleaning Store - Distributed**

No Asbestos

**B00C - R0003 - Laboratory L.S.**

No Asbestos

**B00C - R0004 - Preparation**

No Asbestos

**B00C - R0005 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0006 - Laboratory L.S.**

No Asbestos

**B00C - R0007 - Preparation**

No Asbestos

**B00C - R0008 - Laboratory L.S.**

No Asbestos

**B00C - R0009 - Chemical Store**

No Asbestos

**B00C - R0010 - Apparatus Store**

No Asbestos

**B00C - R0011 - Laboratory L.S.**

No Asbestos

**B00C - R0012 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00C - R0013 - Preparation**

No Asbestos

**B00C - R0014 - Laboratory L.S.**

No Asbestos

**B00C - R0015 - Cleaning Supplies Store**

No Asbestos

**B00C - R0016 - Staff - Toilet**

No Asbestos

**B00C - R0017 - Darkroom Space**

No Asbestos

**B00C - R0018 - Toilets-Girls**

Partition Walls (Cubicles)	Flat AC Sheeting 8578/B00C/R0018/Partition Walls (Cubicles)/S2
----------------------------	---

No Asbestos Detected

**B00C - R0019 - Toilets-Boys**

Partition Walls (Cubicles)	Flat AC Sheeting 8578/B00C/R0018/Partition Walls (Cubicles)/S2
----------------------------	---

No Asbestos Detected

**B00C - R0020 - Interview/Office - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00C - R0021 - External Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings

Flat AC Sheeting  
8578/B00C/R0021/Ceiling Structures/Linings/S1

**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - General Learning/Library - 1986 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00D - R0001 - Main Switchroom**

No Asbestos

**B00D - R0002 - Cleaning Store - Distributed**

No Asbestos

**B00D - R0003 - General Learning Space**

No Asbestos

**B00D - R0004 - General Learning Space**

No Asbestos

**B00D - R0005 - General Learning Space**

No Asbestos

**B00D - R0006 - Computer Learning Space**

No Asbestos

**B00D - R0007 - Resources Store**

No Asbestos

**B00D - R0008 - Seminar**

No Asbestos

**B00D - R0009 - Toilets-Girls**

Partition Walls (Cubicles)	Flat AC Sheeting					
	8578/B00D/R0010/Partition Walls (Cubicles)/S3					<b>No Asbestos Detected</b>

**B00D - R0010 - Toilets-Boys**

Partition Walls (Cubicles)	Flat AC Sheeting					
	8578/B00D/R0010/Partition Walls (Cubicles)/S3					<b>No Asbestos Detected</b>

**B00D - R0011 - Movement**

No Asbestos

**B00D - R0012 - External Movement**

No Asbestos

**B00D - R0013 - General Learning Space**

No Asbestos

**B00D - R0014 - Senior Study**

No Asbestos

**B00D - R0015 - Staff Study**

No Asbestos

**B00D - R0016 - Staff Study**

No Asbestos

**B00D - R0017 - Resources Store**

No Asbestos

**B00D - R0018 - Cleaning Store - Distributed**

No Asbestos

**B00D - R0021 - Interview/Office - Type 1**

No Asbestos

**B00D - R0022 - Staff - Toilet**

No Asbestos

**B00D - R0023 - Seminar**

No Asbestos

**B00D - R0024 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00D - R0025 - Resources Store</b>						
No Asbestos						
<b>B00D - R0026 - Toilets-Disabled</b>						
No Asbestos						
<b>B00D - R0028 - Movement</b>						
No Asbestos						
<b>B00D - R0029 - Main Area</b>						
No Asbestos						
<b>B00D - R0038 - Movement</b>						
No Asbestos						
<b>B00D - R0039 - Resources Store</b>						
No Asbestos						
<b>B00D - R0040 - Lift</b>						
No Asbestos						
<b>B00D - R0041 - Movement</b>						
No Asbestos						
<b>B00D - R0042 - External Movement</b>						
No Asbestos						
<b>B00D - R0043 - Tiered Learning Area</b>						
No Asbestos						
<b>B00D - R0044 - Movement</b>						
No Asbestos						
<b>B00D - R0045 - Workroom</b>						
No Asbestos						
<b>B00D - R0046 - Resources Store</b>						
No Asbestos						
<b>B00D - R0047 - Audio Visual Workroom</b>						
No Asbestos						
<b>B00D - R0048 - Main Area</b>						
No Asbestos						
<b>B00D - R0049 - Seminar</b>						
No Asbestos						
<b>B00D - R0050 - Seminar</b>						
No Asbestos						
<b>B00D - R0051 - Resources Store</b>						
No Asbestos						
<b>B00D - R0052 - Staff Study</b>						
No Asbestos						
<b>B00D - R0053 - Movement</b>						
No Asbestos						
<b>B00D - R0054 - Staff Study</b>						
No Asbestos						
<b>B00D - R0055 - External Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8578/B00D/R0055/Ceiling Structures/Linings/S5					<b>No Asbestos Detected</b>
<b>B00D - R0056 - Stairs</b>						
No Asbestos						
<b>B00D - R0057 - Stairs</b>						
No Asbestos						
<b>B00D - R0058 - Stairs</b>						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00D - R0059 - Stairs</b>						
No Asbestos						
<b>B00D - R0060 - External Movement</b>						
No Asbestos						
<b>B00D - R1002 - Plant Space</b>						
No Asbestos						
<b>B00D - R1003 - General Learning Space</b>						
No Asbestos						
<b>B00D - R1004 - General Learning Space</b>						
No Asbestos						
<b>B00D - R1005 - General Learning Space</b>						
No Asbestos						
<b>B00D - R1006 - General Learning Space</b>						
No Asbestos						
<b>B00D - R1007 - Toilets-Boys</b>						
Partition Walls (Cubicles)	Compressed AC Sheet		8578/B00D/R0010/Partition Walls (Cubicles)/S3			<b>No Asbestos Detected</b>
<b>B00D - R1008 - Seminar</b>						
No Asbestos						
<b>B00D - R1009 - Interview/Office - Type 1</b>						
No Asbestos						
<b>B00D - R1010 - Resources Store</b>						
No Asbestos						
<b>B00D - R1011 - Staff - Toilet</b>						
No Asbestos						
<b>B00D - R1012 - Commonroom</b>						
No Asbestos						
<b>B00D - R1013 - Staff - Toilet</b>						
No Asbestos						
<b>B00D - R1014 - Distribution Board Cupboard</b>						
					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00D - R1015 - Resources Store</b>						
No Asbestos						
<b>B00D - R1016 - Plant Space</b>						
No Asbestos						
<b>B00D - R1017 - Staff Study</b>						
No Asbestos						
<b>B00D - R1018 - Movement</b>						
Ceiling Structures/Linings	Flat AC Sheeting		8578/B00D/R1018/Ceiling Structures/Linings/S6			<b>No Asbestos Detected</b>
<b>B00D - R1019 - General Learning Space</b>						
No Asbestos						
<b>B00D - R1020 - General Learning Space</b>						
No Asbestos						
<b>B00D - R1021 - General Learning Space</b>						
No Asbestos						
<b>B00D - R1022 - General Learning Space</b>						
No Asbestos						
<b>B00D - R1023 - Study Space</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - R1024 - Toilets-Girls**

Partition Walls (Cubicles) Compressed AC Sheet  
 8578/B00D/R0010/Partition Walls (Cubicles)/S3 **No Asbestos Detected**

**B00D - R1025 - Movement**

No Asbestos

**B00D - R1026 - Movement**

No Asbestos

**B00D - R1027 - Plant Space**

No Asbestos

**B00D - R1028 - Movement**

No Asbestos

**B00D - R1029 - Lift**

No Asbestos

**B00D - R1030 - Movement**

No Asbestos

**B00D - R1031 - Movement**

No Asbestos

**B00D - R1032 - Other-Not Used**

No Asbestos

**B00D - R1033 - Stairs**

No Asbestos

**B00D - R1034 - Stairs**

No Asbestos

**B00D - R1035 - Stairs**

No Asbestos

**B00D - R1036 - Stairs**

No Asbestos

**B00D - R1037 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Technological & Applied Studies - 1986 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00E - R0001 - Movement**

No Asbestos

**B00E - R0002 - Metal Technology L.S.**

No Asbestos

**B00E - R0003 - Welding Area**

No Asbestos

**B00E - R0004 - Materials Store**

No Asbestos

**B00E - R0005 - L.P.G. Store**

No Asbestos

**B00E - R0006 - Metal Technology Bay**

No Asbestos

**B00E - R0007 - Materials Store**

No Asbestos

**B00E - R0008 - Welding/Hot Metals Area**

No Asbestos

**B00E - R0009 - Metal Technology L.S.**

No Asbestos

**B00E - R0010 - Wood Technology L.S.**

No Asbestos

**B00E - R0011 - Wood Technology Bay**

No Asbestos

**B00E - R0012 - Wood Technology L.S.**

No Asbestos

**B00E - R0013 - Dust Extraction Space**

No Asbestos

**B00E - R0014 - Cleaning Store - Distributed**

No Asbestos

**B00E - R0015 - Seminar/Technology Space**

No Asbestos

**B00E - R0016 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0017 - External Movement**

Ceiling Structures/Linings	Flat AC Sheeting 8578/B00E/R0017/Ceiling Structures/Linings/S7
----------------------------	---

**No Asbestos Detected**

**B00E - R0018 - Stairs**

No Asbestos

**B00E - R1001 - Movement**

No Asbestos

**B00E - R1002 - Staff Study**

No Asbestos

**B00E - R1003 - Stairs**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Technological & Applied Studies/Music - 1986 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00F - R0005 - Staff Study**

No Asbestos

**B00F - R0006 - Food Technology L.S.**

No Asbestos

**B00F - R0007 - Preparation**

No Asbestos

**B00F - R0008 - Resources Store**

No Asbestos

**B00F - R0009 - Food Technology L.S.**

No Asbestos

**B00F - R0010 - Movement**

No Asbestos

**B00F - R0011 - Lift**

No Asbestos

**B00F - R0012 - Textiles Technology L.S.**

No Asbestos

**B00F - R0013 - Laundry**

No Asbestos

**B00F - R0014 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0015 - Textiles Technology L.S.**

No Asbestos

**B00F - R0016 - Movement**

No Asbestos

**B00F - R0017 - External Movement**

No Asbestos

**B00F - R0018 - External Movement**

No Asbestos

**B00F - R0019 - Stairs**

No Asbestos

**B00F - R1001 - Staff Study**

No Asbestos

**B00F - R1002 - Cleaning Store - Distributed**

No Asbestos

**B00F - R1003 - Resources Store**

No Asbestos

**B00F - R1004 - Movement**

No Asbestos

**B00F - R1005 - Staff - Toilet**

No Asbestos

**B00F - R1006 - Resources Store**

No Asbestos

**B00F - R1007 - Music Learning Space**

No Asbestos

**B00F - R1008 - Resources Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

**B00F - R1009 - Music Learning Space**

No Asbestos

**B00F - R1010 - Movement**

No Asbestos

**B00F - R1011 - Stairs**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00G - Art/Technological & Applied Studies - 1986 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior****B00G - R0001 - Art Learning Space**

No Asbestos

**B00G - R0002 - Visual Arts Workshop**

No Asbestos

**B00G - R0003 - Art Learning Space**

No Asbestos

**B00G - R0004 - Resources Store**

No Asbestos

**B00G - R0005 - Kiln Space**

No Asbestos

**B00G - R0006 - Resources Store**

No Asbestos

**B00G - R0007 - Staff Study**

No Asbestos

**B00G - R0008 - Staff Study**

No Asbestos

**B00G - R0009 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R0010 - Staff - Toilet**

No Asbestos

**B00G - R0011 - Cleaning Store - Distributed**

No Asbestos

**B00G - R0012 - Seminar**

No Asbestos

**B00G - R0013 - Computer Learning Space**

No Asbestos

**B00G - R0014 - Design L.S.**

No Asbestos

**B00G - R0015 - Art Learning Space**

No Asbestos

**B00G - R0016 - Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Agricultural Science - 1986 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00H - R0010 - Animal Space**

Recently Modified Space Requires Inspection

**B00H - R0011 - Workroom**

Recently Modified Space Requires Inspection

**B00H - R0012 - Seminar**

Recently Modified Space Requires Inspection

**B00H - R0013 - External Movement**

Recently Modified Space Requires Inspection

**B00H - R0014 - Toilets-Unisex**

Recently Modified Space Requires Inspection

**B00H - R0015 - Staff Study**

Recently Modified Space Requires Inspection

**B00H - R0016 - Machine Storage**

Recently Modified Space Requires Inspection

**B00H - R0017 - Animal Space**

Recently Modified Space Requires Inspection

**B00H - R0018 - Animal Space**

Recently Modified Space Requires Inspection

**B00H - R0019 - Animal Space**

Recently Modified Space Requires Inspection

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - General Learning - 1994 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior****B00J - R0001 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R0002 - Movement**

No Asbestos

**B00J - R0003 - Seminar**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R0004 - Computer Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R0005 - Computer Resource**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R0006 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R0007 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R0008 - General Learning Space**

No Asbestos

**B00J - R0009 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R0010 - External Movement**

No Asbestos

**B00J - R0011 - External Movement**

No Asbestos

**B00J - R0012 - Stairs**

No Asbestos

**B00J - R0013 - External Stairs**

No Asbestos

**B00J - R1001 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R1002 - Movement**

No Asbestos

**B00J - R1003 - Staff Study**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R1004 - Cleaning Store - Distributed**

No Asbestos

**B00J - R1005 - Resource/Project Store**

No Asbestos

**B00J - R1006 - Interview/Office - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00J - R1007 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00J - R1008 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00J - R1009 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00J - R1010 - General Learning Space**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00J - R1011 - External Movement**

No Asbestos

**B00J - R1012 - Security Store**

No Asbestos

**B00J - R1013 - Stairs**

No Asbestos

**B00J - R1014 - External Stairs**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Administration/Building Services - 2008 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00K - R0001 - General Assistants**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Performing Arts - 2009 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

**Interior**

**B00L - R0001 - External Movement**

No Asbestos

**B00L - R0002 - Performance Workshop**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Storage - - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Void	Requires Inspection
Underfloor Void	Requires Inspection

**Interior**

**B00M - R0001 - Materials Store**

Recently Modified Space	Requires Inspection
-------------------------	---------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 840 - D11051 - Girls Toilet : Placement Date - 7/06/2006**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				2.88 m2

**Interior**

**R1 - Toilets-Girls**

Toilet partitions	Compressed AC Sheet	Assumed Asbestos				4 m2
End wall panel	Flat AC Sheet	Assumed Asbestos				36 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				18 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017