


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Barnsley Public School (1138)
Region : Hunter/Central Coast
State Electorate : Cessnock
Local Government Area : Lake Macquarie

Initial Survey : Noel Arnold & Associates : 22 - Apr - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0003 - Staff Kitchen

No Asbestos

B00A - R0004 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0005 - Sick Bay - Shower/Toilet

No Asbestos

B00A - R0006 - Sick Bay

No Asbestos

B00A - R0007 - Duplicating Workroom

No Asbestos

B00A - R0008 - Clerical Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0009 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0010 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0011 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0012 - General Storeroom

No Asbestos

B00A - R0013 - Cleaning Distributed Store

No Asbestos

B00A - R0014 - Staff Toilet

No Asbestos

B00A - R0015 - Staff Toilet

No Asbestos

B00A - R0016 - Staff Toilet

No Asbestos

B00A - R0017 - Security Store

No Asbestos

B00A - R0018 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0019 - Movement

No Asbestos

B00A - R0020 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00B - General Learning - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Withdrawal Space - 1hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0004 - Practical Activities - 1hb

No Asbestos

B00B - R0005 - Personal Effects Storage

No Asbestos

B00B - R0006 - Personal Effects Storage

No Asbestos

B00B - R0007 - Practical Activities - 1hb

No Asbestos

B00B - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0009 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0011 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0013 - Practical Activities - 1hb

No Asbestos

B00B - R0014 - Personal Effects Storage

No Asbestos

B00B - R0015 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0017 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0019 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R0020 - Personal Effects Storage

No Asbestos

B00B - R0021 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0022 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0023 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Reading Area**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0003 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Tiered Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0002 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0003 - Plant

No Asbestos

B00D - R0004 - Cleaning Distributed Store

No Asbestos

B00D - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1994 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Personal Effects Storage

No Asbestos

B00E - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0003 - Practical Activities - 1hb

No Asbestos

B00E - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0006 - Practical Activities - 1hb

No Asbestos

B00E - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0008 - Personal Effects Storage

No Asbestos

B00E - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0011 - Personal Effects Storage

No Asbestos

B00E - R0012 - Practical Activities - 1hb

No Asbestos

B00E - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0014 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0015 - Practical Activities - 1hb

No Asbestos

B00E - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0017 - Personal Effects Storage

No Asbestos

B00E - R0018 - Personal Effects Storage

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0019 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0020 - Distribution Board

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00E - R0021 - Movement

No Asbestos

B00E - R0022 - Movement

No Asbestos

B00E - R0023 - Movement

No Asbestos

B00E - R0024 - Movement

No Asbestos

B00E - R0025 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00F - R0001 - Movement**

No Asbestos

B00F - R0002 - Toilets - Girls

No Asbestos

B00F - R0003 - Kiln Room

No Asbestos

B00F - R0004 - Toilets - Boys

No Asbestos

B00F - R0005 - Personal Effects Storage

No Asbestos

B00F - R0006 - Home Base StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0007 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0008 - Withdrawal Space - 1hb**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0009 - Home Base**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0010 - Home Base Store**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00F - R0011 - Personal Effects Storage**

No Asbestos

B00F - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0013 - Movement

No Asbestos

B00F - R0014 - Practical Activities - 1hb

No Asbestos

B00F - R0015 - Practical Activities - 1hb

No Asbestos

B00F - R0016 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1994 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Canteen

No Asbestos

B00G - R0002 - Canteen Office/Store

No Asbestos

B00G - R0003 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00H - Communal Facilities - 1994 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00H - R0001 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0002 - General Assistant/Bulk Store

No Asbestos

B00H - R0003 - Cleaning Supplies

No Asbestos

B00H - R0004 - Cleaning Supplies

No Asbestos

B00H - R0005 - Garden Store

No Asbestos

B00H - R0006 - Toilets - Girls

No Asbestos

B00H - R0007 - Shower/Change

No Asbestos

B00H - R0008 - Movement

No Asbestos

B00H - R0009 - Raised Platform

No Asbestos

B00H - R0010 - Communal Space

No Asbestos

B00H - R0011 - Movement

No Asbestos

B00H - R0012 - Toilets - Boys

No Asbestos

B00H - R0013 - Sports Store

No Asbestos

B00H - R0014 - P.E. Store

No Asbestos

B00H - R0015 - Hall Chair Store

No Asbestos

B00H - R0016 - General Assistant/Bulk Store

No Asbestos

B00H - R0017 - Disabled Toilet

No Asbestos

B00H - R0018 - Movement

No Asbestos

B00H - R0019 - General Storeroom

No Asbestos

B00H - R0020 - Movement

No Asbestos

B00H - R0021 - Movement

No Asbestos

B00H - R0022 - Movement

No Asbestos

B00H - R0023 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00I - General Learning/Special Purpose Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - External Movement

No Asbestos

B00I - R0002 - Practical Activities - 1hb

No Asbestos

B00I - R0003 - Home Base Store

No Asbestos

B00I - R0004 - Home Base

No Asbestos

B00I - R0005 - Withdrawal Space - 2hb

No Asbestos

B00I - R0006 - Practical Activities - 1hb

No Asbestos

B00I - R0007 - Home Base

No Asbestos

B00I - R0008 - Home Base Store

No Asbestos

B00I - R0009 - Main Switch Board

No Asbestos

B00I - R0010 - Practical Activities - 1hb

No Asbestos

B00I - R0011 - Withdrawal Space - 1hb

No Asbestos

B00I - R0012 - Home Base

No Asbestos

B00I - R0013 - Home Base Store

No Asbestos

B00I - R0014 - Special Programs Store

No Asbestos

B00I - R0015 - Special Programs Room

No Asbestos

B00I - R0016 - Garden Store

No Asbestos

B00I - R0017 - General Assistant/Bulk Store

No Asbestos

B00I - R0018 - Sports Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017