


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Buxton Public School (1460)
Region : South Western Sydney
State Electorate : Wollondilly
Local Government Area : Wollondilly

Initial Survey : Noel Arnold & Associates : 21 - May - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1997 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0005 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0006 - Interview

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0007 - Cleaning Distributed Store

No Asbestos

B00A - R0008 - Main Switch Board

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0014 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0015 - Staff Toilet

No Asbestos

B00A - R0016 - Staff Toilet

No Asbestos

B00A - R0017 - Staff Toilet

No Asbestos

B00A - R0018 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0019 - Communications Cupboard

No Asbestos

B00A - R0020 - Security Store

No Asbestos

B00A - R0021 - Duplicating Workroom

No Asbestos

B00A - R0023 - Movement

No Asbestos

B00A - R0024 - Sick Bay

No Asbestos

B00A - R0025 - Access Shower/Toilet

No Asbestos

B00A - R0026 - Movement

No Asbestos

B00A - R0027 - General Storeroom

No Asbestos

B00A - R0028 - Community Clinic

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R0029 - Staff Kitchen

No Asbestos

B00A - R0030 - Staff Room

No Asbestos

B00A - R0031 - Staff Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities - 1997 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00B - R0001 - Canteen**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0002 - Garden Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0003 - Distribution Board

Note: No inspection of live electrical installation.

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0004 - General Assistant/Bulk Store

No Asbestos

B00B - R0005 - Cleaning Supplies

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0006 - Cleaning Supplies

No Asbestos

B00B - R0007 - Movement

No Asbestos

B00B - R0008 - Toilets - Girls

No Asbestos

B00B - R0009 - Staff Shower/Change

No Asbestos

B00B - R0010 - Movement

No Asbestos

B00B - R0011 - Raised Platform

No Asbestos

B00B - R0012 - Movement

No Asbestos

B00B - R0013 - Communal Space

No Asbestos

B00B - R0014 - Movement

No Asbestos

B00B - R0015 - Disabled Toilet

No Asbestos

B00B - R0016 - Cleaning Distributed Store

No Asbestos

B00B - R0017 - Hall Chair Store

No Asbestos

B00B - R0018 - P.E. Store

No Asbestos

B00B - R0019 - Sports Store

No Asbestos

B00B - R0020 - Toilets - Boys

No Asbestos

B00B - R0021 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Library - 1997 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Practical Activities - 1hb**

No Asbestos

B00C - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0003 - Home Base Store

No Asbestos

B00C - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0006 - Practical Activities - 1hb

No Asbestos

B00C - R0007 - Home Base Store

No Asbestos

B00C - R0008 - Communications Cupboard

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0009 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0010 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0011 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0012 - Seminar/Study

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0013 - Toilets - Girls

No Asbestos

B00C - R0014 - Toilets - Boys

No Asbestos

B00C - R0015 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00C - R0016 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Home Base Store

No Asbestos

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0006 - Home Base Store

No Asbestos

B00D - R0007 - Practical Activities - 1hb

No Asbestos

B00D - R0008 - Practical Activities - 1hb

No Asbestos

B00D - R0009 - Home Base Store

No Asbestos

B00D - R0010 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0011 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0012 - Toilets - Girls

No Asbestos

B00D - R0013 - Cleaning Distributed Store

No Asbestos

B00D - R0014 - Kiln Room

No Asbestos

B00D - R0015 - Toilets - Boys

No Asbestos

B00D - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0017 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1997 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00E - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0003 - Practical Activities - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - Home Base Store

No Asbestos

B00E - R0008 - Practical Activities - 1hb

No Asbestos

B00E - R0009 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - External Movement

No Asbestos

B00F - R0002 - Practical Activities/Movement - 1hb

No Asbestos

B00F - R0003 - Home Base Store

No Asbestos

B00F - R0004 - Home Base

No Asbestos

B00F - R0005 - Withdrawal Space - 2hb

No Asbestos

B00F - R0006 - Home Base

No Asbestos

B00F - R0007 - Home Base Store

No Asbestos

B00F - R0008 - Practical Activities/Movement - 1hb

No Asbestos

B00F - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0010 - Personal Effects Storage

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Cleaning Distributed Store

No Asbestos

B00G - R0002 - Movement

No Asbestos

B00G - R0003 - Special Programs Room

No Asbestos

B00G - R0004 - Special Programs Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Storage - 2008 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017