


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Blackwell Public School (4559)
Region : Western Sydney
State Electorate : Mulgoa
Local Government Area : Penrith

Initial Survey : Noel Arnold & Associates : 05 - May - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Communal Facilities/Pupil Facilities - 1984 - Brick/Block (Brick/Block)

Exterior

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00A - R0001 - Drinking Facilities

No Asbestos

B00A - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 4559/B00A/R0002/Partition Walls (Cubicles)/S4					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00A - R0003 - Movement

No Asbestos

B00A - R0004 - Canteen

No Asbestos

B00A - R0005 - Canteen Office/Store

No Asbestos

B00A - R0006 - Canteen Office/Store

No Asbestos

B00A - R0007 - Communal Space

No Asbestos

B00A - R0008 - Raised Platform

No Asbestos

B00A - R0009 - Movement

No Asbestos

B00A - R0010 - Disabled Toilet

No Asbestos

B00A - R0011 - General Storeroom

No Asbestos

B00A - R0012 - General Storeroom

Partition Walls (Cubicles)	Compressed AC Sheet 4559/B00A/R0002/Partition Walls (Cubicles)/S4					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00A - R0013 - General Assistant/Bulk Store

No Asbestos

B00A - R0014 - Movement

No Asbestos

B00A - R0015 - P.E. Store

No Asbestos

B00A - R0016 - Hall Chair Store

No Asbestos

B00A - R0017 - Cleaning Distributed Store

No Asbestos

B00A - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0019 - General Storeroom

No Asbestos

B00A - R0020 - Movement

No Asbestos

B00A - R0021 - Toilets - Boys

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Partition Walls (Cubicles) Compressed AC Sheet
 4559/B00A/R0002/Partition Walls (Cubicles)/S4

No Asbestos Detected

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1984 - Brick/Block (Brick/Block)

Exterior

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Cleaning Distributed Store

No Asbestos

B00B - R0003 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 4559/B00D/R0019/Partition Walls (Cubicles)/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00B - R0004 - Movement

No Asbestos

B00B - R0005 - Home Base Store

No Asbestos

B00B - R0006 - Movement

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00B - R0007 - Home Base

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00B - R0008 - Withdrawal Space - 1hb

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00B - R0009 - Home Base

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00B - R0010 - Movement

No Asbestos

B00B - R0011 - Home Base Store

No Asbestos

B00B - R0012 - General Storeroom

No Asbestos

B00B - R0013 - Movement

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00B - R0014 - Practical Activities - 1hb

No Asbestos

B00B - R0015 - Movement

No Asbestos

B00B - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0017 - Toilets - Boys

No Asbestos

B00B - R0018 - Movement

No Asbestos

B00B - R0019 - Home Base Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0020 - Movement						
No Asbestos						
B00B - R0021 - Home Base						
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	4559/B00F/In-fill-panel/S1					
B00B - R0022 - Withdrawal Space - 1hb						
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	4559/B00F/In-fill-panel/S1					
B00B - R0023 - Home Base						
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	4559/B00F/In-fill-panel/S1					
B00B - R0024 - Home Base Store						
No Asbestos						
B00B - R0025 - Movement						
No Asbestos						
B00B - R0026 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning - 1984 - Brick/Block (Brick/Block)

Exterior

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0002 - Toilets - Boys

No Asbestos

B00C - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0004 - Movement

No Asbestos

B00C - R0005 - Practical Activities - 1hb

No Asbestos

B00C - R0006 - Movement

No Asbestos

B00C - R0007 - Movement

No Asbestos

B00C - R0008 - Home Base Store

No Asbestos

B00C - R0009 - Home Base

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00C - R0010 - Movement

No Asbestos

B00C - R0011 - Withdrawal Space - 1hb

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00C - R0012 - Home Base

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00C - R0013 - Movement

No Asbestos

B00C - R0014 - Home Base Store

No Asbestos

B00C - R0015 - Toilets - Girls

No Asbestos

B00C - R0016 - Movement

No Asbestos

B00C - R0017 - Cleaning Distributed Store

No Asbestos

B00C - R0018 - Movement

No Asbestos

B00C - R0019 - Movement

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00C - R0020 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0021 - Home Base Store						
No Asbestos						
B00C - R0022 - Home Base						
No Asbestos						
B00C - R0023 - Withdrawal Space - 1hb						
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	4559/B00F/In-fill-panel/S1					
B00C - R0024 - Movement						
No Asbestos						
B00C - R0025 - Home Base						
In-fill-panel	Flat AC Sheeting					No Asbestos Detected
	4559/B00F/In-fill-panel/S1					
B00C - R0026 - Home Base Store						
No Asbestos						
B00C - R0027 - General Storeroom						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning - 1984 - Brick/Block (Brick/Block)**Exterior**

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior**B00D - R0001 - Movement**

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	-----------------------------

B00D - R0002 - Movement

No Asbestos

B00D - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0004 - Toilets - Boys

No Asbestos

B00D - R0005 - Movement

No Asbestos

B00D - R0006 - Home Base

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	-----------------------------

B00D - R0007 - Home Base Store

No Asbestos

B00D - R0008 - Movement

No Asbestos

B00D - R0009 - Withdrawal Space - 1hb

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	-----------------------------

B00D - R0010 - Movement

No Asbestos

B00D - R0011 - Home Base Store

No Asbestos

B00D - R0012 - Home Base

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	-----------------------------

B00D - R0013 - General Storeroom

No Asbestos

B00D - R0014 - Movement

No Asbestos

B00D - R0015 - Practical Activities - 1hb

No Asbestos

B00D - R0016 - Movement

No Asbestos

B00D - R0017 - Movement

No Asbestos

B00D - R0018 - Cleaning Distributed Store

No Asbestos

B00D - R0019 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet 4559/B00D/R0019/Partition Walls (Cubicles)/S2					No Asbestos Detected
----------------------------	--	--	--	--	--	-----------------------------

B00D - R0020 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00D - R0021 - Home Base

In-fill-panel	Flat AC Sheeting					
	4559/B00F/In-fill-panel/S1					No Asbestos Detected

B00D - R0022 - Home Base Store

No Asbestos

B00D - R0023 - Movement

No Asbestos

B00D - R0024 - Withdrawal Space - 1hb

In-fill-panel	Flat AC Sheeting					
	4559/B00F/In-fill-panel/S1					No Asbestos Detected

B00D - R0025 - Home Base

In-fill-panel	Flat AC Sheeting					
	4559/B00F/In-fill-panel/S1					No Asbestos Detected

B00D - R0026 - Home Base Store

No Asbestos

B00D - R0027 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Administration - 1984 - Brick/Block (Brick/Block)

Exterior

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00E - R0001 - Movement

No Asbestos

B00E - R0002 - Staff Toilet

No Asbestos

B00E - R0003 - Staff Toilet

No Asbestos

B00E - R0004 - Cleaning Distributed Store

No Asbestos

B00E - R0005 - Movement

No Asbestos

B00E - R0006 - Movement

No Asbestos

B00E - R0007 - Practical Activities - 1hb

No Asbestos

B00E - R0008 - Movement

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00E - R0009 - Home Base

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00E - R0010 - Home Base Store

No Asbestos

B00E - R0011 - Movement

No Asbestos

B00E - R0012 - Withdrawal Space - 1hb

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00E - R0013 - Home Base

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00E - R0014 - Movement

No Asbestos

B00E - R0015 - Home Base Store

No Asbestos

B00E - R0016 - Movement

No Asbestos

B00E - R0017 - Movement

No Asbestos

B00E - R0018 - Staff Toilet

Partition Walls (Cubicles)	Compressed AC Sheet 4559/B00E/R0019/Partition Walls (Cubicles)/S3					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

B00E - R0019 - Staff Toilet

Partition Walls (Cubicles)	Compressed AC Sheet 4559/B00E/R0019/Partition Walls (Cubicles)/S3					No Asbestos Detected
----------------------------	--	--	--	--	--	----------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R0020 - Movement						
No Asbestos						
B00E - R0021 - Entry Vestibule						
No Asbestos						
B00E - R0022 - Movement						
No Asbestos						
B00E - R0023 - General Storeroom						
No Asbestos						
B00E - R0024 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00E - R0025 - Security Store						
No Asbestos						
B00E - R0026 - Entry Vestibule						
No Asbestos						
B00E - R0027 - Clerical Office						
No Asbestos						
B00E - R0028 - Duplicating Workroom						
No Asbestos						
B00E - R0029 - Sick Bay						
No Asbestos						
B00E - R0030 - Interview						
No Asbestos						
B00E - R0031 - Deputy Principal						
No Asbestos						
B00E - R0032 - Deputy Principal						
No Asbestos						
B00E - R0033 - Principal						
No Asbestos						
B00E - R0034 - Movement						
No Asbestos						
B00E - R0035 - Staff Room						
No Asbestos						
B00E - R0036 - Staff Room Annexe						
No Asbestos						
B00E - R0037 - Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library/Tiered Learning - 1984 - Brick/Block (Brick/Block)

Exterior

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
Ceiling Voids	Requires Inspection					
Underfloor Voids	Requires Inspection					

Interior

B00F - R0002 - Movement

No Asbestos

B00F - R0003 - Reading Area

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00F - R0004 - Library Office/Workroom

No Asbestos

B00F - R0005 - Garden Store

No Asbestos

B00F - R0006 - Movement

No Asbestos

B00F - R0007 - Communications Room

No Asbestos

B00F - R0008 - Cleaning Distributed Store

No Asbestos

B00F - R0009 - Disabled Toilet

No Asbestos

B00F - R0010 - Interview

In-fill-panel	Flat AC Sheeting 4559/B00F/In-fill-panel/S1					No Asbestos Detected
---------------	--	--	--	--	--	----------------------

B00F - R0011 - Toilets - Boys

No Asbestos

B00F - R0012 - Movement

No Asbestos

B00F - R0013 - Toilets - Girls

No Asbestos

B00F - R0014 - General Storeroom

No Asbestos

B00F - R0016 - Cleaning Supplies

No Asbestos

B00F - R0017 - Special Programs Room

No Asbestos

B00F - R0018 - Special Programs Room

No Asbestos

B00F - R0019 - Plant

No Asbestos

B00F - R0020 - Main Switch Board

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Other-Community Use - 1985 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Out Of School Hours Care Centre

Non Accessible

B00G - R0002 - Other-Community Use

Non Accessible

B00G - R0003 - Other-Community Use

Non Accessible

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - External Movement

No Asbestos

B00H - R0002 - Home Base Store

No Asbestos

B00H - R0003 - Home Base

No Asbestos

B00H - R0004 - Withdrawal Space - 2hb

No Asbestos

B00H - R0005 - Home Base

No Asbestos

B00H - R0006 - Home Base Store

No Asbestos

B00H - R0007 - Practical Activities

No Asbestos

B00H - R0008 - Practical Activities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - External Movement

No Asbestos

B00I - R0002 - Home Base Store

No Asbestos

B00I - R0003 - Home Base

No Asbestos

B00I - R0004 - Withdrawal Space - 2hb

No Asbestos

B00I - R0005 - Home Base

No Asbestos

B00I - R0006 - Home Base Store

No Asbestos

B00I - R0007 - Home Base Store

No Asbestos

B00I - R0008 - Home Base

No Asbestos

B00I - R0009 - Withdrawal Space - 2hb

No Asbestos

B00I - R0010 - Home Base

No Asbestos

B00I - R0011 - Home Base Store

No Asbestos

B00I - R0012 - Practical Activities

No Asbestos

B00I - R0013 - Practical Activities

No Asbestos

B00I - R0014 - Practical Activities

No Asbestos

B00I - R0015 - Practical Activities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D11178 - Learning Unit - Standard With P.A.A. : Placement Date - 23/10/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11245 - Learning Unit - Standard With P.A.A. : Placement Date - 11/02/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11764 - Learning Unit - Standard With P.A.A. : Placement Date - 10/01/2017

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13249 - Learning Unit - Standard With P.A.A. : Placement Date - 31/10/2014

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D14612 - Learning Unit - Standard With P.A.A. : Placement Date - 21/02/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						
OS 603 - D16161 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 29/03/2012						
Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.						
Exterior						
No Asbestos Found.						
Interior						
R1 - Learning space/withdrawal/entry						
No Asbestos Found.						
R2 - Home Base Store						
No Asbestos Found.						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017