


# Asbestos Register

(Hazardous Materials and Risk Assessment)



**School :** Barwon Learning Centre (5762)  
**Region :** New England  
**State Electorate :** Northern Tablelands  
**Local Government Area :** Moree Plains

**Initial Survey :** Noel Arnold & Associates : 27 - Jun - 2008  
**Register Issue Date :** 23 - Mar - 2017



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00B - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00B - R0001 - Home Base**

No Asbestos

**B00B - R0002 - Toilets - Boys/Girls**

No Asbestos

**B00B - R0003 - Toilets - Boys/Girls**

No Asbestos

**B00B - R0004 - Home Base Store**

No Asbestos

**B00B - R0005 - Home Base Store**

No Asbestos

**B00B - R0006 - Home Base**

No Asbestos

**B00B - R0007 - Home Base Store**

No Asbestos

**B00B - R0008 - Home Base Store**

No Asbestos

**B00B - R0009 - Home Base**

No Asbestos

**B00B - R0010 - Disabled Toilet**

No Asbestos

**B00B - R0011 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00E - Administration - 2006 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00E - R0001 - Entry Vestibule**

No Asbestos

**B00E - R0002 - Interview**

No Asbestos

**B00E - R0003 - Principal**

No Asbestos

**B00E - R0004 - Movement**

No Asbestos

**B00E - R0005 - Clerical Office**

No Asbestos

**B00E - R0006 - Sick Bay**

No Asbestos

**B00E - R0007 - Disabled Toilet**

No Asbestos

**B00E - R0008 - General Storeroom**

No Asbestos

**B00E - R0009 - Cleaning Distributed Store**

No Asbestos

**B00E - R0010 - Staff Toilet**

No Asbestos

**B00E - R0011 - Staff Kitchen**

No Asbestos

**B00E - R0012 - Staff Room Annexe**

No Asbestos

**B00E - R0013 - External Movement**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Storage - 2009 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00F - R0001 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Library - 2009 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00G - R0001 - External Movement**

No Asbestos

**B00G - R0002 - Reading Area**

No Asbestos

**B00G - R0003 - Practical Activities**

No Asbestos

**B00G - R0004 - K.L.A. Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Building Services - 2007 - Metal Shed (Metal Shed)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00H - R0001 - Garden Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

### ***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017