


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Byron Bay High School (8577)  
**Region :** North Coast  
**State Electorate :** Ballina  
**Local Government Area :** Byron

**Initial Survey :** Noel Arnold & Associates : 11 - Jun - 2008  
**Reviewed By :** Grencap-NAA : 04 - May - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 8577/B00A/R0020/Ceiling Structures/Linings/S5					<b>No Asbestos Detected</b>

**Interior**

**B00A - R0001 - General Assistants**

No Asbestos

**B00A - R0002 - Public Entry**

No Asbestos

**B00A - R0003 - Administration - Clerical**

No Asbestos

**B00A - R0004 - Administration - Clerical**

No Asbestos

**B00A - R0005 - Interview/Office - Type 1**

No Asbestos

**B00A - R0006 - Cleaning Store - Distributed**

No Asbestos

**B00A - R0007 - Principal Office**

No Asbestos

**B00A - R0008 - Secure Storeroom**

No Asbestos

**B00A - R0009 - Duplicating Workroom**

No Asbestos

**B00A - R0010 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0011 - Clinic - Girls**

No Asbestos

**B00A - R0012 - Staff - Toilet**

No Asbestos

**B00A - R0013 - Staff - Toilet**

No Asbestos

**B00A - R0014 - Clinic - Boys**

No Asbestos

**B00A - R0015 - Ancillary Staff**

No Asbestos

**B00A - R0016 - Deputy Principal Office**

No Asbestos

**B00A - R0017 - Pupil Entry**

No Asbestos

**B00A - R0018 - Movement**

No Asbestos

**B00A - R0019 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00A/R0020/Ceiling Structures/Linings/S5					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0020 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00A/R0020/Ceiling Structures/Linings/S5					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Multi Purpose Facilities - 1987 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids - Flat Roof    Non Accessible Area  
- No manhole

Underfloor Voids - Slab    No Asbestos Found  
on Ground

**Interior****B00B - R0001 - Main Switchroom**

No Asbestos

**B00B - R0002 - Cleaning Supplies Store**

No Asbestos

**B00B - R0003 - Cleaning Supplies Store**

No Asbestos

**B00B - R0004 - Multi-Purpose Space**

No Asbestos

**B00B - R0005 - Sport Equipment Store**

No Asbestos

**B00B - R0006 - Cleaning Store - Distributed**

No Asbestos

**B00B - R0007 - Staff Study**

No Asbestos

**B00B - R0008 - Sport Equipment Store**

Wall Linings Internal    Flat AC Sheeting  
8577/B00B/R0008/Wall Linings Internal/S6

**No Asbestos Detected**

**B00B - R0009 - Maintenance Bulk Store**

No Asbestos

**B00B - R0012 - Movement**

No Asbestos

**B00B - R0013 - Stage**

No Asbestos

**B00B - R0015 - Movement**

No Asbestos

**B00B - R0016 - General Storeroom**

No Asbestos

**B00B - R0017 - General Storeroom**

No Asbestos

**B00B - R0018 - Staff Shower**

No Asbestos

**B00B - R0019 - Toilets-Boys**

Ceiling Structures/Linings    Flat AC Sheeting  
8577/B00B/R0020/Ceiling Structures/Linings/S8

**No Asbestos Detected**

**B00B - R0020 - Toilets-Girls**

Ceiling Structures/Linings    Flat AC Sheeting  
8577/B00B/R0020/Ceiling Structures/Linings/S8

**No Asbestos Detected**

**B00B - R0026 - Movement**

Chalk Board    Flat AC Sheeting  
8577/B00B/R0020/Ceiling Structures/Linings/S8

**No Asbestos Detected**

**B00B - R0027 - Movement**

No Asbestos

**B00B - R0028 - Toilet - Lobby**

Ceiling Structures/Linings    Flat AC Sheeting  
8577/B00B/R0032/Ceiling Structures/Linings/S7

**No Asbestos Detected**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00B - R0029 - Toilets-Boys</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8577/B00B/R0032/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R0030 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8577/B00B/R0032/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R0031 - Toilet - Lobby</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8577/B00B/R0032/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R0032 - Toilets-Girls</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8577/B00B/R0032/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>
<b>B00B - R0033 - General Storeroom</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8577/B00B/R0032/Ceiling Structures/Linings/S7					<b>No Asbestos Detected</b>

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Technological & Applied Studies - 1987 - Brick/Block (Brick/Block)****Exterior**

Eaves Linings	Flat AC Sheeting 8577/B00C/Eaves Linings/S3					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					
Underfloor Voids	Non Accessible Area - Area inaccessible					

**Interior****B00C - R0001 - Resources Store**

No Asbestos

**B00C - R0002 - Staff - Toilet**

No Asbestos

**B00C - R0003 - Computer Learning Space**

No Asbestos

**B00C - R0004 - Staff Study**

No Asbestos

**B00C - R0005 - Materials Technology L.S.**

No Asbestos

**B00C - R0006 - Wood Technology Bay**

No Asbestos

**B00C - R0007 - Materials Technology L.S.**

No Asbestos

**B00C - R0008 - Resources Store**

No Asbestos

**B00C - R0009 - L.P.G. Store**

No Asbestos

**B00C - R0010 - Workshop**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00C/R0010/Ceiling Structures/Linings/S9					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00C - R0011 - Welding Area**

No Asbestos

**B00C - R0012 - Materials Technology L.S.**

No Asbestos

**B00C - R0013 - Metal Technology Bay**

No Asbestos

**B00C - R0014 - Materials Technology L.S.**

No Asbestos

**B00C - R0015 - Design L.S.**

No Asbestos

**B00C - R0016 - Seminar/Technology Space**

No Asbestos

**B00C - R0017 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00D/R0022/Ceiling Structures/Linings/S1					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00C - R0018 - Dust Extraction Space**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00C/R0010/Ceiling Structures/Linings/S9					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00C - R0019 - Distribution Board Cupboard**No Asbestos Note: No inspection of live electrical installation.**B00C - R0020 - Materials Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0021 - Materials Store</b>						
No Asbestos						
<b>B00C - R0022 - Materials Store</b>						
No Asbestos						
<b>B00C - R0023 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00C - R0024 - Resources Store</b>						
No Asbestos						
<b>B00C - R0025 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Art/Music - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - No ceiling space					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 8577/B00C/Eaves Linings/S3					<b>No Asbestos Detected</b>

**Interior**

**B00D - R0001 - Toilets-Girls**

No Asbestos

**B00D - R0002 - Art Learning Space**

No Asbestos

**B00D - R0003 - Kiln Space**

No Asbestos

**B00D - R0004 - Art Learning Space**

No Asbestos

**B00D - R0005 - Music Store**

No Asbestos

**B00D - R0006 - Music Learning Space**

No Asbestos

**B00D - R0007 - Resources Store**

No Asbestos

**B00D - R0008 - Resources Store**

No Asbestos

**B00D - R0009 - Music Learning Space**

No Asbestos

**B00D - R0010 - Practice/Seminar**

No Asbestos

**B00D - R0011 - Staff Study**

No Asbestos

**B00D - R0012 - Staff Study**

No Asbestos

**B00D - R0013 - Resources Store**

No Asbestos

**B00D - R0014 - Resources Store**

No Asbestos

**B00D - R0015 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00D - R0016 - Movement**

No Asbestos

**B00D - R0017 - Art Learning Space**

No Asbestos

**B00D - R0018 - Resources Store**

No Asbestos

**B00D - R0019 - Cleaning Store - Distributed**

No Asbestos

**B00D - R0020 - Staff - Toilet**

No Asbestos

**B00D - R0022 - Movement**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings	Flat AC Sheeting		8577/B00D/R0022/Ceiling Structures/Linings/S1			No Asbestos Detected
----------------------------	------------------	--	---	--	--	----------------------

**B00D - R0023 - Movement**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00E - Science Learning - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - No ceiling space					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 8577/B00C/Eaves Linings/S3					<b>No Asbestos Detected</b>

**Interior**

**B00E - R0001 - Toilets-Boys**

No Asbestos

**B00E - R0002 - Laboratory L.S.**

No Asbestos

**B00E - R0003 - Preparation**

No Asbestos

**B00E - R0004 - Laboratory L.S.**

No Asbestos

**B00E - R0005 - Laboratory L.S.**

No Asbestos

**B00E - R0006 - Preparation**

No Asbestos

**B00E - R0007 - Chemical Store**

No Asbestos

**B00E - R0008 - Staff Study**

No Asbestos

**B00E - R0009 - Apparatus Store**

No Asbestos

**B00E - R0010 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00E - R0011 - Laboratory L.S.**

No Asbestos

**B00E - R0012 - Preparation**

No Asbestos

**B00E - R0013 - Laboratory L.S.**

No Asbestos

**B00E - R0015 - Cleaning Store - Distributed**

No Asbestos

**B00E - R0016 - Staff - Toilet**

No Asbestos

**B00E - R0017 - Movement**

No Asbestos

**B00E - R0018 - General Storeroom**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00C/Eaves Linings/S3					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

**B00E - R0019 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00C/Eaves Linings/S3					<b>No Asbestos Detected</b>
----------------------------	--	--	--	--	--	-----------------------------

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - Technological & Applied Studies - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 8577/B00C/Eaves Linings/S3					<b>No Asbestos Detected</b>

**Interior**

**B00F - R0001 - Computer Learning Space**

No Asbestos

**B00F - R0002 - Laundry**

No Asbestos

**B00F - R0003 - Toilets-Disabled**

No Asbestos

**B00F - R0004 - Food Technology L.S.**

No Asbestos

**B00F - R0005 - Preparation**

No Asbestos

**B00F - R0006 - Seminar**

No Asbestos

**B00F - R0007 - Food Technology L.S.**

No Asbestos

**B00F - R0008 - Interview/Office - Type 1**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B00F - R0009 - Distribution Board Cupboard** Note: No inspection of live electrical installation.

No Asbestos

**B00F - R0010 - Resources Store**

No Asbestos

**B00F - R0011 - Staff Study**

No Asbestos

**B00F - R0012 - Materials Technology L.S.**

No Asbestos

**B00F - R0013 - Cleaning Store - Distributed**

No Asbestos

**B00F - R0014 - Toilets-Girls**

No Asbestos

**B00F - R0016 - Preparation**

No Asbestos

**B00F - R0017 - Movement**

Ceiling Structures/Linings Flat AC Sheeting  
8577/B00D/R0022/Ceiling Structures/Linings/S1 **No Asbestos Detected**

**B00F - R0018 - Movement**

No Asbestos

**B00F - R0019 - Movement**

Ceiling Structures/Linings Flat AC Sheeting  
8577/B00D/R0022/Ceiling Structures/Linings/S1 **No Asbestos Detected**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - General Learning/Tiered Learning - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting					
	8577/B00G/Eaves Linings/S12					<b>No Asbestos Detected</b>

**Interior**

<b>B00G - R0001 - General Learning Space</b>	No Asbestos					
<b>B00G - R0002 - Darkroom Space</b>	No Asbestos					
<b>B00G - R0003 - Resources Store</b>	No Asbestos					
<b>B00G - R0004 - General Learning Space</b>	No Asbestos					
<b>B00G - R0005 - General Learning Space</b>	No Asbestos					
<b>B00G - R0006 - General Learning Space</b>	No Asbestos					
<b>B00G - R0007 - General Learning Space</b>	No Asbestos					
<b>B00G - R0008 - Resources Store</b>	No Asbestos					
<b>B00G - R0009 - Study Space</b>	No Asbestos					
<b>B00G - R0010 - Seminar</b>	No Asbestos					
<b>B00G - R0011 - Resources Store</b>	No Asbestos					
<b>B00G - R0012 - General Learning Space</b>	No Asbestos					
<b>B00G - R0013 - General Learning Space</b>	No Asbestos					
<b>B00G - R0014 - Design/Technology L.S.</b>	No Asbestos					
<b>B00G - R0015 - Design/Technology L.S.</b>	No Asbestos					
<b>B00G - R0016 - Design/Technology L.S.</b>	No Asbestos					
<b>B00G - R0017 - Computer Resource</b>	No Asbestos					
<b>B00G - R0018 - Staff Study</b>	No Asbestos					
<b>B00G - R0019 - General Learning Space</b>	No Asbestos					
<b>B00G - R0020 - General Learning Space</b>	No Asbestos					
<b>B00G - R0021 - Staff Study</b>	No Asbestos					
<b>B00G - R0022 - Study Space</b>	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00G - R0023 - Tiered Learning Area</b>						
No Asbestos						
<b>B00G - R0024 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00G - R0025 - Seminar</b>						
No Asbestos						
<b>B00G - R0026 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00G - R0027 - Interview/Office - Type 1</b>						
No Asbestos						
<b>B00G - R0028 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00G - R0029 - Resources Store</b>						
No Asbestos						
<b>B00G - R0030 - Movement</b>						
No Asbestos						
<b>B00G - R0031 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00G - R0032 - Cleaning Store - Distributed</b>						
No Asbestos						
<b>B00G - R0033 - Toilets-Girls</b>						
Partition Walls (Cubicles)	Compressed AC Sheet					
	8577/B00G/R0034/Partition Walls (Cubicles)/S2					<b>No Asbestos Detected</b>
<b>B00G - R0034 - Toilets-Boys</b>						
Partition Walls (Cubicles)	Compressed AC Sheet					
	8577/B00G/R0034/Partition Walls (Cubicles)/S2					<b>No Asbestos Detected</b>
<b>B00G - R0036 - Movement</b>						
No Asbestos						
<b>B00G - R0038 - Darkroom Space</b>						
No Asbestos						
<b>B00G - R0039 - Movement</b>						
No Asbestos						
<b>B00G - R0040 - Stairs</b>						
No Asbestos						
<b>B00G - R0041 - Stairs</b>						
Ceiling Structures/Linings	Flat AC Sheeting					
	8577/B00G/R1015/Ceiling Structures/Linings/S13					<b>No Asbestos Detected</b>
<b>B00G - R1001 - Resources Store</b>						
No Asbestos						
<b>B00G - R1002 - Staff - Toilet</b>						
No Asbestos						
<b>B00G - R1004 - Distribution Board Cupboard</b>					Note: No inspection of live electrical installation.	
No Asbestos						
<b>B00G - R1005 - General Storeroom</b>						
No Asbestos						
<b>B00G - R1006 - Plant</b>						
No Asbestos						
<b>B00G - R1007 - General Learning Space</b>						
No Asbestos						
<b>B00G - R1008 - Seminar</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

**B00G - R1009 - Senior Study**

No Asbestos

**B00G - R1010 - Commonroom**

No Asbestos

**B00G - R1011 - Resources Store**

No Asbestos

**B00G - R1012 - Staff Study**

No Asbestos

**B00G - R1013 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00G - R1014 - General Learning Space**

No Asbestos

**B00G - R1015 - Movement**

Ceiling Structures/Linings Flat AC Sheeting  
8577/B00G/R1015/Ceiling Structures/Linings/S13

**No Asbestos Detected**

**B00G - R1016 - Stairs**

Ceiling Structures/Linings Flat AC Sheeting  
8577/B00G/R1015/Ceiling Structures/Linings/S13

**No Asbestos Detected**

**B00G - R1017 - Stairs**

Ceiling Structures/Linings Flat AC Sheeting  
8577/B00G/R1015/Ceiling Structures/Linings/S13

**No Asbestos Detected**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Library - 1987 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - No manhole					
Eaves Linings	Flat AC Sheeting 8577/B00H/Eaves Linings/S4					<b>No Asbestos Detected</b>

**Interior**

<b>B00H - R0001 - Pupil Entry</b>	No Asbestos					
<b>B00H - R0002 - Main Area</b>	No Asbestos					
<b>B00H - R0003 - Workroom</b>	No Asbestos					
<b>B00H - R0004 - Audio Visual Workroom</b>	No Asbestos					
<b>B00H - R0005 - Seminar</b>	No Asbestos					
<b>B00H - R0006 - Seminar</b>	No Asbestos					
<b>B00H - R0007 - Seminar</b>	No Asbestos					
<b>B00H - R0008 - Covered Area</b>	No Asbestos					
<b>B00H - R0009 - Movement</b>	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B001 - Agricultural Science - 1987 - Brick/Block (Brick/Block)****Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	Non Accessible Area - No ceiling space					
Eaves Linings	Flat AC Sheeting 8577/B001/Eaves Linings/S10					No Asbestos Detected
Wall Cladding	Flat AC Sheeting 8577/B001/Wall Cladding/S11					No Asbestos Detected

**Interior****B001 - R0001 - Growing/Breeding**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00C/R0010/Ceiling Structures/Linings/S9					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 8577/B00B/R0008/Wall Linings Internal/S6					No Asbestos Detected

**B001 - R0002 - Class Tools Storage**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00C/R0010/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

**B001 - R0003 - Resources Store**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00C/R0010/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

**B001 - R0004 - Animal Space**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00C/R0010/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

**B001 - R0005 - Animal Space**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00C/R0010/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

**B001 - R0006 - Animal Space**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00C/R0010/Ceiling Structures/Linings/S9					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

**B001 - R0007 - Machine Storage**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00J - Pupil Facilities - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Raked Ceiling      No Asbestos Found

Underfloor Voids - Slab on Ground      No Asbestos Found

**Interior**

**B00J - R0001 - Student Canteen**

Wall Linings Internal      Flat AC Sheeting  
 8577/B00J/R0001/Wall Linings Internal/S14      **No Asbestos Detected**

**B00J - R0002 - General Storeroom**

No Asbestos

**B00J - R0003 - Toilets-Disabled**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00K - Art/Music - 1987 - Brick/Block (Brick/Block)**

**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - NoCeiling Space					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 8577/B00C/Eaves Linings/S3					<b>No Asbestos Detected</b>

**Interior**

**B00K - R0001 - Kiln Space**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00B/R0020/Ceiling Structures/Linings/S8					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00K - R0002 - Bulk Store**

Ceiling Structures/Linings	Flat AC Sheeting 8577/B00B/R0020/Ceiling Structures/Linings/S8					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00L - Performing Arts - 2003 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00L - R0001 - Movement**

No Asbestos

**B00L - R0002 - Performance Workspace**

No Asbestos

**B00L - R0003 - Movement**

No Asbestos

**B00L - R0004 - Movement**

No Asbestos

**B00L - R0005 - External Movement**

No Asbestos

**B00L - R0006 - G.L.S. Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00M - Multi Purpose Facilities - 2008 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

**Interior**

**B00M - R0001 - External Movement**

No Asbestos

**B00M - R0002 - Gymnasium**

No Asbestos

**B00M - R0003 - General Learning Space - Type 13**

No Asbestos

**B00M - R0004 - G.L.S. Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 601 - D11207 - Learning Unit - Standard/Withdrawal : Placement Date - 4/05/2016**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 840 - D12802 - Girls Toilet : Placement Date - 5/10/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Toilets-Girls**

No Asbestos Found.

**OS 601 - D14891 - Learning Unit - Standard/Withdrawal : Placement Date - 25/01/2011**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 601 - D15780 - Learning Unit - Standard/Withdrawal : Placement Date - 25/01/2011**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

**OS 600 - D17126 - Learning Unit - Small : Placement Date - 5/10/2016**

**Exterior**

Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos	8.64 m2

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Interior**

**R1 - General Learning Space**

End wall panel	Flat AC Sheet	Assumed Asbestos				50 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2

**OS 601 - D17728 - Learning Unit - Standard/Withdrawal : Placement Date - 18/01/2012**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - General Learning Space**

No Asbestos Found.

**R3 - Store**

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017