


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Glenbrook Public School (1994)
Region : Western Sydney
State Electorate : Penrith
Local Government Area : Blue Mountains

Initial Survey : Noel Arnold & Associates : 26 - Mar - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1961 - Brick/Veneer (Brick/Veneer)**Exterior**

Gable Verge Lining	Flat AC Sheeting	30m	East facing	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------	------------------	-----	-------------	--------------------	---------	--------------------

Assumed Asbestos

Ceiling Voids Requires Inspection

Underfloor Voids Requires Inspection

Interior**B00A - R0028 - Main Switch Board**

No Asbestos

B00A - R0033 - Movement

No Asbestos

B00A - R0034 - Covered Vehicle Area/Porte Cochere

No Asbestos

B00A - R0035 - Entry Vestibule

No Asbestos

B00A - R0036 - Sick Bay

No Asbestos

B00A - R0037 - Interview

No Asbestos

B00A - R0038 - Principal

No Asbestos

B00A - R0039 - Deputy Principal

No Asbestos

B00A - R0040 - Access Shower/Toilet

No Asbestos

B00A - R0041 - Movement

No Asbestos

B00A - R0042 - Security Store

No Asbestos

B00A - R0043 - Interview

No Asbestos

B00A - R0044 - Duplicating Workroom

No Asbestos

B00A - R0045 - Clerical Office

No Asbestos

B00A - R0046 - Movement

No Asbestos

B00A - R0047 - Cleaning Distributed Store

No Asbestos

B00A - R0048 - Interview

No Asbestos

B00A - R0049 - Interview

No Asbestos

B00A - R0050 - Staff Kitchen

No Asbestos

B00A - R0051 - Staff Room

No Asbestos

B00A - R0052 - Staff Room Annexe

No Asbestos

B00A - R0053 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
	No Asbestos					
	B00A - R0054 - Practical Activities - 1hb					
	No Asbestos					
	B00A - R0055 - Practical Activities - 1hb					
	No Asbestos					
	B00A - R0056 - Distribution Board Cupboard				Note: No inspection of live electrical installation.	
	No Asbestos					
	B00A - R0057 - Movement					
	No Asbestos					
	B00A - R0058 - Cleaning Supplies					
	No Asbestos					
	B00A - R0059 - Access Shower/Toilet - Type 2					
	No Asbestos					
	B00A - R0060 - Laundry - Type 2					
	No Asbestos					
	B00A - R0061 - Withdrawal Space - 1hb					
	No Asbestos					
	B00A - R0062 - Home Base Store					
	No Asbestos					
	B00A - R0063 - Home Base					
	No Asbestos					
	B00A - R0064 - Home Base					
	No Asbestos					
	B00A - R0065 - Home Base Store					
	No Asbestos					
	B00A - R0066 - Withdrawal Space - 1hb					
	No Asbestos					
	B00A - R0067 - General Storeroom					
	No Asbestos					
	B00A - R0068 - Staff Toilet					
	No Asbestos					
	B00A - R0069 - Staff Toilet					
	No Asbestos					
	B00A - R0070 - Movement					
	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Library - 1961 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00B - R0016 - Movement

No Asbestos

B00B - R0017 - Staff Toilet

No Asbestos

B00B - R0018 - Cleaning Distributed Store

No Asbestos

B00B - R0019 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0020 - Movement

No Asbestos

B00B - R0021 - Reading Area

No Asbestos

B00B - R0022 - Library Office/Workroom

No Asbestos

B00B - R0023 - K.L.A. Store

No Asbestos

B00B - R0024 - Communications Room

No Asbestos

B00B - R0025 - Special Programs Store

No Asbestos

B00B - R0026 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Pupil Facilities - 1961 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - Movement

No Asbestos

B00C - R0012 - Toilets - Boys

No Asbestos

B00C - R0013 - Toilets - Girls

No Asbestos

B00C - R0014 - Practical Activities - 1hb

No Asbestos

B00C - R0015 - Home Base Store

No Asbestos

B00C - R0016 - Home Base

No Asbestos

B00C - R0017 - Withdrawal Space - 2hb

No Asbestos

B00C - R0018 - Home Base

No Asbestos

B00C - R0019 - Home Base Store

No Asbestos

B00C - R0020 - Practical Activities - 1hb

No Asbestos

B00C - R0021 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 2004 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - Movement

No Asbestos

B00G - R0002 - Practical Activities - 1hb

No Asbestos

B00G - R0003 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0005 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0007 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0008 - Practical Activities - 1hb

No Asbestos

B00G - R0009 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0010 - Practical Activities - 1hb

No Asbestos

B00G - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0013 - Withdrawal Space - 2hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0015 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0016 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00P - Communal Facilities/Pupil Facilities - 1960 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

Interior**B00P - R0001 - Garden Store**

No Asbestos

B00P - R0002 - General Storeroom

No Asbestos

B00P - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00P - R0004 - P.E. Store

No Asbestos

B00P - R0005 - Toilets - Girls

No Asbestos

B00P - R0006 - Raised Platform

No Asbestos

B00P - R0007 - Toilets - Boys

No Asbestos

B00P - R0008 - Hall Chair Store

No Asbestos

B00P - R0009 - Communal Space

No Asbestos

B00P - R0010 - Cleaning Distributed Store

No Asbestos

B00P - R0011 - Disabled Toilet

No Asbestos

B00P - R0012 - Sports Store

No Asbestos

B00P - R0013 - Plant

No Asbestos

B00P - R0015 - General Assistant/Bulk Store

No Asbestos

B00P - R0016 - Canteen Office/Store

No Asbestos

B00P - R0017 - Canteen

No Asbestos

B00P - R0018 - Covered Outdoor Learning Area

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Q - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00Q - R0001 - External Movement

No Asbestos

B00Q - R0002 - Practical Activities - 1hb

No Asbestos

B00Q - R0003 - Home Base Store

No Asbestos

B00Q - R0004 - Home Base

No Asbestos

B00Q - R0005 - Withdrawal Space - 2hb

No Asbestos

B00Q - R0006 - Home Base

No Asbestos

B00Q - R0007 - Home Base Store

No Asbestos

B00Q - R0008 - Practical Activities - 1hb

No Asbestos

B00Q - R0009 - Home Base Store

No Asbestos

B00Q - R0010 - Home Base

No Asbestos

B00Q - R0011 - Practical Activities - 1hb

No Asbestos

B00Q - R0012 - Withdrawal Space - 2hb

No Asbestos

B00Q - R0013 - Home Base

No Asbestos

B00Q - R0014 - Home Base Store

No Asbestos

B00Q - R0015 - Practical Activities - 1hb

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017