


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Gravesend Public School (2068)
Region : New England
State Electorate : Northern Tablelands
Local Government Area : Gwydir

Initial Survey : Noel Arnold & Associates : 21 - May - 2008
Reviewed By : Greencap-NAA : 04 - May - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1927 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting 2068/B00A/Eaves Linings/S3					No Asbestos Detected
Electrical Backing Board	Resinous Board 2068/B00A/Electrical Backing Board/S8					No Asbestos Detected
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Raked Ceiling	Non Accessible Area - height - 4 meters					

Interior

B00A - R0002 - Home Base

No Asbestos

B00A - R0003 - General Storeroom

No Asbestos

B00A - R0004 - Clerical Office

No Asbestos

B00A - R0005 - Staff Room

No Asbestos

B00A - R0008 - Practical Activities - 1hb

No Asbestos

B00A - R0010 - Movement

No Asbestos

B00A - R0011 - Principal

No Asbestos

B00A - R0012 - Covered Outdoor Learning Area

No Asbestos

B00A - R0013 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	22m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2068/B00A/R0013/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)
Wall Linings Internal	Flat AC Sheeting	2m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2068/B00A/R0013/Wall Linings Internal/S6					Chrysotile (white asbestos)

B00A - R0014 - Disabled Toilet

Ceiling Structures/Linings	Flat AC Sheeting	9m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2068/B00A/R0013/Ceiling Structures/Linings/S5					Chrysotile (white asbestos)

B00A - R0015 - Withdrawal Space - 1hb

No Asbestos

B00A - R0016 - Clerical/Printing

No Asbestos

B00A - R0017 - Principal

No Asbestos

B00A - R0018 - General Storeroom

No Asbestos

B00A - R0019 - Home Base

No Asbestos

B00A - R0020 - Withdrawal Space - 1hb

No Asbestos

B00A - R0021 - General Storeroom

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - R0022 - Sick Bay

No Asbestos

B00A - R0023 - Home Base

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Building Services - 1955 - Timber Shed (Timber Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids - Flat Roof No Asbestos Found

Interior

B00B - R0001 - Cleaning Distributed Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Shed - 2004 - Steel (Steel)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00C - R0001 - Sports Store

No Asbestos

B00C - R0002 - General Assistant/Bulk Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Pupil Facilities - 1962 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	10m2	North, South, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2068/B00D/R0007/Ceiling Structures/Linings/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00D - R0002 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2068/B00D/R0005/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0003 - Staff Toilet

No Asbestos

B00D - R0004 - Staff Toilet

No Asbestos

B00D - R0005 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	2068/B00D/R0005/Partition Walls (Cubicles)/S1					Chrysotile (white asbestos) , Amosite (brown asbestos)

B00D - R0006 - Staff Toilet

No Asbestos

B00D - R0007 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	27m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2068/B00D/R0007/Ceiling Structures/Linings/S2					Chrysotile (white asbestos) , Amosite (brown asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1955 - Timber (Timber)

Exterior

Electrical Backing Board	Resinous Board 2068/B00A/Electrical Backing Board/S8					No Asbestos Detected
Underfloor Voids - Packing to Floor Joists	No Asbestos Found					
Ceiling Voids - Raked Ceiling	No Asbestos Found					

Interior

B00E - R0001 - Canteen

Wall Linings Internal	Flat AC Sheeting 2068/B00E/R0002/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00E - R0002 - Canteen Office/Store

Wall Linings Internal	Flat AC Sheeting 2068/B00E/R0002/Wall Linings Internal/S4					No Asbestos Detected
-----------------------	--	--	--	--	--	-----------------------------

B00E - R0003 - Movement

No Asbestos

B00E - R0004 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Library - 2009 - Fibre Cement Clad (Fibre Cement Clad)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00F - R0001 - Reading Area

No Asbestos

B00F - R0002 - K.L.A. Store

No Asbestos

B00F - R0003 - Practical Activities

No Asbestos

B00F - R0004 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 531 - D10678 - Library : Placement Date - 30/06/1995

Exterior

Step Treads	Compressed AC Sheet	Assumed Asbestos		1.08 m2
Landing	Compressed AC Sheet	Assumed Asbestos		1.2 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos		11.52 m2

Interior

R1 - Entry/classroom

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		63 m2

R2 - Reading Area/workroom

End wall panel	Flat AC Sheet	Assumed Asbestos		18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos		10 m2

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017