


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Gulargambone Central School (2094)  
**Region :** Western NSW  
**State Electorate :** Barwon  
**Local Government Area :** Coonamble

**Initial Survey :** Noel Arnold & Associates : 11 - Mar - 2008  
**Reviewed By :** Parsons Brinckerhoff : 01 - Nov - 2016



# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Library - 1983 - Brick/Block (Brick/Block)**

**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

**Interior**

**B00A - M0001 - Resource/Project Store**

No Asbestos

**B00A - R0001 - Practice/Seminar**

Floor Coverings Res/Textile Vinyl Tiles  
 2094/B00A/R0074/Floor Coverings Res/Textile/S2 **No Asbestos Detected**

**B00A - R0002 - Cleaning Distributed Store**

Floor Coverings Res/Textile Vinyl Tiles  
 2094/B00A/R0074/Floor Coverings Res/Textile/S2 **No Asbestos Detected**

**B00A - R0003 - Movement**

Floor Coverings Res/Textile Vinyl Tiles  
 2094/B00A/R0074/Floor Coverings Res/Textile/S2 **No Asbestos Detected**

**B00A - R0004 - Movement**

No Asbestos

**B00A - R0005 - Cleaning Supplies**

No Asbestos

**B00A - R0006 - Cleaning Distributed Store**

Floor Coverings Res/Textile Vinyl Tiles  
 2094/B00A/R0074/Floor Coverings Res/Textile/S2 **No Asbestos Detected**

**B00A - R0007 - Cleaning Distributed Store**

No Asbestos

**B00A - R0008 - P.E. Store**

No Asbestos

**B00A - R0009 - Hall Chair Store**

No Asbestos

**B00A - R0010 - Raised Platform**

No Asbestos

**B00A - R0011 - Cleaning Distributed Store**

No Asbestos

**B00A - R0012 - Communal Space**

No Asbestos

**B00A - R0013 - Shower/Change**

Partition Walls (Cubicles) Compressed AC Sheet 30m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)  
 2094/B00A/R0077/Partition Walls (Cubicles)/S1 **Chrysotile (white asbestos)**

**B00A - R0014 - Shower/Change**

No Asbestos

**B00A - R0015 - Movement**

Floor Coverings Res/Textile Vinyl Tiles  
 2094/B00A/R0074/Floor Coverings Res/Textile/S2 **No Asbestos Detected**

**B00A - R0016 - Music Store**

No Asbestos

**B00A - R0017 - Movement**

No Asbestos

**B00A - R0018 - Materials Technology L.S.**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No		Test Result				
No Asbestos						
<b>B00A - R0019 - Welding Area</b>						
No Asbestos						
<b>B00A - R0020 - Materials Store</b>						
No Asbestos						
<b>B00A - R0021 - Staff Room Annexe</b>						
No Asbestos						
<b>B00A - R0022 - Materials Technology L.S.</b>						
No Asbestos						
<b>B00A - R0023 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0024 - Distribution Board</b>						
						Note: No inspection of live electrical installation.
No Asbestos						
<b>B00A - R0025 - T.A.S. Outdoor Area</b>						
No Asbestos						
<b>B00A - R0026 - Distribution Board</b>						
						Note: No inspection of live electrical installation.
No Asbestos						
<b>B00A - R0027 - External Movement</b>						
No Asbestos						
<b>B00A - R0028 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0029 - Uniform Shop</b>						
No Asbestos						
<b>B00A - R0030 - Canteen</b>						
No Asbestos						
<b>B00A - R0031 - Canteen Office/Store</b>						
No Asbestos						
<b>B00A - R0032 - External Movement</b>						
No Asbestos						
<b>B00A - R0033 - Toilets - Girls</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2094/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>	
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	North	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Encapsulated Material within unit</b>						
<b>B00A - R0034 - Toilets - Boys</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2094/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0035 - General Learning Space</b>						
No Asbestos						
<b>B00A - R0036 - K.L.A. Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
2094/B00A/R0074/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>	
<b>B00A - R0037 - Music Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
2094/B00A/R0074/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>	
<b>B00A - R0038 - Workshop</b>						
No Asbestos						
<b>B00A - R0039 - Kiln Room</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R0040 - Distribution Board</b> <span style="float: right;">Note: No inspection of live electrical installation.</span>						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Some Damage / Unsealed (3)	Low (1)	Low Priority (2-3)
2094/B00A/R0040/Ceiling Structures/Linings/S8					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0041 - Laundry</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
2094/B00A/R0074/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>	
<b>B00A - R0042 - Materials Store</b>						
No Asbestos						
<b>B00A - R0043 - Food/Research Space</b>						
No Asbestos						
<b>B00A - R0045 - Staff Kitchen</b>						
No Asbestos						
<b>B00A - R0046 - Movement</b>						
No Asbestos						
<b>B00A - R0047 - External Movement</b>						
No Asbestos						
<b>B00A - R0048 - General Learning Space</b>						
No Asbestos						
<b>B00A - R0049 - General Learning Space</b>						
No Asbestos						
<b>B00A - R0050 - General Learning Space</b>						
No Asbestos						
<b>B00A - R0051 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
2094/B00A/R0074/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>	
<b>B00A - R0052 - Staff Room Annexe</b>						
No Asbestos						
<b>B00A - R0053 - Staff Toilet</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2094/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>	
<b>B00A - R0054 - Staff Toilet</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2094/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>	
Incinerette	Encapsulated Insulation material within unit	1Unit(s)	West	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Encapsulated material within unit</b>						
<b>B00A - R0055 - Staff Room</b>						
No Asbestos						
<b>B00A - R0056 - Staff Room Annexe</b>						
No Asbestos						
<b>B00A - R0057 - External Movement</b>						
No Asbestos						
<b>B00A - R0058 - External Movement</b>						
No Asbestos						
<b>B00A - R0059 - Movement</b>						
No Asbestos						
<b>B00A - R0060 - Distribution Board</b> <span style="float: right;">Note: No inspection of live electrical installation.</span>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0061 - Home Base Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	2094/B00A/R0074/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0062 - External Movement</b>						
No Asbestos						
<b>B00A - R0063 - External Movement</b>						
No Asbestos						
<b>B00A - R0064 - Home Base</b>						
No Asbestos						
<b>B00A - R0065 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0066 - Computer Learning Space</b>						
No Asbestos						
<b>B00A - R0067 - External Movement</b>						
No Asbestos						
<b>B00A - R0068 - Withdrawal Space - 1hb</b>						
No Asbestos						
<b>B00A - R0069 - Computer Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	2094/B00A/R0074/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0070 - Seminar/Study</b>						
No Asbestos						
<b>B00A - R0071 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	2094/B00A/R0074/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0072 - Home Base</b>						
No Asbestos						
<b>B00A - R0073 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0074 - Home Base Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
	2094/B00A/R0074/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
<b>B00A - R0075 - External Movement</b>						
No Asbestos						
<b>B00A - R0076 - Toilets - Girls</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2094/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
Incinerette	Encapsulated Insulation material within unit	1Unit	West	Friable Asbestos (5)	Low (1)	High Priority (6-8)
	<b>Assumed Asbestos - Encapsulated material within unit</b>					
<b>B00A - R0077 - Toilets - Boys</b>						
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2094/B00A/R0077/Partition Walls (Cubicles)/S1					<b>Chrysotile (white asbestos)</b>
<b>B00A - R0078 - Interview</b>						
No Asbestos						
<b>B00A - R0079 - Deputy Principal</b>						
No Asbestos						
<b>B00A - R0080 - Principal</b>						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
<b>B00A - R0081 - Duplicating Workroom</b>						
No Asbestos						
<b>B00A - R0082 - Disabled Toilet</b>						
No Asbestos						
<b>B00A - R0083 - Clerical Office</b>						
No Asbestos						
<b>B00A - R0084 - External Movement</b>						
No Asbestos						
<b>B00A - R0085 - Sick Bay</b>						
No Asbestos						
<b>B00A - R0086 - Staff Room Annexe</b>						
No Asbestos						
<b>B00A - R0087 - Staff Toilet</b>						
No Asbestos						
<b>B00A - R0088 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0089 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R0090 - Special Programs Room</b>						
No Asbestos						
<b>B00A - R0091 - Security Store</b>						
Floor Coverings Res/Textile	Vinyl Tiles					
2094/B00A/R0074/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>	
<b>B00A - R0092 - Library Office/Workroom</b>						
No Asbestos						
<b>B00A - R0093 - General Storeroom</b>						
No Asbestos						
<b>B00A - R0094 - Seminar/Study</b>						
No Asbestos						
<b>B00A - R0095 - Seminar/Study</b>						
No Asbestos						
<b>B00A - R0096 - Reading Area</b>						
No Asbestos						
<b>B00A - R0097 - Main Switch Board</b>						
No Asbestos						
<b>B00A - R0098 - Kitchen - Type 1</b>						
No Asbestos						
<b>B00A - R0099 - Resource/Project Store</b>						
No Asbestos						
<b>B00A - R0100 - Plant</b>						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - General Learning/Support Unit - 1955 - Timber (Timber)**

**Exterior**

Eaves Linings	Flat AC Sheeting 2094/B00B/Eaves Linings/S6					<b>No Asbestos Detected</b>
---------------	--	--	--	--	--	-----------------------------

**Interior**

**B00B - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting 2094/B00B/R0001/Ceiling Structures/Linings/S3					<b>No Asbestos Detected</b>
----------------------------	---	--	--	--	--	-----------------------------

**B00B - R0002 - Home Base - M**

No Asbestos

**B00B - R0003 - Toilet - M**

Wall Linings Internal	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2094/B00B/R0008/Wall Linings Internal/S4						<b>Chrysotile (white asbestos)</b>

**B00B - R0004 - Home Base Store - M**

Floor Coverings Res/Textile	Vinyl Tiles					<b>No Asbestos Detected</b>
2094/B00B/R0004/Floor Coverings Res/Textile/S5						

**B00B - R0005 - Practical Activities - M - 1hb**

No Asbestos

**B00B - R0006 - Withdrawal Space - 1hb**

No Asbestos

**B00B - R0007 - Home Base**

No Asbestos

**B00B - R0008 - Home Base Store**

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
2094/B00B/R0008/Wall Linings Internal/S4						<b>Chrysotile (white asbestos)</b>

Incinerette	Encapsulated Insulation material within unit	1Unit(s)	East	Friable Asbestos (5)	Low (1)	Low Priority (2-3)
<b>Assumed Asbestos - Encapsulated material within unit</b>						

**B00B - R0009 - Practical Activities - 1hb**

No Asbestos

**B00B - R0010 - Home Base Store**

No Asbestos

**B00B - R0011 - Home Base**

No Asbestos

**B00B - R0012 - Home Base**

No Asbestos

**B00B - R0013 - Home Base Store**

No Asbestos

**B00B - R0014 - Darkroom Space**

No Asbestos

**B00B - R0015 - Practical Activities - 1hb**

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning/Science Learning - 1963 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Eaves Linings	Flat AC Sheeting	25m2	South	Good Condition (1)	Low (1)	Low Priority (2-3)
	2094/B00C/Eaves Linings/S7				<b>Chrysotile (white asbestos) , Crocidolite (blue asbestos)</b>	

**Interior**

**B00C - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	47m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	2094/B00C/R0001/Ceiling Structures/Linings/S9				<b>Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)</b>	

**B00C - R0002 - Apparatus Store**

Floor Coverings Res/Textile	Vinyl Sheet					<b>No Asbestos Detected</b>
	2094/B00C/R0002/Floor Coverings Res/Textile/S13					
Floor Coverings Res/Textile	Vinyl Sheet					<b>No Asbestos Detected</b>
	2094/B00C/R0002/Floor Coverings Res/Textile/S11					

**B00C - R0003 - Chemical Store**

Infill panel	Flat AC Sheeting					<b>No Asbestos Detected</b>
	2094/B00C/R0003/Infill panel/S12					
Infill panel	Flat AC Sheeting					<b>No Asbestos Detected</b>
	2094/B00C/R0003/Infill Panel to Window/S10					

**B00C - R0004 - Laboratory L.S.**

No Asbestos

**B00C - R0005 - Apparatus Store**

No Asbestos

**B00C - R0006 - Preparation**

No Asbestos

**B00C - R0007 - General Learning Space**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00F - General Learning - 2012 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B00F - R0001 - Welding/Hot Metals Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Agricultural Science - 2012 - Steel (Steel)**

**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

**Interior**

**B00G - R0001 - Agriculture Covered Area**

No Asbestos

**B00G - R0002 - Shed Workshop**

No Asbestos

**B00G - R0003 - Shed Workshop**

No Asbestos

**B00G - R0004 - Animal Space**

No Asbestos

**B00G - R0005 - Machine Storage**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017