


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Grahamstown Public School (4609)
Region : Hunter/Central Coast
State Electorate : Port Stephens
Local Government Area : Port Stephens

Initial Survey : Noel Arnold & Associates : 24 - Apr - 2008
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/Staff Facilities - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0004 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0005 - Duplicating Workroom

No Asbestos

B00A - R0006 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0007 - Security Store

No Asbestos

B00A - R0008 - Staff Toilet

No Asbestos

B00A - R0009 - Staff Toilet

No Asbestos

B00A - R0010 - Staff Toilet

No Asbestos

B00A - R0011 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0012 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0013 - General Storeroom

No Asbestos

B00A - R0014 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0015 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0016 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0017 - Sick Bay - Shower/Toilet

No Asbestos

B00A - R0018 - Sick Bay

No Asbestos

B00A - R0019 - Main Switch Board

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities/Pupil Facilities - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Toilets - Girls

No Asbestos

B00B - R0002 - Shower/Change

No Asbestos

B00B - R0003 - External Movement

No Asbestos

B00B - R0004 - Raised Platform

No Asbestos

B00B - R0005 - External Movement

No Asbestos

B00B - R0006 - Toilets - Boys

No Asbestos

B00B - R0007 - P.E. Store

No Asbestos

B00B - R0008 - Plant

No Asbestos

B00B - R0009 - Hall Chair Store

No Asbestos

B00B - R0010 - Sports Store

No Asbestos

B00B - R0011 - Disabled Toilet

No Asbestos

B00B - R0012 - P.E. Store

No Asbestos

B00B - R0013 - Communal Space

No Asbestos

B00B - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0015 - General Assistant/Bulk Store

No Asbestos

B00B - R0016 - Cleaning Supplies

No Asbestos

B00B - R0017 - Uniform Shop

No Asbestos

B00B - R0018 - Garden Store

No Asbestos

B00B - R0019 - External Movement

No Asbestos

B00B - R0020 - Plant

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - General Learning/Library - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0004 - Practical Activities - 1hb

No Asbestos

B00C - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0007 - Practical Activities - 1hb

No Asbestos

B00C - R0008 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0010 - General Storeroom

No Asbestos

B00C - R0011 - Plant

No Asbestos

B00C - R0012 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0013 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0014 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0015 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0016 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00C - R0018 - Toilets - Girls

No Asbestos

B00C - R0019 - Kiln Room

No Asbestos

B00C - R0020 - Toilets - Boys

No Asbestos

B00C - R0021 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0022 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0023 - Practical Activities - 1hb						
No Asbestos						
B00C - R0024 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0025 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0026 - Practical Activities - 1hb						
No Asbestos						
B00C - R0027 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0028 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00C - R0029 - Reading Area						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0030 - Special Programs Room						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1993 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - External Movement

No Asbestos

B00D - R0002 - Toilets - Boys

No Asbestos

B00D - R0003 - Cleaning Distributed Store

No Asbestos

B00D - R0004 - Toilets - Girls

No Asbestos

B00D - R0005 - Practical Activities - 1hb

No Asbestos

B00D - R0006 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0008 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0010 - Practical Activities - 1hb

No Asbestos

B00D - R0011 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0012 - Practical Activities - 1hb

No Asbestos

B00D - R0013 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0015 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0017 - Practical Activities - 1hb

No Asbestos

B00D - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0019 - Practical Activities - 1hb

No Asbestos

B00D - R0020 - Home Base Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0021 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0022 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0023 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0024 - Practical Activities - 1hb						
No Asbestos						
B00D - R0025 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00D - R0026 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R0027 - External Movement						
No Asbestos						
B00D - R0028 - External Movement						
No Asbestos						
B00D - R0029 - External Movement						
No Asbestos						
B00D - R0030 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00D - R0031 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Pupil Facilities - 1993 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Canteen Office/Store

No Asbestos

B00E - R0002 - Canteen

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Other - 2008 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Multi Purpose Facilities - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Practical Activities - 1hb

No Asbestos

B00G - R0003 - Home Base Store

No Asbestos

B00G - R0004 - Home Base

No Asbestos

B00G - R0005 - Withdrawal Space - 2hb

No Asbestos

B00G - R0006 - Home Base

No Asbestos

B00G - R0007 - Home Base Store

No Asbestos

B00G - R0008 - Practical Activities - 1hb

No Asbestos

B00G - R0009 - Practical Activities - 1hb

No Asbestos

B00G - R0010 - Home Base Store

No Asbestos

B00G - R0011 - Home Base

No Asbestos

B00G - R0012 - Withdrawal Space - 2hb

No Asbestos

B00G - R0013 - Home Base

No Asbestos

B00G - R0014 - Home Base Store

No Asbestos

B00G - R0015 - Practical Activities - 1hb

No Asbestos

B00G - R0016 - Movement

No Asbestos

B00G - R0017 - Special Programs Room

No Asbestos

B00G - R0018 - Special Programs Store

No Asbestos



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Building Services - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00H - R0001 - General Storeroom

No Asbestos

B00H - R0002 - General Storeroom

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

4609_ASB_261112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017