


# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** G S Kidd Memorial School (5685)  
**Region :** New England  
**State Electorate :**  
**Local Government Area :** Gunnedah

**Initial Survey :** Noel Arnold & Associates : 25 - Mar - 2008  
**Reviewed By :** AECOM : 29 - Apr - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - Administration/Library - 2013 - Fibre Cement Clad (Fibre Cement Clad)****Exterior**

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible					
Wall Cladding	Flat AC Sheeting 5685/B00A/Wall Cladding/S1					<b>No Asbestos Detected</b>
Ceiling Voids	No Asbestos Found					

**Interior****B00A - R0001 - External Movement**

No Asbestos

**B00A - R0002 - Library Administration**

Floor Coverings Res/Textile	Compressed AC Sheet 5685/B00A/R0002/Floor Coverings Res/Textile/S2					<b>No Asbestos Detected</b>
-----------------------------	---	--	--	--	--	-----------------------------

**B00A - R0003 - Store**

No Asbestos

**B00A - R0004 - Communication Space**

No Asbestos

**B00A - R0005 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00A - R0006 - Practical Activities**

No Asbestos

**B00A - R0007 - Store**

No Asbestos

**B00A - R0008 - Store**

No Asbestos

**B00A - R0009 - Plant**

No Asbestos

**B00A - R0010 - Movement**

No Asbestos

**B00A - R0011 - Administration - Clerical**

No Asbestos

**B00A - R0012 - Interview/Meeting**

No Asbestos

**B00A - R0013 - Toilets-Disabled**

No Asbestos

**B00A - R0014 - Toilets-Unisex**

No Asbestos

**B00A - R0015 - Cleaning Supplies Store**

No Asbestos

**B00A - R0016 - Administration - Executive**

No Asbestos

**B00A - R0017 - Staff Lounge**

No Asbestos

**B00A - R0018 - Principal Office**

No Asbestos

**B00A - R0019 - Clinic**

No Asbestos

**B00A - R0020 - Store**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0021 - Movement</b>						
No Asbestos						
<b>B00A - R0022 - Toilets-Disabled</b>						
No Asbestos						
<b>B00A - R0023 - Distribution Board Cupboard</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00A - R0024 - Movement</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Multi Purpose Facilities - 2013 - Timber (Timber)****Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area

- Area inaccessible

Ceiling Voids      No Asbestos Found

**Interior****B00B - R0001 - Staff Kitchen**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0002 - Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0003 - Dining Room**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0004 - Multi-Purpose Space**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0005 - Sport Equipment Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0006 - Sport Equipment Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0007 - Toilets - Girls**

No Asbestos

**B00B - R0008 - Toilets - Boys**

No Asbestos

**B00B - R0009 - Toilets-Disabled**

No Asbestos

**B00B - R0010 - Store**

No Asbestos

**B00B - R0011 - General Assistants**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0012 - Store**

No Asbestos

**B00B - R0013 - External Movement**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B00B - R0014 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

**B00B - R0015 - Plant**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - General Learning - 2013 - Brick/Veneer (Brick/Veneer)****Exterior**

Underfloor Voids - Slab on Ground      Non Accessible Area

- Area inaccessible

Ceiling Voids      No Asbestos Found

**Interior****B00C - R0001 - Plant**

No Asbestos

**B00C - R0002 - G.L.S. Store**

No Asbestos

**B00C - R0003 - Other**

No Asbestos

**B00C - R0004 - General Learning Space**

No Asbestos

**B00C - R0005 - Other**

No Asbestos

**B00C - R0006 - Practical Activities**

No Asbestos

**B00C - R0007 - Laundry**

No Asbestos

**B00C - R0008 - Toilets-Disabled**

No Asbestos

**B00C - R0009 - Laundry**

No Asbestos

**B00C - R0010 - Change**

No Asbestos

**B00C - R0011 - General Learning Space**

No Asbestos

**B00C - R0012 - Cleaning Store - Distributed**

No Asbestos

**B00C - R0013 - G.L.S. Store**

No Asbestos

**B00C - R0014 - Therapy**

No Asbestos

**B00C - R0015 - Therapy**

No Asbestos

**B00C - R0016 - G.L.S. Store**

No Asbestos

**B00C - R0017 - Store**

No Asbestos

**B00C - R0018 - General Learning Space**

No Asbestos

**B00C - R0019 - Change**

No Asbestos

**B00C - R0020 - Practical Activities**

No Asbestos

**B00C - R0021 - Toilets-Disabled**

No Asbestos

**B00C - R0022 - Breakout Area**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00C - R0023 - General Learning Space</b>						
No Asbestos						
<b>B00C - R0024 - Toilets-Disabled</b>						
No Asbestos						
<b>B00C - R0025 - G.L.S. Store</b>						
No Asbestos						
<b>B00C - R0026 - Therapy</b>						
No Asbestos						
<b>B00C - R0027 - External Movement</b>						
No Asbestos						
<b>B00C - R0028 - Breakout Area</b>						
No Asbestos						
<b>B00C - R0029 - Breakout Area</b>						
No Asbestos						
<b>B00C - R0030 - Practical Activities</b>						
No Asbestos						
<b>B00C - R0031 - Distribution Board Cupboard</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00C - R0032 - Distribution Board Cupboard</b>				Note: No inspection of live electrical installation.		
No Asbestos						
<b>B00C - R0033 - Practical Activities</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00D - Physical Education - 2013 - Steel (Steel)****Exterior**

Underfloor Voids - Packing to Floor Joists      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior****B00D - R0001 - Movement**

No Asbestos

**B00D - R0002 - Movement**

No Asbestos

**B00D - R0003 - Hydrotherapy - Pool**

No Asbestos

**B00D - R0004 - Plant**

No Asbestos

**B00D - R0005 - Store**

No Asbestos

**B00D - R0006 - Toilets-Disabled**

No Asbestos

**B00D - R0007 - Toilets-Disabled**

No Asbestos

**B00D - R0008 - Change**

No Asbestos

**B00D - R0009 - Distribution Board Cupboard**

Note: No inspection of live electrical installation.

No Asbestos

# 2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 602 - D14203 - Learning Unit - Standard With P.A.A. : Placement Date - 2/07/2014**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017