

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning/Pupil Facilities - 1968 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 2293/B001/Eaves Linings/S7					No Asbestos Detected

Interior

B001 - R0019 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 2293/B003/R0008/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B001 - R0020 - Home Base Store

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0021 - Practical Activities/Movement - 1hb

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0022 - Home Base

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0023 - Withdrawal Space - 2hb

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0024 - Home Base

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0025 - Practical Activities/Movement - 1hb

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0026 - Home Base Store

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0027 - Home Base Store

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0028 - Practical Activities/Movement - 1hb

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0029 - Distribution Board

No Asbestos					Note: No inspection of live electrical installation.	
-------------	--	--	--	--	--	--

B001 - R0030 - Home Base

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0031 - Withdrawal Space - 2hb

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0032 - Practical Activities/Movement - 1hb

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0033 - Home Base

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R0034 - Home Base Store

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R9004 - Movement

Wall Linings Internal	Flat AC Sheeting 2293/B002/R0012/Wall Linings Internal/S2					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B001 - R9005 - Plant

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R9006 - Cleaning Distributed Store

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R9009 - Toilets - Boys

No Asbestos						
-------------	--	--	--	--	--	--

B001 - R9011 - General Assistant/Bulk Store

--	--	--	--	--	--	--

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting		2293/B002/R0012/Wall Linings Internal/S2			No Asbestos Detected
B001 - R9012 - Sports Store						
Wall Linings Internal	Flat AC Sheeting		2293/B002/R0012/Wall Linings Internal/S2			No Asbestos Detected
B001 - R9013 - Toilets - Girls						
No Asbestos						
B001 - R9014 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B002 - General Learning/Pupil Facilities - 1968 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found					
Ceiling Voids - Flat Roof	No Asbestos Found					
Eaves Linings	Flat AC Sheeting 2293/B003/R0008/Ceiling Structures/Linings/S1					No Asbestos Detected
Awnings	Flat AC Sheeting 2293/B002/Awnings/S6					No Asbestos Detected
Fascia	Compressed AC Sheet 2293/B002/Fascia/S8					No Asbestos Detected

Interior

B002 - R0012 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 2293/B002/R0012/Wall Linings Internal/S2					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B002 - R0013 - Staff Toilet

Wall Linings Internal	Flat AC Sheeting 2293/B002/R0012/Wall Linings Internal/S2					No Asbestos Detected
-----------------------	--	--	--	--	--	----------------------

B002 - R0024 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting 2293/B003/R0008/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B002 - R0025 - Movement

Ceiling Structures/Linings	Flat AC Sheeting 2293/B003/R0008/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B002 - R0026 - Practical Activities/Movement - 1hb

No Asbestos

B002 - R0027 - Home Base Store

No Asbestos

B002 - R0028 - Home Base

No Asbestos

B002 - R0029 - Withdrawal Space - 2hb

No Asbestos

B002 - R0030 - Home Base

No Asbestos

B002 - R0031 - Practical Activities/Movement - 1hb

No Asbestos

B002 - R0032 - Home Base Store

No Asbestos

B002 - R0033 - Interview

No Asbestos

B002 - R0034 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B002 - R0035 - Practical Activities/Movement - 1hb

No Asbestos

B002 - R0036 - Home Base Store

No Asbestos

B002 - R0037 - Home Base

No Asbestos

B002 - R0038 - Withdrawal Space - 2hb

No Asbestos

B002 - R0039 - Home Base

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B002 - R0040 - Practical Activities/Movement - 1hb						
No Asbestos						
B002 - R0041 - Home Base Store						
No Asbestos						
B002 - R0042 - Stairs						
Ceiling Structures/Linings	Flat AC Sheeting					
	2293/B003/R0008/Ceiling Structures/Linings/S1					No Asbestos Detected
B002 - R0044 - External Movement						
No Asbestos						
B002 - R9001 - Cleaning Distributed Store						
No Asbestos						
B002 - R9006 - Kiln Room						
No Asbestos						
B002 - R9010 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting					
	2293/B003/R0008/Ceiling Structures/Linings/S1					No Asbestos Detected
B002 - R9011 - Sports Store						
No Asbestos						
B002 - R9012 - Special Programs Store						
No Asbestos						
B002 - R9013 - Special Programs Room						
No Asbestos						
B002 - R9014 - Plant						
No Asbestos						
B002 - R9015 - Toilets - Girls						
No Asbestos						
B002 - R9016 - Toilets - Boys						
No Asbestos						
B002 - R9017 - Movement						
No Asbestos						
B002 - R9018 - Stairs						
No Asbestos						
B002 - R9019 - Covered Outdoor Learning Area						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B003 - Library/General Learning - 1871 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Flat Roof	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					
Fascia	Compressed AC Sheet 2293/B003/Fascia/S4					No Asbestos Detected
Eaves Linings	Flat AC Sheeting 2293/B003/Eaves Linings/S5					No Asbestos Detected

Interior

B003 - R0008 - Stairs

Ceiling Structures/Linings	Flat AC Sheeting 2293/B003/R0008/Ceiling Structures/Linings/S1					No Asbestos Detected
----------------------------	---	--	--	--	--	----------------------

B003 - R9001 - Garden Store

No Asbestos

B003 - R9002 - General Assistant/Bulk Store

No Asbestos

B003 - R9004 - Stairs

No Asbestos

B003 - R9005 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Communal Facilities/Pupil Facilities - 2000 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00E - R0001 - Covered Outdoor Learning Area

No Asbestos

B00E - R0002 - Communal Space

No Asbestos

B00E - R0003 - Movement

No Asbestos

B00E - R0004 - Raised Platform

No Asbestos

B00E - R0005 - Movement

No Asbestos

B00E - R0006 - External Movement

No Asbestos

B00E - R0007 - Toilets - Girls

No Asbestos

B00E - R0008 - Hall Chair Store

No Asbestos

B00E - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0010 - P.E. Store

No Asbestos

B00E - R0011 - Garden Store

No Asbestos

B00E - R0012 - Cleaning Distributed Store

No Asbestos

B00E - R0013 - Communications Cupboard

No Asbestos

B00E - R0014 - Toilets - Boys

No Asbestos

B00E - R0015 - Disabled Toilet

No Asbestos

B00E - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0017 - Cleaning Supplies

No Asbestos

B00E - R0018 - Canteen Office/Store

No Asbestos

B00E - R0019 - Canteen

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 2001 - Timber (Timber)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00F - R0001 - Home Base Store

No Asbestos

B00F - R0002 - Home Base Store

No Asbestos

B00F - R0003 - External Movement

No Asbestos

B00F - R0004 - Special Programs Room

No Asbestos

B00F - R0005 - Staff Kitchen

No Asbestos

B00F - R0006 - Withdrawal Space - 1hb

No Asbestos

B00F - R0007 - Home Base Store

No Asbestos

B00F - R0008 - Practical Activities/Movement - 1hb

No Asbestos

B00F - R0009 - Home Base

No Asbestos

B00F - R0010 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Sports Store - 2009 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

Interior

B00G - R0001 - P.E. Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Building Services - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B00H - R0001 - Sports Store

No Asbestos

B00H - R0002 - General Assistant/Bulk Store

No Asbestos

B00H - R0003 - Garden Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - General Learning - 2011 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids	No Asbestos Found

Interior

B001 - R0001 - Special Programs Store

No Asbestos

B001 - R0002 - Special Programs Store

No Asbestos

B001 - R0003 - Special Programs Room

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0C1 - Administration/Library - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 2293/B0C1/Wall Cladding/S3					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior**B0C1 - R0001 - External Movement**

No Asbestos

B0C1 - R0002 - External Stairs

No Asbestos

B0C1 - R0003 - Entry Vestibule

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0C1 - R0004 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0C1 - R0005 - Sick Bay

No Asbestos

B0C1 - R0006 - Disabled Toilet

No Asbestos

B0C1 - R0007 - Cleaning Distributed Store

No Asbestos

B0C1 - R0008 - Staff Toilet

No Asbestos

B0C1 - R0009 - Staff Toilet

No Asbestos

B0C1 - R0010 - Staff Toilet

No Asbestos

B0C1 - R0011 - General Storeroom

No Asbestos

B0C1 - R0012 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0C1 - R0013 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0C1 - R0014 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0C1 - R0015 - Interview

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0C1 - R0016 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0C1 - R0017 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0C1 - R0018 - Principal

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0C1 - R0019 - Duplicating Workroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B0C1 - R0020 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B0C1 - R0021 - Lift						
No Asbestos						
B0C1 - R0022 - External Stairs						
No Asbestos						
B0C1 - R0023 - External Movement						
No Asbestos						
B0C1 - R1001 - External Movement						
No Asbestos						
B0C1 - R1002 - Reading Area						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0C1 - R1003 - Communications Room						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0C1 - R1004 - Library Office/Workroom						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0C1 - R1005 - K.L.A. Store						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0C1 - R1006 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B0C1 - R1007 - Cleaning Distributed Store						
No Asbestos						
B0C1 - R1008 - Special Programs Room						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0C1 - R1009 - General Storeroom						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0C1 - R1010 - Disabled Toilet						
No Asbestos						
B0C1 - R1011 - Lift						
No Asbestos						
B0C1 - R1012 - External Stairs						
No Asbestos						
B0C1 - R1013 - External Movement						
No Asbestos						
B0C1 - R1014 - External Stairs						
No Asbestos						
B0C1 - R9001 - Movement						
No Asbestos						
B0C1 - R9002 - Plant						
No Asbestos						
B0C1 - R9003 - Lift						
No Asbestos						
B0C1 - R9004 - General Storeroom						
No Asbestos						



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0D1 - General Learning - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Underfloor Voids - Slab on Ground	No Asbestos Found					
Wall Cladding	Compressed AC Sheet 2293/B0C1/Wall Cladding/S3					No Asbestos Detected
Ceiling Voids	No Asbestos Found					

Interior**B0D1 - R0001 - External Movement**

No Asbestos

B0D1 - R0002 - Main Switch Board

No Asbestos

B0D1 - R0003 - Personal Effects Storage

No Asbestos

B0D1 - R0004 - Practical Activities - 1hb

No Asbestos

B0D1 - R0005 - Home Base Store

No Asbestos

B0D1 - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0D1 - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0D1 - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0D1 - R0009 - Home Base Store

No Asbestos

B0D1 - R0010 - Practical Activities - 1hb

No Asbestos

B0D1 - R0011 - Personal Effects Storage

No Asbestos

B0D1 - R0012 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B0D1 - R0013 - Personal Effects Storage

No Asbestos

B0D1 - R0014 - Practical Activities - 1hb

No Asbestos

B0D1 - R0015 - Home Base Store

No Asbestos

B0D1 - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0D1 - R0017 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0D1 - R0018 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B0D1 - R0019 - Home Base Store

No Asbestos

B0D1 - R0020 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B0D1 - R0021 - Personal Effects Storage						
No Asbestos						
B0D1 - R0022 - Cleaning Distributed Store						
No Asbestos						
B0D1 - R0023 - External Stairs						
No Asbestos						
B0D1 - R1001 - External Movement						
No Asbestos						
B0D1 - R1002 - Personal Effects Storage						
No Asbestos						
B0D1 - R1003 - Practical Activities - 1hb						
No Asbestos						
B0D1 - R1004 - Home Base Store						
No Asbestos						
B0D1 - R1005 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0D1 - R1006 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0D1 - R1007 - Personal Effects Storage						
No Asbestos						
B0D1 - R1008 - Practical Activities - 1hb						
No Asbestos						
B0D1 - R1009 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0D1 - R1010 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0D1 - R1011 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B0D1 - R1012 - Personal Effects Storage						
No Asbestos						
B0D1 - R1013 - Practical Activities - 1hb						
No Asbestos						
B0D1 - R1014 - Cleaning Distributed Store						
No Asbestos						
B0D1 - R1015 - Home Base Store						
No Asbestos						
B0D1 - R1016 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0D1 - R1017 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0D1 - R1018 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						
B0D1 - R1019 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0D1 - R1020 - Practical Activities - 1hb						
No Asbestos						
B0D1 - R1021 - Personal Effects Storage						
No Asbestos						
B0D1 - R1022 - External Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 602 - D16298 - Learning Unit - Standard With P.A.A. : Placement Date - 12/03/2015

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017