


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Katoomba Public School (4546)
Region : Western Sydney
State Electorate : Blue Mountains
Local Government Area : Blue Mountains

Initial Survey : Noel Arnold & Associates : 23 - May - 2008
Reviewed By : Parsons Brinckerhoff : 25 - Nov - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration/General Learning - 1902 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	100m2	Throughout, Upper & Lower	Good Condition (1)	Low (1)	Low Priority (2-3)
	4546/B00A/Eaves Linings/S2					Chrysotile (white asbestos)
Ceiling Void	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00A - R0001 - Home Base

No Asbestos

B00A - R0002 - Home Base Store

No Asbestos

B00A - R0003 - Withdrawal Space - 1hb

No Asbestos

B00A - R0004 - Home Base Store

No Asbestos

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Toilets - Girls

No Asbestos

B00A - R0007 - Practical Activities - 1hb

No Asbestos

B00A - R0008 - Practical Activities - 1hb

No Asbestos

B00A - R0009 - Practical Activities - 1hb

No Asbestos

B00A - R0010 - Toilets - Boys

No Asbestos

B00A - R0011 - Home Base

No Asbestos

B00A - R0012 - Home Base Store

No Asbestos

B00A - R0013 - Withdrawal Space - 1hb

No Asbestos

B00A - R0014 - Home Base Store

No Asbestos

B00A - R0015 - Home Base

No Asbestos

B00A - R0016 - Movement

No Asbestos

B00A - R0017 - General Storeroom

No Asbestos

B00A - R0018 - Disabled Shower/Toilet

No Asbestos

B00A - R0019 - Cleaning Distributed Store

No Asbestos

B00A - R0020 - Movement

No Asbestos

B00A - R0021 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0022 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R0023 - Distribution Board					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings		Flat AC Sheeting		4546/B00A/R0023/Ceiling Structures/Linings/S1		
No Asbestos Detected						
B00A - R0024 - Practical Activities - M - 1hb						
No Asbestos						
B00A - R0025 - Home Base - M						
No Asbestos						
B00A - R0026 - Movement						
No Asbestos						
B00A - R0027 - Movement						
No Asbestos						
B00A - R0028 - General Storeroom						
No Asbestos						
B00A - R0029 - Practical Activities - 1hb						
No Asbestos						
B00A - R0030 - Home Base						
No Asbestos						
B00A - R0031 - Staff Toilet						
No Asbestos						
B00A - R0032 - Staff Toilet						
No Asbestos						
B00A - R0033 - Cleaning Distributed Store						
No Asbestos						
B00A - R0034 - Toilets - Girls						
No Asbestos						
B00A - R0035 - Cleaning Distributed Store						
No Asbestos						
B00A - R0036 - Movement						
No Asbestos						
B00A - R0037 - Duplicating Workroom						
No Asbestos						
B00A - R0038 - Clerical Office						
No Asbestos						
B00A - R0039 - Sick Bay						
No Asbestos						
B00A - R0040 - Movement						
No Asbestos						
B00A - R0041 - Entry Vestibule						
No Asbestos						
B00A - R0042 - Movement						
No Asbestos						
B00A - R0043 - Principal						
No Asbestos						
B00A - R0044 - Interview						
No Asbestos						
B00A - R0045 - Deputy Principal						
No Asbestos						
B00A - R0046 - Interview						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R0047 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R0048 - Community Clinic						
No Asbestos						
B00A - R0049 - Community Clinic						
No Asbestos						
B00A - R0050 - Community Clinic						
No Asbestos						
B00A - R0051 - Movement						
No Asbestos						
B00A - R0052 - Uniform Shop						
No Asbestos						
B00A - R0053 - Movement						
No Asbestos						
B00A - R0054 - Movement						
No Asbestos						
B00A - R0055 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4546/B00A/R0055/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	
B00A - R0056 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	67m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4546/B00A/R0055/Ceiling Structures/Linings/S4					Chrysotile (white asbestos)	
B00A - R0057 - Movement						
No Asbestos						
B00A - R0058 - Movement						
No Asbestos						
B00A - R0059 - Stairs						
No Asbestos						
B00A - R0060 - Stairs						
No Asbestos						
B00A - R0061 - Stairs						
No Asbestos						
B00A - R0062 - Stairs						
No Asbestos						
B00A - R0063 - Movement						
Infill Panels under Windows	Flat AC Sheeting					
4546/B00A/R0063/Infill Panels under Windows/S5					No Asbestos Detected	
B00A - R1001 - Home Base						
No Asbestos						
B00A - R1002 - Home Base Store						
No Asbestos						
B00A - R1003 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R1004 - General Storeroom						
No Asbestos						
B00A - R1005 - Home Base Store						
No Asbestos						
B00A - R1006 - Practical Activities - 1hb						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1007 - Movement						
No Asbestos						
B00A - R1008 - Home Base						
No Asbestos						
B00A - R1009 - Cleaning Distributed Store						
No Asbestos						
B00A - R1010 - Special Programs Room						
No Asbestos						
B00A - R1011 - Distribution Board					Note: No inspection of live electrical installation.	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4546/B00A/R1011/Ceiling Structures/Linings/S3					Chrysotile (white asbestos)	
B00A - R1012 - General Storeroom						
No Asbestos						
B00A - R1013 - Plant						
No Asbestos						
B00A - R1014 - Movement						
No Asbestos						
B00A - R1015 - General Storeroom						
No Asbestos						
B00A - R1016 - General Storeroom						
No Asbestos						
B00A - R1017 - Toilets - Boys						
No Asbestos						
B00A - R1018 - Toilets - Girls						
No Asbestos						
B00A - R1019 - Special Programs Room						
No Asbestos						
B00A - R1020 - Practical Activities - 1hb						
No Asbestos						
B00A - R1021 - Home Base						
No Asbestos						
B00A - R1022 - Withdrawal Space - 1hb						
No Asbestos						
B00A - R1023 - Interview						
No Asbestos						
B00A - R1024 - Personal Effects Storage						
No Asbestos						
B00A - R1025 - Practical Activities - 1hb						
No Asbestos						
B00A - R1026 - Home Base						
No Asbestos						
B00A - R1027 - General Storeroom						
No Asbestos						
B00A - R1028 - Staff Room						
No Asbestos						
B00A - R1029 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00A - R1030 - Staff Toilet						
No Asbestos						
B00A - R1031 - Staff Toilet						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00A - R1032 - Staff Shower/Change

No Asbestos

B00A - R1033 - Staff Shower/Change

No Asbestos

B00A - R1034 - Movement

No Asbestos

B00A - R1035 - Stairs

No Asbestos

B00A - R1036 - Stairs

No Asbestos

B00A - R1037 - Stairs

No Asbestos

B00A - R1038 - Stairs

No Asbestos

B00A - R1039 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Communal Facilities/Pupil Facilities - 1980 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	Non Accessible Area - No Access - No manhole to Building

Interior

B00B - R0001 - Movement

No Asbestos

B00B - R0002 - Communal Space

No Asbestos

B00B - R0003 - P.E. Store

No Asbestos

B00B - R0004 - Plant

No Asbestos

B00B - R0005 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0006 - Hall Chair Store

No Asbestos

B00B - R0007 - Movement

No Asbestos

B00B - R0008 - Movement

No Asbestos

B00B - R0009 - Raised Platform

No Asbestos

B00B - R0010 - Movement

No Asbestos

B00B - R0011 - Canteen

No Asbestos

B00B - R0012 - Movement

No Asbestos

B00B - R0013 - Canteen Office/Store

No Asbestos

B00B - R0014 - Canteen Office/Store

No Asbestos

B00B - R0015 - Staff Toilet

No Asbestos

B00B - R0016 - Canteen Office/Store

No Asbestos

B00B - R0017 - Movement

No Asbestos

B00B - R0018 - General Assistant/Bulk Store

No Asbestos

B00B - R0019 - General Assistant/Bulk Store

No Asbestos

B00B - R0020 - Cleaning Supplies

No Asbestos

B00B - R0021 - Movement

No Asbestos

B00B - R0022 - General Storeroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R0023 - Movement

No Asbestos

B00B - R0024 - Movement

No Asbestos

B00B - R0025 - Movement

No Asbestos

B00B - R0026 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library/Pupil Facilities - 1980 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	Non Accessible Area - No Access - No Manhole to building

Interior

B00C - R0001 - Special Programs Room	No Asbestos
B00C - R0002 - Library Office/Workroom	No Asbestos
B00C - R0003 - Library Office/Workroom	No Asbestos
B00C - R0004 - K.L.A. Store	No Asbestos
B00C - R0005 - Reading Area	No Asbestos
B00C - R0006 - Craft Store	No Asbestos
B00C - R0007 - Toilets - Boys	No Asbestos
B00C - R0008 - Main Switch Board	No Asbestos
B00C - R0009 - Kiln Room	No Asbestos
B00C - R0010 - General Assistant/Bulk Store	No Asbestos
B00C - R0011 - Movement	No Asbestos
B00C - R0013 - Seminar/Study	No Asbestos
B00C - R0014 - Seminar/Study	No Asbestos
B00C - R0015 - Cleaning Distributed Store	No Asbestos
B00C - R0016 - Toilets - Boys	No Asbestos
B00C - R0017 - Toilets - Girls	No Asbestos
B00C - R0018 - Movement	No Asbestos
B00C - R0019 - Movement	No Asbestos
B00C - R0020 - Movement	No Asbestos
B00C - R0021 - Movement	No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - General Learning/Pupil Facilities - 1980 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	Non Accessible Area - No Access - No manhole to building

Interior

B00D - R0001 - Movement

No Asbestos

B00D - R0002 - Practical Activities - 1hb

No Asbestos

B00D - R0003 - Home Base Store

No Asbestos

B00D - R0004 - Home Base

No Asbestos

B00D - R0005 - Withdrawal Space - 1hb

No Asbestos

B00D - R0006 - Home Base

No Asbestos

B00D - R0007 - Home Base Store

No Asbestos

B00D - R0008 - Personal Effects Storage

No Asbestos

B00D - R0009 - Movement

No Asbestos

B00D - R0010 - Practical Activities - 1hb

No Asbestos

B00D - R0011 - Home Base

No Asbestos

B00D - R0012 - Withdrawal Space - 1hb

No Asbestos

B00D - R0013 - Home Base Store

No Asbestos

B00D - R0014 - Home Base

No Asbestos

B00D - R0015 - Home Base Store

No Asbestos

B00D - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0017 - Cleaning Distributed Store

No Asbestos

B00D - R0018 - Disabled Toilet

No Asbestos

B00D - R0019 - Toilets - Boys

No Asbestos

B00D - R0020 - Personal Effects Storage

No Asbestos

B00D - R0021 - Movement

No Asbestos

B00D - R0022 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00D - R0023 - Movement

No Asbestos

B00D - R0024 - Staff Room Annexe

No Asbestos

B00D - R0025 - Movement

No Asbestos

B00D - R0026 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning/Pupil Facilities - 1980 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	No Asbestos Found
Ceiling Voids - Raked Ceiling	Non Accessible Area - No Access - No manhole to building

Interior

B00E - R0001 - Movement	No Asbestos
B00E - R0002 - Practical Activities - 1hb	No Asbestos
B00E - R0003 - Home Base Store	No Asbestos
B00E - R0004 - Home Base	No Asbestos
B00E - R0005 - Withdrawal Space - 1hb	No Asbestos
B00E - R0006 - Home Base	No Asbestos
B00E - R0007 - Home Base Store	No Asbestos
B00E - R0008 - Personal Effects Storage	No Asbestos
B00E - R0009 - Movement	No Asbestos
B00E - R0010 - Practical Activities - 1hb	No Asbestos
B00E - R0011 - Home Base	No Asbestos
B00E - R0012 - Withdrawal Space - 1hb	No Asbestos
B00E - R0013 - Home Base Store	No Asbestos
B00E - R0014 - Home Base	No Asbestos
B00E - R0015 - Home Base Store	No Asbestos
B00E - R0016 - Distribution Board	Note: No inspection of live electrical installation.
B00E - R0017 - Cleaning Distributed Store	No Asbestos
B00E - R0018 - Toilets - Girls	No Asbestos
B00E - R0019 - Personal Effects Storage	No Asbestos
B00E - R0020 - Movement	No Asbestos
B00E - R0021 - Practical Activities - 1hb	No Asbestos
B00E - R0022 - Movement	No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00E - R0023 - Staff Room Annexe

No Asbestos

B00E - R0024 - Movement

No Asbestos

B00E - R0025 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Support Unit - 1980 - Steel (Steel)

Exterior

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Void No Asbestos Found

Interior

B00F - R0005 - Communal Space

No Asbestos

B00F - R0006 - Covered Outdoor Learning Area

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

4546_ASB_010713_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017