


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lucas Heights Community School (8271)
Region : Sydney
State Electorate : Holsworthy
Local Government Area : Sutherland

Initial Survey : Noel Arnold & Associates : 13 - Jun - 2008
Register Issue Date : 24 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning/Pupil Facilities - 1991 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00A - R0001 - Cleaning Store - Distributed

No Asbestos

B00A - R0002 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0003 - Practical Activities - 1hb

No Asbestos

B00A - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0007 - Practical Activities - 1hb

No Asbestos

B00A - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0012 - Practical Activities - 1hb

No Asbestos

B00A - R0013 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0014 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0015 - Practical Activities - 1hb

No Asbestos

B00A - R0016 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00A - R0017 - Toilets - Girls

No Asbestos

B00A - R0018 - Toilets - Boys

No Asbestos

B00A - R0021 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning/Pupil Facilities - 1991 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00B - R0001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0002 - Practical Activities - 1hb

No Asbestos

B00B - R0003 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0006 - Cleaning Store - Distributed

No Asbestos

B00B - R0007 - Practical Activities - 1hb

No Asbestos

B00B - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0009 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0010 - Practical Activities - 1hb

No Asbestos

B00B - R0011 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0012 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00B - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0016 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Administration/General Learning - 1991 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00C - R0001 - Deputy Principal Office**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0002 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0003 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0004 - Entry

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0005 - External Movement

No Asbestos

B00C - R0006 - Administration - Clerical

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0007 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0008 - Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0009 - Deputy Principal Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0010 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0011 - Ancillary Staff

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0012 - Staff - Toilet

No Asbestos

B00C - R0013 - Security Store

No Asbestos

B00C - R0014 - Clinic - Girls

No Asbestos

B00C - R0015 - Clinic-Toilets

No Asbestos

B00C - R0016 - Clinic-Toilets

No Asbestos

B00C - R0017 - Clinic - Boys

No Asbestos

B00C - R0018 - Teachers Aides

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00C - R0019 - General Storeroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0020 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R0021 - External Movement						
No Asbestos						
B00C - R0022 - Duplicating Workroom						
No Asbestos						
B00C - R0023 - External Movement						
No Asbestos						
B00C - R0024 - Staff - Toilet						
No Asbestos						
B00C - R0025 - General Storeroom						
No Asbestos						
B00C - R0026 - Security Store						
No Asbestos						
B00C - R0027 - Staff - Toilet						
No Asbestos						
B00C - R0028 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R0029 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0031 - External Movement						
No Asbestos						
B00C - R0032 - Cleaning Store - Distributed						
No Asbestos						
B00C - R0033 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0034 - Practical Activities - 1hb						
No Asbestos						
B00C - R0035 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0036 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0038 - Practical Activities - 1hb						
No Asbestos						
B00C - R0039 - Home Base						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0040 - Home Base Store						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00C - R0041 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00C - R0042 - Toilets - Boys						
No Asbestos						
B00C - R0043 - Toilets - Girls						
No Asbestos						
B00C - R0044 - External Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00C - R0045 - Student Canteen

No Asbestos

B00C - R0046 - Disabled Toilet

No Asbestos

B00C - R0047 - Canteen Office/Store

No Asbestos

B00C - R0048 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0049 - External Movement

No Asbestos

B00C - R0051 - External Movement

No Asbestos

B00C - R0052 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Library/Staff Facilities - 1991 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00D - R0001 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0002 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0003 - External Movement

No Asbestos

B00D - R0004 - Cleaning Store - Distributed

No Asbestos

B00D - R0005 - Commonroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0006 - Staff - Toilet

No Asbestos

B00D - R0007 - Staff - Toilet

No Asbestos

B00D - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0009 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0010 - Librarian

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0011 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0012 - Library Office/Workroom

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0013 - Reading Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0014 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0015 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0016 - External Movement

No Asbestos

B00D - R0017 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0018 - Seminar

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00D - R0019 - Seminar

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00D - R0020 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1991 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00E - R0001 - Kiln Space

No Asbestos

B00E - R0002 - Sport Equipment Store

No Asbestos

B00E - R0003 - External Movement

No Asbestos

B00E - R0004 - Cleaning Supplies Store

No Asbestos

B00E - R0005 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0007 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0008 - Practical Activities - 1hb

No Asbestos

B00E - R0009 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0010 - Disabled Toilet

No Asbestos

B00E - R0011 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0012 - External Movement

No Asbestos

B00E - R0013 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0014 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0015 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0017 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00E - R0018 - External Movement

No Asbestos

B00E - R0019 - Home Base/Practical Activities

No Asbestos

B00E - R0020 - Disabled Shower/Toilet

No Asbestos

B00E - R0021 - Home Base Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning/Staff Facilities - 1991 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00F - R0001 - Cleaning Supplies Store

No Asbestos

B00F - R0002 - General Assistant/Bulk Store

No Asbestos

B00F - R0003 - Cleaning Supplies Store

No Asbestos

B00F - R0004 - Canteen Office/Store

No Asbestos

B00F - R0005 - Student Canteen

No Asbestos

B00F - R0006 - Disabled Toilet

No Asbestos

B00F - R0007 - Cleaning Store - Distributed

No Asbestos

B00F - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0009 - Serviced Learning Space

No Asbestos

B00F - R0010 - Wheelchair Store

No Asbestos

B00F - R0011 - Cleaning Store - Distributed

No Asbestos

B00F - R0012 - Therapy

No Asbestos

B00F - R0013 - Toilet - P

No Asbestos

B00F - R0014 - Laundry - P

No Asbestos

B00F - R0015 - Movement

No Asbestos

B00F - R0016 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0017 - Special Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0018 - Movement

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0019 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0020 - Computer Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0021 - Computer Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0022 - Darkroom Space						
No Asbestos						
B00F - R0023 - General Storeroom						
No Asbestos						
B00F - R0024 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00F - R0025 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0026 - Computer Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0027 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0028 - Staff Room Annexe						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0029 - Movement						
No Asbestos						
B00F - R0030 - Interview/Meeting						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R0031 - Staff - Toilet						
No Asbestos						
B00F - R0032 - External Movement						
No Asbestos						
B00F - R0033 - External Movement						
No Asbestos						
B00F - R0034 - External Movement						
No Asbestos						
B00F - R0035 - External Movement						
No Asbestos						
B00F - R0036 - External Stairs						
No Asbestos						
B00F - R0037 - External Stairs						
No Asbestos						
B00F - R0038 - External Stairs						
No Asbestos						
B00F - R0039 - External Stairs						
No Asbestos						
B00F - R1001 - External Movement						
No Asbestos						
B00F - R1002 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1003 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1004 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R1005 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1006 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1007 - General Storeroom						
No Asbestos						
B00F - R1008 - General Storeroom						
No Asbestos						
B00F - R1009 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1010 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1011 - Distribution Board				Note: No inspection of live electrical installation.		
No Asbestos						
B00F - R1012 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1013 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1014 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1015 - General Storeroom						
No Asbestos						
B00F - R1016 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1017 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1018 - External Movement						
No Asbestos						
B00F - R1019 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1020 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1021 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1022 - External Movement						
No Asbestos						
B00F - R1023 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1024 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1025 - Withdrawal Space - 1hb						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1026 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1027 - External Movement						
No Asbestos						
B00F - R1028 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1029 - General Storeroom						
No Asbestos						
B00F - R1030 - Staff - Toilet						
No Asbestos						
B00F - R1031 - Cleaning Store - Distributed						
No Asbestos						
B00F - R1032 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B00F - R1033 - General Learning Space						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1034 - Movement						
Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
B00F - R1035 - External Stairs						
No Asbestos						
B00F - R1036 - External Stairs						
No Asbestos						
B00F - R1037 - External Stairs						
No Asbestos						
B00F - R1038 - External Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities/Building Services - 1992 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00G - R0001 - External Movement

No Asbestos

B00G - R0002 - Communal Space

No Asbestos

B00G - R0003 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00G - R0004 - Staff Shower/Change

No Asbestos

B00G - R0005 - Cleaning Store - Distributed

No Asbestos

B00G - R0006 - Sport Equipment Store

No Asbestos

B00G - R0007 - General Storeroom

No Asbestos

B00G - R0008 - Sport Equipment Store

No Asbestos

B00G - R0009 - Shower/Change

No Asbestos

B00G - R0010 - Shower/Change

No Asbestos

B00G - R0011 - Shower/Change

No Asbestos

B00G - R0012 - Shower/Change

No Asbestos

B00G - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Performing Arts/Other-After School Care - 1991 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00H - R0001 - External Movement**

No Asbestos

B00H - R0002 - Disabled Toilet

No Asbestos

B00H - R0003 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0004 - Out Of School Hours Care Centre

No Asbestos

B00H - R0005 - Out Of School Hours Care Centre

No Asbestos

B00H - R0006 - Out Of School Hours Care Centre

No Asbestos

B00H - R0007 - Out Of School Hours Care Centre

No Asbestos

B00H - R0008 - Out Of School Hours Care Centre

No Asbestos

B00H - R0009 - Out Of School Hours Care Centre

No Asbestos

B00H - R0010 - Out Of School Hours Care Centre

No Asbestos

B00H - R0011 - Out Of School Hours Care Centre

No Asbestos

B00H - R0012 - Performance Workspace

No Asbestos

B00H - R0013 - Toilets - Boys

No Asbestos

B00H - R0014 - Toilets - Girls

No Asbestos

B00H - R0015 - Performing Arts Chair Store

No Asbestos

B00H - R0016 - Plant

No Asbestos

B00H - R0017 - Plant

No Asbestos

B00H - R0018 - Main Switch Board

No Asbestos

B00H - R0019 - General Storeroom

No Asbestos

B00H - R0020 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - Tiered Learning/Staff Facilities - 1991 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00I - R0001 - Staff Room Annexe

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0002 - Disabled Toilet

No Asbestos

B00I - R0003 - External Movement

No Asbestos

B00I - R0004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0005 - Special Programs Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0006 - Tiered Learning Area

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00I - R0007 - Garden Store Room

No Asbestos

B00I - R0008 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - Science/Music - 1991 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00J - R0001 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00J - R0002 - Cleaning Store - Distributed

No Asbestos

B00J - R0003 - Music Entry/Display

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0004 - Music Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0005 - Music Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0006 - Practice/Seminar

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0007 - Resources

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0008 - Music Store

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00J - R0009 - Laboratory L.S.

No Asbestos

B00J - R0010 - Laboratory L.S.

No Asbestos

B00J - R0011 - Apparatus Store

No Asbestos

B00J - R0012 - General Storeroom

No Asbestos

B00J - R0013 - Preparation

No Asbestos

B00J - R0014 - Growing/Breeding

No Asbestos

B00J - R0015 - External Movement

No Asbestos

B00J - R0016 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00J - R0017 - Chemical Store

No Asbestos

B00J - R0018 - Laboratory L.S.

No Asbestos

B00J - R0019 - Toilets - Girls

No Asbestos

B00J - R0020 - Toilets - Boys

No Asbestos

B00J - R0021 - Laboratory L.S.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00J - R0022 - Laboratory L.S.

No Asbestos

B00J - R0023 - Movement

No Asbestos

B00J - R0024 - Laboratory L.S.

No Asbestos

B00J - R0028 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1992 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00K - R0001 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0002 - Cleaning Store - Distributed

No Asbestos

B00K - R0003 - Practical Activities - 1hb

No Asbestos

B00K - R0004 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0005 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0007 - Practical Activities - 1hb

No Asbestos

B00K - R0008 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0009 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0010 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0011 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0012 - Practical Activities - 1hb

No Asbestos

B00K - R0013 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0014 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0016 - Practical Activities - 1hb

No Asbestos

B00K - R0017 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0018 - Home Base Store

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00K - R0019 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00L - Communal Facilities/Pupil Facilities - 1992 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00L - R0001 - General Storeroom**

No Asbestos

B00L - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0003 - Chair Store

No Asbestos

B00L - R0004 - Movement

No Asbestos

B00L - R0005 - Raised Platform

No Asbestos

B00L - R0006 - External Movement

No Asbestos

B00L - R0007 - Cleaning Supplies Store

No Asbestos

B00L - R0008 - Communal Space

No Asbestos

B00L - R0009 - External Movement

No Asbestos

B00L - R0010 - Plant

No Asbestos

B00L - R0011 - Toilets - Girls

No Asbestos

B00L - R0012 - Toilets - Boys

No Asbestos

B00L - R0013 - Shower/Change

No Asbestos

B00L - R0014 - Cleaning Store - Distributed

No Asbestos

B00L - R0015 - Sport Equipment Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning/Pupil Facilities - 1992 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00M - R0001 - External Movement**

No Asbestos

B00M - R0002 - Careers Advisers Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0003 - Careers Advisers Office

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0004 - No Access

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0005 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0006 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0007 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0008 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0009 - External Movement

No Asbestos

B00M - R0010 - Toilets - Boys

No Asbestos

B00M - R0011 - Disabled Toilet

No Asbestos

B00M - R0012 - Toilets - Girls

No Asbestos

B00M - R0013 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0014 - General Learning Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0015 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0016 - General Storeroom

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0017 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0018 - Cleaning Store - Distributed

No Asbestos

B00M - R0019 - Seminar

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

B00M - R0020 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found					
---	-------------------	--	--	--	--	--

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Technological & Applied Studies/Computer Learning - 1992 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00N - R0001 - Interview/Office - Type 1

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00N - R0002 - Cleaning Store - Distributed

No Asbestos

B00N - R0003 - Laundry

No Asbestos

B00N - R0004 - Staff - Toilet

No Asbestos

B00N - R0005 - Staff - Toilet

No Asbestos

B00N - R0006 - Food/Research Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00N - R0007 - Food Technology L.S.

No Asbestos

B00N - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0009 - Materials Technology L.S.

No Asbestos

B00N - R0010 - Design L.S.

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00N - R0011 - Wood Technology Bay

No Asbestos

B00N - R0012 - Materials Technology L.S.

No Asbestos

B00N - R0013 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00N - R0014 - Design L.S.

No Asbestos

B00N - R0015 - Design/Technology L.S.

No Asbestos

B00N - R0016 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00N - R0017 - Resource/Project Store

No Asbestos

B00N - R0018 - Computer Learning Space

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00N - R0019 - Metal Technology Bay

No Asbestos

B00N - R0020 - Materials Store

No Asbestos

B00N - R0021 - Resource/Project Store

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00N - R0022 - Personal Effects Storage						
No Asbestos						
B00N - R0023 - Welding Area						
No Asbestos						
B00N - R0024 - Dust Extraction Space						
No Asbestos						
B00N - R0025 - Pantry						
No Asbestos						
B00N - R0026 - Food Technology L.S.						
No Asbestos						
B00N - R0027 - External Movement						
No Asbestos						
B00N - R0028 - External Movement						
No Asbestos						
B00N - R0029 - Covered Vehicle Area/Porte Cochere						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00P - Art - 1992 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00P - R0001 - External Movement

No Asbestos

B00P - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00P - R0003 - Cleaning Store - Distributed

No Asbestos

B00P - R0004 - Kiln Space

No Asbestos

B00P - R0005 - Workshop

No Asbestos

B00P - R0006 - Art Learning Space

No Asbestos

B00P - R0007 - Resources Store

No Asbestos

B00P - R0008 - Cleaning Supplies Store

No Asbestos

B00P - R0009 - Art Learning Space

No Asbestos

B00P - R0010 - Art Learning Space

No Asbestos

B00P - R0011 - Resources Store

No Asbestos

B00P - R0012 - Art Learning Space

No Asbestos

B00P - R0013 - Resources Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00P - R0014 - Resources Space

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00Q - General Learning/Other - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00Q - R0001 - General Assistant/Bulk Store**

No Asbestos

B00Q - R0002 - Home Base Store

No Asbestos

B00Q - R0003 - Home Base

No Asbestos

B00Q - R0004 - Withdrawal Space - 2hb

No Asbestos

B00Q - R0005 - Home Base

No Asbestos

B00Q - R0006 - Home Base Store

No Asbestos

B00Q - R0007 - Special Programs Store

No Asbestos

B00Q - R0008 - Special Programs Room

No Asbestos

B00Q - R0009 - Home Base

No Asbestos

B00Q - R0010 - Practical Activities - 1hb

No Asbestos

B00Q - R0011 - Home Base Store

No Asbestos

B00Q - R0012 - Home Base

No Asbestos

B00Q - R0013 - Withdrawal Space - 2hb

No Asbestos

B00Q - R0014 - Home Base Store

No Asbestos

B00Q - R0015 - Practical Activities - 1hb

No Asbestos

B00Q - R0016 - Movement

No Asbestos

B00Q - R0017 - Practical Activities - 1hb

No Asbestos

B00Q - R0018 - Practical Activities - 1hb

No Asbestos

B00Q - R0019 - Sports Store

No Asbestos

B00Q - R0020 - Secure Storeroom

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017