

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Lisarow High School (8544)
Region : Hunter/Central Coast
State Electorate : The Entrance
Local Government Area : Gosford

Initial Survey : Noel Arnold & Associates : 29 - Mar - 2008
Reviewed By : Greencap-NAA : 20 - Mar - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Performance Learning/Staff Facilities - 1979 - Brick/Block (Brick/Block)**Exterior**

Wall Cladding to Room AR 00 15	Flat AC Sheeting					
	8544/B00A/Wall Cladding to Room AR 00 15/S6					No Asbestos Detected
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00A - R0001 - Performance Store**

No Asbestos

B00A - R0002 - Performance Store

No Asbestos

B00A - R0003 - Performance Workshop

No Asbestos

B00A - R0004 - Toilets-Girls

Partition Walls (Cubicles)	Compressed AC Sheet	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8544/B00A/R0005/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)

B00A - R0005 - Toilets-Boys

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8544/B00A/R0005/Partition Walls (Cubicles)/S3					Chrysotile (white asbestos)

B00A - R0006 - Cleaning Supplies Store

No Asbestos

B00A - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0008 - Cleaning Store - Distributed

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Movement

No Asbestos

B00A - R0014 - External Movement

No Asbestos

B00A - R0015 - General Storeroom

No Asbestos

B00A - R0016 - External Movement

No Asbestos

B00A - R0017 - Stairs

No Asbestos

B00A - R0018 - Dark Room

No Asbestos

B00A - R0019 - General Storeroom

No Asbestos

B00A - R0020 - Darkroom Space

No Asbestos

B00A - R0021 - Dark Room

No Asbestos

B00A - R1002 - Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00A - R1003 - Stairs						
No Asbestos						
B00A - R1004 - Commonroom						
No Asbestos						
B00A - R1005 - Staff Kitchen						
Sink Pad	Resinous Membrane					
	8544/B00C/R0008/Sink Pad/S28					No Asbestos Detected
B00A - Room+1 - AR 0014						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration - 1979 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
No Asbestos Found

Underfloor Voids - Slab on Ground
No Asbestos Found

Interior**B00B - R0001 - General Assistants**

Floor Coverings Res/Textile
Vinyl Tiles
8544/B00B/R0008/Floor Coverings Res/Textile/S1
No Asbestos Detected

B00B - R0002 - Leading Teacher

No Asbestos

B00B - R0003 - Staff - Toilet

Partition Walls (Cubicles)
Compressed AC Sheet
10m2
East, West
Good Condition (1)
Low (1) Low Priority (2-3)
8544/B00B/R0004/Partition Walls (Cubicles)/S2
Chrysotile (white asbestos)

B00B - R0004 - Toilets-Disabled

Partition Walls (Cubicles)
Compressed AC Sheet
3m2
East, West
Good Condition (1)
Low (1) Low Priority (2-3)
8544/B00B/R0004/Partition Walls (Cubicles)/S2
Chrysotile (white asbestos)

B00B - R0005 - Staff - Toilet

Partition Walls (Cubicles)
Compressed AC Sheet
15m2
East, West
Good Condition (1)
Low (1) Low Priority (2-3)
8544/B00B/R0004/Partition Walls (Cubicles)/S2
Chrysotile (white asbestos)

B00B - R0006 - Archive Store

No Asbestos

B00B - R0007 - Ancillary Staff

No Asbestos

B00B - R0008 - Clinic - Girls

Floor Coverings Res/Textile
Vinyl Tiles (Under Floor Covering/Carpet)
8544/B00B/R0008/Floor Coverings Res/Textile/S1
No Asbestos Detected

B00B - R0009 - Toilets-Girls

No Asbestos

B00B - R0010 - Clinic - Boys

Floor Coverings Res/Textile
Vinyl Tiles
8544/B00B/R0008/Floor Coverings Res/Textile/S1
No Asbestos Detected

B00B - R0011 - Toilets-Boys

No Asbestos

B00B - R0012 - Principal Office

No Asbestos

B00B - R0013 - Printing/Photocopying

Floor Coverings Res/Textile
Vinyl Tiles
8544/B00B/R0008/Floor Coverings Res/Textile/S1
No Asbestos Detected

B00B - R0014 - Administration - Clerical

No Asbestos

B00B - R0015 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00B - R0016 - Leading Teacher

No Asbestos

B00B - R0017 - Administration - Clerical

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00B - R0018 - Deputy Principal Office						
No Asbestos						
B00B - R0019 - Deputy Principal Office						
No Asbestos						
B00B - R0020 - Movement						
No Asbestos						
B00B - R0021 - Public Reception						
No Asbestos						
B00B - R0022 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Technological & Applied Studies/Music - 1979 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00C - R0001 - Design L.S.

No Asbestos

B00C - R0002 - Design L.S.

No Asbestos

B00C - R0003 - Food Technology L.S.

Floor Coverings Res/Textile	Vinyl Tiles					
	8544/B00C/R0006/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00C - R0004 - Preparation - Materials

Floor Coverings Res/Textile	Vinyl Tiles					
	8544/B00C/R0006/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00C - R0005 - Food Technology L.S.

Floor Coverings Res/Textile	Vinyl Tiles					
	8544/B00C/R0006/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00C - R0006 - Laundry

Floor Coverings Res/Textile	Vinyl Tiles					
	8544/B00C/R0006/Floor Coverings Res/Textile/S14					No Asbestos Detected

B00C - R0008 - General Learning Space

Floor Coverings Res/Textile	Vinyl Tiles					
	8544/B00B/R0008/Floor Coverings Res/Textile/S1					No Asbestos Detected

Sink Pad	Resinous Membrane					
	8544/B00C/R0008/Sink Pad/S28					No Asbestos Detected

B00C - R0009 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0010 - Toilets-Boys

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8544/B00C/R0010/Partition Walls (Cubicles)/S13					Chrysotile (white asbestos)

B00C - R0011 - Toilets-Girls

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8544/B00C/R0010/Partition Walls (Cubicles)/S13					Chrysotile (white asbestos)

B00C - R0012 - Cleaning Store - Distributed

No Asbestos

B00C - R0014 - External Movement

No Asbestos

B00C - R0015 - Movement

No Asbestos

B00C - R0016 - Movement

No Asbestos

B00C - R0017 - External Movement

No Asbestos

B00C - R0018 - Staff Study

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Wall Linings Internal	Flat AC Sheeting		8544/B00C/R0018/Wall Linings Internal/S29			No Asbestos Detected
B00C - R0019 - Stairs						
No Asbestos						
B00C - R1001 - Music Learning Space						
No Asbestos						
B00C - R1002 - Music Learning Space						
No Asbestos						
B00C - R1003 - Practice/Seminar						
No Asbestos						
B00C - R1004 - Staff Study						
No Asbestos						
B00C - R1005 - Office/Store						
Sink Pad	Resinous Membrane		8544/B00C/R0008/Sink Pad/S28			No Asbestos Detected
B00C - R1006 - Music Store						
Floor Coverings Res/Textile	Vinyl Tiles		8544/B00C/R1006/Floor Coverings Res/Textile/S12			No Asbestos Detected
B00C - R1007 - Movement						
No Asbestos						
B00C - R1008 - External Movement						
No Asbestos						
B00C - R1009 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Art - 1979 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
No Asbestos Found

Underfloor Voids - Slab on Ground
No Asbestos Found

Interior**B00D - R0001 - Resources Store**

Floor Coverings Res/Textile
Vinyl Tiles
8544/B00D/R1005/Floor Coverings Res/Textile/S11
No Asbestos Detected

B00D - R0002 - Art Learning Space

Floor Coverings Res/Textile
Vinyl Tiles
8544/B00D/R1005/Floor Coverings Res/Textile/S11
No Asbestos Detected

B00D - R0003 - Art Learning Space

Floor Coverings Res/Textile
Vinyl Tiles
8544/B00D/R1005/Floor Coverings Res/Textile/S11
No Asbestos Detected

B00D - R0004 - Kiin Space

No Asbestos

B00D - R0005 - Art Learning Space

Floor Coverings Res/Textile
Vinyl Tiles
8544/B00D/R1005/Floor Coverings Res/Textile/S11
No Asbestos Detected

B00D - R0006 - Cleaning Store - Distributed

Ceiling Structures/Linings
Flat AC Sheeting
8544/B00D/R0006/Ceiling Structures/Linings/S30
No Asbestos Detected

B00D - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0008 - Staff - Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00D/R0008/Partition Walls (Cubicles)/S10						Chrysotile (white asbestos)

B00D - R0009 - Staff - Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00D/R0008/Partition Walls (Cubicles)/S10						Chrysotile (white asbestos)

B00D - R0010 - Toilets-Boys

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00D/R0008/Partition Walls (Cubicles)/S10						Chrysotile (white asbestos)

B00D - R0011 - Toilets-Girls

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00D/R0008/Partition Walls (Cubicles)/S10						Chrysotile (white asbestos)

B00D - R0012 - General Storeroom

No Asbestos

B00D - R0013 - Movement

Floor Coverings Res/Textile
Vinyl Tiles
8544/B00D/R1005/Floor Coverings Res/Textile/S11
No Asbestos Detected

B00D - R0014 - External Movement

No Asbestos

B00D - R0015 - Stairs

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0016 - Stairs						
No Asbestos						
B00D - R1001 - Art Learning Space						
Floor Coverings Res/Textile	Vinyl Tiles					
			8544/B00D/R1005/Floor Coverings Res/Textile/S11			No Asbestos Detected
B00D - R1002 - Computer Learning Space						
Floor Coverings Res/Textile	Vinyl Tiles					
			8544/B00D/R1005/Floor Coverings Res/Textile/S11			No Asbestos Detected
B00D - R1003 - Office/Store						
No Asbestos						
B00D - R1004 - General Storeroom						
No Asbestos						
B00D - R1005 - Workshop						
Floor Coverings Res/Textile	Vinyl Tiles					
			8544/B00D/R1005/Floor Coverings Res/Textile/S11			No Asbestos Detected
B00D - R1006 - Stairs						
No Asbestos						
B00D - R1007 - Stairs						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - Technological & Applied Studies - 1979 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00E - R0001 - Metal Technology L.S.

Floor Coverings Res/Textile	Vinyl Sheet					
8544/B00E/R0005/Floor Coverings Res/Textile/S9					No Asbestos Detected	

B00E - R0002 - Metal Technology Bay

No Asbestos

B00E - R0003 - Welding Area

No Asbestos

B00E - R0004 - Welding Area

No Asbestos

B00E - R0005 - Metal Technology L.S.

Floor Coverings Res/Textile	Vinyl Sheet					
8544/B00E/R0005/Floor Coverings Res/Textile/S9					No Asbestos Detected	

B00E - R0006 - Wood Technology L.S.

No Asbestos

B00E - R0007 - Project Store - Type 1

No Asbestos

B00E - R0008 - Materials Learning Space - Type 1

No Asbestos

B00E - R0009 - Design L.S.

No Asbestos

B00E - R0010 - Cleaning Store - Distributed

No Asbestos

B00E - R0011 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0012 - Materials Store

No Asbestos

B00E - R0013 - General Learning Space

No Asbestos

B00E - R0014 - Movement

No Asbestos

B00E - R0015 - Main Switchroom

No Asbestos

B00E - R0016 - External Movement

No Asbestos

B00E - R0017 - Movement

No Asbestos

B00E - R0018 - Stairs

No Asbestos

B00E - R0019 - Dust Extraction Space

Ceiling Structures/Linings	Flat AC Sheeting					
8544/B00E/R0019/Ceiling Structures/Linings/S31					No Asbestos Detected	

B00E - R1001 - Staff Study

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00E - R1002 - Design/Technology L.S.						
No Asbestos						
B00E - R1003 - Computer Resource						
No Asbestos						
B00E - R1005 - Resources Store						
No Asbestos						
B00E - R1006 - Handwashing Facilities						
No Asbestos						
B00E - R1008 - External Movement						
No Asbestos						
B00E - R1009 - Stairs						
No Asbestos						
B00E - R1010 - Computer Learning Space						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - Pupil Facilities - 1979 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00F - R0001 - Covered Area

Floor Coverings Res/Textile	Vinyl Tiles					
8544/B00F/R0001/Floor Coverings Res/Textile/S15					No Asbestos Detected	

B00F - R0002 - Student Canteen

No Asbestos

B00F - R0003 - Office/Store

No Asbestos

B00F - R0004 - Staff - Toilet

No Asbestos

B00F - R0005 - Pantry

No Asbestos

B00F - R0008 - Covered Area

No Asbestos

B00F - R0009 - External Movement

No Asbestos

B00F - R0010 - Toilet - Lobby

No Asbestos

B00F - R0011 - Toilets-Boys

Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00F/R0007/Partition Walls (Cubicles)/S16					Chrysotile (white asbestos)	

B00F - R0012 - Toilet - Lobby

No Asbestos

B00F - R0013 - Toilets-Girls

Partition Walls (Cubicles)	Compressed AC Sheet	20m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00F/R0007/Partition Walls (Cubicles)/S16					Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Multi Purpose Facilities - 1979 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior

B00G - M0002 - Stairs

No Asbestos

B00G - M0003 - Movement

No Asbestos

B00G - M0004 - Fitness Laboratory

No Asbestos

B00G - R0001 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0002 - Toilets-Boys

Partition Walls (Cubicles)	Compressed AC Sheet	40m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00G/R0003/Partition Walls (Cubicles)/S25					Chrysotile (white asbestos)	

B00G - R0003 - Change

Partition Walls (Cubicles)	Compressed AC Sheet	60m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00G/R0003/Partition Walls (Cubicles)/S25					Chrysotile (white asbestos)	

B00G - R0004 - Stage

No Asbestos

B00G - R0005 - Multi-Purpose Space

No Asbestos

B00G - R0007 - Sport Equipment Store

No Asbestos

B00G - R0008 - Sport Equipment Store

Floor Coverings Res/Textile	Vinyl Tiles				
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected

B00G - R0009 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles				
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected

B00G - R0010 - Movement

Floor Coverings Res/Textile	Vinyl Tiles				
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected

B00G - R0011 - External Movement

No Asbestos

B00G - R0012 - Plant

Floor Coverings Res/Textile	Vinyl Tiles				
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected

B00G - R0013 - Movement

Floor Coverings Res/Textile	Vinyl Tiles				
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected

B00G - R0014 - Movement

Floor Coverings Res/Textile	Vinyl Tiles				
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - R0015 - External Movement						
No Asbestos						
B00G - R0017 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles					
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected	
B00G - R0019 - Sport Equipment Store						
No Asbestos						
B00G - R0020 - Chair Store						
No Asbestos						
B00G - R0021 - Chair Store						
No Asbestos						
B00G - R0022 - Stairs						
No Asbestos						
B00G - R0023 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles					
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected	
B00G - R0024 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles					
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected	
B00G - R0025 - Stairs						
No Asbestos						
B00G - R1001 - Toilets-Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00G/R0003/Partition Walls (Cubicles)/S25					Chrysotile (white asbestos)	
B00G - R1002 - Change						
Partition Walls (Cubicles)	Compressed AC Sheet	60m2	Variable positions	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00G/R0003/Partition Walls (Cubicles)/S25					Chrysotile (white asbestos)	
B00G - R1003 - Performance Store						
Floor Coverings Res/Textile	Vinyl Tiles					
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected	
B00G - R1004 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles					
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected	
B00G - R1005 - Staff Shower						
No Asbestos						
B00G - R1006 - Movement						
Floor Coverings Res/Textile	Vinyl Tiles					
8544/B00G/R0014/Floor Coverings Res/Textile/S24					No Asbestos Detected	
B00G - R1007 - General Storeroom						
No Asbestos						
B00G - R1008 - Stairs						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00H - Science Learning - 1979 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
No Asbestos Found

Underfloor Voids - Slab on Ground
No Asbestos Found

Interior**B00H - R0001 - Laboratory L.S.**

Floor Coverings Res/Textile
Vinyl Sheet
8544/B00H/R0002/Floor Coverings Res/Textile/S23
No Asbestos Detected

B00H - R0002 - Preparation - Science

Floor Coverings Res/Textile
Vinyl Sheet
8544/B00H/R0002/Floor Coverings Res/Textile/S23
No Asbestos Detected

B00H - R0003 - Laboratory L.S.

Floor Coverings Res/Textile
Vinyl Sheet
8544/B00H/R0002/Floor Coverings Res/Textile/S23
No Asbestos Detected

B00H - R0004 - Laboratory L.S.

Floor Coverings Res/Textile
Vinyl Sheet
8544/B00H/R0002/Floor Coverings Res/Textile/S23
No Asbestos Detected

B00H - R0005 - Staff Study

Floor Coverings Res/Textile
Vinyl Sheet
8544/B00H/R0002/Floor Coverings Res/Textile/S23
No Asbestos Detected

B00H - R0006 - Laboratory L.S.

Floor Coverings Res/Textile
Vinyl Sheet
8544/B00H/R0002/Floor Coverings Res/Textile/S23
No Asbestos Detected

B00H - R0007 - Laboratory L.S.

Floor Coverings Res/Textile
Vinyl Sheet
8544/B00H/R0002/Floor Coverings Res/Textile/S23
No Asbestos Detected

B00H - R0008 - Preparation - Science

Floor Coverings Res/Textile
Vinyl Sheet
8544/B00H/R0002/Floor Coverings Res/Textile/S23
No Asbestos Detected

B00H - R0009 - Laboratory L.S.

Floor Coverings Res/Textile
Vinyl Sheet
8544/B00H/R0002/Floor Coverings Res/Textile/S23
No Asbestos Detected

B00H - R0010 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0011 - Chemical Store

No Asbestos

B00H - R0012 - Cleaning Store - Distributed

No Asbestos

B00H - R0013 - Resources Store

No Asbestos

B00H - R0014 - Preparation - Science

No Asbestos

B00H - R0015 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00H - R0016 - General Storeroom

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00H - R0017 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 1979 - Brick/Block (Brick/Block)

Exterior

Window panel to staff toilet (female)	Flat AC Sheeting					
	8544/B00J/Window Panel to staff Toilet (women)/S26					No Asbestos Detected
Ceiling Voids - Raked Ceiling	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00J - R0001 - General Learning Space

No Asbestos

B00J - R0002 - General Learning Space

No Asbestos

B00J - R0003 - General Learning Space

No Asbestos

B00J - R0004 - General Learning Space

No Asbestos

B00J - R0005 - Cleaning Store - Distributed

No Asbestos

B00J - R0006 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00J - R0007 - Staff - Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8544/B00J/R0009/Partition Walls (Cubicles)/S20					Chrysotile (white asbestos)

B00J - R0008 - Staff - Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8544/B00J/R0009/Partition Walls (Cubicles)/S20					Chrysotile (white asbestos)

B00J - R0009 - Toilets-Boys

Partition Walls (Cubicles)	Compressed AC Sheet	10m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8544/B00J/R0009/Partition Walls (Cubicles)/S20					Chrysotile (white asbestos)

B00J - R0010 - Toilets-Girls

Partition Walls (Cubicles)	Compressed AC Sheet	15m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	8544/B00J/R0009/Partition Walls (Cubicles)/S20					Chrysotile (white asbestos)

B00J - R0014 - General Storeroom

No Asbestos

B00J - R0016 - External Movement

No Asbestos

B00J - R0017 - Movement

No Asbestos

B00J - R0018 - Stairs

No Asbestos

B00J - R0019 - Movement

No Asbestos

B00J - R0020 - Resources Store

Wall Linings Internal	Flat AC Sheeting					
	8544/B00J/R0020/Wall Linings Internal/S21					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles					
	8544/B00J/R1011/Floor Coverings Res/Textile/S22					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00J - R0021 - External Movement						
No Asbestos						
B00J - R0022 - Computer Learning Space						
No Asbestos						
B00J - R1001 - General Learning Space						
No Asbestos						
B00J - R1002 - General Learning Space						
No Asbestos						
B00J - R1003 - General Learning Space						
No Asbestos						
B00J - R1004 - General Learning Space						
No Asbestos						
B00J - R1008 - Office/Store						
No Asbestos						
B00J - R1010 - External Movement						
No Asbestos						
B00J - R1011 - General Storeroom						
Wall Linings Internal	Flat AC Sheeting					No Asbestos Detected
			8544/B00J/R0020/Wall Linings Internal/S21			
Floor Coverings Res/Textile	Vinyl Tiles					No Asbestos Detected
			8544/B00J/R1011/Floor Coverings Res/Textile/S22			
B00J - R1012 - Movement						
No Asbestos						
B00J - R1013 - Stairs						
No Asbestos						
B00J - R1014 - Staff Study						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00K - General Learning - 1979 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00K - R0001 - Staff Study

No Asbestos

B00K - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0003 - Cleaning Store - Distributed

No Asbestos

B00K - R0004 - General Learning Space

No Asbestos

B00K - R0005 - General Learning Space

No Asbestos

B00K - R0006 - General Learning Space

No Asbestos

B00K - R0007 - General Learning Space

No Asbestos

B00K - R0008 - Interview/Office - Type 1

No Asbestos

B00K - R0009 - General Storeroom

No Asbestos

B00K - R0011 - Resources Store

No Asbestos

B00K - R0012 - Toilets-Girls

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00K/R0012/Partition Walls (Cubicles)/S19					Chrysotile (white asbestos)	

B00K - R0013 - Toilets-Boys

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00K/R0012/Partition Walls (Cubicles)/S19					Chrysotile (white asbestos)	

B00K - R0015 - External Movement

No Asbestos

B00K - R0018 - Stairs

No Asbestos

B00K - R0019 - Resources Store

Wall Linings Internal	Flat AC Sheeting				
8544/B00K/R0019/Wall Linings Internal/S17					No Asbestos Detected

B00K - R0020 - Movement

No Asbestos

B00K - R1001 - General Learning Space

No Asbestos

B00K - R1002 - General Learning Space

No Asbestos

B00K - R1003 - General Learning Space

No Asbestos

B00K - R1004 - General Learning Space

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00K - R1006 - Resources Store						
No Asbestos						
B00K - R1010 - External Movement						
No Asbestos						
B00K - R1011 - General Storeroom						
Wall Linings Internal	Flat AC Sheeting					
	8544/B00K/R0019/Wall Linings Internal/S17					No Asbestos Detected
Floor Coverings Res/Textile	Vinyl Tiles					
	8544/B00K/R1011/Floor Coverings Res/Textile/S18					No Asbestos Detected
B00K - R1012 - Movement						
No Asbestos						
B00K - R1013 - Stairs						
No Asbestos						
B00K - R1014 - Staff Study						
No Asbestos						
B00K - R1015 - Tea Room						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00L - Library - 1979 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling No Asbestos Found

Underfloor Voids - Slab on Ground No Asbestos Found

Interior**B00L - R0006 - Cleaning Store - Distributed**

No Asbestos

B00L - R0007 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00L - R0013 - Study Space

No Asbestos

B00L - R0015 - Main Entry

No Asbestos

B00L - R0016 - Careers Advisers Office

No Asbestos

B00L - R0017 - System Administrators Office

No Asbestos

B00L - R0018 - Computer Room

No Asbestos

B00L - R0019 - Staff - Toilet

No Asbestos

B00L - R0020 - Toilets-Disabled

No Asbestos

B00L - R0021 - Main Area

No Asbestos

B00L - R0022 - Senior Study

No Asbestos

B00L - R0023 - Seminar

No Asbestos

B00L - R0024 - Seminar

No Asbestos

B00L - R0025 - Seminar

No Asbestos

B00L - R0026 - Movement

No Asbestos

B00L - R0027 - Library Administration

No Asbestos

B00L - R0028 - Tea Room

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 1979 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00M - R0001 - Interview/Office - Type 1

No Asbestos

B00M - R0002 - Distribution Board Cupboard

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0003 - Cleaning Store - Distributed

No Asbestos

B00M - R0004 - General Learning Space

No Asbestos

B00M - R0005 - General Learning Space

No Asbestos

B00M - R0006 - General Learning Space

No Asbestos

B00M - R0007 - General Learning Space

No Asbestos

B00M - R0009 - Resources Store

No Asbestos

B00M - R0012 - Toilets-Girls

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00M/R0013/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	

B00M - R0013 - Toilets-Boys

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
8544/B00M/R0013/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	

B00M - R0015 - External Movement

No Asbestos

B00M - R0016 - Stairs

No Asbestos

B00M - R0017 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
8544/B00M/R1011/Floor Coverings Res/Textile/S7					No Asbestos Detected	
Wall Linings Internal	Flat AC Sheeting					
8544/B00M/R0017/Wall Linings Internal/S8					No Asbestos Detected	

B00M - R0018 - Movement

No Asbestos

B00M - R0019 - Staff Study

No Asbestos

B00M - R0020 - Tea Room

No Asbestos

B00M - R1001 - Computer Learning Space

No Asbestos

B00M - R1002 - General Learning Space

No Asbestos

B00M - R1003 - General Learning Space

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00M - R1004 - General Learning Space

No Asbestos

B00M - R1006 - Resources Store

No Asbestos

B00M - R1009 - Movement

No Asbestos

B00M - R1010 - External Movement

No Asbestos

B00M - R1011 - General Storeroom

Floor Coverings
Res/Textile

Vinyl Tiles

8544/B00M/R1011/Floor Coverings Res/Textile/S7

No Asbestos Detected

Wall Linings Internal

Flat AC Sheeting

8544/B00M/R0017/Wall Linings Internal/S8

No Asbestos Detected

B00M - R1012 - Stairs

No Asbestos

B00M - R1013 - Staff Study

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00N - Agricultural Science - 1979 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00N - R0003 - Office/Store

No Asbestos

B00N - R0004 - Growing/Breeding

No Asbestos

B00N - R0005 - External Movement

No Asbestos

B00N - R0006 - Movement

No Asbestos

B00N - R0007 - General Storeroom

No Asbestos

B00N - R0008 - Staff - Toilet

No Asbestos

B00N - R0009 - Plant

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B000 - Storage - 1979 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B000 - R0001 - Machine Storage

No Asbestos

B000 - R0002 - Shed Workshop

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00Z - Other - 2010 - Metal Shed (Metal Shed)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B00Z - R0001 - No Access

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 522 - D18179 - Staff Study : Placement Date - 17/11/2006

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Staff Room

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017