


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Unanderra Public School (3308)
Region : Illawarra and South East
State Electorate : Wollongong
Local Government Area : Wollongong

Initial Survey : Noel Arnold & Associates : 04 - Apr - 2008
Register Issue Date : 22 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00A - Administration - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00A - R0001 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0002 - Movement

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0003 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0004 - Duplicating Workroom

No Asbestos

B00A - R0005 - Sick Bay

No Asbestos

B00A - R0006 - Disabled Toilet

No Asbestos

B00A - R0007 - Clerical Office

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0008 - Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0009 - General Storeroom

No Asbestos

B00A - R0010 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0011 - Staff Toilet

No Asbestos

B00A - R0012 - Staff Toilet

No Asbestos

B00A - R0013 - Staff Toilet

No Asbestos

B00A - R0014 - Deputy Principal

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0015 - Cleaning Supplies

No Asbestos

B00A - R0016 - Staff Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00A - R0017 - Staff Kitchen

No Asbestos

B00A - R0019 - Main Switch Board

No Asbestos

B00A - R0020 - Movement

No Asbestos

B00A - R0021 - Interview/Office - Type 3

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - R0022 - Interview

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00F - General Learning - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00F - R0001 - Practical Activities - 1hb**

No Asbestos

B00F - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0003 - Home Base Store

No Asbestos

B00F - R0004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0005 - Practical Activities - 1hb

No Asbestos

B00F - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0007 - Home Base Store

No Asbestos

B00F - R0008 - Practical Activities - 1hb

No Asbestos

B00F - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00F - R0010 - Home Base Store

No Asbestos

B00F - R0013 - Toilets - Girls

No Asbestos

B00F - R0014 - Disabled Shower/Toilet

No Asbestos

B00F - R0015 - Toilets - Boys

No Asbestos

B00F - R0016 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00F - R0018 - Practical Activities - 1hb

No Asbestos

B00F - R0019 - Home Base Store

No Asbestos

B00F - R0020 - Home Base

No Asbestos

B00F - R0021 - Withdrawal Space - 2hb

No Asbestos

B00F - R0022 - Home Base

No Asbestos

B00F - R0023 - Home Base Store

No Asbestos

B00F - R0024 - Practical Activities - 1hb

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00F - R0025 - Practical Activities - 1hb						
No Asbestos						
B00F - R0026 - Home Base						
No Asbestos						
B00F - R0027 - Withdrawal Space - 1hb						
No Asbestos						
B00F - R0028 - Home Base Store						
No Asbestos						
B00F - R0029 - External Movement						
No Asbestos						
B00F - R0030 - Entry Vestibule						
No Asbestos						
B00F - R0031 - Special Programs Room						
No Asbestos						
B00F - R0032 - Security Store						
No Asbestos						
B00F - R0033 - Withdrawal Space - 1hb						
No Asbestos						
B00F - R1001 - Practical Activities - 1hb						
No Asbestos						
B00F - R1002 - Home Base						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00F - R1003 - Home Base Store						
No Asbestos						
B00F - R1004 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00F - R1005 - Practical Activities - 1hb						
No Asbestos						
B00F - R1006 - Home Base						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00F - R1007 - Home Base Store						
No Asbestos						
B00F - R1008 - Withdrawal Space - 1hb						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00F - R1009 - Practical Activities - 1hb						
No Asbestos						
B00F - R1010 - Home Base						
Vinyl Tiles (Under Floor No Asbestos Found Covering/Carpet)						
B00F - R1011 - Home Base Store						
No Asbestos						
B00F - R1012 - Toilets - Girls						
No Asbestos						
B00F - R1013 - Distribution Board						
No Asbestos						
B00F - R1014 - Cleaning Supplies						
No Asbestos						
B00F - R1015 - Toilets - Boys						

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B00F - R1017 - Practical Activities - 1hb					
	No Asbestos					
	B00F - R1018 - Home Base Store					
	No Asbestos					
	B00F - R1019 - Home Base					
	No Asbestos					
	B00F - R1020 - Withdrawal Space - 2hb					
	No Asbestos					
	B00F - R1021 - Home Base					
	No Asbestos					
	B00F - R1022 - Home Base Store					
	No Asbestos					
	B00F - R1023 - Practical Activities - 1hb					
	No Asbestos					
	B00F - R1024 - Practical Activities - 1hb					
	No Asbestos					
	B00F - R1025 - Home Base					
	No Asbestos					
	B00F - R1026 - Withdrawal Space - 1hb					
	No Asbestos					
	B00F - R1027 - Home Base Store					
	No Asbestos					
	B00F - R1028 - External Movement					
	No Asbestos					

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00I - Communal Facilities - 1999 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00I - R0001 - Communal Space**

No Asbestos

B00I - R0002 - Raised Platform

No Asbestos

B00I - R0003 - Toilets - Girls

No Asbestos

B00I - R0004 - P.E. Store

No Asbestos

B00I - R0005 - Hall Chair Store

No Asbestos

B00I - R0006 - Plant

No Asbestos

B00I - R0007 - Toilets - Boys

No Asbestos

B00I - R0008 - Disabled Toilet

No Asbestos

B00I - R0009 - Cleaning Supplies

No Asbestos

B00I - R0010 - Staff RoomVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00I - R0011 - Special Programs Room**Vinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00I - R0012 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0013 - General Storeroom

No Asbestos

B00I - R0014 - General Assistant/Bulk StoreVinyl Tiles (Under Floor
Covering/Carpet) No Asbestos Found**B00I - R0015 - Canteen**

No Asbestos

B00I - R0016 - Canteen Office/Store

No Asbestos

B00I - R0017 - Movement

No Asbestos

B00I - R0018 - Movement

No Asbestos

B00I - R0019 - Movement

No Asbestos

B00I - R0020 - Movement

No Asbestos

B00I - R0021 - Movement

No Asbestos

B00I - R0022 - Lift

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00K - General Learning - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00K - R0001 - Toilets - Boys**

No Asbestos

B00K - R0002 - Kiln Room

No Asbestos

B00K - R0003 - Toilets - Girls

No Asbestos

B00K - R0004 - Practical Activities - 1hb

No Asbestos

B00K - R0005 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0006 - Home Base Store

No Asbestos

B00K - R0007 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0008 - Practical Activities - 1hb

No Asbestos

B00K - R0009 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0010 - Home Base Store

No Asbestos

B00K - R0011 - Practical Activities - 1hb

No Asbestos

B00K - R0012 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0013 - Home Base Store

No Asbestos

B00K - R0014 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0015 - Practical Activities - 1hb

No Asbestos

B00K - R0016 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00K - R0017 - Home Base Store

No Asbestos

B00K - R0018 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00K - R0019 - Movement

No Asbestos

B00K - R0020 - Movement

No Asbestos

B00K - R0021 - Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00K - R0022 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00L - Library - 1999 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior**B00L - R0002 - Library Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0003 - Communications Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0004 - Communications Cupboard

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0005 - Special Programs Room

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0006 - Home Base Store - M

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

B00L - R0007 - Staff Toilet

No Asbestos

B00L - R0008 - Cleaning Supplies

No Asbestos

B00L - R0009 - External Movement

No Asbestos

B00L - R0010 - Reading Area

No Asbestos

B00L - R0011 - Computer Room

No Asbestos

B00L - R9001 - Cleaning Distributed Store

No Asbestos

B00L - R9002 - Sports Store

No Asbestos

B00L - R9003 - Garden Store

No Asbestos

B00L - R9004 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00M - General Learning - 1999 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

Interior

B00M - R0001 - Practical Activities - 1hb

No Asbestos

B00M - R0002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0003 - Home Base Store

No Asbestos

B00M - R0004 - No Access

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0005 - Practical Activities - 1hb

No Asbestos

B00M - R0006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R0007 - Home Base Store

No Asbestos

B00M - R0008 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00M - R0009 - Movement

No Asbestos

B00M - R0010 - External Movement

No Asbestos

B00M - R0011 - External Stairs

No Asbestos

B00M - R0012 - External Stairs

No Asbestos

B00M - R1001 - Practical Activities - 1hb

No Asbestos

B00M - R1002 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R1003 - Home Base Store

No Asbestos

B00M - R1004 - Withdrawal Space - 1hb

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R1005 - Practical Activities - 1hb

No Asbestos

B00M - R1006 - Home Base

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

B00M - R1007 - Home Base Store

No Asbestos

B00M - R1008 - External Movement

No Asbestos

B00M - R1009 - External Stairs

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00M - R1010 - External Stairs

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

3308_ASB_050608_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017