

# Asbestos Register

(Hazardous Materials and Risk Assessment)

**School :** Wauchope Public School (3404)  
**Region :** North Coast  
**State Electorate :** Oxley  
**Local Government Area :** Port Macquarie-Hastings

**Initial Survey :** Noel Arnold & Associates : 05 - May - 2008  
**Reviewed By :** Parsons Brinckerhoff : 29 - Aug - 2016



2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B001 - General Learning - 1953 - Brick/Block (Brick/Block)**

**Exterior**

|                                   |                             |      |                            |   |         |                    |
|-----------------------------------|-----------------------------|------|----------------------------|---|---------|--------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found           |      |                            |   |         |                    |
| Eaves Linings                     | Flat AC Sheeting            | 20m2 | North facing, South facing | Good Condition (1)  | Low (1) | Low Priority (2-3) |
|                                   | 3404/B001/Eaves Linings/S14 |      |                            | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |         |                    |
| Ceiling Void                      | No Asbestos Found           |      |                            |   |         |                    |

**Interior**

**B001 - R0001 - Home Base**

No Asbestos

**B001 - R0002 - Home Base Store**

No Asbestos

**B001 - R0003 - Home Base Store**

No Asbestos

**B001 - R0004 - Home Base Store**

No Asbestos

**B001 - R0005 - Home Base**

No Asbestos

**B001 - R0006 - Practical Activities - 1hb**

No Asbestos

**B001 - R0007 - Home Base Store**

No Asbestos

**B001 - R0008 - Home Base**

No Asbestos

**B001 - R0009 - Home Base Store**

No Asbestos

**B001 - R0010 - P.E. Store**

No Asbestos

**B001 - R0011 - Toilets - Boys**

|                            |   |     |              |                                    |         |                    |
|----------------------------|---|-----|--------------|------------------------------------|---------|--------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet                           | 4m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                            | 3404/B001/R0011/Partition Walls (Cubicles)/S5 |     |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B001 - R0012 - Toilets - Girls**

|                            |   |     |              |                                    |         |                    |
|----------------------------|---|-----|--------------|------------------------------------|---------|--------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet                           | 6m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                            | 3404/B001/R0011/Partition Walls (Cubicles)/S5 |     |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B001 - R0013 - Communications Room**

No Asbestos

**B001 - R0014 - Movement**

No Asbestos

**B001 - R0015 - Staff Room Annexe**

No Asbestos

**B001 - R0016 - Staff Room**

No Asbestos

**B001 - R0017 - Sick Bay**

No Asbestos

**B001 - R0018 - External Movement**

No Asbestos

**B001 - R0019 - External Movement**

No Asbestos

| Product  | Material Description                     | Extent | Location Reference                           | Material Condition  | Risk Status | Control Priority   |
|--|--|--------|--|---|-------------|--------------------|
| Sample No  |  |        |  | Test Result   |             |                    |
| <b>B001 - R0020 - Stairs</b>                     |  |        |  |   |             |                    |
| No Asbestos                                      |  |        |  |   |             |                    |
| <b>B001 - R0021 - Stairs</b>                     |  |        |  |   |             |                    |
| No Asbestos                                      |  |        |  |   |             |                    |
| <b>B001 - R1001 - Toilets - Boys</b>             |  |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting                         | 10m2   | All surfaces                                 | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
|  | 3404/B001/R1010/Wall Linings Internal/S4 |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1002 - Home Base Store</b>            |  |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting                         | 10m2   | All surfaces                                 | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
|  | 3404/B001/R1010/Wall Linings Internal/S4 |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1003 - Movement</b>                   |  |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting                         | 15m2   | All surfaces                                 | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
|  | 3404/B001/R1010/Wall Linings Internal/S4 |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1004 - Practical Activities - 1hb</b> |  |        |  |   |             |                    |
| No Asbestos                                      |  |        |  |   |             |                    |
| <b>B001 - R1005 - Home Base Store</b>            |  |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting                         | 12m2   | North facing,<br>East facing,<br>West facing | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
|  | 3404/B001/R1010/Wall Linings Internal/S4 |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1006 - Home Base</b>                  |  |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting                         | 30m2   | North facing,<br>East facing,<br>West facing | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
|  | 3404/B001/R1010/Wall Linings Internal/S4 |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1007 - Practical Activities - 1hb</b> |  |        |  |   |             |                    |
| No Asbestos                                      |  |        |  |   |             |                    |
| <b>B001 - R1008 - Home Base</b>                  |  |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting                         | 30m2   | North facing,<br>East facing,<br>West facing | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
|  | 3404/B001/R1010/Wall Linings Internal/S4 |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1009 - Home Base Store</b>            |  |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting                         | 15m2   | North facing,<br>East facing,<br>West facing | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
|  | 3404/B001/R1010/Wall Linings Internal/S4 |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1010 - Withdrawal Space - 1hb</b>     |  |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting                         | 11m2   | North facing,<br>East facing,<br>West facing | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
|  | 3404/B001/R1010/Wall Linings Internal/S4 |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1011 - Practical Activities - 1hb</b> |  |        |  |   |             |                    |
| No Asbestos                                      |  |        |  |   |             |                    |
| <b>B001 - R1012 - Home Base</b>                  |  |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting                         | 30m2   | North facing,<br>East facing,<br>West facing | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
|  | 3404/B001/R1010/Wall Linings Internal/S4 |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |

| Product  | Material Description | Extent | Location Reference                           | Material Condition  | Risk Status | Control Priority   |
|--|----------------------|--------|--|---|-------------|--------------------|
| Sample No  |                      |        |  |   | Test Result |                    |
| <b>B001 - R1013 - Practical Activities - 1hb</b> |                      |        |  |   |             |                    |
| No Asbestos                                      |                      |        |  |   |             |                    |
| <b>B001 - R1014 - Home Base</b>                  |                      |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting     | 40m2   | North facing,<br>East facing,<br>West facing | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
| 3404/B001/R1010/Wall Linings Internal/S4         |                      |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1015 - Home Base Store</b>            |                      |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting     | 18m2   | North facing,<br>East facing,<br>West facing | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
| 3404/B001/R1010/Wall Linings Internal/S4         |                      |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1016 - Home Base Store</b>            |                      |        |  |   |             |                    |
| Wall Linings Internal                            | Flat AC Sheeting     | 30m2   | North facing,<br>East facing,<br>West facing | Good Condition (1)  | Low (1)     | Low Priority (2-3) |
| 3404/B001/R1010/Wall Linings Internal/S4         |                      |        |  | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |             |                    |
| <b>B001 - R1017 - External Movement</b>          |                      |        |  |   |             |                    |
| No Asbestos                                      |                      |        |  |   |             |                    |
| <b>B001 - R1018 - External Movement</b>          |                      |        |  |   |             |                    |
| No Asbestos                                      |                      |        |  |   |             |                    |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B002 - General Learning - 1955 - Timber (Timber)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Void      No Asbestos Found

**Interior**

**B002 - R0005 - External Movement**

No Asbestos

**B002 - R0006 - External Movement**

No Asbestos

**B002 - R0007 - Practical Activities - 1hb**

No Asbestos

**B002 - R0008 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B002 - R0009 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B002 - R0010 - Practical Activities - 1hb**

No Asbestos

**B002 - R1001 - Practical Activities - 1hb**

No Asbestos

**B002 - R1002 - Practical Activities - 1hb**

No Asbestos

**B002 - R1003 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B002 - R1004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B002 - R1005 - External Movement**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B003 - General Learning/Pupil Facilities - 1950 - Brick/Block (Brick/Block)**

**Exterior**

|                                   |                             |      |                            |   |         |                    |
|-----------------------------------|-----------------------------|------|----------------------------|---|---------|--------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found           |      |                            |   |         |                    |
| Eaves Linings                     | Flat AC Sheeting            | 30m2 | North facing, South facing | Good Condition (1)  | Low (1) | Low Priority (2-3) |
|                                   | 3404/B001/Eaves Linings/S14 |      |                            | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |         |                    |
| Ceiling Void                      | No Asbestos Found           |      |                            |   |         |                    |

**Interior**

**B003 - R0001 - Staff Toilet**

|                            |   |     |              |                                    |         |                    |
|----------------------------|---|-----|--------------|------------------------------------|---------|--------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet                           | 2m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                            | 3404/B003/R0001/Partition Walls (Cubicles)/S8 |     |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B003 - R0002 - Toilets - Girls**

|                            |   |      |              |                                    |         |                    |
|----------------------------|---|------|--------------|------------------------------------|---------|--------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet                           | 12m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                            | 3404/B003/R0001/Partition Walls (Cubicles)/S8 |      |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B003 - R0003 - Toilets - Boys**

|                            |   |     |              |                                    |         |                    |
|----------------------------|---|-----|--------------|------------------------------------|---------|--------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet                           | 8m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                            | 3404/B003/R0001/Partition Walls (Cubicles)/S8 |     |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B003 - R0004 - Staff Toilet**

|                            |   |     |              |                                    |         |                    |
|----------------------------|---|-----|--------------|------------------------------------|---------|--------------------|
| Partition Walls (Cubicles) | Compressed AC Sheet                           | 2m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                            | 3404/B003/R0001/Partition Walls (Cubicles)/S8 |     |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B003 - R0005 - External Movement**

No Asbestos

**B003 - R0006 - External Stairs**

No Asbestos

**B003 - R1001 - Movement**

|                       |  |      |              |                                    |         |                    |
|-----------------------|--|------|--------------|------------------------------------|---------|--------------------|
| Wall Linings Internal | Flat AC Sheeting                         | 30m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                       | 3404/B003/R1001/Wall Linings Internal/S9 |      |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B003 - R1002 - Home Base Store**

|                       |  |      |              |                                    |         |                    |
|-----------------------|--|------|--------------|------------------------------------|---------|--------------------|
| Wall Linings Internal | Flat AC Sheeting                         | 15m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                       | 3404/B003/R1001/Wall Linings Internal/S9 |      |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B003 - R1003 - Home Base Store**

|                       |  |      |              |                                    |         |                    |
|-----------------------|--|------|--------------|------------------------------------|---------|--------------------|
| Wall Linings Internal | Flat AC Sheeting                         | 20m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                       | 3404/B003/R1001/Wall Linings Internal/S9 |      |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B003 - R1004 - Home Base**

|                       |  |      |              |                                    |         |                    |
|-----------------------|--|------|--------------|------------------------------------|---------|--------------------|
| Wall Linings Internal | Flat AC Sheeting                         | 60m2 | All surfaces | Good Condition (1)                 | Low (1) | Low Priority (2-3) |
|                       | 3404/B003/R1001/Wall Linings Internal/S9 |      |              | <b>Chrysotile (white asbestos)</b> |         |                    |

**B003 - R1005 - External Stairs**

No Asbestos

**B003 - R1006 - External Stairs**

No Asbestos

**B003 - R1007 - External Stairs**

No Asbestos

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B004 - Communal Facilities - 1950 - Brick/Block (Brick/Block)****Exterior**

|                                   |   |      |                               |   |            |                                    |
|-----------------------------------|---|------|-------------------------------|---|------------|------------------------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found                                 |      |                               |   |            |                                    |
| Eaves Linings                     | Flat AC Sheeting<br>3404/B001/Eaves Linings/S14   | 60m2 | North facing,<br>South facing | Good Condition (1)  | Low (1)    | Low Priority (2-3)                 |
|                                   |   |      |                               | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |            |                                    |
| Ceiling Void                      | AC Fragments/Debris<br>3404/B004/Ceiling Void/S19 | 1m2  | South                         | Poor Condition - Extensive Damage (4)                         | Medium (2) | High Priority (6-8)                |
|                                   |   |      |                               |   |            | <b>Chrysotile (white asbestos)</b> |
| Firebreak wall                    | Flat AC Sheeting<br>3404/B004/Ceiling Void/S19    | 5m2  | South                         | Poor Condition - Extensive Damage (4)                         | Medium (2) | High Priority (6-8)                |
|                                   |   |      |                               |   |            | <b>Chrysotile (white asbestos)</b> |

**Interior****B004 - R0001 - Canteen**

|                             |   |  |  |  |  |                             |
|-----------------------------|---|--|--|--|--|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles<br>3404/B004/R0001/Floor Coverings Res/Textile/S7 |  |  |  |  | <b>No Asbestos Detected</b> |
|-----------------------------|---|--|--|--|--|-----------------------------|

**B004 - R0002 - Canteen Office/Store**

|                             |   |  |  |  |  |                             |
|-----------------------------|---|--|--|--|--|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles<br>3404/B004/R0001/Floor Coverings Res/Textile/S7 |  |  |  |  | <b>No Asbestos Detected</b> |
|-----------------------------|---|--|--|--|--|-----------------------------|

**B004 - R0003 - Staff Toilet**

No Asbestos

**B004 - R0004 - Canteen Office/Store**

|                             |   |  |  |  |  |                             |
|-----------------------------|---|--|--|--|--|-----------------------------|
| Floor Coverings Res/Textile | Vinyl Tiles<br>3404/B004/R0001/Floor Coverings Res/Textile/S7 |  |  |  |  | <b>No Asbestos Detected</b> |
|-----------------------------|---|--|--|--|--|-----------------------------|

**B004 - R0006 - Cleaning Supplies**

No Asbestos

**B004 - R0007 - P.E. Store**

No Asbestos

**B004 - R0008 - General Assistant/Bulk Store**

No Asbestos

**B004 - R0009 - Main Switch Board**

No Asbestos

**B004 - R0010 - Plant**

No Asbestos

**B004 - R0011 - External Movement**

No Asbestos

**B004 - R0012 - General Storeroom**

No Asbestos

**B004 - R0013 - General Storeroom**

No Asbestos

**B004 - R0014 - General Assistant/Bulk Store**

No Asbestos

**B004 - R1001 - Practical Activities - 1hb**

|                       |  |      |                                |                    |         |                                    |
|-----------------------|--|------|--------------------------------|--------------------|---------|------------------------------------|
| Wall Linings Internal | Flat AC Sheeting<br>3404/B004/R1003/Wall Linings Internal/S6 | 10m2 | All surfaces,<br>Upper portion | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|                       |  |      |                                |                    |         | <b>Chrysotile (white asbestos)</b> |

**B004 - R1002 - Practical Activities - 1hb**

| Product                                  | Material Description | Extent | Location Reference          | Material Condition | Risk Status                 | Control Priority   |
|--|----------------------|--------|-----------------------------|--------------------|-----------------------------|--------------------|
| Sample No                                |                      |        |                             |                    | Test Result                 |                    |
| Wall Linings Internal                    | Flat AC Sheeting     | 20m2   | All surfaces, Upper portion | Good Condition (1) | Low (1)                     | Low Priority (2-3) |
| 3404/B004/R1003/Wall Linings Internal/S6 |                      |        |                             |                    | Chrysotile (white asbestos) |                    |

**B004 - R1004 - External Movement**

No Asbestos

**B004 - R1005 - Raised Platform**

No Asbestos

**B004 - R1006 - Communal Space**

No Asbestos

2017



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B005 - General Learning - 1944 - Brick/Block (Brick/Block)**

**Exterior**

|                                   |                             |      |                            |   |         |                    |
|-----------------------------------|-----------------------------|------|----------------------------|---|---------|--------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found           |      |                            |   |         |                    |
| Eaves Linings                     | Flat AC Sheeting            | 40m2 | North facing, South facing | Good Condition (1)  | Low (1) | Low Priority (2-3) |
|                                   | 3404/B001/Eaves Linings/S14 |      |                            | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |         |                    |
| Ceiling Void                      | No Asbestos Found           |      |                            |   |         |                    |

**Interior**

**B005 - R0002 - Special Programs Store**

No Asbestos

**B005 - R0003 - Interview**

No Asbestos

**B005 - R0004 - Interview**

No Asbestos

**B005 - R0005 - Interview/Office - Type 1**

No Asbestos

**B005 - R0006 - Movement**

No Asbestos

**B005 - R0007 - Withdrawal Space - 1hb**

No Asbestos

**B005 - R0008 - Special Programs Room**

No Asbestos

**B005 - R0009 - Distribution Board**

Note: No inspection of live electrical installation.

No Asbestos

**B005 - R1010 - Home Base**

No Asbestos

**B005 - R1011 - Home Base Store**

No Asbestos

**B005 - R1012 - Practical Activities - 2hb**

No Asbestos

**B005 - R1013 - Withdrawal Space - 2hb**

No Asbestos

**B005 - R1014 - Home Base**

No Asbestos

**B005 - R1015 - Movement**

No Asbestos

**B005 - R1016 - External Movement**

No Asbestos



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B006 - General Learning - 1917 - Timber (Timber)****Exterior**

|                 |                             |      |              |                    |   |                    |
|-----------------|-----------------------------|------|--------------|--------------------|---|--------------------|
| Eaves Linings   | Flat AC Sheeting            | 80m2 | All surfaces | Good Condition (1) | Low (1)   | Low Priority (2-3) |
|                 | 3404/B006/Eaves Linings/S15 |      |              |                    | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |                    |
| Ceiling Void    | No Asbestos Found           |      |              |                    |   |                    |
| Underfloor Void | No Asbestos Found           |      |              |                    |   |                    |

**Interior****B006 - R0001 - Home Base Store**

|                             |  |  |  |  |                             |  |
|-----------------------------|--|--|--|--|-----------------------------|--|
| Floor Coverings Res/Textile | Vinyl Tiles                                    |  |  |  |                             |  |
|                             | 3404/B006/R0005/Floor Coverings Res/Textile/S3 |  |  |  | <b>No Asbestos Detected</b> |  |

**B006 - R0002 - Home Base Store**

|                             |  |  |  |  |                             |  |
|-----------------------------|--|--|--|--|-----------------------------|--|
| Floor Coverings Res/Textile | Vinyl Tiles                                    |  |  |  |                             |  |
|                             | 3404/B006/R0005/Floor Coverings Res/Textile/S3 |  |  |  | <b>No Asbestos Detected</b> |  |

**B006 - R0003 - Home Base Store**

No Asbestos

**B006 - R0004 - Withdrawal Space - 1hb**

No Asbestos

**B006 - R0005 - Movement**

|                             |  |  |  |  |                             |  |
|-----------------------------|--|--|--|--|-----------------------------|--|
| Floor Coverings Res/Textile | Vinyl Tiles                                    |  |  |  |                             |  |
|                             | 3404/B006/R0005/Floor Coverings Res/Textile/S3 |  |  |  | <b>No Asbestos Detected</b> |  |

**B006 - R0006 - Home Base**

|                       |  |  |  |  |                             |  |
|-----------------------|--|--|--|--|-----------------------------|--|
| Wall Linings Internal | Flat AC Sheeting                         |  |  |  |                             |  |
|                       | 3404/B006/R0013/Wall Linings Internal/S2 |  |  |  | <b>No Asbestos Detected</b> |  |

**B006 - R0007 - Practical Activities - 1hb**

|                       |  |  |  |  |                             |  |
|-----------------------|--|--|--|--|-----------------------------|--|
| Wall Linings Internal | Flat AC Sheeting                         |  |  |  |                             |  |
|                       | 3404/B006/R0013/Wall Linings Internal/S2 |  |  |  | <b>No Asbestos Detected</b> |  |

**B006 - R0008 - Movement**

|                             |  |  |  |  |                             |  |
|-----------------------------|--|--|--|--|-----------------------------|--|
| Floor Coverings Res/Textile | Vinyl Tiles                                    |  |  |  |                             |  |
|                             | 3404/B006/R0013/Floor Coverings Res/Textile/S1 |  |  |  | <b>No Asbestos Detected</b> |  |
| Wall Linings Internal       | Flat AC Sheeting                               |  |  |  |                             |  |
|                             | 3404/B006/R0013/Wall Linings Internal/S2       |  |  |  | <b>No Asbestos Detected</b> |  |

**B006 - R0009 - Staff Room Annexe**

|                       |  |  |  |  |                             |  |
|-----------------------|--|--|--|--|-----------------------------|--|
| Wall Linings Internal | Flat AC Sheeting                         |  |  |  |                             |  |
|                       | 3404/B006/R0013/Wall Linings Internal/S2 |  |  |  | <b>No Asbestos Detected</b> |  |

**B006 - R0010 - General Storeroom**

|                       |  |  |  |  |                             |  |
|-----------------------|--|--|--|--|-----------------------------|--|
| Wall Linings Internal | Flat AC Sheeting                         |  |  |  |                             |  |
|                       | 3404/B006/R0013/Wall Linings Internal/S2 |  |  |  | <b>No Asbestos Detected</b> |  |

**B006 - R0011 - Home Base**

|                       |  |  |  |  |                             |  |
|-----------------------|--|--|--|--|-----------------------------|--|
| Wall Linings Internal | Flat AC Sheeting                         |  |  |  |                             |  |
|                       | 3404/B006/R0013/Wall Linings Internal/S2 |  |  |  | <b>No Asbestos Detected</b> |  |

**B006 - R0012 - Practical Activities - 1hb**

|                             |  |  |  |  |                             |  |
|-----------------------------|--|--|--|--|-----------------------------|--|
| Floor Coverings Res/Textile | Vinyl Tiles                                    |  |  |  |                             |  |
|                             | 3404/B006/R0013/Floor Coverings Res/Textile/S1 |  |  |  | <b>No Asbestos Detected</b> |  |
| Wall Linings Internal       | Flat AC Sheeting                               |  |  |  |                             |  |
|                             | 3404/B006/R0013/Wall Linings Internal/S2       |  |  |  | <b>No Asbestos Detected</b> |  |

**B006 - R0013 - Practical Activities - 1hb**

| Product  | Material Description                           | Extent | Location Reference | Material Condition | Risk Status | Control Priority            |
|--|--|--------|--------------------|--------------------|-------------|-----------------------------|
| Sample No  |  |        |                    |                    | Test Result |                             |
| Floor Coverings Res/Textile                      | Vinyl Tiles                                    |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Floor Coverings Res/Textile/S1 |        |                    |                    |             | <b>No Asbestos Detected</b> |
| Wall Linings Internal                            | Flat AC Sheeting                               |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Wall Linings Internal/S2       |        |                    |                    |             | <b>No Asbestos Detected</b> |
| <b>B006 - R0014 - Home Base</b>                  |  |        |                    |                    |             |                             |
| Wall Linings Internal                            | Flat AC Sheeting                               |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Wall Linings Internal/S2       |        |                    |                    |             | <b>No Asbestos Detected</b> |
| <b>B006 - R0015 - Practical Activities - 1hb</b> |  |        |                    |                    |             |                             |
| Floor Coverings Res/Textile                      | Vinyl Tiles                                    |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Floor Coverings Res/Textile/S1 |        |                    |                    |             | <b>No Asbestos Detected</b> |
| Wall Linings Internal                            | Flat AC Sheeting                               |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Wall Linings Internal/S2       |        |                    |                    |             | <b>No Asbestos Detected</b> |
| <b>B006 - R0016 - Home Base</b>                  |  |        |                    |                    |             |                             |
| Wall Linings Internal                            | Flat AC Sheeting                               |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Wall Linings Internal/S2       |        |                    |                    |             | <b>No Asbestos Detected</b> |
| <b>B006 - R0017 - Practical Activities - 1hb</b> |  |        |                    |                    |             |                             |
| Floor Coverings Res/Textile                      | Vinyl Tiles                                    |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Floor Coverings Res/Textile/S1 |        |                    |                    |             | <b>No Asbestos Detected</b> |
| Wall Linings Internal                            | Flat AC Sheeting                               |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Wall Linings Internal/S2       |        |                    |                    |             | <b>No Asbestos Detected</b> |
| <b>B006 - R0018 - Home Base</b>                  |  |        |                    |                    |             |                             |
| Wall Linings Internal                            | Flat AC Sheeting                               |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Wall Linings Internal/S2       |        |                    |                    |             | <b>No Asbestos Detected</b> |
| <b>B006 - R0019 - Practical Activities - 1hb</b> |  |        |                    |                    |             |                             |
| Floor Coverings Res/Textile                      | Vinyl Tiles                                    |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Floor Coverings Res/Textile/S1 |        |                    |                    |             | <b>No Asbestos Detected</b> |
| Wall Linings Internal                            | Flat AC Sheeting                               |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Wall Linings Internal/S2       |        |                    |                    |             | <b>No Asbestos Detected</b> |
| <b>B006 - R0020 - Home Base</b>                  |  |        |                    |                    |             |                             |
| Wall Linings Internal                            | Flat AC Sheeting                               |        |                    |                    |             |                             |
|  | 3404/B006/R0013/Wall Linings Internal/S2       |        |                    |                    |             | <b>No Asbestos Detected</b> |
| <b>B006 - R0021 - External Movement</b>          |  |        |                    |                    |             |                             |
| No Asbestos                                      |  |        |                    |                    |             |                             |
| <b>B006 - R0022 - External Movement</b>          |  |        |                    |                    |             |                             |
| No Asbestos                                      |  |        |                    |                    |             |                             |
| <b>B006 - R0023 - External Movement</b>          |  |        |                    |                    |             |                             |
| No Asbestos                                      |  |        |                    |                    |             |                             |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B007 - Special Purpose - 1900 - Timber (Timber)**

**Exterior**

|                 |  |      |                               |   |         |  |
|-----------------|--|------|-------------------------------|---|---------|--|
| Eaves Linings   | Flat AC Sheeting<br>3404/B008/Eaves Linings/S16      | 20m2 | North facing,<br>South facing | Good Condition (1)                          | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b>       |
| Ceiling Void    | Non Accessible Area<br>- No manhole in building      |      |                               |   |         |  |
| Underfloor Void | AC Fragments/Debris<br>3404/B007/Underfloor Void/S21 | 1m2  | Variable positions            | Poor Condition -<br>Extensive Damage<br>(4) | Low (1) | Medium Priority<br>(4-5)<br><b>Chrysotile (white asbestos)</b> |

**Interior**

**B007 - R0001 - Practical Activities - 1hb**

No Asbestos

**B007 - R0002 - Other-Community Use**

|                             |  |      |              |                    |         |  |
|-----------------------------|--|------|--------------|--------------------|---------|--|
| Floor Coverings Res/Textile | Vinyl Tiles<br>3404/B007/R0002/Floor Coverings Res/Textile/S12                               | 44m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)<br><b>Chrysotile (white asbestos)</b> |
| Wall Linings Internal       | Flat AC Sheeting<br>3404/B007/R0002/Wall Linings Internal/S13<br><b>No Asbestos Detected</b> |      |              |                    |         |  |

**B007 - R0003 - Craft Store**

|                       |  |  |  |  |  |  |
|-----------------------|--|--|--|--|--|--|
| Wall Linings Internal | Flat AC Sheeting<br>3404/B007/R0002/Wall Linings Internal/S13<br><b>No Asbestos Detected</b> |  |  |  |  |  |
|-----------------------|--|--|--|--|--|--|

**B007 - R0004 - Toilets-Boys/Girls**

|                       |  |  |  |  |  |  |
|-----------------------|--|--|--|--|--|--|
| Wall Linings Internal | Flat AC Sheeting<br>3404/B007/R0002/Wall Linings Internal/S13<br><b>No Asbestos Detected</b> |  |  |  |  |  |
|-----------------------|--|--|--|--|--|--|

**B007 - R0005 - External Movement**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B008 - General Learning - 1950 - Timber (Timber)**

**Exterior**

|                                   |                             |      |                            |                                       |   |                       |
|-----------------------------------|-----------------------------|------|----------------------------|---------------------------------------|---|-----------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found           |      |                            |                                       |   |                       |
| Eaves Linings                     | Flat AC Sheeting            | 20m2 | North facing, South facing | Good Condition (1)                    | Low (1)   | Low Priority (2-3)    |
|                                   | 3404/B008/Eaves Linings/S16 |      |                            |                                       | <b>Chrysotile (white asbestos)</b>                            |                       |
| Ceiling Void                      | AC Fragments/Debris         | 1m2  | East                       | Poor Condition - Extensive Damage (4) | Low (1)   | Medium Priority (4-5) |
|                                   | 3404/B008/Ceiling Void/S20  |      |                            |                                       | <b>Chrysotile (white asbestos) , Amosite (brown asbestos)</b> |                       |

**Interior**

**B008 - R0001 - Practical Activities - 1hb**

|                             |   |  |  |  |                             |  |
|-----------------------------|---|--|--|--|-----------------------------|--|
| Floor Coverings Res/Textile | Vinyl Tiles                                     |  |  |  |                             |  |
|                             | 3404/B008/R0003/Floor Coverings Res/Textile/S10 |  |  |  | <b>No Asbestos Detected</b> |  |
| Wall Linings Internal       | Flat AC Sheeting                                |  |  |  |                             |  |
|                             | 3404/B008/R0003/Wall Linings Internal/S11       |  |  |  | <b>No Asbestos Detected</b> |  |

**B008 - R0002 - Home Base**

|                       |   |  |  |  |                             |  |
|-----------------------|---|--|--|--|-----------------------------|--|
| Wall Linings Internal | Flat AC Sheeting                          |  |  |  |                             |  |
|                       | 3404/B008/R0003/Wall Linings Internal/S11 |  |  |  | <b>No Asbestos Detected</b> |  |

**B008 - R0003 - Practical Activities - 1hb**

|                             |   |  |  |  |                             |  |
|-----------------------------|---|--|--|--|-----------------------------|--|
| Floor Coverings Res/Textile | Vinyl Tiles                                     |  |  |  |                             |  |
|                             | 3404/B008/R0003/Floor Coverings Res/Textile/S10 |  |  |  | <b>No Asbestos Detected</b> |  |
| Wall Linings Internal       | Flat AC Sheeting                                |  |  |  |                             |  |
|                             | 3404/B008/R0003/Wall Linings Internal/S11       |  |  |  | <b>No Asbestos Detected</b> |  |

**B008 - R0004 - Home Base**

|                       |   |  |  |  |                             |  |
|-----------------------|---|--|--|--|-----------------------------|--|
| Wall Linings Internal | Flat AC Sheeting                          |  |  |  |                             |  |
|                       | 3404/B008/R0003/Wall Linings Internal/S11 |  |  |  | <b>No Asbestos Detected</b> |  |

**B008 - R0005 - External Movement**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B009 - Pupil Facilities - 1950 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                                   |                             |      |                            |                    |         |                                    |
|-----------------------------------|-----------------------------|------|----------------------------|--------------------|---------|------------------------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found           |      |                            |                    |         |                                    |
| Eaves Linings                     | Flat AC Sheeting            | 15m2 | North facing, South facing | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|                                   | 3404/B009/Eaves Linings/S17 |      |                            |                    |         | <b>Chrysotile (white asbestos)</b> |
| Ceiling Void                      | No Asbestos Found           |      |                            |                    |         |                                    |

**Interior**

**B009 - R0001 - Movement**

|                            |  |      |              |                    |         |                                    |
|----------------------------|--|------|--------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                               | 10m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|                            | 3404/B009/R0002/Ceiling Structures/Linings/S18 |      |              |                    |         | <b>Chrysotile (white asbestos)</b> |

**B009 - R0002 - Movement**

|                            |  |      |              |                    |         |                                    |
|----------------------------|--|------|--------------|--------------------|---------|------------------------------------|
| Ceiling Structures/Linings | Flat AC Sheeting                               | 10m2 | All surfaces | Good Condition (1) | Low (1) | Low Priority (2-3)                 |
|                            | 3404/B009/R0002/Ceiling Structures/Linings/S18 |      |              |                    |         | <b>Chrysotile (white asbestos)</b> |

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B010 - Library/Staff Facilities - 2003 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Underfloor Voids - Slab on Ground No Asbestos Found

Ceiling Voids No Asbestos Found

**Interior**

**B010 - R0001 - Staff Room**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B010 - R0002 - Staff Room Annexe**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B010 - R0003 - Movement**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B010 - R0004 - Staff Toilet**

No Asbestos

**B010 - R0005 - Staff Toilet**

No Asbestos

**B010 - R0006 - Staff Toilet**

No Asbestos

**B010 - R0007 - Access Shower/Toilet**

No Asbestos

**B010 - R0008 - Security Store**

No Asbestos

**B010 - R0009 - Clerical Office/Workroom**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B010 - R0010 - Clerical Office**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B010 - R0011 - Sick Bay**

No Asbestos

**B010 - R0012 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B010 - R0013 - Deputy Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B010 - R0014 - Principal**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B010 - R0015 - Interview**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B010 - R0016 - Cleaning Distributed Store**

No Asbestos

**B010 - R0017 - Entry Vestibule**

Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found

**B010 - R0018 - Movement**

No Asbestos

**B010 - R0019 - Lift**

No Asbestos

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status  | Control Priority |
|---|----------------------|--------|--------------------|--------------------|--|------------------|
| Sample No   |                      |        |                    |                    | Test Result  |                  |
| <b>B010 - R0020 - Plant</b>                                 |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R0021 - Main Switch Board</b>                     |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R0022 - External Movement</b>                     |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R0023 - External Stairs</b>                       |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R0024 - External Movement</b>                     |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R0025 - Movement</b>                              |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R0026 - External Movement</b>                     |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R0027 - External Stairs</b>                       |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R1001 - Reading Area</b>                          |                      |        |                    |                    |  |                  |
| Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found |                      |        |                    |                    |  |                  |
| <b>B010 - R1002 - Clerical Office</b>                       |                      |        |                    |                    |  |                  |
| Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found |                      |        |                    |                    |  |                  |
| <b>B010 - R1003 - Security Store</b>                        |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R1004 - Security Store</b>                        |                      |        |                    |                    |  |                  |
| Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found |                      |        |                    |                    |  |                  |
| <b>B010 - R1005 - Communications Room</b>                   |                      |        |                    |                    |  |                  |
| Vinyl Tiles (Under Floor Covering/Carpet) No Asbestos Found |                      |        |                    |                    |  |                  |
| <b>B010 - R1006 - Disabled Toilet</b>                       |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R1007 - Movement</b>                              |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R1008 - Distribution Board</b>                    |                      |        |                    |                    | Note: No inspection of live electrical installation. |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R1009 - Communications Room</b>                   |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R1010 - Cleaning Distributed Store</b>            |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R1011 - External Movement</b>                     |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R1012 - External Stairs</b>                       |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R1013 - External Movement</b>                     |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |
| <b>B010 - R1014 - Lift</b>                                  |                      |        |                    |                    |  |                  |
| No Asbestos   |                      |        |                    |                    |  |                  |



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B013 - General Learning - 2006 - Fibre Cement Clad (Fibre Cement Clad)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B013 - R0001 - External Movement**

No Asbestos

**B013 - R0002 - Practical Activities - 1hb**

No Asbestos

**B013 - R0003 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B013 - R0004 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B013 - R0005 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B013 - R0006 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B013 - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)      No Asbestos Found

**B013 - R0008 - Practical Activities - 1hb**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B014 - Storage - 2006 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B014 - R0001 - P.E. Store**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B015 - Communal Facilities - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                                   |                   |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids                     | No Asbestos Found |

**Interior**

**B015 - R0001 - Communal Space**

No Asbestos

**B015 - R0002 - Raised Platform**

No Asbestos

**B015 - R0003 - Hall Chair Store**

No Asbestos

**B015 - R0004 - Communal/Performance Store**

No Asbestos

**B015 - R0005 - P.E. Store**

No Asbestos

**B015 - R0006 - Toilet - Lobby**

No Asbestos

**B015 - R0007 - Toilets - Girls**

No Asbestos

**B015 - R0008 - Sound Cupboard**

No Asbestos

**B015 - R0009 - Toilet - Lobby**

No Asbestos

**B015 - R0010 - Toilets - Boys**

No Asbestos

**B015 - R0011 - Cleaning Distributed Store**

No Asbestos

**B015 - R0012 - Plant**

No Asbestos

**B015 - R0013 - Main Switch Board**

No Asbestos

**B015 - R0014 - Access Shower/Toilet**

No Asbestos

**B015 - R0015 - External Movement**

No Asbestos

**B015 - R0016 - Movement**

No Asbestos

**B015 - R0017 - Ramp**

No Asbestos

**B015 - R0018 - Movement**

No Asbestos



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B016 - Pupil Facilities - 2012 - Brick/Veneer (Brick/Veneer)**

**Exterior**

|                                   |                   |
|-----------------------------------|-------------------|
| Underfloor Voids - Slab on Ground | No Asbestos Found |
| Ceiling Voids                     | No Asbestos Found |

**Interior**

**B016 - R0001 - Canteen**

No Asbestos

**B016 - R0002 - Canteen Office/Store**

No Asbestos

**B016 - R0003 - General Storeroom**

No Asbestos

**B016 - R0004 - Servery Covered Area**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B017 - General Learning/Support Unit (M P S) - 2014 - Steel (Steel)**

**Exterior**

|                 |                   |
|-----------------|-------------------|
| Ceiling Voids   | No Asbestos Found |
| Underfloor Void | No Asbestos Found |

**Interior**

**B017 - R0001 - Home Base - M**

No Asbestos

**B017 - R0002 - General Storeroom**

No Asbestos

**B017 - R0003 - Disabled Toilet**

No Asbestos

**B017 - R0004 - Staff Toilet**

No Asbestos

**B017 - R0005 - External Movement**

No Asbestos

**B017 - R0006 - External Movement**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**B018 - Storage - 2015 - Metal Shed (Metal Shed)**

**Exterior**

Underfloor Voids - Slab on Ground      No Asbestos Found

Ceiling Voids      No Asbestos Found

**Interior**

**B018 - R0001 - General Storeroom**

No Asbestos

2017

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**Demountables**

**Demountable details as per the AMS records as of 15 Feb 2017.**

**OS 620 - D10670 - Single Learning Unit - H/Cap : Placement Date - 9/01/2015**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Entry**

No Asbestos Found.

**R2 - Home Base-I.O.**

No Asbestos Found.

**R3 - Disabled Shower/laundry**

No Asbestos Found.

**OS 601 - D11611 - Learning Unit - Standard/Withdrawal : Placement Date - 16/03/2006**

**Exterior**

|             |                     |                  |          |
|-------------|---------------------|------------------|----------|
| Step Treads | Compressed AC Sheet | Assumed Asbestos | 1.08 m2  |
| Landing     | Compressed AC Sheet | Assumed Asbestos | 1.2 m2   |
| Eave Lining | Flat AC Sheet       | Assumed Asbestos | 11.52 m2 |

**Interior**

**R1 - Entry**

|                |               |                  |       |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos | 8 m2  |

**R2 - General Learning Space**

|                |               |                  |       |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos | 55 m2 |

**R3 - Store**

|         |               |                  |       |
|---------|---------------|------------------|-------|
| Ceiling | Flat AC Sheet | Assumed Asbestos | 10 m2 |
|---------|---------------|------------------|-------|

**OS 601 - D12558 - Learning Unit - Standard/Withdrawal : Placement Date - 27/01/2006**

**Exterior**

|             |                     |                  |          |
|-------------|---------------------|------------------|----------|
| Step Treads | Compressed AC Sheet | Assumed Asbestos | 1.08 m2  |
| Landing     | Compressed AC Sheet | Assumed Asbestos | 1.2 m2   |
| Eave Lining | Flat AC Sheet       | Assumed Asbestos | 11.52 m2 |

**Interior**

**R1 - Entry**

|                |               |                  |       |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos | 8 m2  |

**R2 - General Learning Space**

|                |               |                  |       |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos | 55 m2 |

**R3 - Store**

|         |               |                  |       |
|---------|---------------|------------------|-------|
| Ceiling | Flat AC Sheet | Assumed Asbestos | 10 m2 |
|---------|---------------|------------------|-------|

**OS 602 - D12749 - Learning Unit - Standard With P.A.A. : Placement Date - 22/01/2016**

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

**Exterior**

No Asbestos Found.

| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 602 - D14434 - Learning Unit - Standard With P.A.A. : Placement Date - 5/07/2010**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

**OS 601 - D16214 - Learning Unit - Standard/Withdrawal : Placement Date - 30/06/1995**

**Exterior**

|             |                     |                  |          |
|-------------|---------------------|------------------|----------|
| Step Treads | Compressed AC Sheet | Assumed Asbestos | 1.08 m2  |
| Landing     | Compressed AC Sheet | Assumed Asbestos | 1.2 m2   |
| Eave Lining | Flat AC Sheet       | Assumed Asbestos | 11.52 m2 |

**Interior**

**R1 - Entry**

|                |               |                  |       |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos | 8 m2  |

**R2 - General Learning Space**

|                |               |                  |       |
|----------------|---------------|------------------|-------|
| End wall panel | Flat AC Sheet | Assumed Asbestos | 18 m2 |
| Ceiling        | Flat AC Sheet | Assumed Asbestos | 55 m2 |

**R3 - Store**

|         |               |                  |       |
|---------|---------------|------------------|-------|
| Ceiling | Flat AC Sheet | Assumed Asbestos | 10 m2 |
|---------|---------------|------------------|-------|

**OS 602 - D18161 - Learning Unit - Standard With P.A.A. : Placement Date - 11/10/2016**

**Exterior**

No Asbestos Found.

**Interior**

**R1 - Learning space/withdrawal/entry**

No Asbestos Found.

**R2 - Home Base Store**

No Asbestos Found.

2017



| Product   | Material Description | Extent | Location Reference | Material Condition | Risk Status | Control Priority |
|-----------|----------------------|--------|--------------------|--------------------|-------------|------------------|
| Sample No |                      |        |                    |                    | Test Result |                  |

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017