


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Wamberal Public School (4522)
Region : Hunter/Central Coast
State Electorate : Terrigal
Local Government Area : Gosford

Initial Survey : Noel Arnold & Associates : 21 - Mar - 2008
Reviewed By : AECOM : 29 - Jun - 2016



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - Administration - 1981 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no access to ceiling space, flat roof and no access points.
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground no access points.

Interior

B00A - R0001 - External Movement

No Asbestos

B00A - R0002 - Entry Vestibule

No Asbestos

B00A - R0003 - Clerical Office

No Asbestos

B00A - R0004 - Sick Bay

Floor Coverings Res/Textile	Vinyl Tiles 4522/B00A/R0018/Floor Coverings Res/Textile/S6	No Asbestos Detected
-----------------------------	---	-----------------------------

B00A - R0005 - Principal

No Asbestos

B00A - R0006 - Interview

No Asbestos

B00A - R0007 - External Movement

No Asbestos

B00A - R0008 - Staff Room

No Asbestos

B00A - R0009 - Staff Toilet

No Asbestos

B00A - R0010 - Staff Toilet

No Asbestos

B00A - R0011 - Cleaning Distributed Store

No Asbestos

B00A - R0012 - Staff Toilet

No Asbestos

B00A - R0013 - Deputy Principal

No Asbestos

B00A - R0014 - Interview

No Asbestos

B00A - R0015 - Security Store

No Asbestos

B00A - R0016 - Distribution Board

No Asbestos Note: No inspection of live electrical installation.

B00A - R0017 - Interview

No Asbestos

B00A - R0018 - Duplicating Workroom

Floor Coverings Res/Textile	Vinyl Tiles 4522/B00A/R0018/Floor Coverings Res/Textile/S6	No Asbestos Detected
-----------------------------	---	-----------------------------

B00A - R0019 - Movement

No Asbestos

B00A - R0020 - External Movement

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1981 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area					
	- Area inaccessible slab on ground, no access points					
Ceiling Voids - Raked Ceiling	Non Accessible Area					
	- Area inaccessible no access to ceiling space, flat roof and no access points.					

Interior

B00B - R0021 - Cleaning Supplies

Floor Coverings Res/Textile	Vinyl Tiles					
	4522/B00B/R0021/Floor Coverings Res/Textile/S7					No Asbestos Detected

B00B - R0022 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	4522/B00B/R0021/Floor Coverings Res/Textile/S7					No Asbestos Detected

B00B - R0023 - Home Base Store

No Asbestos

B00B - R0024 - Home Base

No Asbestos

B00B - R0025 - Movement

No Asbestos

B00B - R0026 - Home Base Store

No Asbestos

B00B - R0027 - Withdrawal Space - 1hb

No Asbestos

B00B - R0028 - Home Base Store

No Asbestos

B00B - R0029 - Movement

No Asbestos

B00B - R0030 - Home Base

No Asbestos

B00B - R0031 - Movement

No Asbestos

B00B - R0032 - Practical Activities - 1hb

No Asbestos

B00B - R0033 - Craft Store

No Asbestos

B00B - R0034 - General Storeroom

No Asbestos

B00B - R0035 - Personal Effects Storage

No Asbestos

B00B - R0036 - Personal Effects Storage

No Asbestos

B00B - R0037 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4522/B00B/R0039/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)

B00B - R0038 - Cleaning Distributed Store

No Asbestos

B00B - R0039 - Toilets - Boys

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4522/B00B/R0039/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	
B00B - R0040 - General Storeroom						
No Asbestos						
B00B - R0042 - Movement						
No Asbestos						
B00B - R0043 - Movement						
No Asbestos						
B00B - R0044 - External Movement						
No Asbestos						
B00B - R0045 - Personal Effects Storage						
No Asbestos						
B00B - R0046 - Movement						
No Asbestos						
B00B - R0047 - Practical Activities - 1hb						
No Asbestos						
B00B - R0048 - Kiln Room						
No Asbestos						
B00B - R0049 - Craft Store						
No Asbestos						
B00B - R0050 - Movement						
No Asbestos						
B00B - R0051 - Personal Effects Storage						
No Asbestos						
B00B - R0052 - External Movement						
No Asbestos						
B00B - R0053 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4522/B00B/R0039/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	
B00B - R0054 - Distribution Board						
No Asbestos						
B00B - R0055 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4522/B00B/R0039/Partition Walls (Cubicles)/S5					Chrysotile (white asbestos)	
B00B - R0056 - K.L.A. Store						
No Asbestos						
B00B - R0057 - External Movement						
No Asbestos						
B00B - R0058 - Home Base						
No Asbestos						
B00B - R0059 - Home Base Store						
No Asbestos						
B00B - R0060 - Withdrawal Space - 1hb						
No Asbestos						
B00B - R0061 - Home Base Store						
No Asbestos						
B00B - R0062 - Home Base						
No Asbestos						
B00B - R0064 - External Movement						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

B00B - R0065 - Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Library - 1981 - Brick/Veneer (Brick/Veneer)

Exterior

Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible no access to ceiling space, flat roof and no access points.
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points

Interior

B00C - R0001 - External Movement

No Asbestos

B00C - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00C - R0003 - Library Office/Workroom

No Asbestos

B00C - R0004 - Library Office/Workroom

No Asbestos

B00C - R0005 - Security Store

No Asbestos

B00C - R0006 - Reading Area

No Asbestos

B00C - R0007 - Seminar/Study

No Asbestos

B00C - R0008 - K.L.A. Store

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities/Pupil Facilities - 1981 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Flat Roof	Non Accessible Area - Area inaccessible no access to ceiling space, flat roof and no access points.
Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible slab to ground no access points

Interior**B00D - R0001 - Communal Space**

No Asbestos

B00D - R0002 - Sports Store

No Asbestos

B00D - R0003 - Music Store

No Asbestos

B00D - R0004 - P.E. Store

No Asbestos

B00D - R0005 - Cleaning Distributed Store

No Asbestos

B00D - R0006 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	------	------------	--------------------	---------	--------------------

4522/B00D/R0008/Partition Walls (Cubicles)/S2

Chrysotile (white asbestos)**B00D - R0007 - General Storeroom**

Non Accessible

B00D - R0008 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	---------------------	------	------------	--------------------	---------	--------------------

4522/B00D/R0008/Partition Walls (Cubicles)/S2

Chrysotile (white asbestos)**B00D - R0009 - Raised Platform**

No Asbestos

B00D - R0010 - Movement

No Asbestos

B00D - R0011 - Movement

No Asbestos

B00D - R0012 - Plant

No Asbestos

B00D - R0013 - General Assistant/Bulk Store

Floor Coverings Res/Textile	Vinyl Tiles					
		4522/B00D/R0013/Floor Coverings Res/Textile/S1				

No Asbestos Detected**B00D - R0014 - Garden Store**

No Asbestos

B00D - R0015 - External Movement

No Asbestos

B00D - R0016 - Canteen

Floor Coverings Res/Textile	Vinyl Tiles					
		4522/B00D/R0013/Floor Coverings Res/Textile/S1				

No Asbestos Detected**B00D - R0017 - Canteen Office/Store**

Floor Coverings Res/Textile	Vinyl Tiles					
		4522/B00D/R0013/Floor Coverings Res/Textile/S1				

No Asbestos Detected**B00D - R0018 - Canteen Office/Store**

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Floor Coverings
Res/Textile

Vinyl Tiles

4522/B00D/R0013/Floor Coverings Res/Textile/S1

No Asbestos Detected

B00D - R0019 - Staff Toilet

No Asbestos

B00D - R0020 - General Storeroom

No Asbestos

B00D - R0021 - External Movement

No Asbestos

B00D - R0022 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0023 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00E - General Learning/Pupil Facilities - 1981 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible no access to ceiling space, flat roof and no access points.

Interior

B00E - R0001 - Communications Room

No Asbestos

B00E - R0002 - Cleaning Distributed Store

No Asbestos

B00E - R0003 - Staff Toilet

No Asbestos

B00E - R0004 - Staff Toilet

No Asbestos

B00E - R0005 - Security Store

No Asbestos

B00E - R0006 - External Movement

No Asbestos

B00E - R0007 - Home Base

No Asbestos

B00E - R0008 - External Movement

No Asbestos

B00E - R0009 - Home Base Store

No Asbestos

B00E - R0010 - Withdrawal Space - 1hb

No Asbestos

B00E - R0011 - Home Base Store

No Asbestos

B00E - R0012 - External Movement

No Asbestos

B00E - R0013 - Home Base

No Asbestos

B00E - R0014 - Personal Effects Storage

No Asbestos

B00E - R0015 - External Movement

No Asbestos

B00E - R0016 - Kiln Room

No Asbestos

B00E - R0017 - Practical Activities - 1hb

No Asbestos

B00E - R0018 - Movement

No Asbestos

B00E - R0019 - Personal Effects Storage

No Asbestos

B00E - R0020 - Movement

No Asbestos

B00E - R0021 - Sports Store

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

B00E - R0022 - Toilets - Girls

Partition Walls (Cubicles) Compressed AC Sheet 5m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

4522/B00E/R0024/Partition Walls (Cubicles)/S3

Chrysotile (white asbestos)

B00E - R0023 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00E - R0024 - Toilets - Boys

Partition Walls (Cubicles) Compressed AC Sheet 2m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)

4522/B00E/R0024/Partition Walls (Cubicles)/S3

Chrysotile (white asbestos)

B00E - R0025 - Home Base

No Asbestos

B00E - R0026 - Home Base Store

No Asbestos

B00E - R0027 - Withdrawal Space - 1hb

No Asbestos

B00E - R0028 - Home Base Store

No Asbestos

B00E - R0029 - External Movement

No Asbestos

B00E - R0030 - Home Base

No Asbestos

B00E - R0031 - Personal Effects Storage

No Asbestos

B00E - R0032 - External Movement

No Asbestos

B00E - R0033 - Practical Activities - 1hb

No Asbestos

B00E - R0034 - Craft Store

No Asbestos

B00E - R0035 - Movement

No Asbestos

B00E - R0036 - Personal Effects Storage

No Asbestos

B00E - R0037 - External Movement

No Asbestos

B00E - R0038 - Cleaning Distributed Store

No Asbestos

B00E - R0039 - Movement

No Asbestos

B00E - R0040 - External Movement

No Asbestos

B00E - R0041 - Withdrawal Space - 1hb

No Asbestos

B00E - R0042 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning/Pupil Facilities - 1981 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground, no access points
Ceiling Voids - Raked Ceiling	Non Accessible Area - Area inaccessible no access to ceiling space, flat roof and no access points.

Interior

B00G - R0001 - General Storeroom	No Asbestos
B00G - R0003 - Toilets - Girls	No Asbestos
B00G - R0004 - Cleaning Distributed Store	No Asbestos
B00G - R0005 - Toilets - Boys	No Asbestos
B00G - R0006 - Home Base Store	No Asbestos
B00G - R0007 - Home Base	No Asbestos
B00G - R0008 - External Movement	No Asbestos
B00G - R0009 - Home Base Store	No Asbestos
B00G - R0010 - Withdrawal Space - 1hb	No Asbestos
B00G - R0011 - Home Base Store	No Asbestos
B00G - R0012 - External Movement	No Asbestos
B00G - R0013 - Home Base	No Asbestos
B00G - R0014 - Personal Effects Storage	No Asbestos
B00G - R0016 - Practical Activities - 1hb	No Asbestos
B00G - R0017 - Movement	No Asbestos
B00G - R0018 - Personal Effects Storage	No Asbestos
B00G - R0019 - General Storeroom	No Asbestos
B00G - R0020 - Craft Store	No Asbestos
B00G - R0021 - External Movement	No Asbestos
B00G - R0022 - Special Programs Room	No Asbestos
B00G - R0023 - General Storeroom	No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result
No Asbestos						
B00G - R0024 - Home Base						
No Asbestos						
B00G - R0025 - External Movement						
No Asbestos						
B00G - R0026 - Home Base Store						
No Asbestos						
B00G - R0027 - Withdrawal Space - 1hb						
No Asbestos						
B00G - R0028 - Home Base Store						
No Asbestos						
B00G - R0029 - External Movement						
No Asbestos						
B00G - R0030 - Home Base						
No Asbestos						
B00G - R0031 - Personal Effects Storage						
No Asbestos						
B00G - R0032 - External Movement						
No Asbestos						
B00G - R0033 - Movement						
No Asbestos						
B00G - R0034 - Practical Activities - 1hb						
No Asbestos						
B00G - R0035 - Personal Effects Storage						
No Asbestos						
B00G - R0036 - Craft Store						
No Asbestos						
B00G - R0037 - Craft Store						
No Asbestos						
B00G - R0038 - External Movement						
No Asbestos						
B00G - R0039 - Toilets - Girls						
Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4522/B00G/R0039/Partition Walls (Cubicles)/S4						Chrysotile (white asbestos)
B00G - R0040 - Distribution Board						
Note: No inspection of live electrical installation.						
Electrical Backing Board	Resinous Board					No Asbestos Detected
4522/B00G/R0040/Electrical Backing Board/S8						
B00G - R0041 - Toilets - Boys						
Partition Walls (Cubicles)	Compressed AC Sheet	3m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4522/B00G/R0039/Partition Walls (Cubicles)/S4						Chrysotile (white asbestos)
B00G - R0042 - Withdrawal Space - 1hb						
No Asbestos						
B00G - R0043 - Home Base						
No Asbestos						
B00G - R0044 - External Movement						
No Asbestos						
B00G - R0045 - Home Base Store						
No Asbestos						
B00G - R0046 - Withdrawal Space - 1hb						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00G - R0047 - Home Base Store						
No Asbestos						
B00G - R0048 - Home Base						
No Asbestos						
B00G - R0049 - Personal Effects Storage						
No Asbestos						
B00G - R0050 - External Movement						
No Asbestos						
B00G - R0051 - Movement						
No Asbestos						
B00G - R0052 - Practical Activities - 1hb						
No Asbestos						
B00G - R0053 - Personal Effects Storage						
No Asbestos						
B00G - R0054 - Movement						
No Asbestos						
B00G - R0055 - Craft Store						
No Asbestos						
B00G - R0056 - Cleaning Distributed Store						
No Asbestos						
B00G - R0057 - External Movement						
No Asbestos						
B00G - R0058 - Uniform Shop						
Non Accessible						
B00G - R0059 - External Movement						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Other-Community Use/Other - 2008 - Metal Shed (Metal Shed)

Exterior

Underfloor Voids - Slab on Ground Non Accessible Area
 - Area inaccessible, shed slab on ground, no access points.

Ceiling Voids No Asbestos Found

Interior

B00H - R0001 - Other-Community Use

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00I - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab to ground, no access points
Ceiling Voids	No Asbestos Found

Interior

B00I - R0001 - Practical Activities - 1hb

No Asbestos

B00I - R0002 - Personal Effects Storage

No Asbestos

B00I - R0003 - Home Base Store

No Asbestos

B00I - R0004 - Home Base

No Asbestos

B00I - R0005 - Withdrawal Space - 2hb

No Asbestos

B00I - R0006 - Practical Activities - 1hb

No Asbestos

B00I - R0007 - Personal Effects Storage

No Asbestos

B00I - R0008 - Home Base Store

No Asbestos

B00I - R0009 - Home Base

No Asbestos

B00I - R0010 - Practical Activities - 1hb

No Asbestos

B00I - R0011 - Personal Effects Storage

No Asbestos

B00I - R0012 - Home Base Store

No Asbestos

B00I - R0013 - Home Base

No Asbestos

B00I - R0014 - Withdrawal Space - 2hb

No Asbestos

B00I - R0015 - Practical Activities - 1hb

No Asbestos

B00I - R0016 - Personal Effects Storage

No Asbestos

B00I - R0017 - Home Base Store

No Asbestos

B00I - R0018 - Home Base

No Asbestos

B00I - R0019 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00I - R0020 - External Movement

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00J - General Learning - 2010 - Brick/Veneer (Brick/Veneer)

Exterior

Underfloor Voids - Slab on Ground	Non Accessible Area - Area inaccessible, slab on ground no access points
Ceiling Voids	No Asbestos Found

Interior

B00J - R0001 - Practical Activities - 1hb	No Asbestos
B00J - R0002 - Personal Effects Storage	No Asbestos
B00J - R0003 - Home Base Store	No Asbestos
B00J - R0004 - Home Base	No Asbestos
B00J - R0005 - Withdrawal Space - 2hb	No Asbestos
B00J - R0006 - Practical Activities - 1hb	No Asbestos
B00J - R0007 - Personal Effects Storage	No Asbestos
B00J - R0008 - Home Base Store	No Asbestos
B00J - R0009 - Home Base	No Asbestos
B00J - R0010 - Distribution Board	Note: No inspection of live electrical installation.
B00J - R0011 - External Movement	No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

Demountable details as per the AMS records as of 15 Feb 2017.

OS 603 - D10105 - Learning Unit - Standard With P.A.A. A/C : Placement Date - 3/01/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10336 - Learning Unit - Standard With P.A.A. : Placement Date - 8/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D10605 - Learning Unit - Standard With P.A.A. : Placement Date - 24/09/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D11477 - Learning Unit - Standard With P.A.A. : Placement Date - 3/01/2013

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 840 - D11883 - Girls Toilet : Placement Date - 24/09/2013

Exterior

No Asbestos Found.

Interior

R1 - Toilets-Girls

No Asbestos Found.

OS 601 - D12515 - Learning Unit - Standard/Withdrawal : Placement Date - 27/12/1995

Exterior

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2

Interior

R1 - Entry

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				8 m2

R2 - General Learning Space

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				55 m2

R3 - Store

Ceiling	Flat AC Sheet	Assumed Asbestos				10 m2
---------	---------------	------------------	--	--	--	-------

OS 602 - D12662 - Learning Unit - Standard With P.A.A. : Placement Date - 5/04/2012

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D13326 - Learning Unit - Standard With P.A.A. : Placement Date - 10/11/2014

Exterior

Landing	Compressed AC Sheet	Assumed Asbestos				1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos				1.08 m2
Eave Lining	Flat AC Sheet	Assumed Asbestos				11.52 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos				70 m2
---------	---------------	------------------	--	--	--	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos				18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos				3 m2

OS 602 - D13873 - Learning Unit - Standard With P.A.A. : Placement Date - 8/12/2015

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D14190 - Learning Unit - Standard With P.A.A. : Placement Date - 27/01/2015

Exterior

No Asbestos Found.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

OS 602 - D15812 - Learning Unit - Standard With P.A.A. : Placement Date - 3/01/2013

Exterior

Eave Lining	Flat AC Sheet	Assumed Asbestos	11.52 m2
Landing	Compressed AC Sheet	Assumed Asbestos	1.2 m2
Step Treads	Compressed AC Sheet	Assumed Asbestos	1.08 m2

Interior

R1 - Learning space/withdrawal/entry

Ceiling	Flat AC Sheet	Assumed Asbestos	70 m2
---------	---------------	------------------	-------

R2 - Home Base Store

End wall panel	Flat AC Sheet	Assumed Asbestos	18 m2
Ceiling	Flat AC Sheet	Assumed Asbestos	3 m2

OS 602 - D16799 - Learning Unit - Standard With P.A.A. : Placement Date - 24/09/2014

Note: This refurbished demountable may have asbestos present in remnant mastic in window frames.

Exterior

No Asbestos Found.

Interior

R1 - Learning space/withdrawal/entry

No Asbestos Found.

R2 - Home Base Store

No Asbestos Found.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017