

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Administrative Office - Strathfield (0215)
Region : South Western Sydney
State Electorate : Strathfield
Local Government Area : Strathfield

Initial Survey : Parsons Brinckerhoff : 20 - Jun - 2016
Reviewed By : Parsons Brinckerhoff : 20 - Jun - 2016

0215 - Administrative Office - Strathfield
Site Plan (12284)



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - DoE Admin Office - 1901 - Brick/Veneer (Brick/Veneer)

Exterior

Infill Panel behind Shingle Tiles	Flat AC Sheeting	1m2	South-West (External Room R0003)	Minimal Damage (2)	Low (1)	Low Priority (2-3)
	0215/B001/Exterior/Infill Panel behind Shingle Tiles/S3				Chrysotile (white asbestos)	
Underfloor Voids	No Asbestos Found					
Ceiling Void	No Asbestos Found					

Interior

B001 - R0001 - Other - D.E.T. Admin

No Asbestos

B001 - R0002 - Other - D.E.T. Admin

No Asbestos

B001 - R0003 - Other - D.E.T. Admin

No Asbestos

B001 - R0004 - Other - D.E.T. Admin

No Asbestos

B001 - R0005 - Other - D.E.T. Admin

No Asbestos

B001 - R0006 - Other - D.E.T. Admin

No Asbestos

B001 - R0007 - Other - D.E.T. Admin

Floor Coverings Res/Textile	Vinyl Tiles					
	0215/B001/R0007/Floor Coverings Res/Textile/S5				No Asbestos Detected	
Floor Coverings Res/Textile	Vinyl Tiles					
	0215/B001/R0007/Floor Coverings Res/Textile/S6				No Asbestos Detected	

B001 - R0008 - Other - D.E.T. Admin

Wall Linings Internal	Corrugated AC Sheeting	8m2	East & West	Some Damage - Unsealed (3)	Low (1)	Medium Priority (4-5)
	0215/B001/R0008/Wall Linings Internal/S4				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B001 - R0009 - Other - D.E.T. Admin

No Asbestos

B001 - R0010 - Other - D.E.T. Admin

No Asbestos

B001 - R0011 - Other - D.E.T. Admin

No Asbestos

B001 - R0012 - Other - D.E.T. Admin

No Asbestos

B001 - R0013 - Other - D.E.T. Admin

No Asbestos

B001 - R0014 - Other - D.E.T. Admin

No Asbestos

B001 - R0015 - Other - D.E.T. Admin

No Asbestos

B001 - R0016 - Other - D.E.T. Admin

No Asbestos

B001 - R0017 - Other - D.E.T. Admin

No Asbestos

B001 - R0018 - Other - D.E.T. Admin

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B001 - R0019 - Other - D.E.T. Admin						
No Asbestos						
B001 - R0020 - Other - D.E.T. Admin						
No Asbestos						
B001 - R0021 - Other - D.E.T. Admin						
Electrical Backing Board	Encapsulated Insulation material within unit	1Unit	East	Good Condition (1)	Low (1)	Low Priority (2-3)
Assumed Asbestos - Electrical Hazard - Metal Encased Unit						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B002 - DoE Admin Office - 1901 - Brick/Block (Brick/Block)

Exterior

Window Frames	Putty 0215/B002/Window Frames/S7					No Asbestos Detected
Underfloor Voids	No Asbestos Found					
Ceiling Void	No Asbestos Found					

Interior

B002 - R0001 - Other - D.E.T. Admin

No Asbestos

B002 - R0002 - Other - D.E.T. Admin

No Asbestos

B002 - R0003 - Other - D.E.T. Admin

Floor Coverings Res/Textile	Vinyl Tiles (Under Floor Covering/Carpet) 0215/B002/R0003/Floor Coverings Res/Textile/S10					No Asbestos Detected
-----------------------------	----------------------------------------------------------------------------------------------	--	--	--	--	----------------------

B002 - R0004 - Other - D.E.T. Admin

Ceiling Structures/Linings	Flat AC Sheeting 0215/B002/R0006/Ceiling Structures/Linings/S9					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 0215/B002/R0006/Wall Linings Internal/S8	3m2	North	Good Condition (1)	Low (1) Low Priority (2-3)	Chrysotile (white asbestos)

B002 - R0005 - Other - D.E.T. Admin

No Asbestos

B002 - R0006 - Other - D.E.T. Admin

Wall Linings Internal	Flat AC Sheeting 0215/B002/R0006/Wall Linings Internal/S8	5m2	West	Good Condition (1)	Low (1) Low Priority (2-3)	Chrysotile (white asbestos)
Ceiling Structures/Linings	Flat AC Sheeting 0215/B002/R0006/Ceiling Structures/Linings/S9					No Asbestos Detected

B002 - R0007 - Other - D.E.T. Admin

Ceiling Structures/Linings	Flat AC Sheeting 0215/B002/R0006/Ceiling Structures/Linings/S9					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 0215/B002/R0006/Wall Linings Internal/S8	10m2	West	Good Condition (1)	Low (1) Low Priority (2-3)	Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B003 - DoE Admin Office - 2000 - Timber (Timber)

Exterior

Ceiling Void	Non Accessible Area - No Manhole in Building					
Underfloor Voids	No Asbestos Found					

Interior

B003 - R0001 - Other - D.E.T. Admin

Ceiling Structures/Linings	Flat AC Sheeting 0215/B003/R0001/Ceiling Structures/Linings/S1					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 0215/B003/R0001/Wall Linings Internal/S2					No Asbestos Detected

B003 - R0002 - Other - D.E.T. Admin

No Asbestos

B003 - R0003 - Other - D.E.T. Admin

Electrical Backing Board	Encapsulated Insulation material within unit	1Unit	West	Good Condition (1)	Low (1)	Low Priority (2-3)
--------------------------	----------------------------------------------	-------	------	--------------------	---------	--------------------

Assumed Asbestos - Electrical Hazard - Metal encased unit

B003 - R0004 - Other - D.E.T. Admin

No Asbestos

B003 - R0005 - Other - D.E.T. Admin

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B004 - DoE Admin Office - 2000 - Timber (Timber)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Voids - Slab on Ground	No Asbestos Found

Interior

B004 - R0001 - Other - D.E.T. Admin

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017