



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00A - General Learning/Administration - 1909 - Timber (Timber)****Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior****B00A - R0001 - Movement**

No Asbestos

**B00A - R0002 - Home Base**

No Asbestos

**B00A - R0003 - Practical Activities - 1hb**

No Asbestos

**B00A - R0004 - Home Base**

No Asbestos

**B00A - R0005 - Home Base**

No Asbestos

**B00A - R0006 - Movement**

No Asbestos

**B00A - R0007 - Staff Room Annexe**

No Asbestos

**B00A - R0008 - Interview**

No Asbestos

**B00A - R0009 - Principal**

No Asbestos

**B00A - R0010 - General Storeroom**

Floor Coverings Res/Textile	Vinyl Tiles	17m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00A/R0030/Floor Coverings Res/Textile/S3					<b>Chrysotile (White asbestos)</b>	

**B00A - R0011 - Movement**

No Asbestos

**B00A - R0012 - Duplicating Workroom**

No Asbestos

**B00A - R0013 - Clerical Office**

No Asbestos

**B00A - R0014 - Sick Bay**

No Asbestos

**B00A - R0015 - Entry Vestibule**

No Asbestos

**B00A - R0016 - Movement**

No Asbestos

**B00A - R0017 - Toilets - Boys/Girls**

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00A/R0017/Wall Linings Internal/S4					<b>Chrysotile (White asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00A/R0017/Ceiling Structures/Linings/S5					<b>Chrysotile (White asbestos)</b>	

**B00A - R0018 - Shower/Change**

Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00A/R0017/Wall Linings Internal/S4					<b>Chrysotile (White asbestos)</b>	
Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00A/R0017/Ceiling Structures/Linings/S5					<b>Chrysotile (White asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
<b>B00A - R0019 - Movement</b>						
No Asbestos						
<b>B00A - R0020 - Home Base</b>						
No Asbestos						
<b>B00A - R0021 - Home Base</b>						
No Asbestos						
<b>B00A - R0022 - Practical Activities - 1hb</b>						
No Asbestos						
<b>B00A - R0023 - Movement</b>						
No Asbestos						
<b>B00A - R0024 - Staff Toilet</b>						
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00A/R0017/Wall Linings Internal/S4					<b>Chrysotile (White asbestos)</b>	
<b>B00A - R0025 - Staff Toilet</b>						
Wall Linings Internal	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00A/R0017/Wall Linings Internal/S4					<b>Chrysotile (White asbestos)</b>	
<b>B00A - R0026 - Staff Room</b>						
No Asbestos						
<b>B00A - R0027 - Staff Room Annexe</b>						
No Asbestos						
<b>B00A - R0028 - Cleaning Distributed Store</b>						
No Asbestos						
<b>B00A - R0029 - Staff Room Annexe</b>						
No Asbestos						
<b>B00A - R0030 - General Storeroom</b>						
Floor Coverings Res/Textile	Vinyl Tiles	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00A/R0030/Floor Coverings Res/Textile/S3					<b>Chrysotile (White asbestos)</b>	
<b>B00A - R9001 - General Assistant/Bulk Store</b>						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00B - Communal Facilities/Pupil Facilities - 1981 - Brick/Block (Brick/Block)****Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior****B00B - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	95m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00B/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>	

**B00B - R0002 - Communal Space**

Ceiling Structures/Linings	Flat AC Sheeting	61m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00B/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>	

**B00B - R0003 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	31m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00B/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>	

**B00B - R0004 - P.E. Store**

No Asbestos

**B00B - R0005 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	25m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00B/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00B/R0005/Partition Walls (Cubicles)/S2					<b>Chrysotile (White asbestos)</b>	

**B00B - R0006 - Cleaning Distributed Store**

Ceiling Structures/Linings	Flat AC Sheeting	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00B/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>	

**B00B - R0007 - Toilets - Girls**

Ceiling Structures/Linings	Flat AC Sheeting	23m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00B/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>	
Partition Walls (Cubicles)	Compressed AC Sheet	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00B/R0005/Partition Walls (Cubicles)/S2					<b>Chrysotile (White asbestos)</b>	

**B00B - R0008 - Canteen**

No Asbestos

**B00B - R0009 - Movement**

No Asbestos

**B00B - R0010 - Canteen Office/Store**

No Asbestos

**B00B - R0011 - Staff Toilet**

Ceiling Structures/Linings	Flat AC Sheeting	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1003/B00B/R0001/Ceiling Structures/Linings/S1					<b>Chrysotile (White asbestos)</b>	

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00C - Library - 1981 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	Requires Inspection
Underfloor Voids	Requires Inspection

**Interior**

**B00C - R0001 - Movement**

No Asbestos

**B00C - R0002 - Security Store**

No Asbestos

**B00C - R0003 - Library Office/Workroom**

Floor Coverings Res/Textile	Vinyl Tiles	1003/B00C/R0003/Floor Coverings Res/Textile/S6	<b>No Asbestos Detected</b>
-----------------------------	-------------	--	-----------------------------

**B00C - R0004 - Reading Area**

No Asbestos

**B00C - R0005 - Distribution Board**

Note: No inspection of live electrical installation.

Non Accessible

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00E - General Learning - 2002 - Brick/Veneer (Brick/Veneer)****Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior****B00E - R0001 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0002 - Practical Activities - 1hb**

No Asbestos

**B00E - R0003 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0004 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0005 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0006 - Practical Activities - 1hb**

No Asbestos

**B00E - R0007 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0008 - Laundry - Type 2**

No Asbestos

**B00E - R0009 - Access Shower/Toilet - Type 2**

No Asbestos

**B00E - R0010 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0011 - Practical Activities - 1hb**

No Asbestos

**B00E - R0012 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0013 - Withdrawal Space - 2hb**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0014 - Home Base**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0015 - Practical Activities - 1hb**

No Asbestos

**B00E - R0016 - Home Base Store**

Vinyl Tiles (Under Floor Covering/Carpet)	No Asbestos Found
---	-------------------

**B00E - R0017 - Main Switch Board**

No Asbestos

**B00E - R0018 - External Movement**

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

**B00F - General Learning/Library - 2010 - Brick/Veneer (Brick/Veneer)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00F - R0001 - External Movement**

No Asbestos

**B00F - R0002 - Practical Activities - 1hb**

No Asbestos

**B00F - R0003 - Home Base**

No Asbestos

**B00F - R0004 - Home Base Store**

No Asbestos

**B00F - R0005 - Withdrawal Space - 2hb**

No Asbestos

**B00F - R0006 - Home Base**

No Asbestos

**B00F - R0007 - Practical Activities - 1hb**

No Asbestos

**B00F - R0008 - Home Base Store**

No Asbestos

**B00F - R0009 - Staff Toilet**

No Asbestos

**B00F - R0010 - Cleaning Distributed Store**

No Asbestos

**B00F - R0011 - Main Switch Board**

No Asbestos

**B00F - R0012 - Toilet - Lobby**

No Asbestos

**B00F - R0013 - K.L.A. Store**

No Asbestos

**B00F - R0014 - Communications Room**

No Asbestos

**B00F - R0015 - Library Office/Workroom**

No Asbestos

**B00F - R0016 - Reading Area**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00G - Communal Facilities - 2007 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00G - R0001 - Communal Space**

No Asbestos

**B00G - R0002 - Raised Platform**

No Asbestos

**B00G - R0003 - Communal/Performance Store**

No Asbestos

**B00G - R0004 - External Movement**

No Asbestos

**B00G - R0005 - No Access**

No Asbestos

2017



Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

**B00H - Other - 2007 - Steel (Steel)**

**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	Requires Inspection

**Interior**

**B00H - R0001 - General Assistant/Bulk Store**

No Asbestos

**B00H - R0002 - Sports Store**

No Asbestos

**B00H - R0003 - Sports Store**

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

***Demountables***

**There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

*Listing of Electronic Attachments as of 22/03/2017*

**There are no asbestos related file attachment(s) for this school.**

2017