


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Austral Public School (1077)
Region : South Western Sydney
State Electorate : Camden
Local Government Area : Liverpool

Initial Survey : Noel Arnold & Associates : 01 - May - 2008
Reviewed By : Parsons Brinckerhoff : 05 - Aug - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1978 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	85m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00B/Eaves Linings/S17					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00A - R0001 - Home Base**

No Asbestos

B00A - R0002 - Distribution Board

Note: No inspection of live electrical installation.

No Asbestos

B00A - R0003 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00A/R0003/Floor Coverings Res/Textile/S3					No Asbestos Detected

B00A - R0004 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)

B00A - R0005 - Home Base

No Asbestos

B00A - R0006 - Home Base

No Asbestos

B00A - R0007 - Practical Activities - 1hb

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00A/R0003/Floor Coverings Res/Textile/S3					No Asbestos Detected

B00A - R0008 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)

B00A - R0009 - Home Base

No Asbestos

B00A - R0010 - General Storeroom

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00A/R0003/Floor Coverings Res/Textile/S3					No Asbestos Detected

B00A - R0011 - Sports Store

No Asbestos

B00A - R0012 - Movement

No Asbestos

B00A - R0013 - Cleaning Distributed Store

No Asbestos

B00A - R1001 - Cleaning Distributed Store

No Asbestos

B00A - R1002 - Security Store

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00A/R0003/Floor Coverings Res/Textile/S3					No Asbestos Detected

B00A - R1003 - Home Base

No Asbestos

B00A - R1004 - Practical Activities - 1hb

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No						Test Result

Floor Coverings Res/Textile Vinyl Tiles
 1077/B00A/R0003/Floor Coverings Res/Textile/S3 **No Asbestos Detected**

B00A - R1005 - Home Base

No Asbestos

B00A - R1006 - Home Base

No Asbestos

B00A - R1007 - Practical Activities - 1hb

Floor Coverings Res/Textile Vinyl Tiles
 1077/B00A/R0003/Floor Coverings Res/Textile/S3 **No Asbestos Detected**

B00A - R1008 - Home Base

No Asbestos

B00A - R1009 - Distribution Board Note: No inspection of live electrical installation.

No Asbestos

B00A - R1010 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	57m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
----------------------------	------------------	------	------------	--------------------	---------	--------------------

1077/B00A/R1010/Ceiling Structures/Linings/S22 **Chrysotile (white asbestos)**

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - Administration/Library - 1978 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	70m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00B/Eaves Linings/S17					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00B - R0001 - Main Switch Board**

No Asbestos

B00B - R0002 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)

B00B - R0003 - Movement

No Asbestos

B00B - R0004 - Movement

No Asbestos

B00B - R0005 - Movement

Ceiling Structures/Linings	Flat AC Sheeting	8m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)

B00B - R0006 - Movement

No Asbestos

B00B - R0007 - Deputy Principal

No Asbestos

B00B - R0008 - Staff Room Annexe

No Asbestos

B00B - R0009 - Disabled Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00B/R0009/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)

B00B - R0010 - Staff Toilet

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00B/R0009/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)

B00B - R0011 - Staff Room Annexe

No Asbestos

B00B - R0012 - Community Clinic

No Asbestos

B00B - R0013 - Staff Room

No Asbestos

B00B - R0014 - Duplicating Workroom

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00B/R0014/Floor Coverings Res/Textile/S1					No Asbestos Detected

B00B - R0015 - Sick Bay

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00B/R0014/Floor Coverings Res/Textile/S1					No Asbestos Detected

B00B - R0016 - Principal

No Asbestos

B00B - R0017 - Clerical Office

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
No Asbestos						
B00B - R0018 - Entry Vestibule						
No Asbestos						
B00B - R0019 - Security Store						
Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00B/R0014/Floor Coverings Res/Textile/S1					No Asbestos Detected
B00B - R0020 - Cleaning Distributed Store						
No Asbestos						
B00B - R0021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)
B00B - R0022 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	10m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)
B00B - R1001 - Library Office/Workroom						
No Asbestos						
B00B - R1002 - K.L.A. Store						
No Asbestos						
B00B - R1003 - Library Office/Workroom						
No Asbestos						
B00B - R1004 - Movement						
No Asbestos						
B00B - R1005 - Seminar/Study						
No Asbestos						
B00B - R1006 - Seminar/Study						
No Asbestos						
B00B - R1008 - Cleaning Distributed Store						
No Asbestos						
B00B - R1009 - Staff Toilet						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00B/R0009/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)
B00B - R1010 - Entry Vestibule						
No Asbestos						
B00B - R1011 - Distribution Board						
No Asbestos						
Note: No inspection of live electrical installation.						
B00B - R1012 - Staff Toilet						
Partition Walls (Cubicles)	Compressed AC Sheet	4m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00B/R0009/Partition Walls (Cubicles)/S2					Chrysotile (white asbestos)
B00B - R1014 - General Storeroom						
Ceiling Structures/Linings	Flat AC Sheeting	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)
B00B - R1015 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	49m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)
B00B - R1016 - Reading Area						
No Asbestos						
B00B - R1017 - Special Programs Room						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Communal Facilities/Pupil Facilities - 1978 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	75m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00B/Eaves Linings/S17					Chrysotile (white asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00C - R0001 - Movement**

Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)

B00C - R0002 - Communal Space

No Asbestos

B00C - R0003 - Hall Chair Store

No Asbestos

B00C - R0004 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00C/R0004/Partition Walls (Cubicles)/S7					Chrysotile (white asbestos)

B00C - R0005 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00C/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

B00C - R0006 - Raised Platform

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00C/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

B00C - R0007 - Movement

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00C/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

B00C - R0008 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00C/R0004/Partition Walls (Cubicles)/S7					Chrysotile (white asbestos)

B00C - R0009 - Hall Chair Store

No Asbestos

B00C - R0010 - P.E. Store

Ceiling Structures/Linings	Flat AC Sheeting	15m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)
Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00C/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

B00C - R0011 - Staff Toilet

No Asbestos

B00C - R0012 - Canteen Office/Store

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00C/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

B00C - R0013 - Canteen Office/Store

Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00C/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0014 - Canteen						
Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00C/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00C - R0015 - General Storeroom						
Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00C/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00C - R0016 - Cleaning Supplies						
Floor Coverings Res/Textile	Vinyl Tiles					
	1077/B00C/R0005/Floor Coverings Res/Textile/S6					No Asbestos Detected
B00C - R0017 - Garden Store						
No Asbestos						
B00C - R0018 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	18m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)
B00C - R0019 - Distribution Board						
No Asbestos						
B00C - R0020 - Cleaning Supplies						
Ceiling Structures/Linings	Flat AC Sheeting	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)
B00C - R0021 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	95m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)
B00C - R0022 - Movement						
Ceiling Structures/Linings	Flat AC Sheeting	35m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00A/R1010/Ceiling Structures/Linings/S22					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Other-Non-Govt Pre-School - 1967 - Brick/Veneer (Brick/Veneer)**Exterior**

Eaves Linings	Flat AC Sheeting 1077/B00D/Eaves Linings/S18					No Asbestos Detected
Gable Verge Lining	Flat AC Sheeting 1077/B00D/Gable Verge Lining/S19	20m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Underfloor Voids - Packing to Floor Joists	Flat AC Sheeting 1077/B00D/Underfloor Voids - Packing to Floor Joists/S21	1m2	Variable positions	Some Damage - Unsealed (3)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos)
Ceiling Voids	No Asbestos Found					

Interior**B00D - R0002 - Other-Non Government Pre-Sch**

No Asbestos

B00D - R0003 - Other-Non Government Pre-Sch

Ceiling Structures/Linings	Flat AC Sheeting 1077/B00D/R0019/Ceiling Structures/Linings/S23	14m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00D - R0004 - Other-Non Government Pre-Sch

Ceiling Structures/Linings	Flat AC Sheeting 1077/B00D/R0019/Ceiling Structures/Linings/S23	7m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
In-fill-panel	Flat AC Sheeting 1077/B00D/R0019/Ceiling Structures/Linings/S23	4m	South, Upper portion	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00D - R0005 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile	Vinyl Tiles 1077/B00D/R0017/Floor Coverings Res/Textile/S15					No Asbestos Detected
-----------------------------	--	--	--	--	--	-----------------------------

B00D - R0006 - Other-Non Government Pre-Sch

No Asbestos

B00D - R0007 - Other-Non Government Pre-Sch

Floor Coverings Res/Textile	Vinyl Tiles 1077/B00D/R0017/Floor Coverings Res/Textile/S15					No Asbestos Detected
Wall Linings Internal	Flat AC Sheeting 1077/B00D/R0007/Wall Linings Internal/S24	12m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
						Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)

B00D - R0008 - Other-Non Government Pre-Sch

No Asbestos

B00D - R0009 - Other-Non Government Pre-Sch

No Asbestos

B00D - R0010 - Other-Non Government Pre-Sch

No Asbestos

B00D - R0011 - Other-Non Government Pre-Sch

No Asbestos

B00D - R0013 - Other-Non Government Pre-Sch

No Asbestos

B00D - R0014 - Other-Non Government Pre-Sch

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00D - R0015 - Other-Non Government Pre-Sch						
Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
1077/B00D/R0015/Ceiling Structures/Linings/S16				Chrysotile (white asbestos) , Amosite (brown asbestos)		
B00D - R0016 - Other-Non Government Pre-Sch						
No Asbestos						
B00D - R0017 - Other-Non Government Pre-Sch						
Floor Coverings Res/Textile	Vinyl Tiles					
1077/B00D/R0017/Floor Coverings Res/Textile/S15				No Asbestos Detected		
B00D - R0018 - Other-Non Government Pre-Sch						
No Asbestos						
B00D - R0019 - Other-Non Government Pre-Sch						
Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Minimal Damage (2)	Low (1)	Low Priority (2-3)
1077/B00D/R0019/Ceiling Structures/Linings/S23				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)		
B00D - R0020 - Home Base - Pre						
No Asbestos						
B00D - R0021 - Home Base - Pre						
No Asbestos						
B00D - R0022 - Other-Non Government Pre-Sch						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1957 - Timber (Timber)

Exterior

Eaves Linings	Flat AC Sheeting	36m2	North, South	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00E/Eaves Linings/S14				Chrysotile (white asbestos) , Amosite (brown asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids	No Asbestos Found					

Interior

B00E - R0006 - External Movement

Ceiling Structures/Linings	Flat AC Sheeting	73m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00E/R0006/Ceiling Structures/Linings/S13				Chrysotile (white asbestos) , Amosite (brown asbestos)	

B00E - R0007 - Home Base

No Asbestos

B00E - R0008 - Practical Activities

No Asbestos

B00E - R0009 - Home Base

No Asbestos

B00E - R0010 - Practical Activities

No Asbestos

B00E - R0011 - Special Programs Room

No Asbestos

B00E - R0012 - Home Base

No Asbestos

B00E - R0013 - Practical Activities

No Asbestos

B00E - R0014 - Home Base

No Asbestos

B00E - R0015 - Practical Activities

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - Pupil Facilities - 1978 - Brick/Block (Brick/Block)

Exterior

Eaves Linings	Flat AC Sheeting	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00H/Eaves Linings/S20					Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior

B00G - R0001 - Toilets - Girls

Partition Walls (Cubicles)	Compressed AC Sheet	6m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00G/R0006/Partition Walls (Cubicles)/S9					Chrysotile (white asbestos)

B00G - R0002 - Drinking Facilities

No Asbestos

B00G - R0003 - Cleaning Supplies

No Asbestos

B00G - R0004 - Cleaning Supplies

No Asbestos

B00G - R0005 - Drinking Facilities

No Asbestos

B00G - R0006 - Toilets - Boys

Partition Walls (Cubicles)	Compressed AC Sheet	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00G/R0006/Partition Walls (Cubicles)/S9					Chrysotile (white asbestos)

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - Pupil Facilities - 1967 - Brick/Block (Brick/Block)**Exterior**

Eaves Linings	Flat AC Sheeting	50m2	East, West	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00H/Eaves Linings/S20				Chrysotile (white asbestos) , Amosite (brown asbestos) , Crocidolite (blue asbestos)	
Ceiling Voids	No Asbestos Found					
Underfloor Voids - Slab on Ground	No Asbestos Found					

Interior**B00H - R0001 - Toilets - Boys**

Ceiling Structures/Linings	Flat AC Sheeting	52m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00H/R0001/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)	

B00H - R0002 - Garden Store

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00H/R0001/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)	

B00H - R0003 - Cleaning Supplies

Ceiling Structures/Linings	Flat AC Sheeting	5m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00H/R0001/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)	

B00H - R0004 - Toilets - Girls

Ceiling Structures/Linings	Flat AC Sheeting	48m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	1077/B00H/R0001/Ceiling Structures/Linings/S8				Chrysotile (white asbestos)	

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B00I - General Learning - 2010 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Voids	No Asbestos Found
Underfloor Voids	No Asbestos Found

Interior**B00I - R0001 - Practical Activities - 1hb**

No Asbestos

B00I - R0002 - Home Base

No Asbestos

B00I - R0003 - Home Base Store

No Asbestos

B00I - R0004 - Withdrawal Space - 2hb

No Asbestos

B00I - R0005 - Practical Activities - 1hb

No Asbestos

B00I - R0006 - Home Base

No Asbestos

B00I - R0007 - Home Base Store

No Asbestos

B00I - R0008 - Practical Activities - 1hb

No Asbestos

B00I - R0009 - Home Base

No Asbestos

B00I - R0010 - Home Base Store

No Asbestos

B00I - R0011 - Withdrawal Space - 2hb

No Asbestos

B00I - R0012 - Practical Activities - 1hb

No Asbestos

B00I - R0013 - Home Base

No Asbestos

B00I - R0014 - Home Base Store

No Asbestos

B00I - R0015 - Movement

No Asbestos

B00I - R0016 - Special Programs Room

No Asbestos

B00I - R0017 - Special Programs Store

No Asbestos

B00I - R0018 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B00I - R0019 - External Movement

No Asbestos

B00I - R0020 - Personal Effects Storage

No Asbestos

B00I - R0021 - Personal Effects Storage

No Asbestos

B00I - R0022 - Personal Effects Storage

No Asbestos

B00I - R0023 - Personal Effects Storage

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

Available Asbestos Related Electronic Files

1077_ASB_021112_AMP.pdf

* Note : Refer to AMS for details of the attachment(s).

2017