

Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Ambarvale Public School (4505)
Region : South Western Sydney
State Electorate : Campbelltown
Local Government Area : Campbelltown

Initial Survey : Noel Arnold & Associates : 21 - May - 2008
Reviewed By : Greencap-NAA : 29 - May - 2015



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00A - General Learning - 1985 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- Area inaccessible

Underfloor Voids - Slab on Ground

Interior**B00A - R0001 - Drinking Facilities (1.81 m2)**

Ceiling Structures/Linings Flat AC Sheeting
4505/B00A/R0001/Ceiling Structures/Linings/S10
No Asbestos Detected

B00A - R0002 - Distribution Board (1.17 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings Flat AC Sheeting
4505/B00A/R0001/Ceiling Structures/Linings/S10
No Asbestos Detected

B00A - R0003 - External Movement (0.9 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00A/R0001/Ceiling Structures/Linings/S10
No Asbestos Detected

B00A - R0004 - Security Store (6.7 m2)

No Asbestos

B00A - R0005 - Personal Effects Storage (0.91 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00A/R0001/Ceiling Structures/Linings/S10
No Asbestos Detected

B00A - R0006 - Personal Effects Storage (1.26 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00A/R0001/Ceiling Structures/Linings/S10
No Asbestos Detected

B00A - R0007 - Personal Effects Storage (1.26 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00A/R0001/Ceiling Structures/Linings/S10
No Asbestos Detected

B00A - R0008 - Personal Effects Storage (0.55 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00A/R0001/Ceiling Structures/Linings/S10
No Asbestos Detected

B00A - R0009 - Practical Activities - 1hb (36.3 m2)

No Asbestos

B00A - R0010 - Home Base Store (4.86 m2)

No Asbestos

B00A - R0011 - Home Base (58.94 m2)

No Asbestos

B00A - R0012 - External Movement (14.42 m2)

No Asbestos

B00A - R0013 - Withdrawal Space - 1hb (11.05 m2)

No Asbestos

B00A - R0014 - External Movement (14.42 m2)

No Asbestos

B00A - R0015 - Home Base (58.85 m2)

No Asbestos

B00A - R0016 - Home Base Store (4.86 m2)

No Asbestos

B00A - R0017 - External Movement (0.95 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00A/R0001/Ceiling Structures/Linings/S10
No Asbestos Detected

B00A - R0018 - Toilets - Boys (11.33 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Ceiling Structures/Linings	Flat AC Sheeting		4505/B00A/R0001/Ceiling Structures/Linings/S10			No Asbestos Detected
----------------------------	------------------	--	--	--	--	-----------------------------

Partition Walls (Cubicles)	Compressed AC Sheet		4505/B00A/R0018/Partition Walls (Cubicles)/S3			No Asbestos Detected
----------------------------	---------------------	--	---	--	--	-----------------------------

B00A - R0019 - External Movement (23.31 m2)

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00B - General Learning - 1985 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- Area inaccessible

Underfloor Voids - Slab on Ground

Interior**B00B - R0001 - Cleaning Distributed Store (3.99 m2)**

No Asbestos

B00B - R0002 - Disabled Toilet (6.3 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00B/R0002/Ceiling Structures/Linings/S11
No Asbestos Detected

B00B - R0003 - External Movement (0.95 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00B/R0002/Ceiling Structures/Linings/S11
No Asbestos Detected

B00B - R0004 - Personal Effects Storage (1.03 m2)

No Asbestos

B00B - R0005 - Personal Effects Storage (1.27 m2)

No Asbestos

B00B - R0006 - Personal Effects Storage (1.27 m2)

No Asbestos

B00B - R0007 - Personal Effects Storage (0.96 m2)

No Asbestos

B00B - R0008 - External Movement (0.95 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00B/R0002/Ceiling Structures/Linings/S11
No Asbestos Detected

B00B - R0009 - Practical Activities - 1hb (36.41 m2)

In-fill-panel Flat AC Sheeting
4505/B00B/R0002/Ceiling Structures/Linings/S11
No Asbestos Detected

B00B - R0010 - Security Store (6.7 m2)

No Asbestos

B00B - R0011 - Home Base (58.85 m2)

In-fill-panel Flat AC Sheeting
4505/B00B/R0002/Ceiling Structures/Linings/S11
No Asbestos Detected

B00B - R0012 - Home Base Store (4.86 m2)

No Asbestos

B00B - R0013 - External Movement (14.42 m2)

No Asbestos

B00B - R0014 - Withdrawal Space - 1hb (11.02 m2)

No Asbestos

B00B - R0015 - External Movement (14.39 m2)

No Asbestos

B00B - R0016 - Home Base (58.93 m2)

In-fill-panel Flat AC Sheeting
4505/B00B/R0002/Ceiling Structures/Linings/S11
No Asbestos Detected

B00B - R0017 - Home Base Store (4.86 m2)

No Asbestos

B00B - R0018 - Distribution Board (1.18 m2)

Note: No inspection of live electrical installation.

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting		4505/B00B/R0002/Ceiling Structures/Linings/S11			No Asbestos Detected
B00B - R0019 - Drinking Facilities (1.71 m2)						
Ceiling Structures/Linings	Flat AC Sheeting		4505/B00B/R0002/Ceiling Structures/Linings/S11			No Asbestos Detected
B00B - R0020 - External Movement (68.77 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00C - Admin/Computer Learning - 1978 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- Area inaccessible

Underfloor Voids - Slab on Ground

Interior**B00C - R0001 - Drinking Facilities (1.71 m2)**

Ceiling Structures/Linings Flat AC Sheeting
4505/B00C/R0002/Ceiling Structures/Linings/S12
No Asbestos Detected

B00C - R0002 - Distribution Board (1.2 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings Flat AC Sheeting
4505/B00C/R0002/Ceiling Structures/Linings/S12
No Asbestos Detected

On Ground AC Fragments/Debris
4505/B00C/R0002/On Ground/S13
No Asbestos Detected

B00C - R0003 - External Movement (1 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00C/R0002/Ceiling Structures/Linings/S12
No Asbestos Detected

B00C - R0004 - Movement (1 m2)

No Asbestos

B00C - R0005 - K.L.A. Store (7.8 m2)

No Asbestos

B00C - R0006 - Personal Effects Storage (5.76 m2)

No Asbestos

B00C - R0007 - Personal Effects Storage (7.16 m2)

No Asbestos

B00C - R0008 - Personal Effects Storage (5.67 m2)

No Asbestos

B00C - R0009 - Practical Activities - 1hb (45.62 m2)

No Asbestos

B00C - R0010 - External Movement (1 m2)

Ceiling Structures/Linings Flat AC Sheeting
4505/B00C/R0002/Ceiling Structures/Linings/S12
No Asbestos Detected

B00C - R0011 - Home Base (58.86 m2)

No Asbestos

B00C - R0012 - Home Base Store (4.61 m2)

No Asbestos

B00C - R0013 - External Movement (15.05 m2)

No Asbestos

B00C - R0014 - Withdrawal Space - 1hb (8.12 m2)

No Asbestos

B00C - R0015 - External Movement (12.92 m2)

No Asbestos

B00C - R0016 - Home Base (58.93 m2)

No Asbestos

B00C - R0017 - Home Base Store (4.59 m2)

No Asbestos

B00C - R0018 - Home Base (58.93 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00C - R0019 - Home Base Store (4.86 m2)						
No Asbestos						
B00C - R0020 - Withdrawal Space - 1hb (8.15 m2)						
No Asbestos						
B00C - R0021 - External Movement (15.42 m2)						
No Asbestos						
B00C - R0022 - Toilets - Girls (15.82 m2)						
Ceiling Structures/Linings	Flat AC Sheeting		4505/B00C/R0002/Ceiling Structures/Linings/S12			No Asbestos Detected
Partition Walls (Cubicles)	Compressed AC Sheet		4505/B00C/R0022/Partition Walls (Cubicles)/S14			No Asbestos Detected
B00C - R0023 - External Movement (39.27 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00D - Communal Facilities - 1978 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling
 Non Accessible Area
 - Area inaccessible

Underfloor Voids - Slab on Ground

Interior

B00D - R0001 - Sports Store (18.85 m2)

No Asbestos

B00D - R0002 - Cleaning Supplies (13.97 m2)

No Asbestos

B00D - R0003 - Canteen (44.97 m2)

No Asbestos

B00D - R0004 - Cleaning Distributed Store (8.06 m2)

No Asbestos

B00D - R0005 - Staff Toilet (4.27 m2)

No Asbestos

B00D - R0006 - Canteen Office/Store (4.56 m2)

No Asbestos

B00D - R0007 - Hall Chair Store (27.11 m2)

No Asbestos

B00D - R0008 - Movement (38.55 m2)

No Asbestos

B00D - R0009 - Toilets - Boys (7.46 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00D/R0009/Partition Walls (Cubicles)/S15					Chrysotile (white asbestos)	

B00D - R0010 - Toilets - Girls (7.44 m2)

Partition Walls (Cubicles)	Compressed AC Sheet	4m2	West	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00D/R0009/Partition Walls (Cubicles)/S15					Chrysotile (white asbestos)	

B00D - R0011 - Distribution Board (0.79 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00D - R0012 - General Storeroom (11.63 m2)

No Asbestos

B00D - R0013 - Raised Platform (35.73 m2)

No Asbestos

B00D - R0014 - Communal Space (243.72 m2)

No Asbestos

B00D - R0015 - Hall Chair Store (4.06 m2)

No Asbestos

B00D - R0016 - Plant (4.06 m2)

No Asbestos

B00D - R0017 - External Movement (184.19 m2)

No Asbestos

B00D - R0018 - External Movement (214.37 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00E - General Learning - 1978 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- Area inaccessible

Underfloor Voids - Slab on Ground

Interior**B00E - R0001 - Home Base (61.72 m2)**

No Asbestos

B00E - R0002 - Home Base Store (0.85 m2)

Ceiling Structures/Linings	Flat AC Sheeting	0.85m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00E/R0002/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)	

B00E - R0003 - Home Base Store (1.28 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1.28m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00E/R0002/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)	

B00E - R0004 - Withdrawal Space - 1hb (18.09 m2)

No Asbestos

B00E - R0005 - Home Base (61.95 m2)

No Asbestos

B00E - R0006 - Home Base Store (1.24 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1.24m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00E/R0002/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)	

B00E - R0007 - Home Base Store (0.87 m2)

Ceiling Structures/Linings	Flat AC Sheeting	0.87m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00E/R0002/Ceiling Structures/Linings/S18					Chrysotile (white asbestos)	

B00E - R0008 - Practical Activities - 1hb (26.39 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
4505/B00H/R0012/Floor Coverings Res/Textile/S6					No Asbestos Detected	

B00E - R0009 - Drinking Facilities (3.91 m2)

No Asbestos

B00E - R0010 - External Movement (60.32 m2)

No Asbestos

B00E - R0011 - Toilets - Boys (30.46 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00F - General Learning - 1985 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- Area inaccessible

Underfloor Voids - Slab on Ground

Interior**B00F - R0001 - Toilets - Girls (24.22 m2)**

Partition Walls (Cubicles) Compressed AC Sheet
4505/B00A/R0018/Partition Walls (Cubicles)/S3 **No Asbestos Detected**

B00F - R0002 - Distribution Board (0.9 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings Flat AC Sheeting 1m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
4505/B00F/R0010/Ceiling Structures/Linings/S19 **Chrysotile (white asbestos)**

B00F - R0003 - Staff Toilet (4.92 m2)

No Asbestos

B00F - R0004 - Home Base (61.81 m2)

No Asbestos

B00F - R0005 - Home Base Store (0.85 m2)

Ceiling Structures/Linings Flat AC Sheeting 1m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
4505/B00F/R0010/Ceiling Structures/Linings/S19 **Chrysotile (white asbestos)**

B00F - R0006 - Home Base Store (1.33 m2)

Ceiling Structures/Linings Flat AC Sheeting 1m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
4505/B00F/R0010/Ceiling Structures/Linings/S19 **Chrysotile (white asbestos)**

B00F - R0007 - Withdrawal Space - 1hb (19.4 m2)

No Asbestos

B00F - R0008 - Home Base (61.67 m2)

No Asbestos

B00F - R0009 - Home Base Store (1.26 m2)

Ceiling Structures/Linings Flat AC Sheeting 1m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
4505/B00F/R0010/Ceiling Structures/Linings/S19 **Chrysotile (white asbestos)**

B00F - R0010 - Home Base Store (0.85 m2)

Ceiling Structures/Linings Flat AC Sheeting 1m2 Throughout Good Condition (1) Low (1) Low Priority (2-3)
4505/B00F/R0010/Ceiling Structures/Linings/S19 **Chrysotile (white asbestos)**

B00F - R0011 - Practical Activities - 1hb (24.92 m2)

Floor Coverings Res/Textile Vinyl Tiles
4505/B00H/R0012/Floor Coverings Res/Textile/S6 **No Asbestos Detected**

B00F - R0012 - Drinking Facilities (5.04 m2)

No Asbestos

B00F - R0013 - External Movement (47.04 m2)

No Asbestos

B00F - R0014 - External Movement (239.83 m2)

No Asbestos

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00G - General Learning - 1978 - Brick/Block (Brick/Block)**Exterior**

Ceiling Voids - Raked Ceiling
Non Accessible Area
- Area inaccessible

Underfloor Voids - Slab on Ground

Interior**B00G - R0001 - Toilets - Girls (24.35 m2)**

No Asbestos

B00G - R0002 - Distribution Board (1.05 m2)

Note: No inspection of live electrical installation.

No Asbestos

B00G - R0003 - Home Base (61.51 m2)

No Asbestos

B00G - R0004 - Home Base Store (0.85 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00G/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)	

B00G - R0005 - Home Base Store (1.29 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00G/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)	

B00G - R0006 - Withdrawal Space - 1hb (17.96 m2)

No Asbestos

B00G - R0007 - Home Base (60.85 m2)

No Asbestos

B00G - R0008 - Home Base Store (1.28 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00G/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)	

B00G - R0009 - Home Base Store (0.85 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00G/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)	

B00G - R0010 - Practical Activities - 1hb (23.78 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
4505/B00H/R0012/Floor Coverings Res/Textile/S6					No Asbestos Detected	

B00G - R0011 - Drinking Facilities (5.04 m2)

No Asbestos

B00G - R0012 - Cleaning Distributed Store (5.05 m2)

No Asbestos

B00G - R0013 - Staff Room Annexe (11.54 m2)

No Asbestos

B00G - R0014 - Home Base (60.81 m2)

No Asbestos

B00G - R0015 - Home Base Store (0.75 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00G/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)	

B00G - R0016 - Home Base Store (1.14 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00G/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)	
B00G - R0017 - Personal Effects Storage (18.82 m2)						
No Asbestos						
B00G - R0018 - Home Base (63.68 m2)						
No Asbestos						
B00G - R0019 - Home Base Store (1.12 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00G/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)	
B00G - R0020 - Home Base Store (0.75 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00G/R0004/Ceiling Structures/Linings/S17					Chrysotile (white asbestos)	
B00G - R0021 - Practical Activities - 1hb (26.02 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
4505/B00H/R0012/Floor Coverings Res/Textile/S6					No Asbestos Detected	
B00G - R0022 - Drinking Facilities (3.78 m2)						
No Asbestos						
B00G - R0023 - Toilets - Boys (28.55 m2)						
Partition Walls (Cubicles)	Compressed AC Sheet					
4505/B00A/R0018/Partition Walls (Cubicles)/S3					No Asbestos Detected	
B00G - R0024 - Security Store (13.83 m2)						
No Asbestos						
B00G - R0025 - General Assistant/Bulk Store (14.31 m2)						
No Asbestos						
B00G - R0026 - Movement (1.23 m2)						
No Asbestos						
B00G - R0027 - External Movement (60.25 m2)						
No Asbestos						
B00G - R0028 - External Movement (59.67 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B00H - General Learning - 1978 - Brick/Block (Brick/Block)

Exterior

Ceiling Voids - Raked Ceiling
 Non Accessible Area
 - Area inaccessible

Underfloor Voids - Slab on Ground

Interior

B00H - R0001 - Security Store (12.88 m2)

No Asbestos

B00H - R0002 - Security Store (12.23 m2)

No Asbestos

B00H - R0003 - Distribution Board (1.05 m2)

Note: No inspection of live electrical installation.

Ceiling Structures/Linings	Flat AC Sheeting	2m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00H/R0003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00H - R0004 - Home Base (70.93 m2)

No Asbestos

B00H - R0005 - Home Base Store (0.85 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00H/R0003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00H - R0006 - Home Base Store (1.3 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00H/R0003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00H - R0007 - Toilets - Boys/Girls (2.87 m2)

No Asbestos

B00H - R0008 - Withdrawal Space - 1hb (17.9 m2)

No Asbestos

B00H - R0009 - Toilets - Boys/Girls (2.93 m2)

No Asbestos

B00H - R0010 - Home Base (75.84 m2)

No Asbestos

B00H - R0011 - Home Base Store (1.1 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00H/R0003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00H - R0012 - Practical Activities - 1hb (25.34 m2)

Floor Coverings Res/Textile	Vinyl Tiles					
4505/B00H/R0012/Floor Coverings Res/Textile/S6					No Asbestos Detected	

B00H - R0013 - Drinking Facilities (5.04 m2)

No Asbestos

B00H - R0014 - Home Base Store (0.85 m2)

Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00H/R0003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	

B00H - R0015 - Home Base (71.41 m2)

No Asbestos

B00H - R0016 - Home Base Store (0.85 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00H/R0003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00H - R0017 - Home Base Store (0.85 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00H/R0003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00H - R0018 - Toilets - Boys/Girls (2.95 m2)						
No Asbestos						
B00H - R0019 - Withdrawal Space - 1hb (17.52 m2)						
No Asbestos						
B00H - R0020 - Toilets - Boys/Girls (3.33 m2)						
No Asbestos						
B00H - R0021 - Home Base Store (0.68 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00H/R0003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00H - R0022 - Home Base Store (0.85 m2)						
Ceiling Structures/Linings	Flat AC Sheeting	1m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00H/R0003/Ceiling Structures/Linings/S16					Chrysotile (white asbestos)	
B00H - R0023 - Home Base (73.33 m2)						
No Asbestos						
B00H - R0024 - Practical Activities - 1hb (24.27 m2)						
Floor Coverings Res/Textile	Vinyl Tiles					
4505/B00H/R0012/Floor Coverings Res/Textile/S6					No Asbestos Detected	
B00H - R0025 - Drinking Facilities (3.36 m2)						
No Asbestos						
B00H - R0026 - External Movement (94.58 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B001 - Administration/Library - 1978 - Brick/Block (Brick/Block)

Exterior

Underfloor Voids - Slab on Ground

Ceiling Voids - Raked Ceiling
 Non Accessible Area
 - Area inaccessible

Interior

B001 - R0001 - Staff Room (93.03 m2)

Ceiling Structures/Linings Vermiculite
 4505/B001/R0022/Ceiling Structures/Linings/S7
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0002 - Community Clinic (17.81 m2)

Ceiling Structures/Linings Vermiculite
 4505/B001/R0022/Ceiling Structures/Linings/S7
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0003 - Staff Toilet (9.26 m2)

Ceiling Structures/Linings Vermiculite
 4505/B001/R0022/Ceiling Structures/Linings/S7
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0004 - Staff Toilet (9.2 m2)

Ceiling Structures/Linings Vermiculite
 4505/B001/R0022/Ceiling Structures/Linings/S7
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

Partition Walls (Cubicles) Compressed AC Sheet 3m2 North Good Condition (1) Low (1) Low Priority (2-3)
 4505/B001/R0004/Partition Walls (Cubicles)/S8 **Chrysotile (white asbestos)**

B001 - R0005 - Staff Room Annexe (14.02 m2)

Ceiling Structures/Linings Vermiculite
 4505/B001/R0022/Ceiling Structures/Linings/S7
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0006 - Staff Room Annexe (13.17 m2)

Ceiling Structures/Linings Vermiculite
 4505/B001/R0022/Ceiling Structures/Linings/S7
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0007 - Movement (22.2 m2)

Ceiling Structures/Linings Vermiculite
 4505/B001/R0022/Ceiling Structures/Linings/S7
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0009 - Principal (20.72 m2)

Ceiling Structures/Linings Vermiculite 21m2 Throughout Friable Asbestos (5) Low (1) Low Priority (2-3)
Assumed Asbestos

B001 - R0010 - Clerical Office (12.32 m2)

Ceiling Structures/Linings Vermiculite
 4505/B001/R0022/Ceiling Structures/Linings/S7
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0011 - Duplicating Workroom (14 m2)

Ceiling Structures/Linings Vermiculite
 4505/B001/R0022/Ceiling Structures/Linings/S7
Limited Samples Taken
Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works

B001 - R0012 - Clerical Office (11.16 m2)

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
Ceiling Structures/Linings	Vermiculite					
	4505/B001/R0022/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R0015 - Cleaning Supplies (14.4 m2)						
Ceiling Structures/Linings	Vermiculite					
	4505/B001/R0022/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R0016 - Cleaning Distributed Store (6.14 m2)						
Ceiling Structures/Linings	Vermiculite					
	4505/B001/R0022/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R0017 - Security Store (23.13 m2)						
Ceiling Structures/Linings	Vermiculite					
	4505/B001/R0022/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
Floor Coverings Res/Textile	Vinyl Tiles	24m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
	4505/B001/R0001/Floor Coverings Res/Textile/S1					Chrysotile (white asbestos)
B001 - R0018 - External Movement (8.37 m2)						
No Asbestos						
B001 - R0019 - Main Switch Board (4.92 m2)						
No Asbestos						
B001 - R0020 - External Movement (44.64 m2)						
No Asbestos						
B001 - R0021 - Principal (17.57 m2)						
Ceiling Structures/Linings	Vermiculite					
	4505/B001/R0022/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R0022 - Entry Vestibule (11.14 m2)						
Ceiling Structures/Linings	Vermiculite					
	4505/B001/R0022/Ceiling Structures/Linings/S7					Limited Samples Taken
<i>Vermiculite Ceilings may contain asbestos. Asbestos testing MUST be conducted prior to any disturbance works</i>						
B001 - R0023 - External Movement (3.92 m2)						
No Asbestos						
B001 - R0024 - External Stairs (3.95 m2)						
No Asbestos						
B001 - R0025 - Stairs (23.34 m2)						
No Asbestos						
B001 - R1001 - Movement (14.62 m2)						
No Asbestos						
B001 - R1002 - Toilets - Boys (4.02 m2)						
No Asbestos						
B001 - R1003 - Toilets - Girls (4.04 m2)						
No Asbestos						
B001 - R1004 - Cleaning Distributed Store (2.44 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	11m2	Throughout	Good Condition (1)	Low (1)	Low Priority (2-3)
	4505/B001/R1004/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)
B001 - R1005 - Distribution Board (2.41 m2)						
No Asbestos						
Note: No inspection of live electrical installation.						
B001 - R1006 - Library Office/Workroom (7.13 m2)						
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B00I - R1007 - Security Store (12.03 m2)						
Floor Coverings Res/Textile	Vinyl Tiles	13m2	North	Good Condition (1)	Low (1)	Low Priority (2-3)
4505/B00I/R1004/Floor Coverings Res/Textile/S9					Chrysotile (white asbestos)	
B00I - R1008 - Library Office/Workroom (23.1 m2)						
No Asbestos						
B00I - R1009 - Seminar/Study (13.09 m2)						
No Asbestos						
B00I - R1010 - Seminar/Study (13.75 m2)						
No Asbestos						
B00I - R1012 - External Movement (44.64 m2)						
No Asbestos						
B00I - R1013 - Special Programs Room (31.48 m2)						
No Asbestos						
B00I - R1014 - External Stairs (17.01 m2)						
No Asbestos						
B00I - R1015 - External Stairs (17.13 m2)						
No Asbestos						
B00I - R1016 - Reading Area (221.63 m2)						
No Asbestos						

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017