


Asbestos Register

(Hazardous Materials and Risk Assessment)

School : Anzac Park Public School (4656)
Region : Northern Sydney
State Electorate : Willoughby
Local Government Area : Northern Sydney

Initial Survey : :
Register Issue Date : 23 - Mar - 2017



2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result

B0D1 - General Learning - 2016 - Brick/Veneer (Brick/Veneer)**Exterior**

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior**B0D1 - R0001 - Communal Space**

No Asbestos

B0D1 - R0002 - Communal/Performance Store

No Asbestos

B0D1 - R0003 - Communal/Performance Store

No Asbestos

B0D1 - R0004 - Hall Chair Store

No Asbestos

B0D1 - R0005 - Raised Platform

No Asbestos

B0D1 - R0006 - P.E. Store

No Asbestos

B0D1 - R0007 - Access Shower/Toilet/Change

No Asbestos

B0D1 - R0008 - Distribution Board

No Asbestos

Note: No inspection of live electrical installation.

B0D1 - R0009 - Movement

No Asbestos

B0D1 - R0010 - Movement

No Asbestos

B0D1 - R0011 - Movement

No Asbestos

B0D1 - R0012 - External Movement

No Asbestos

B0D1 - R0013 - Lift

No Asbestos

B0D1 - R0014 - Canteen

No Asbestos

B0D1 - R0015 - Canteen Office/Store

No Asbestos

B0D1 - R0016 - External Movement

No Asbestos

B0D1 - R0017 - Plant

No Asbestos

B0D1 - R0018 - Plant

No Asbestos

B0D1 - R1001 - Entry Vestibule

No Asbestos

B0D1 - R1002 - Interview

No Asbestos

B0D1 - R1003 - Interview

No Asbestos

B0D1 - R1004 - Access Shower/Toilet

No Asbestos

B0D1 - R1005 - Sick Bay

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B0D1 - R1006 - Security Store					
	No Asbestos					
	B0D1 - R1007 - Deputy Principal					
	No Asbestos					
	B0D1 - R1008 - Deputy Principal					
	No Asbestos					
	B0D1 - R1009 - Staff Toilet					
	No Asbestos					
	B0D1 - R1010 - Staff Toilet					
	No Asbestos					
	B0D1 - R1011 - Staff Toilet					
	No Asbestos					
	B0D1 - R1012 - Staff Room					
	No Asbestos					
	B0D1 - R1013 - Staff Room					
	No Asbestos					
	B0D1 - R1014 - Staff Toilet					
	No Asbestos					
	B0D1 - R1015 - Staff Toilet					
	No Asbestos					
	B0D1 - R1016 - Deputy Principal					
	No Asbestos					
	B0D1 - R1017 - Interview/Office - Type 3					
	No Asbestos					
	B0D1 - R1018 - Principal					
	No Asbestos					
	B0D1 - R1019 - Clerical/Printing					
	No Asbestos					
	B0D1 - R1020 - Clerical/Printing					
	No Asbestos					
	B0D1 - R1021 - External Movement					
	No Asbestos					
	B0D1 - R1022 - Distribution Board					Note: No inspection of live electrical installation.
	No Asbestos					
	B0D1 - R1023 - Main Switch Board					
	No Asbestos					
	B0D1 - R1024 - Movement					
	No Asbestos					
	B0D1 - R1025 - Sports Store					
	No Asbestos					
	B0D1 - R1026 - Special Programs Room					
	No Asbestos					
	B0D1 - R1027 - Special Programs Store					
	No Asbestos					
	B0D1 - R1028 - Special Programs Room					
	No Asbestos					
	B0D1 - R1029 - Special Programs Store					
	No Asbestos					
	B0D1 - R1030 - Reading Area					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0D1 - R1031 - General Storeroom						
No Asbestos						
B0D1 - R1032 - Library Office/Workroom						
No Asbestos						
B0D1 - R1033 - Staff Toilet						
No Asbestos						
B0D1 - R1034 - Communications Room						
No Asbestos						
B0D1 - R1035 - Special Programs Room - Type 2						
No Asbestos						
B0D1 - R1036 - Special Programs Store						
No Asbestos						
B0D1 - R1037 - Special Programs Room - Type 2						
No Asbestos						
B0D1 - R1038 - Special Programs Store						
No Asbestos						
B0D1 - R1039 - Toilets - Boys						
No Asbestos						
B0D1 - R1040 - Disabled Toilet						
No Asbestos						
B0D1 - R1041 - Disabled Toilet						
No Asbestos						
B0D1 - R1042 - Toilets - Girls						
No Asbestos						
B0D1 - R1043 - Cleaning Distributed Store						
No Asbestos						
B0D1 - R1044 - Deputy Principal						
No Asbestos						
B0D1 - R1045 - Movement						
No Asbestos						
B0D1 - R1046 - Stairs						
No Asbestos						
B0D1 - R1047 - Movement						
No Asbestos						
B0D1 - R1048 - Staff Kitchen						
No Asbestos						
B0D1 - R1049 - Staff Kitchen						
No Asbestos						
B0D1 - R1050 - Stairs						
No Asbestos						
B0D1 - R1051 - Plant						
No Asbestos						
B0D1 - R1052 - General Storeroom						
No Asbestos						
B0D1 - R1053 - Plant						
No Asbestos						
B0D1 - R1054 - Plant						
No Asbestos						
B0D1 - R1055 - Plant						
No Asbestos						
B0D1 - R1056 - Plant						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
	No Asbestos					
	B0D1 - R2001 - Practical Activities					
	No Asbestos					
	B0D1 - R2002 - Home Base					
	No Asbestos					
	B0D1 - R2003 - Home Base Store					
	No Asbestos					
	B0D1 - R2004 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R2005 - Practical Activities					
	No Asbestos					
	B0D1 - R2006 - Home Base					
	No Asbestos					
	B0D1 - R2007 - Home Base Store					
	No Asbestos					
	B0D1 - R2008 - Practical Activities					
	No Asbestos					
	B0D1 - R2009 - Home Base					
	No Asbestos					
	B0D1 - R2010 - Home Base Store					
	No Asbestos					
	B0D1 - R2011 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R2012 - Practical Activities					
	No Asbestos					
	B0D1 - R2013 - Home Base					
	No Asbestos					
	B0D1 - R2014 - Home Base Store					
	No Asbestos					
	B0D1 - R2015 - Home Base					
	No Asbestos					
	B0D1 - R2016 - Home Base Store					
	No Asbestos					
	B0D1 - R2017 - Practical Activities					
	No Asbestos					
	B0D1 - R2018 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R2019 - Home Base					
	No Asbestos					
	B0D1 - R2020 - Practical Activities					
	No Asbestos					
	B0D1 - R2021 - Home Base Store					
	No Asbestos					
	B0D1 - R2022 - Toilets - Boys					
	No Asbestos					
	B0D1 - R2023 - Toilets - Girls					
	No Asbestos					
	B0D1 - R2024 - Home Base					
	No Asbestos					
	B0D1 - R2025 - Home Base Store					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0D1 - R2026 - Practical Activities						
No Asbestos						
B0D1 - R2027 - Withdrawal Space - 2hb						
No Asbestos						
B0D1 - R2028 - Home Base						
No Asbestos						
B0D1 - R2029 - Practical Activities						
No Asbestos						
B0D1 - R2030 - Home Base Store						
No Asbestos						
B0D1 - R2031 - Practical Activities						
No Asbestos						
B0D1 - R2032 - Home Base						
No Asbestos						
B0D1 - R2033 - Home Base Store						
No Asbestos						
B0D1 - R2034 - Withdrawal Space - 2hb						
No Asbestos						
B0D1 - R2035 - Practical Activities						
No Asbestos						
B0D1 - R2036 - Home Base						
No Asbestos						
B0D1 - R2037 - Home Base Store						
No Asbestos						
B0D1 - R2038 - Practical Activities - M - 1hb						
No Asbestos						
B0D1 - R2039 - Home Base - M						
No Asbestos						
B0D1 - R2040 - Home Base Store - M						
No Asbestos						
B0D1 - R2041 - Withdrawal - M						
No Asbestos						
B0D1 - R2042 - Practical Activities - M - 1hb						
No Asbestos						
B0D1 - R2043 - Home Base Store - M						
No Asbestos						
B0D1 - R2044 - Home Base Store - M						
No Asbestos						
B0D1 - R2045 - Cleaning Distributed Store						
No Asbestos						
B0D1 - R2046 - Toilets - Girls/Disabled Cubicle						
No Asbestos						
B0D1 - R2047 - Toilets - Boys						
No Asbestos						
B0D1 - R2048 - Toilets - Girls						
No Asbestos						
B0D1 - R2049 - Home Base						
No Asbestos						
B0D1 - R2050 - Home Base Store						
No Asbestos						
B0D1 - R2051 - Practical Activities						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
	No Asbestos					
	B0D1 - R2052 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R2053 - Home Base					
	No Asbestos					
	B0D1 - R2054 - Practical Activities					
	No Asbestos					
	B0D1 - R2055 - Home Base Store					
	No Asbestos					
	B0D1 - R2056 - Distribution Board				Note: No inspection of live electrical installation.	
	No Asbestos					
	B0D1 - R2057 - External Movement					
	No Asbestos					
	B0D1 - R2058 - Distribution Board				Note: No inspection of live electrical installation.	
	No Asbestos					
	B0D1 - R2059 - Movement					
	No Asbestos					
	B0D1 - R2060 - External Movement					
	No Asbestos					
	B0D1 - R2061 - Stairs					
	No Asbestos					
	B0D1 - R2062 - External Stairs					
	No Asbestos					
	B0D1 - R2063 - Stairs					
	No Asbestos					
	B0D1 - R2064 - Stairs					
	No Asbestos					
	B0D1 - R2065 - General Storeroom					
	No Asbestos					
	B0D1 - R2066 - External Movement					
	No Asbestos					
	B0D1 - R2067 - Stairs					
	No Asbestos					
	B0D1 - R2068 - Movement					
	No Asbestos					
	B0D1 - R2069 - Stairs					
	No Asbestos					
	B0D1 - R2070 - Stairs					
	No Asbestos					
	B0D1 - R3001 - Practical Activities					
	No Asbestos					
	B0D1 - R3002 - Home Base					
	No Asbestos					
	B0D1 - R3003 - Home Base Store					
	No Asbestos					
	B0D1 - R3004 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R3005 - Practical Activities					
	No Asbestos					
	B0D1 - R3006 - Home Base					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0D1 - R3007 - Home Base Store						
No Asbestos						
B0D1 - R3008 - Practical Activities						
No Asbestos						
B0D1 - R3009 - Home Base						
No Asbestos						
B0D1 - R3010 - Home Base Store						
No Asbestos						
B0D1 - R3011 - Withdrawal Space - 2hb						
No Asbestos						
B0D1 - R3012 - Practical Activities						
No Asbestos						
B0D1 - R3013 - Home Base						
No Asbestos						
B0D1 - R3014 - Home Base Store						
No Asbestos						
B0D1 - R3015 - Home Base						
No Asbestos						
B0D1 - R3016 - Home Base Store						
No Asbestos						
B0D1 - R3017 - Practical Activities						
No Asbestos						
B0D1 - R3018 - Withdrawal Space - 2hb						
No Asbestos						
B0D1 - R3019 - Home Base						
No Asbestos						
B0D1 - R3020 - Practical Activities						
No Asbestos						
B0D1 - R3021 - Home Base Store						
No Asbestos						
B0D1 - R3022 - Toilets - Boys						
No Asbestos						
B0D1 - R3023 - Toilets - Girls						
No Asbestos						
B0D1 - R3024 - Home Base						
No Asbestos						
B0D1 - R3025 - Home Base Store						
No Asbestos						
B0D1 - R3026 - Practical Activities						
No Asbestos						
B0D1 - R3027 - Withdrawal Space - 2hb						
No Asbestos						
B0D1 - R3028 - Home Base						
No Asbestos						
B0D1 - R3029 - Practical Activities						
No Asbestos						
B0D1 - R3030 - Home Base Store						
No Asbestos						
B0D1 - R3031 - Practical Activities						
No Asbestos						
B0D1 - R3032 - Home Base						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
	No Asbestos					
	B0D1 - R3033 - Home Base Store					
	No Asbestos					
	B0D1 - R3034 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R3035 - Practical Activities					
	No Asbestos					
	B0D1 - R3036 - Home Base					
	No Asbestos					
	B0D1 - R3037 - Home Base Store					
	No Asbestos					
	B0D1 - R3038 - Practical Activities					
	No Asbestos					
	B0D1 - R3039 - Home Base					
	No Asbestos					
	B0D1 - R3040 - Home Base Store					
	No Asbestos					
	B0D1 - R3041 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R3042 - Practical Activities					
	No Asbestos					
	B0D1 - R3043 - Home Base					
	No Asbestos					
	B0D1 - R3044 - Home Base Store					
	No Asbestos					
	B0D1 - R3045 - Disabled Toilet					
	No Asbestos					
	B0D1 - R3046 - Cleaning Distributed Store					
	No Asbestos					
	B0D1 - R3047 - Toilets - Boys					
	No Asbestos					
	B0D1 - R3048 - Toilets - Girls					
	No Asbestos					
	B0D1 - R3049 - Home Base					
	No Asbestos					
	B0D1 - R3050 - Home Base Store					
	No Asbestos					
	B0D1 - R3051 - Withdrawal Space - 1hb					
	No Asbestos					
	B0D1 - R3052 - Practical Activities					
	No Asbestos					
	B0D1 - R3053 - Practical Activities					
	No Asbestos					
	B0D1 - R3054 - Home Base					
	No Asbestos					
	B0D1 - R3055 - Home Base Store					
	No Asbestos					
	B0D1 - R3056 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R3057 - Practical Activities					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0D1 - R3058 - Home Base						
No Asbestos						
B0D1 - R3059 - Home Base Store						
No Asbestos						
B0D1 - R3060 - Practical Activities						
No Asbestos						
B0D1 - R3061 - Home Base						
No Asbestos						
B0D1 - R3062 - Home Base Store						
No Asbestos						
B0D1 - R3063 - Withdrawal Space - 2hb						
No Asbestos						
B0D1 - R3064 - Practical Activities						
No Asbestos						
B0D1 - R3065 - Home Base						
No Asbestos						
B0D1 - R3066 - Home Base Store						
No Asbestos						
B0D1 - R3067 - Home Base						
No Asbestos						
B0D1 - R3068 - Practical Activities						
No Asbestos						
B0D1 - R3069 - Withdrawal Space - 2hb						
No Asbestos						
B0D1 - R3070 - Home Base - S						
No Asbestos						
B0D1 - R3071 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B0D1 - R3072 - External Movement						
No Asbestos						
B0D1 - R3073 - Distribution Board					Note: No inspection of live electrical installation.	
No Asbestos						
B0D1 - R3074 - External Stairs						
No Asbestos						
B0D1 - R3075 - Movement						
No Asbestos						
B0D1 - R3076 - Stairs						
No Asbestos						
B0D1 - R3077 - Stairs						
No Asbestos						
B0D1 - R3078 - External Stairs						
No Asbestos						
B0D1 - R3079 - External Stairs						
No Asbestos						
B0D1 - R3080 - Movement						
No Asbestos						
B0D1 - R3081 - Stairs						
No Asbestos						
B0D1 - R3082 - Stairs						
No Asbestos						
B0D1 - R3083 - Movement						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
	Sample No					Test Result
	No Asbestos					
	B0D1 - R3084 - Stairs					
	No Asbestos					
	B0D1 - R3085 - Stairs					
	No Asbestos					
	B0D1 - R4001 - Home Base					
	No Asbestos					
	B0D1 - R4002 - Home Base Store					
	No Asbestos					
	B0D1 - R4003 - Practical Activities					
	No Asbestos					
	B0D1 - R4004 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R4005 - Home Base					
	No Asbestos					
	B0D1 - R4006 - Practical Activities					
	No Asbestos					
	B0D1 - R4007 - Home Base Store					
	No Asbestos					
	B0D1 - R4008 - Home Base					
	No Asbestos					
	B0D1 - R4009 - Home Base Store					
	No Asbestos					
	B0D1 - R4010 - Practical Activities					
	No Asbestos					
	B0D1 - R4011 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R4012 - Home Base					
	No Asbestos					
	B0D1 - R4013 - Practical Activities					
	No Asbestos					
	B0D1 - R4014 - Home Base Store					
	No Asbestos					
	B0D1 - R4015 - Home Base					
	No Asbestos					
	B0D1 - R4016 - Home Base Store					
	No Asbestos					
	B0D1 - R4017 - Practical Activities					
	No Asbestos					
	B0D1 - R4018 - Withdrawal Space - 2hb					
	No Asbestos					
	B0D1 - R4019 - Home Base					
	No Asbestos					
	B0D1 - R4020 - Practical Activities					
	No Asbestos					
	B0D1 - R4021 - Home Base Store					
	No Asbestos					
	B0D1 - R4022 - Toilets - Boys					
	No Asbestos					
	B0D1 - R4023 - Disabled Toilet					
	No Asbestos					

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	
B0D1 - R4024 - Cleaning Distributed Store						
No Asbestos						
B0D1 - R4025 - Toilets - Girls						
No Asbestos						
B0D1 - R4026 - Home Base						
No Asbestos						
B0D1 - R4027 - Home Base Store						
No Asbestos						
B0D1 - R4028 - Practical Activities						
No Asbestos						
B0D1 - R4029 - Withdrawal Space - 1hb						
No Asbestos						
B0D1 - R4030 - Home Base						
No Asbestos						
B0D1 - R4031 - Home Base Store						
No Asbestos						
B0D1 - R4032 - Practical Activities						
No Asbestos						
B0D1 - R4033 - Withdrawal Space - 2hb						
No Asbestos						
B0D1 - R4034 - Home Base						
No Asbestos						
B0D1 - R4035 - Practical Activities						
No Asbestos						
B0D1 - R4036 - Home Base Store						
No Asbestos						
B0D1 - R4037 - External Movement						
No Asbestos						
B0D1 - R4038 - Toilets - Girls						
No Asbestos						
B0D1 - R4039 - Toilets - Boys						
No Asbestos						
B0D1 - R4040 - Movement						
No Asbestos						
B0D1 - R4041 - Stairs						
No Asbestos						
B0D1 - R4042 - External Stairs						
No Asbestos						
B0D1 - R4043 - External Movement						
No Asbestos						
B0D1 - R4044 - External Stairs						
No Asbestos						
B0D1 - R4045 - External Stairs						
No Asbestos						
B0D1 - R4046 - External Stairs						
No Asbestos						
B0D1 - R4047 - Distribution Board						
No Asbestos					Note: No inspection of live electrical installation.	
No Asbestos						

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

B0D2 - Storage - 2016 - Metal Clad (Metal Clad)

Exterior

Ceiling Void	No Asbestos Found
Underfloor Void	No Asbestos Found

Interior

B0D2 - R0001 - Garden Store

No Asbestos

B0D2 - R0002 - External Movement

No Asbestos

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Demountables

There are no Demountable(s) located at this school as per the AMS records as of 15 Feb 2017.

2017

Product	Material Description	Extent	Location Reference	Material Condition	Risk Status	Control Priority
Sample No					Test Result	

Listing of Electronic Attachments as of 22/03/2017

There are no asbestos related file attachment(s) for this school.

2017